

Surveyor

REF: CS3 / FWD18018534 / G116<sup>52</sup>-1

Special Instruction:

ASSIGNMENT (Office)

From (Person): Clara Li of FWD Date/Time: 22/11/2018  
Estimated Cost: Bill to:

US: \$ 12500.00

Third Parties:

Claimant:

Surveyor: Sincere Appraisal

Workshop: Team Auto pro

OD/FP Re-inspection / Evaluation

To Inspect Vehicle No: SJU 8171H Insured: SGG 1389C  
at Workshop m/s Team Auto pro Tel:  
of 8 Kaki Bukit Ave 4 # 01-07

Policy No: Claim No: 1201800012743 -002/CL

Sum Insured: Excess:

Make of Veh: D.O.A. 04-10-2018  
(Client's Record)

28-11-2018 (Wednesday) @ 4pm

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig, days (Red \$ / %; Original 8 days)

Date/Time: 28/12/18 Submit Final Fig 6550, 7 days (Red \$ 5950, 48%; Original 8 days)

Date/Time	Action/Instruction
	385 Sim Ming Dr #01-02 Vam Inspection Centre (Beside Exit Gate) (KC-8139 9703)
	SJU 8171H - CS3 / FWD18018534 / G116 <sup>52</sup>
	SGG 1389C - X
	D.O.A. 04-10-2018
	RECEIVED 27 DEC 2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Put Doc @ mention

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

Fee Charged:

Basic & Add  
Transport  
Photos  
Others  
Total

Date:


- 1) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_ 2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_
- 3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_ 4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_
- 5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_ 6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_



ASS. REC. BY:

REF: CS3|FWD18018534|Gcd3<sup>92</sup> Special Instruction:

Surveyor: Gino Giano  
Munier clara ti

ASSIGNMENT (Office)

From (Person): clara ti of FWD Date/Time: 11/10/18 6:10 pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJU 8171H Insured: SAG 1389C

at Workshop m/s Team Autopro Tel: 6258 1955

of No. 8 kaki Blk Ave 4 # 06-21 Premier

Policy No: \_\_\_\_\_ Claim No: 1201800012743/CL

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 04/10/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>1up?</sup> H.O.D. Endorsement: 15/10/2018

Date/Time: 12/10/18 10:16am Person Contacted: Michelle Vehicle-IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	<u>SJU 8171H - X</u>
	<u>SAG 1389C - X.</u>
	<u>Dismantle: 16/10/2018</u>



## Catherine Chong (LKK Auto)

---

**From:** clara.li@fwd.com  
**Sent:** Thursday, 22 November, 2018 3:11 PM  
**To:** roynpartners@roynpartners.com.sg  
**Cc:** motorclaims.sg@fwd.com; assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Subject:** [Acknowledgement & Request for Re-Inspection] Your Ref: MKR/404/8310/2018/as.wl Our Ref: 1201800012743-002/CL

### WITHOUT PREJUDICE

Dear Sir,

We acknowledge receipt of your Letter of Demand dated 05 November 2018 with enclosures received on 09 November 2018.

We would like to conduct a physical re-inspection on your client's vehicle SJU8171H.

Please advise our appointed surveyor M/s LKK Auto Consultant Pte Ltd on the date, time and venue 5 working days in advance.

Thank you.

*\*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

*\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.*

Kind Regards

Clara Li  
Senior Executive, Claims

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722  
E [clara.li@fwd.com](mailto:clara.li@fwd.com)  
W [fwd.com.sg](http://fwd.com.sg)



**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**Catherine Chong (LKK Auto)**

---

**From:** clara.li@fwd.com  
**Sent:** Thursday, 22 November, 2018 6:14 PM  
**To:** assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Cc:** teamautooffice@gmail.com; ashley@roypartners.com.sg; motorclaims.sg@fwd.com; william@roypartners.com.sg  
**Subject:** RE: [Acknowledgement & Request for Re-Inspection] Your Ref: MKR/404/8310/2018/as.wl Our Ref: 1201800012743-002/CL

Hi LKK team,

Please confirm the RI arrangement below with William.

Thank you.

*\*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

*\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.*

Kind Regards

Clara Li  
Senior Executive, Claims

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722  
E [clara.li@fwd.com](mailto:clara.li@fwd.com)  
W [fwd.com.sg](http://fwd.com.sg)



---

**From:** William Lee [<mailto:william@roypartners.com.sg>]  
**Sent:** Thursday, 22 November, 2018 6:09 PM

**To:** Clara Li Zirong - SGUser; Motor Claims SG - SG Common

**Cc:** 'TeamAuto Pro'; 'Ashley (Mr)'

**Subject:** RE: [Acknowledgement & Request for Re-Inspection] Your Ref: MKR/404/8310/2018/as.wl Our Ref: 1201800012743-002/CL

**Importance:** High

Dear Sirs,

We refer to our email below.

Kindly let us have your confirmation to the appointment below for re-inspection:28

Date : 28<sup>th</sup> November 2018 (Wednesday)  
Time : 4.00 pm  
Venue : 385 Sin Ming Drive #01-02 Vicom Inspection Centre Singapore 575718 (Beside Exit Gate)  
Contact : 8139 9703 (KC)

Kindly let us have your reply as soon as possible.

Thanks & regards,

**William Lee**

M/s Roy & Partners

101 Cecil Street

#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : [william@roypartners.com.sg](mailto:william@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

**From:** TeamAutoPro North [<mailto:teamautopl@gmail.com>]

**Sent:** Thursday, 22 November, 2018 4:58 PM

**To:** William Lee <[william@roypartners.com.sg](mailto:william@roypartners.com.sg)>

**Cc:** TeamAuto Pro <[teamautooffice@gmail.com](mailto:teamautooffice@gmail.com)>; Ashley (Mr) <[ashley@roypartners.com.sg](mailto:ashley@roypartners.com.sg)>

**Subject:** Re: [Acknowledgement & Request for Re-Inspection] Your Ref: MKR/404/8310/2018/as.wl Our Ref: 1201800012743-002/CL

Dear William,

28/11/2018 4pm survey at Sin Ming Vicom.

Please let me know if this is a good timing.

--

\*The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.\*

-----  
Cheers,



# SINCERE

APPRAISAL SERVICES PTE LTD

## VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 750/TP/2018

Date: 26/10/2018

### REFERENCE

Date of loss: 4/10/2018  
 Claimant: Stanley Express

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU8171H	Make &	Chevrolet
Reg date:	29/12/2009	Model	Cruze 1.6L Auto
Colour:	Silver	Engine No:	F16D35140601
Type:	Motor Car	Chassis No:	KL1JA6961AK587581
Type of Claims:	Third Party	Odometer No:	176199km
		Engine Cap:	1598cc

### CONDITION OF VEHICLE AT THE TIME OF SURVEY (STATIC ONLY)

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

### CONDITION OF TYRES

Front Left Size: Goodyear 215/55R17 70%	Front Right Size: Goodyear 215/55R17 70%
Rear Left Size: Goodyear 215/55R17 70%	Rear Right Size: Goodyear 215/55R17 70%

*The above percentages represent the remaining life of the tyre threads*

### COST OF REPAIRS


	Repairer S\$	Adjuster S\$
Parts	\$ 11,587.60	\$ 10,306.90
Labour	\$ 6,420.00	\$ 5,300.00
Calculated Cost (S\$) :	<u>\$ 18,007.60</u>	<u>\$ 15,606.90</u>

**Recommended Lump Sum Repair Cost (S\$) : \$ 12,500.00**

Date of Assignment: 15/10/2018  
 Date Inspected: 15/10/2018  
 Est. repair Period: 08 days

Inspected At: Team AutoPro Pte Ltd  
 8 Kaki Bukit Avenue 4  
 #01-07 Premier  
 Singapore 415875

## POINT OF IMPACT

Damaged at the front, left hand front and left hand rear portion	
--	--

## BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle at the Shell Petrol Kiosk of Sri Pelangi Road, Johor Bahru, Malaysia.

## GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the front, left hand front and left hand rear portion.

## SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$18,007.60. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$12,500.00.

We have not authorised the repair. Under normal circumstances, estimated **08** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



**Dave Chang**  
Automotive Appraiser  
AUTO. ENG, CAE, CGI  
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

*Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.*

ANNEX A

**REPAIR DETAILS**

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Front bumper assy	dented/warped/grazed	\$ 845.00	\$ 845.00 ✓
2	1	Front bumper left bracket	bent/necessary	\$ 66.00	\$ 66.00 X <i>NA</i>
3	1	Front bumper left side retainer	bent/necessary	\$ 66.00	\$ 66.00 ✓
4	1	Front left fender assy	dented/warped/grazed	\$ 882.00	\$ 882.00 ✓
5	1	Front left wing mirror assy	malfunction	\$ 478.00	\$ 478.00 X <i>Repair</i>
6	1	Front left door panel	grazed/dented	\$ 1,235.00	\$ 1,235.00 ✓
7	2	Front left door hinges	bent/necessary	\$ 126.00	\$ 126.00 X
8	1	Front left door lock mechanism	bent	\$ 283.00	\$ 283.00 X
9	1	Front left door regulator with motor	malfunction	\$ 498.00	\$ 498.00 X <i>NA</i>
10	1	Front left lower arm	bent	\$ 395.00	\$ 395.00 X
11	1	Front left knuckle arm	bent	\$ 452.00	\$ 452.00 X
12	1	Front left suspension assy	bent	\$ 1,120.00	\$ 1,120.00 ✓
13	1	Front left wheel hub bearing	necessary	\$ 351.00	\$ 351.00 ✓
				\$ 6,797.00	\$ 6,797.00 <i>3379</i>
		Less 10%		\$ 679.70	\$ 679.70
				\$ 6,117.30	\$ 6,117.30 <i>3099.1</i>
<u>Special Nett Items</u>					
1	10	Front bumper clips	necessary	\$ 50.00	\$ 50.00 ✓
2	1	Front left wheel rim	grazed/cut	\$ 750.00	\$ 750.00 <i>550</i>
3	1	Front no plate with garnish	necessary	\$ 80.00	\$ 80.00 X <i>NA</i>
				\$ 880.00	\$ 880.00 <i>600</i>
<b>Total parts</b>				\$ 6,997.30	\$ 6,997.30

ANNEX A

**REPAIR DETAILS**

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Rear left fender	repair	\$ 1,423.00	\$ -
2	1	Rear left door panel	grazed/dented	\$ 1,235.00	\$ 1,235.00 ✓
3	2	Rear left door hinges	necessary/bent	\$ 126.00	\$ 126.00 X
4	1	Rear left door regulator with motor	malfunction	\$ 398.00	\$ 398.00 X
5	1	Rear left door lock mechanism	bent	\$ 253.00	\$ 253.00 X
6	1	Rear left shock absorber assy	bent	\$ 560.00	\$ 560.00 X
7	1	Rear left wheel hub bearing	necessary	\$ 272.00	\$ 272.00 ✓
				\$ 4,267.00	\$ 2,844.00 (15%)
Less 10%				\$ 426.70	\$ 284.40
				<u>\$ 3,840.30</u>	<u>\$ 2,559.60</u> 1356.3
 <u>Special Nett Items</u>					
1	1	Rear left wheel rim	grazed/cut	\$ 750.00	\$ 750.00 550
				<u>\$ 750.00</u>	<u>\$ 750.00</u>
 <b>Total parts</b>				 <b>\$ 4,590.30</b>	 <b>\$ 3,309.60</b>

ANNEX B

**REPAIR DETAILS**

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten front, front left affected area and replace front and front left damaged parts.	\$ 1,200.00	\$ 1,000.00 400
2	To putty and spray painting front and front left portion.	\$ 1,200.00	\$ 1,000.00 700
3	To apply anti rust proofing to front and front left affected area.	\$ 120.00	\$ 100.00 40
4	To balance front left wheel.	\$ 50.00	\$ 30.00 /
5	To remove and install front left undercarriage parts.	\$ 350.00	\$ 300.00 100
6	To remove and install front left door lock mechanism.	\$ 80.00	\$ 60.00 30
7	To transfer front left door glass to new door.	\$ 80.00	\$ 60.00 30
8	Labour for panel beating, cut, weld, straighten rear left affected area and replace rear left damaged parts.	\$ 1,200.00	\$ 1,000.00 400
9	To putty and spray painting rear left portion.	\$ 1,200.00	\$ 1,000.00 600
10	To apply anti rust proofing to rear left affected area.	\$ 120.00	\$ 100.00 40
11	To balance rear left wheel.	\$ 50.00	\$ 30.00 /
12	To conduct wheel alignment.	\$ 80.00	\$ 60.00 /
13	To remove and install rear left undercarriage parts.	\$ 350.00	\$ 300.00 100
14	To remove and install rear left door lock mechanism.	\$ 80.00	\$ 60.00
15	To check door central locking for function.	\$ 80.00	\$ 60.00 80
16	To transfer rear left door glass to new door.	\$ 80.00	\$ 60.00
17	Towing service.	\$ 100.00	\$ 80.00 x MV
<b>Total labour :</b>		<b>\$ 6,420.00</b>	<b>\$ 5,300.00</b>

2640

ANNEX C

**REPAIR DETAILS**

Adjusted Repair Cost

8187.4  
20% = 6550

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 11,587.60	\$ 10,306.90
Total labour :	\$ 6,420.00	\$ 5,300.00
<b>Total repair cost :</b>	<b>\$ 18,007.60</b>	<b>\$ 15,606.90</b>

**Adjusted Repair Cost (Lump Sum Repair)**

**\$ 12,500.00**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS3/FWD18018534/Gtbs2-1	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986		Date : 27-12-2018	
		Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SGG 1389C	Veh. Inspected	SJU 8171H
Policy No.	PNPV2017-00003447-01	Coverage (\$)	0.00
Claim No.	1201800012743	Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	22/11/2018
2. Vehicle Particulars & Condition			
Make & Model	CHEVROLET CRUZE	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KL1JA6961AK587581	Colour	SILVER
Odometer	183028	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55R17	GOODYEAR	5 mm
L/H Front Tyre	215/55R17	GOODYEAR	5 mm
R/H Rear Tyre	215/55R17	YOKOHAMA	5 mm
L/H Rear Tyre	215/55R17	YOKOHAMA	5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	04/10/2018	Inspection Date	28/11/2018
Survey held at	385 SIN MING DRIVE #01-02		
Repairer	TEAM AUTOPRO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 8171H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER ASSY	REPLACED	845.00	845.00
1	FRONT BUMPER LEFT BRACKET	NOT NECESSARY	66.00	-
1	FRONT BUMPER LEFT SIDE RETAINER	REPLACED	66.00	66.00
1	FRONT LEFT FENDER ASSY	REPLACED	882.00	882.00
1	FRONT LEFT WING MIRROR ASSY	REPAIRED SEE LABOUR	478.00	-
1	FRONT LEFT DOOR PANEL	REPLACED	1,235.00	1,235.00
2	FRONT LEFT DOOR HINGES	NOT NECESSARY	126.00	-
1	FRONT LEFT DOOR LOCK MECHANISM	NOT NECESSARY	283.00	-
1	FRONT LEFT DOOR REGULATOR WITH MOTOR	NOT NECESSARY	498.00	-
1	FRONT LEFT LOWER ARM	NOT NECESSARY	395.00	-
1	FRONT LEFT KNUCKLE ARM	NOT NECESSARY	452.00	-
1	FRONT LEFT SUSPENSION ASSY	NOT NECESSARY	1,120.00	-
1	FRONT LEFT WHEEL HUB BEARING	REPLACED	351.00	351.00
1	REAR LEFT FENDER	REPAIRED SEE LABOUR	1,423.00	-
1	REAR LEFT DOOR PANEL	REPLACED	1,235.00	1,235.00
2	REAR LEFT DOOR HINGES	NOT NECESSARY	126.00	-
1	REAR LEFT DOOR REGULATOR WITH MOTOR	NOT NECESSARY	398.00	-
1	REAR LEFT DOOR LOCK MECHANISM	NOT NECESSARY	253.00	-
1	REAR LEFT SHOCK ABSORBER ASSY	NOT NECESSARY	560.00	-
1	REAR LEFT WHEEL HUB BEARING	REPLACED	272.00	272.00
	LESS 10% DISCOUNT		-1,106.40	-488.60
			9,957.60	4,397.40
<b><u>SPECIAL NETT ITEMS</u></b>				
10	FRONT BUMPER CLIPS (SN)	REPLACED	50.00	50.00
1	FRONT LEFT WHEEL RIM (SN)	REPLACED	750.00	550.00
1	FRONT NO PLATE WITH GARNISH (SN)	NOT NECESSARY	80.00	-
1	REAR LEFT WHEEL RIM (SN)	REPLACED	750.00	550.00
			1,630.00	1,150.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT, FRONT LEFT AFFECTED AREA AND REPLACE FRONT AND FRONT LEFT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT LEFT WING MIRROR ASSY.		1,200.00	400.00
	TO PUTTY AND SPRAY PAINT FRONT AND FRONT LEFT PORTION.		1,200.00	700.00
	TO APPLY ANTI RUST PROOFING TO FRONT AND FRONT LEFT AFFECTED AREA.		120.00	40.00
	TO BALANCE FRONT LEFT WHEEL.		50.00	30.00
	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS.		350.00	100.00
	TO REMOVE AND INSTALL FRONT LEFT DOOR LOCK MECHANISM.		80.00	30.00
	TO TRANSFER FRONT LEFT DOOR GLASS TO NEW DOOR.		80.00	30.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR LEFT AFFECTED AREA AND REPLACE REAR LEFT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR LEFT FENDER.		1,200.00	400.00
	TO PUTTY AND SPRAY PAINTING REAR LEFT PORTION.		1,200.00	600.00
	TO APPLY ANTI RUST PROOFING TO REAR LEFT AFFECTED AREA.		120.00	40.00
	TO BALANCE REAR LEFT WHEEL.		50.00	30.00
	TO CONDUCT WHEEL ALIGNMENT.		80.00	60.00
	TO REMOVE AND INSTALL REAR LEFT UNDERCARRIAGE PARTS.		350.00	100.00
	TO REMOVE AND INSTALL REAR LEFT DOOR LOCK MECHANISM. }		80.00	80.00
	TO CHECK DOOR CENTRAL LOCKING FOR FUNCTION. }		80.00	-
	TO TRANSFER REAR LEFT DOOR GLASS TO NEW DOOR. }		80.00	-
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			<b>6,420.00</b>	<b>2,640.00</b>
	<b>GRAND TOTAL</b>		<b>18,007.60</b>	<b>8,187.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,550.00</b>

Report Ref No. CS3/FWD18018534/Gtbs2-1



Report Ref No. CS3/FWD18018534/Gtbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.