

ASS. REC. BY:

REF:

CS/GAU8021310/Dgbn2

Special Instruction:

Surveyor:

Bryan

ASSIGNMENT (Office)

From (Person):

Sharon Ng

of

GAL

Date/Time:

23/11/2018 11:01am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 8026Z

Insured:

GHE 4553K

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

Blk 10 Amk Ind Park 2A #03-19

Policy No:

Claim No:

CLMDMVP000000910

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20-11-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

23-11-2018 11:11am

Person Contacted:

Lore

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 8026Z - X

GHE 4553K - CVI / ML13013582 / US

29/11/18 @ 3:18pm revised to Sharon Ng by email.

REF:

Surveyor

ASSIGNMENT

8026

COE June 2023

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s:

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 12.10 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHA 826 Z

Yr Regn:

2015 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

C.C.

1685

Colour

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

553224

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDEU# 416994

C/No:

KMH LB41UMGU074935

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5'

mm

R/Bal.

5'

mm

L/Bal.

5'

mm

L/Bal.

5'

mm

D.O.A.

20/11/2018

D.O.I.

23/11/2018

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frnt y N/S Body y N/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Great American SGE 4553K

10/12/18

Invoice 2/5 18600/- with 12 days of work
(Red 19351.60, 51%)

RECEIVED 13 DEC 2018

Date/Time, File Pass to?



: Preli. Report

11/12/18



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

12

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S * RS * SI

Photos

Others

TOTAL

450

Report Format :

TP

Lump Sum / I.B.I. (\$

18600

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CLMOMVP000000910

Date: 29th November 2018

Our Ref: CS/GAI18021210/Dqb

The Motor Claims Department
Great American Insurance Company

Attn: Sharon Ng

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHA 8026Z .


We thank you for the instruction on 23/11/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/11/2018 at the premises of M/s CHUNNI MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>37,951.60</u> .
Revised Estimate Amount	: S\$ <u>23,216.88</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the n/s front, n/s rear portion & n/s body.



Comments/ Present Status:

Damages consistent.

We have NOT authorise repair.

Yours faithfully

ANG BRYAN TANI

Automotive Assessor / Investigator

Catherine Chong (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com> on behalf of Motor Claims <MotorClaims@sg.gaig.com>
Sent: Friday, 23 November, 2018 11:01 AM
To: SUR; assignments
Subject: RE: Re: Fwd: Accident involving veh no: SHA 8026Z & SGE 4553K on 20.11.18 || GAIC ref: CLMOMVP000000910
Attachments: SGE4553K (OI).pdf; SHA8026Z (FCI).pdf; Estimates.pdf

Dear LKK

Please arrange TP survey to SHA8026Z. **AMK Autopoint, Soon Hock Motor,#01-05/06.**

Regards
Sharon Ng
Great American

From: Chunni Motor <chunnimotor@gmail.com>
Sent: Friday, November 23, 2018 10:38 AM
To: Motor Claims <MotorClaims@sg.gaig.com>
Subject: [External] Re: Fwd: Accident involving veh no: SHA 8026Z & SGE 4553K on 20.11.18

Dear Sir,

We agree to appoint LKK Auto Consultants P/L

Thank you

Regards,
Lynn
Chunni Motor Work P/L

----- Forwarded message -----

From: **Chunni Motor** <chunnimotor@gmail.com>
Date: Wed, Nov 21, 2018 at 4:57 PM
Subject: Accident involving veh no: SHA 8026Z & SGE 4553K on 20.11.18
To: General Claims <generalclaims@sg.gaig.com>

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor,#01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 29 November 2018 3:18 PM
To: 'Motor Claims'
Cc: SUR; assignments
Subject: RE: Re: Fwd: Accident involving veh no: SHA 8026Z & SGE 4553K on 20.11.18 || GAIC ref: CLMOMVP000000910
Attachments: CSGAI18021210Dqb.pdf

Dear Sharon,

Enclosed herewith preliminary advice of SHA 8026Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 23 November 2018 11:14 AM
To: 'Motor Claims' <MotorClaims@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: Re: Fwd: Accident involving veh no: SHA 8026Z & SGE 4553K on 20.11.18 || GAIC ref: CLMOMVP000000910

Dear Sharon,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon [<mailto:Sharon.Ng@sg.gaig.com>] **On Behalf Of** Motor Claims
Sent: Friday, 23 November, 2018 11:01 AM
To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: Re: Fwd: Accident involving veh no: SHA 8026Z & SGE 4553K on 20.11.18 || GAIC ref: CLMOMVP000000910

Dear LKK

Please arrange TP survey to SHA8026Z. AMK Autopoint, Soon Hock Motor, #01-05/06.

Regards
Sharon Ng
Great American

SHA 8026Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender Advertisement Logo (LH) <i>Nec</i>			\$ 100.00	Nett ✓
	Front Door Comfort Logo (LH) <i>Nec</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (LH) <i>Nec</i>			\$ 100.00	Nett ✓
	Front Windscreen Sealant <i>Nec</i>			\$ 46.00	Nett ✓
	Front Tyre (LH) <i>Svc</i>		321.00	\$ 216.00	Nett X
				\$ 537.00	
	Rear Bumper <i>distorted / deformed</i>			\$ 553.00	✓
	Rear Bumper Clip 10 pcs <i>Nec</i>			\$ 22.00	✓
	Rear Fender With Housing (LH) <i>from Dental</i>		2020.00	\$ 4,736.80	X ✓
	Rear Fender Inner Lining (LH) <i>Svc</i>			\$ 169.30	X
	Rear Windscreen Moulding <i>distorted</i>			\$ 28.30	X ✓
	Rear Door (LH) <i>from</i>			\$ 2,201.10	X
	Rear Door Rubber (LH) <i>Svc</i>			\$ 280.50	X
	Rocker Panel Outer Garnish (LH) <i>mounting plate</i>			\$ 341.40	✓
	Rear Tyre Rim (LH) <i>2 distorted</i>			\$ 325.30	2 ✓
	Rear Wheel Hub-Cap (LH) <i>cut</i>			\$ 107.10	✓
	Rear Wheelbearing IN & Hub <i>2 Down</i>			\$ 362.00	2 ✓
	Rear Trailing Arm (LH) <i>2 distorted</i>			\$ 192.00	2 ✓
	Rear Assist (LH) <i>2 distorted</i>			\$ 145.70	2 ✓
	Rear Shock Absorber (LH) <i>2 distorted</i>			\$ 276.30	2 ✓
	Rear Shock Absorber Mounting (LH) <i>Nec</i>			\$ 81.30	X
	Rear Crossmember <i>Nec</i>			\$ 1,021.50	X
	Stabilizer Bar <i>2 distorted</i> <i>Nec</i>			\$ 199.60	2 from X
	Stabilizer Link <i>2 distorted</i> <i>Nec</i>			\$ 85.90	2 from X
	Rear Upper Arm (LH) <i>2 distorted</i>		5608.25	\$ 335.75	2 ✓
	Rear Lower Arm (LH) <i>2 distorted</i>		4486.60	\$ 353.80	2 ✓
	Rear Knuckle Arm (LH) <i>2 distorted</i>			\$ 545.60	2 ✓
				\$ 12,364.25	
				\$ 2,472.85	
				\$ 9,891.40	
	Rear Bumper Advertisement Logo <i>Nec</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>Nec</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>Nec</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>distorted</i> <i>Nec</i>			\$ 46.00	Nett X ✓
	Rear Door Advertisement Logo (LH) <i>Nec</i>			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>Nec</i>			\$ 80.00	Nett ✓
	Rear Tyre (LH) <i>Svc</i>		526.00	\$ 216.00	Nett X
				\$ 742.00	

SHA 8026Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,400.00 1200/-
	Spray Painting Charge			\$ 1,800.00 1200/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 50.00 NM
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 40 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	Transfer of Door		\$ 120.00	\$ 240.00 60/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Four Wheel Alignment			\$ 120.00 60/-
	Re-set Frt & Rear ABS System		\$ 200.00	\$ 400.00 NM
	Re-set Frt & Rear Power Window System		\$ 200.00	\$ 400.00 NM
	Remove/Refix Aircon & Refill Gas			\$ 150.00 NM
	Remove/Refix Engine			\$ 500.00 NM
	Remove/Refix Dashboard			\$ 350.00 NM
	Remove/Refix Fuse Box			\$ 180.00 NM
	Remove/Refix Front Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 NM
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 NM
			3170.00	
	TOTAL LABOUR			\$ 8,320.00
	ESTIMATE TOTAL			\$ 37,951.60
	23/11/2018 @ 1400hrs		23342.88	
	N/A Antenna		4/5 18600/-	
	L/Smm 12			
	1 ryan			
	LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHA 8026 Z
Technician:
Mileage: 553223
Time Printed 22.11.18 5:12 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-3°29'		-3°00' 3°00'
4°12'		-0°19' 5°41'
-7°10'		-1°30' 1°30'
21°47'		
18°18'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-1°22'		-3°00' 3°00'
4°11'		-0°19' 5°41'
0°30'		-1°30' 1°30'
13°48'		
12°25'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-2°07'		-3°00' 3°00'
0°01'		-3°00' 3°00'
8°00'		-3°00' 3°00'
-6°40'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
1°48'		-3°30' 2°30'
5°44'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
1°34'		-3°30' 2°30'
0°46'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°15'		-3°00' 3°00'
6°30'		-3°00' 3°00'
2°29'		-3°00' 3°00'

Thank you for your kind assistance.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18021210/Dqbn2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 19-12-2018		
		Code : GAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGE 4553K	Veh. Inspected	SHA 8026Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVP000000910	Excess (\$)	0.00	
Assign From	SHARON NG	Assign Date	23/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU074935	Colour	YELLOW	
Odometer	553224	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT, N/S REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/11/2018	Inspection Date	23/11/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8026Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	DISTORTED / CRACKED	1,052.20	1,052.20
1	FRONT BUMPER BRACKET (LH)	SERVICEABLE	24.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (LH)	MOUNTING CRACKED	1,388.00	1,388.00
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	174.90	-
1	FRONT DOOR (LH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR RUBBER	NECESSARY	290.50	290.50
1	FRONT DOOR GEAR/REGULATOR (LH)	CRACKED	250.60	250.60
1	FRONT DOOR HIGE UPPER (LH)	NOT NECESSARY	36.10	-
1	FRONT DOOR HINGE LOWER (LH)	NOT NECESSARY	36.10	-
1	FRONT DOOR CHECK (LH)	NOT NECESSARY	39.20	-
1	FRONT DOOR POWER MOTOR,LH	NOT NECESSARY	172.70	-
1	FRONT DOOR TRIM BOARD (LH)	MOUNTING CRACKED	973.50	973.50
1	DOOR CENTRE PILLAR OUTER (LH)	DENTED	2,527.80	2,527.80
1	FRONT WINDSCREEN MOULDING	NECESSARY	113.30	113.30
1	FRONT WINDSCREEN PILLAR OUTER (LH)	DENTED	1,745.50	1,745.50
1	FRONT WHEEL RIM (LH)	DISTORTED	325.30	325.30
1	FRONT WHEEL HUB CAP (LH)	CUT	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	150.90	150.90
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (LH)	DISTORTED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	969.60	969.60
1	STG TIE END	DISTORTED	62.60	62.60
1	STABILIZER BAR	DISTORTED	252.30	252.30
1	STABILIZER BAR BUSH (LH)	NOT NECESSARY	16.40	-
1	STABILIZER BAR LINK	DISTORTED	61.10	61.10
1	STABILIZER BRACKET	NOT NECESSARY	24.00	-

Report Ref No. CS/GAI18021210/Dqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	529.30	529.30
1	KNUCKLE ARM (LH)	DISTORTED	552.00	552.00
1	ENGINE UNDER COVER	NOT NECESSARY	334.60	-
1	ENGINE CROSSMEMBER	DISTORTED	2,094.40	2,094.40
1	ABS SENSOR	NOT NECESSARY	234.00	-
1	WIRING-ENGINE	NOT NECESSARY	3,326.00	-
1	REAR BUMPER	DISTORTED / DEFORMED	553.00	553.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR FENDER (LH)	DENTED	4,736.80	2,020.00
1	REAR FENDER INNER LINING (LH)	SERVICEABLE	169.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (LH)	TO REPAIR SEE LABOUR	2,201.10	-
1	REAR DOOR RUBBER (LH)	SERVICEABLE	280.50	-
1	ROCKER PANEL OUTER GARNISH (LH)	MOUNTING CRACKED	341.40	341.40
1	REAR TYRE RIM (LH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (LH)	CUT	107.10	107.10
1	REAR WHEELBEARING IN & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (LH)	DISTORTED	192.00	192.00
1	REAR ASSIST (LH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,021.50	-
1	STABILIZER BAR	NOT NECESSARY	199.60	-
1	STABILIZER LINK	NOT NECESSARY	85.90	-
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-7,088.15	-4,831.47
			28,352.60	19,325.88
SPECIAL NETT ITEMS				
1	FRONT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00

Report Ref No. CS/GAI18021210/Dqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT TYRE (LH)(SN)	SERVICEABLE	216.00	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
			1,279.00	847.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR (LH).		2,400.00	1,200.00
	SPRAY PAINTING CHARGE.		1,800.00	1,200.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		150.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	TRANSFER OF DOOR.		240.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	RE-SET FRT & REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	RE-SET FRT & REAR POWER WINDOW SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	REMOVE/REFIX ENGINE.	NOT NECESSARY	500.00	-
	REMOVE/REFIX DASHBOARD.	NOT NECESSARY	350.00	-
	REMOVE/REFIX FUSE BOX.	NOT NECESSARY	180.00	-

Report Ref No. CS/GAI18021210/Dqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX FRONT WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT.	NOT NECESSARY	90.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			8,320.00	3,170.00
	GRAND TOTAL		37,951.60	23,342.88
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,600.00

Report Ref No. CS/GAI18021210/Dqbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.