Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18021217/JES3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

e Ltd Policy No:

Claimant PC Vehicle No :

PC3663L Insured Vehicle No: SHD1812B

Date of Loss: 17/08/2016 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC3663L

 Make & Model:
 MERCEDES-BENZ 0405G, 12.0 D (A)
 Engine No:
 HIDDEN

 Reg. Date:
 23/03/2015 (Man. Year: 2015)
 Chassis No:
 BE641JJ10175

Colour: White Odometer: 0 km

Engine Capacity: 2998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 117/116N Rear Tyre Size: 117/116N

Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm

Front Right Side: West Lake 7 mm

Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,381.57	1,628.71	2,752.86	62.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,310.00	1,450.00	52.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,141.57	2,938.71	4,202.86	58.85
Approved Total (Overridden) (S\$)	2,600.00			
Nett Amount (S\$)	7,141.57	2,600.00	4,541.57	63.59
Global Sum S	Global Sum Settlement (S\$)			

INSPECTION

Date of Assignment: 23/11/2018

Date Inspected: 18/12/2018 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference				
Part Source:		(Last Synchronised: 08 Feb 2021)		
Parts:	N/A	MERCEDES-BENZ 0405G 12.0 D (A) (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for PC3663L)			
Validity:	dity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,588.59 F	*1,588.59 FL
2	1		*REAR SIDE PANEL SIGNAL LAMP RH	Cracked	221.09 F	*221.09 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	581.32 F	*- FL
4	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	205.15 F	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Not Necessary	198.45 F	*- FL
6	1		*REAR TAIL LAMP (RED) RH	Not Necessary	355.35 F	*- FL
7	1		*REAR TAIL LAMP PANEL RH	Repair	1,231.62 F	*- FL
F=Fra	F=Franchise part. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 0.00/10.00% (S\$)			4,381.57 0.00	1,809.68 180.97	
				Total Parts (S\$)	4,381.57	1,628.71
	Report was unsubmitted during this print-out.					

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=ge... 9/2/2021

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPAIR RH SIDE DOOR	New	1,200.00	600.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	500.00
3	TOWING (NPA)	New	0.00	0.00
4	TO REMOVE & REFIX SIDE GLASS (NPA)	New	0.00	0.00
5	TO TUFFCOAT AFFECTED AREAS	New	250.00	100.00
6	TO REMOVE & REFIX FRONT WINDSCREEN (NPA)	New	0.00	0.00
7	TO RENEW ENGINE MOUNTINGS (NPA)	New	0.00	0.00
8	TO REMOVE /REFIT AIRCON CONDENSOR ,PIPINGS ,VACUUM AND RECHARGE AIRCON GAS (NPA)	New	0.00	-
9	TO REMOVE /REFIT REPLACE DASHBOARD (NPA)	New	0.00	0.00
10	TO REMOVE AND REFIT INTERRIOR UPHOLSTERY AND SEAT	New	250.00	80.00
11	TO REMOVE AND REPLACE STEERING COLUMN (NPA)	New	0.00	-
12	TO REMOVE /REFIT WIRING CHECK	New	60.00	30.00
13	TO REMOVE /REFIT ADJUST BRAKE 4 WHEEL (NPA)	New	0.00	0.00
14	TO REMOVE /REPLACE EXHAUST SILENCER BOX AND STRAIGHTEN CENTRE PIPE (NPA)	New	0.00	0.00
15	TO REMOVE /REPLACE DOOR MECHANISM (NPA)	New	0.00	0.00
16	TO REMOVE & REPLACE ADVERTISEMENT STICKER (NPA)	New	0.00	0.00
17	TO REMOVE & RENEW FUEL TANK (NPA)	New	0.00	0.00
18	TO REMOVE AND REPLACE FLOOR CARPER (NPA)	New	0.00	0.00
	Gross Labor	ır Cost (S\$)	2,760.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >