

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120**Our File No:** CC3/AIG18021369/AVD3S2**Date:** 30/08/2019REFERENCEInsured/Claimant: LEE WAYNE, SHANE  
Date of Loss: 22/11/2018Policy No:  
Nature of Claim: OD Claim No: 5670221605SGDESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLH5579E</b>	Engine No:	CJE081312
Make & Model:	AUDI A4, 1.8 TFSI MU CVT (A)	Chassis No:	WAUZZZ8K8EA143896
Reg. Date:	31/07/2014 (Man. Year: 2014)	Odometer:	72527 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,319.00	5,050.72	3,268.28	39.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,432.00	6,332.00	2,100.00	24.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,751.00</b>	<b>11,382.72</b>	<b>5,368.28</b>	<b>32.05</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	15,951.00	10,582.72	5,368.28	33.65
<b>+ GST 7.00/7.00% (S\$)</b>	1,116.57	740.79	375.78	33.65
<b>Nett Amount (S\$)</b>	<b>17,067.57</b>	<b>11,323.51</b>	<b>5,744.06</b>	<b>33.65</b>

INSPECTION

Date of Assignment:	27/11/2018		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	27/11/2018	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-LH	Dented	860.00 FS	*688.00 FS
2	1		*ATTACHMENT PARTS FOR FRONT FENDER	Not Necessary	49.00 FS	*- FS
3	1		*BRACKET FOR FENDER	Not Necessary	46.00 FS	*- FS
4	1		*BRACKET FOR DEFORMATION	Not Necessary	43.00 FS	*- FS
5	1		*FRONT FENDER BRACE-LH LOWER	Not Necessary	103.00 FS	*- FS
6	1		*STONE CHIP GUARD-LH FRONT	Necessary	39.00 FS	*37.92 FS
7	1		*WHEEL HOUSING LINER	Not Necessary	215.00 FS	*- FS
8	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	38.00 FS	*- FS
9	1		*FRONT DOOR-LH	Dented	2,509.00 FS	*2,007.20 FS
10	1		*ATTACHMENT PARTS FOR DOOR	Not Necessary	77.00 FS	*- FS
11	1		*OUTER DOOR SEAL	Necessary	184.00 FS	*146.80 FS
12	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
13	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
14	1		*DOOR CATCH	Not Necessary	105.00 FS	*- FS
15	1		*COVER FOR DOOR CATCH	Not Necessary	14.00 FS	*- FS
16	1		*DOOR HANDLE, EXTERIOR	Repair	131.00 FS	*- FS
17	1		*DOOR HANDLE KEY HOLE CAP	Repair	26.00 FS	*- FS
18	1		*DOOR HANDLE MOUNTING BAR	Not Necessary	274.00 FS	*- FS
19	1		*REAR DOOR-LH	Dented	2,509.00 FS	*2,007.20 FS
20	1		*ATTACHMENT PARTS FOR DOOR	Not Necessary	72.00 FS	*- FS
21	1		*OUTER DOOR SEAL-LH RERA	Necessary	192.00 FS	*154.00 FS
22	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
23	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
24	1		*DOOR CATCH	Not Necessary	105.00 FS	*- FS
25	1		*COVER FOR DOOR CATCH	Not Necessary	14.00 FS	*- FS
26	1		*SUNDRIES	Necessary	500.00 FS	*9.60 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>8,319.00</b>	<b>5,050.72</b>
--------------------------	-----------------	-----------------

LKK Auto Consultants Pte Ltd/SLH5579E/30/08/2019 08:45
--

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HANRESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS FRONT AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES.	New	560.00	560.00
3	TO DISMANTLE FRONT BUMPER,LHS FRONT FENDER,LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER AND LHS SILL PANEL.TO RENEW LHS FRONT FENDER,LHS FRONT DOOR AND LHS REAR DOOR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED. INCLUSIVE THE REPAIR OF DOOR HANDLE,EXTERIOR AND DOOR HANDLE KEY HOLE CAP.	New	3,600.00	2,250.00
4	TO RESPRAY LHS FRONT FENDER,LHS FRONT DOOR,DOOR HANDLE,LHS REAR DOOR,LHS REAR FENDER AND LHS SILL PANEL.	New	3,600.00	2,850.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,432.00</b>	<b>6,332.00</b>

LKK Auto Consultants Pte Ltd/SLH5579E/30/08/2019 08:45

< END OF ESTIMATES >