

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info				
	Cust No/Name	/Mr Mohamed Salim S/O Mohd Sana			
LONPAC INSURANCE BHD 100 BEACH ROAD #19-00	Reg No/Reg Date	SLH2234U*1F / 27/10/2016			
SHAW TOWER	Date In/Mileage	27/11/2018/ 0			
SINGAPORE 189702	Chassis No	JMYSRCY1AGU005942			
TEL:62962706	Engine No	4A92CL7525			
Contact No	Make/Model	MIT/16MY LANCER EX 1.6 4AT			
00110400 110	Colour/Trim	P02 / BK			

Acco	ount No	Terms	Date/Time Printed	CSE	Operator		WIP No			
	00040	Credit	27/11/2018/ 08:39	DS	218 / MarsLer		14243			
000	0040	Orcure	Description of Goo	ds / Services		Qty	Unit Price	Disc%	Am	ount
c 1	MIPNT880	88	Description of cos						60	80.00
5 F	TO CHECK	I TGHTIN	AND WIRING SYSTEM	ON REAR AC	CIDENT AFFECTED					
	AREAS	LIGHTIM	a find writing over-				,	-0	1 2	
2	MTPNT880	88					,	340		600.00
	TO REMOV	E AND RE	-INSTALL REAR CAPER	TING & TRIM	MING TO GIVE WAY					
	ACCESS R	EPAIR ON	REAR ACCIDENT AFFE	CTED AREAS					/	300.00
S 1	MIPNT880	88								300.00
	TO REPLA	CE REAR	REVERSE CAMERA LENS						600	2400.00
S I	MIPNT880	88							000	2400.00
	TO REPLA	CE REAR	BUMPERM, REINFORCEME	NT,ETC						
	-CUT & R	E-WELD R	EAR END PANEL	П		1				
	STRAIGHT	EN, REFOR	M, ALIGN ON REAR ACC	DENT AFFE	CITED AREAS	17/0		100	200	200.0
S	MIPNT880	88		5011			7		2	20010
			KIT ON NEW PANEL	00					840	2520.0
S	MIPNT980)88	W DEAD ACCIDENT AFF	TOTED ADEAS	(1.7.				0 (0	
	SPRAY PA	AINTING O	N REAR ACCIDENT AFF	ECIED AREA.	, 42				7	280.0
S	MIPNT880)88 V AND DE	PLACE REAR REVERSE	SENSOR						
		Y AND RE	PLACE REAR REVERSE	SENSOR					/	50.0
	SUNDRY C & C LO	000								
	SUNDRY	Juo							/	45.0
	MIVEC EN	MRI FM								/
	MIPNT880								/	50.0
			E WITH CASING		el.					050 0
	JJ6410B8		FACE, RR B		ME NO	1.00	852.00	0.00		852.0
	JJMU488		CLIP, RR B	UMPER ^	142	1.00	2.00	0.00		26.0
	JJ6430A		BRACKET, L	ICENSE PLAT	Color	2.00	13.00 17.00	0.00		17.0
	JJ6410C		LH BRKT,R	BMPR FACE		1.00	17.00	0.00		17.0
P	JJ6410C		RH BRKT,R	/BMPR FACE	* NN	1.00	231.00	0.00		231.0
Р	JJ6410B	929	REINFORCE	MENT, RR BUM	6	1.00	90.00	0.00		90.0
M	JJ6410B		UPR REINF	ORCEMENT, RR	W.	1.00	556.00	0.00		556.0
M	JJ5281A		PANEL, RR			1.00	58.00	0.00		58.0
P	JJMR574	899	MARK, LANC	ER / NE	L.	1.00		50000		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info			
A CAUCAGO TANGALISTE DAID	Cust No/Name	/Mr Mohamed Salim S/O Mohd Sanau		
LONPAC INSURANCE BHD 100 BEACH ROAD #19-00	Reg No/Reg Date	SLH2234U*1F / 27/10/2016		
SHAW TOWER	Date In/Mileage	27/11/2018/ 0		
SINGAPORE 189702	Chassis No	JMYSRCY1AGU005942		
TEL:62962706	Engine No	4A92CL7525		
Contact No	Make/Model	MIT/16MY LANCER EX 1.6 4AT		
	Colour/Trim	P02 / BK		

Account No T	erms	Date/Time Printed	CSE	Operator		WIP No		The same of
0000040 C	redit	27/11/2018/ 08:39	DS	218 / MarsLer		14243		
	1450	Description of Good			Qty	Unit Price	Disc%	Amount
4 JJ7415A111		MARK, THREE-	DIA / 1	MEC.	1.00	51.00	0.00	51.00
JJ8355A039		LH REFLECTO	R X S	NN	1.00	36.00	0.00	36.00
M JJ8355A040		RH REFLECTO	R X /	0	1.00	36.00		36.00
M JJ8637A134		BUZZER, KEYL	ESS OPERA	1.01	1.00	170.00		170.00
M W8330A001LE	ED	LED TAILLAM	P KIT 🗡	MIV	1.00	855.00		855.00
P JJMR200300		CLIP, BUMPE	R / 16	L	10.00	2.00	0.00	20.00
Z NOTES								
ACCIDENT ON	V 25/11	L/2018 ALONG WOODLAN	DS CHECK	POINT TOWARDS SINGAR	PORE			
OWNER CLAIM								
REQUIRED RE		MENT CAR			_			
TP # SLX28	331L	IP INS : LUNPAU	$\neg \Box$	ima	745			
			211	1110015	2175(5	7]		
			-2) [[2114	フ		
		10-						
		glang.						
		, , ,		1 1 (
		metal or	alut a	hotos.				
		ing our po	1 1					
				2 6 60262				
		Cours Co.	and -	-8280000 r				
		Elu Cer	7	htos. -8286282				
		03/12	1					
		2/10	110					
		05/12	110					
		,						
		LKK Auto Consultor	da bassa -	-416				
		LKK Auto Consultar the Repairer of the	tellauria as	otity				
		To resurvey before/after	following:					
		To display damaged page	r spray paintii	ng				
		Parts prices are subject	t to confirmati	Survey	Doube			3,017.00
Confirm & acc	epted	Third party survey is or	a "Without P	rajudica" basis	Parts Labour			0.0
		No illegal modification(s) is allowed	ojuuluo basis	Standard	Monu		0.0
		 Supplementary item(s) 	must be resur	veved and	00000000			6,430.0
		is subject to final appro	val from Insur	ance Company	Speciali Others(L			0.0
					and the same of the same of	ub, etc)		95.0
		Acknowledged by Repair	er		Sundry Total (w/	o GST)		9,542.00
Authorized si	ignator	y and company stamp			IULAI (W/	0 031)		2,0,=10
Aution Ized 31	. 3	Date*					1	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any auditional parts of labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.