

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118021428/ATD3E2
Date: 08/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN11328117066
Claimant Vehicle No : SKR6701X **Insured Vehicle No** : SGB3598D
Date of Loss: 07/11/2018 Nature of Claim: TP Claim No: SNM18D05253C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR6701X**
Make & Model: NISSAN QASHQAI, 1.2 (A) Engine No: HRA2097845A
Reg. Date: 27/02/2015 (Man. Year: 2014) Chassis No: SJNFEAJ11U1267151
Colour: White Odometer: 82732 km
Engine Capacity: 1197 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 10,480.84 | 1,531.04 | 8,949.80 | 85.39 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,188.00 | 1,208.00 | 2,980.00 | 71.16 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 14,668.84 | 2,739.04 | 11,929.80 | 81.33 |
| Approved Total (Overridden) (S\$) | | 3,508.16 | | |
| (S\$) | 14,668.84 | 3,508.16 | 11,160.68 | 76.08 |
| + GST 7.00/7.00% (S\$) | 1,026.82 | 245.57 | 781.25 | 76.08 |
| Nett Amount (S\$) | 15,695.66 | 3,753.73 | 11,941.93 | 76.08 |

INSPECTION

Date of Assignment: 12/06/2019
Date Inspected: 28/11/2018 Inspected At: Autolution Industrial Pte Ltd (HQ)
19 UBI ROAD 4
Singapore 408623
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,331.04 NETT)

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 08 Apr 2020) |
| Parts: | M1-SUV | NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKR6701X) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|---------------|-------------|------------|
| 1 | 1 | | *ENGINE UNDER COVER (FRT) | Not Necessary | 285.00 FN | *- FN |
| 2 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *20.00 FS |
| 3 | 1 | | *AIRDUCT TURBO | Not Necessary | 242.20 FS | *- FS |
| 4 | 1 | | *TURBO CHARGE INTERCOOLER | Not Necessary | 2,121.60 FS | *- FS |
| 5 | 1 | | *LOW FLEXIBLE HOSE | Not Necessary | 154.00 FS | *- FS |
| 6 | 1 | | *HIGH FLEXIBLE HOSE | Not Necessary | 97.80 FS | *- FS |
| 7 | 1 | | *PIPE-COMPRESSOR TO CONDENSER | Not Necessary | 30.60 FS | *- FS |
| 8 | 1 | | *HIGH PRESSURE PIPE | Not Necessary | 90.60 FS | *- FS |
| 9 | 1 | | *CONDENSER ASSY | Not Necessary | 658.20 FS | *- FS |
| 10 | 1 | | *RADIATOR FAN MOTOR | Not Necessary | 621.70 FS | *- FS |
| 11 | 1 | | *LOWER RADIATOR AIR GUIDE | Not Necessary | 94.50 FS | *- FS |
| 12 | 1 | | *BRKT - RAD MOUNTG TOP | Not Necessary | 14.60 FS | *- FS |
| 13 | 1 | | *RADIATOR ASSY | Not Necessary | 687.40 FS | *- FS |
| 14 | 1 | | *A/TRANSMISSION OIL COOLER | Not Necessary | 504.20 FS | *- FS |
| 15 | 2 | | *FOGLAMP ASSY | Not Necessary | 516.00 FS | *- FS |
| 16 | 1 | | *LH HEADLAMP | Cracked | 559.00 FN | *559.00 FN |
| 17 | 1 | | *RH HEADLAMP | Not Necessary | 559.00 FN | *- FN |
| 18 | 1 | | *BONNET LOCK | Not Necessary | 67.60 FN | *- FN |
| 19 | 1 | | *BONNER LIFT LOCK | Not Necessary | 82.80 FN | *- FN |
| 20 | 1 | | *BONNET SEAL RUBBER FRT | Not Necessary | 89.00 FN | *- FN |
| 21 | 1 | | *BONNET | Repair | 961.40 FN | - |
| 22 | 1 | | *FRT LICENCE PLATE | Bent | 60.00 FS | *60.00 FS |
| 23 | 1 | | *EMBLEM RAD GRIL-NISSAN | Necessary | 73.60 FN | *73.60 FN |
| 24 | 1 | | *GRILLE-RADIATOR | Cracked | 498.30 FN | *498.30 FN |
| 25 | 1 | | *LH STAY FRT BUMPER | Not Necessary | 123.70 FN | *- FN |
| 26 | 1 | | *RH STAY FRT BUMPER | Not Necessary | 173.10 FN | *- FN |
| 27 | 1 | | *UPPER REINFORCEMENT FRT BUMPER | Not Necessary | 675.40 FN | *- FN |
| 28 | 1 | | *UPPER ENERGY ABSORBER FRT BUMPER | Not Necessary | 195.70 FN | *- FN |
| 29 | 1 | | *LOWER REINFORCEMENT FRT BUMPER | Not Necessary | 371.50 FN | *- FN |
| 30 | 2 | | *LOWER ENERGY ABSORBER FRT BUMPER | Not Necessary | 124.40 FN | *- FN |
| 31 | 1 | | *RH SIDE BRACKET FRT BUMPER | Necessary | 20.90 FN | *20.90 FN |
| 32 | 1 | | *LH SIDE BRACKET FRT BUMPER | Necessary | 20.90 FN | *20.90 FN |
| 33 | 1 | | *RH FOGLAMP CHROME GARNISH | Not Necessary | 74.70 FN | *- FN |
| 34 | 1 | | *LH FOGLAMP CHROME GARNISH | Not Necessary | 74.70 FN | *- FN |
| 35 | 1 | | *TOW HOOK COVER FRT BUMPER | Deformed | 19.30 FN | *19.30 FN |
| 36 | 6 | | *CLIP FRT BUMPER | Necessary | 7.20 FN | *7.20 FN |
| 37 | 1 | | *FRT BUMPER | Deformed | 614.60 FN | *614.60 FN |

F=Franchise part. S=SpcNett. N=NettItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 11,615.20 | 1,893.80 |
| - Nett Item Discount on N Items 20.00/20.00% (\$\$) | 1,134.36 | 362.76 |
| Total Parts (\$\$) | 10,480.84 | 1,531.04 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | LABOR CHARGES TO REPAIR RADIATOR SUPPORT, BOTH FRT FENDER, RENEW BONNET AND FRT BUMPER | New | 2,340.00 | 560.00 |
| 2 | CHARGES TO SPRAY PAINTING SAME | New | 1,250.00 | 500.00 |
| 3 | RENEW BOTH HEADLAMP AND FOCUS | New | 48.00 | 48.00 |
| 4 | APPLY SEALANT TO BONNET | New | 100.00 | 100.00 |
| 5 | RENEW AC SYSTEM CONDENSER, VACUUM AND REFILL FREON GAS | New | 120.00 | 0.00 |
| 6 | RENEW A/TRANMISSION OIL COOLER | New | 180.00 | 0.00 |
| 7 | RENEW TURBO INTERCOOLER | New | 150.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 4,188.00 | 1,208.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >