LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18021428/ATD3E2

08/04/2020 Date:

REFERENCE

China Taiping

Handling Insurer: Insurance

Policy No:

DMPCSN11328117066

(Singapore) Pte. Ltd.

Claimant Vehicle No:

SKR6701X

Insured Vehicle No:

SGB3598D

Date of Loss:

07/11/2018

Nature of TP

Claim No: SNM18D05253C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKR6701X

Make & Model: NISSAN QASHQAI, 1.2 (A) Reg. Date:

27/02/2015 (Man. Year: 2014)

Claim:

Engine No: Chassis No: Odometer:

HRA2097845A SJNFEAJ11U1267151

82732 km

Colour: White

Engine Capacity: Market Value/New Car 1197 cc N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Footbrake (Serviceable): Yes Handbrake (Serviceable):

Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Front Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/60 R17 Michelin 6 mm Yes

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,480.84	1,531.04	8,949.80	85.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,188.00	1,208.00	2,980.00	71.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total	(S\$) 14,668.84	2,739.04	11,929.80	81.33
+ GST 7.00/7.00%	(S\$) 1,026.82	191.73	835.09	81.33
Nett Amount	(S\$) 15,695.66	2,930.77	12,764.89	81.33

INSPECTION

Date of Assignment: 12/06/2019

Date Inspected: 28/11/2018 Autolution Industrial Pte Ltd (HQ)

19 UBI ROAD 4

Singapore 408623

Estimated Period of Repair: 5.0 days

Adjuster: Manager: DENISE TAY KWEE CHENG ADRIAN LING

Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$1,331.04 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Apr 2020)

NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0) Parts: M1-SUV

(Price-denominated Standard List) Labour: Repairer's

Print Code: LKK Auto Consultants Pte Ltd/SKR6701X/08/04/2020 13:06

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page Validity:

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE UNDER COVER (FRT)	Not Necessary	285.00 FN	*- FN
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*AIRDUCT TURBO	Not Necessary	242.20 FS	*-FS
4	1		*TURBO CHARGE INTERCOOLER	Not Necessary	2,121.60 FS	*-FS
5	1		*LOW FLEXIBLE HOSE	Not Necessary	154.00 FS	*-FS
6	1		*HIGH FLEXIBLE HOSE	Not Necessary	97.80 FS	*-FS
7	1		*PIPE-CONPRESSOR TO CONDENSER	Not Necessary	30.60 FS	*-FS
8	1		*HIGH PRESSURE PIPE	Not Necessary	90.60 FS	*-FS
9	1		*CONDENSER ASSY	Not Necessary	658.20 FS	*-FS
10	1		*RADIATOR FAN MOTOR	Not Necessary	621.70 FS	*-FS
11	1		*LOWER RADIATOR AIR GUIDE	Not Necessary	94.50 FS	*- FS
12	1		*BRKT - RAD MOUNTG TOP	Not Necessary	14.60 FS	*-FS
13	1		*RADIATOR ASSY	Not Necessary	687.40 FS	*- FS
14	1		*A/TRANSMISSION OIL COOLER	Not Necessary	504.20 FS	*-FS
15	2		*FOGLAMP ASSY	Not Necessary	516.00 FS	*-FS
16	1		*LH HEADLAMP	Cracked	559.00 FN	*559.00 FN
17	1		*RH HEADLAMP	Not Necessary	559.00 FN	*- FN
18	1		*BONNET LOCK	Not Necessary	67.60 FN	*- FN
19	1		*BONNER LIFT LOCK	Not Necessary	82.80 FN	*- FN
20	1		*BONNET SEAL RUBBER FRT	Not Necessary	89.00 FN	*- FN
21	1		*BONNET	Repair	961.40 FN	-
22	1		*FRT LICENCE PLATE	Bent	60.00 FS	*60.00 FS
23	1		*EMBLEM RAD GRIL-NISSAN	Necessary	73.60 FN	*73.60 FN
24	1		*GRILLE-RADIATOR	Cracked	498.30 FN	*498.30 FN
25	1		*LH STAY FRT BUMPER	Not Necessary	123.70 FN	*- FN
26	1		*RH STAY FRT BUMPER	Not Necessary	173.10 FN	*- FN
27	1		*UPPER REINFORCEMENT FRT BUMPER	Not Necessary	675.40 FN	*- FN
28	1		*UPPER ENERGY ABSORBER FRT BUMPER	Not Necessary	195.70 FN	*- FN
29	1		*LOWER REINFORCEMENT FRT BUMPER	Not Necessary	371.50 FN	*- FN
30	2		*LOWER ENERGY ABSORBER FRT BUMPER	Not Necessary	124.40 FN	*- FN
31	1		*RH SIDE BRACKET FRT BUMPER	Necessary	20.90 FN	*20.90 FN
32	1		*LH SIDE BRACKET FRT BUMPER	Necessary	20.90 FN	*20.90 FN
33	1		*RH FOGLAMP CHROME GARNISH	Not Necessary	74.70 FN	*- FN
34	1		*LH FOGLAMP CHROME GARNISH	Not Necessary	74.70 FN	*- FN
35	1		*TOW HOOK COVER FRT BUMPER	Deformed	19.30 FN	*19.30 FN
36	6		*CLIP FRT BUMPER	Necessary	7.20 FN	*7.20 FN
37	1		*FRT BUMPER	Deformed	614.60 FN	*614.60 FN
F=Fra	nchise p	art. S=SpcNe	ett. N=NettItemDisc.			
	Sub Total (S\$) - Nett Item Discount on N Items 20.00/20.00% (S\$)			• • •	11,615.20 1,134.36	1,893.80 362.76
				Total Parts (S\$)	10,480.84	1,531.04

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	LABOR CHARGES TO REPAIR RADIATOR SUPPORT, BOTH FRT FENDER, RENEW BONNET AND FRT BUMPER	New	2,340.00	560.00				
2	CHARGES TO SPRAY PAINTING SAME	New	1,250.00	500.00				
3	RENEW BOTH HEADLAMP AND FOCUS	New	48.00	48.00				
4	APPLY SEALANT TO BONNET	New	100.00	100.00				
5	RENEW AC SYSTEM CONDENSER, VACUUM AND REFILL FREON GAS	New	120.00	0.00				
6	RENEW A/TRANMISSION OIL COOLER	New	180.00	0.00				
7	RENEW TURBO INTERCOOLER	New	150.00	0.00				
	Gross Labou	r Cost (S\$)	4,188.00	1,208.00				

LKK Auto Consultants Pte Ltd/SKR6701X/08/04/2020 13:06. Not valid without Reference section.

< END OF ESTIMATES >