

Form 1021

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHA 3924P Yr Regn: 30 Apr 2011

Type: M. Car / M. Cycle / Bus / Van / Lorry / T. / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe C.C. 1997

Colour: Blue A/C: Ins Good / Std / Nil / NA

Sp. Reading: 778110 T/Radio: Ins Good / Std / Nil / NA

Eng/No: _____

C/No: KMHET41VMBAB10.72

Gen. Cond: Good / Good / Poor / Burnt

Steering: In Good / Jammed / Leaked / Burnt or

Brake: In Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Handwritten

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 26/11/11 D.O.I. 27/11/11

Survey held at CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL _____

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA

Date: 06.12.2018

Our ref: CC3/CTI180

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA 3924P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/11/2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	2,837.04
Revised Estimate Amount	: S\$	1,400.00
"Check" Items Amount	: S\$	
Total (Including Check Items)	: S\$	1,400.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305244009

STOMER

COMFORT TRANSPORTATION PTE LTD

I/MS

7010045

STOMER NO.

383 SIN MING DRIVE

DRESS

Singapore SINGAPORE 575717

65508755

(O)

(R)

(P)

COUNT CARD NO.

REGN NO.

SHA3924P

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

SONATA

DATE/TIME IN

26.11.2018 12:45

YR OF MANU

30.04.2011

TARGET DATE

CHASSIS CODE

KMHET41VMB810072

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 26.11.2018


NATURE: 3P 26.11.2018 -C

S/NO

LABOR CODE

DESCRIPTION

FRONT



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip:

By:

Vehicle No.: SHA3924P CHIANG

Signature:

Exit Pass

Vehicle No.: SHA3924P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 3924P

DATE 26/11/2018 14:17

MAKE :

MODEL : HYUNDAI SONATA

got 5 mths old
 China
 China

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Sponge X			\$ 136.30
	Front Bumper Reinforcement X			\$ 504.10
	Front Bumper Grille (LH) X			\$ 17.60
	Front Bumper Bracket Top (LH) X			\$ 22.40
	Front Bumper Protector (LH) X			\$ 29.20
	Headlamp (LH) ✓			\$ 797.90
	Front Fender (LH) X repair			
	SUB TOTAL			\$ 2,046.30
	LESS 20%			\$ 409.26
	DISCOUNTED TOTAL			\$ 1,637.04
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating-Repair Fender			\$ 400.00 200
	Spray Painting Charge			\$ 600.00 400
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 X
	TOTAL LABOUR			\$ 1,100.00
	ESTIMATE TOTAL			\$ 2,837.04
Kalvin 16/11/18 27/10/18 11:15 hrs 2 days 45 After Repair photo LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary details must be surveyed is subject to final approval from LKK Auto Consultants Acknowledged by: _____ Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 3924P

MAKE :

MODEL : HYUNDAI SONATA

DATE 26/11/2018 14:17

got 5 mth old

China

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover / <i>cr</i>			\$ 538.80
	Front Bumper Sponge X <i>sc</i>			\$ 136.30
	Front Bumper Reinforcement X <i>sc</i>			\$ 504.10
	Front Bumper Grille (LH) X <i>sc</i>			\$ 17.60
	Front Bumper Bracket Top (LH) X <i>sc</i>			\$ 22.40
	Front Bumper Protector (LH) X <i>sc</i>			\$ 29.20
	Headlamp (LH) / <i>cr</i>			\$ 797.90
	Front Fender (LH) X <i>sc</i>			
	SUB TOTAL			\$ 2,046.30
	LESS 20%			\$ 409.26
	DISCOUNTED TOTAL			\$ 1,637.04
	Front Fender Advertisement Logo (LH) / <i>sc</i>			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating-Repair Fender			\$ 400.00 <i>200</i>
	Spray Painting Charge			\$ 600.00 <i>400</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	TOTAL LABOUR			\$ 1,100.00
	ESTIMATE TOTAL			\$ 2,837.04
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hereby notify the Repairer of the following:

- To display damaged parts during survey
- Parts prices are subject to surveyor's decision
- No legal liability for the repairer on a "police" basis
- Surplus parts must be returned to the insurance company

Acknowledged by Repairer

Signature: _____

Date: _____

Kalvin (K14)

27/11/18 11:15 hrs

2 days

45

After Repair photo

Our Job Ref No : 305244009
Date : 26/11/18

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHA3924P
Fax : 23.11.018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: CHINA SBE1188K
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost \$1400.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : KALVIN
Date : 28/11/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Mei Kwan (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 21 December, 2018 2:10 PM
To: Mei Kwan (LKKAuto)
Cc: Elaine Cheong
Subject: RE: Direct Settlement - Accident Involving SBE1188K (OI : CTI - SNM18D05540C02) and SHA3924P (TP : LKK REF - CC3/CTI18021468/K1pa3) on 26/11/2018
Attachments: MSNH18153347-SBE1188K.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Sir,

Case Handler : Elaine Cheong

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 7 December, 2018 9:41 AM
To: Claims Dept of CTI
Cc: Lucas Lee; Elaine Cheong; Hsiao Tong (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving SBE1188K (OI : CTI - TBA) and SHA3924P (TP : LKK REF - CC3/CTI18021468/K1pa3) on 26/11/2018

WITHOUT PREJUDICE

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 18 July 2019 6:02 PM
To: William Tan Thoo Seng; Catherine Koh Mui Gek
Subject: Your Ref: T1118/SHA3924P/WT(st), ACCIDENT INVOLVING SHA 3924P AND SBE 1188K ON 26/11/2018.
Attachments: LETTER OF DISCHARGE (DV).pdf; LOD.pdf

Your Ref: T1118/SHA3924P/WT(st)
Our Ref: CC3/CTI18021468/K1ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi William,

We refer to the above matter.

ACCIDENT INVOLVING SHA 3924P AND SBE 1188K ON 26/11/2018.

Our principal inform that our insured have sucessfully claim from your client @ 80% enclosed the document proof for your necessary action.

On a without prejudice, for a quick and amicable settlement, we propose the settlement at Global Sum S\$400.00 (all-in).

Please kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18021468/K1ea3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date : 13-08-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBE 1188K	Veh. Inspected	SHA 3924P	
Policy No.	DMPCSN1629291802	Coverage (\$)	0.00	
Claim No.	SNM18D05540C02	Excess (\$)	0.00	
Assign From		Assign Date	27/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMHET41VMBA810072	Colour	BLUE	
Odometer	778110	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	HANKOOK	7 mm	
L/H Front Tyre	215/60 R16	HANKOOK	7 mm	
R/H Rear Tyre	215/60 R16	HANKOOK	7 mm	
L/H Rear Tyre	215/60 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/11/2018	Inspection Date	27/11/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3924P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	CRACKED	538.80	538.80
1	FRONT BUMPER SPONGE	SERVICEABLE	136.30	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	504.10	-
1	FRONT BUMPER GRILLE (LH)	SERVICEABLE	17.60	-
1	FRONT BUMPER BRACKET TOP (LH)	SERVICEABLE	22.40	-
1	FRONT BUMPER PROTECTOR (LH)	SERVICEABLE	29.20	-
1	HEADLAMP (LH)	CRACKED	797.90	797.90
1	FRONT FENDER (LH)(NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-409.26	-267.34
			1,637.04	1,069.36
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER (LH).		400.00	200.00
	SPRAY PAINTING CHARGE.		600.00	400.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
			1,100.00	620.00
	GRAND TOTAL		2,837.04	1,789.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CC3/CT118021468/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.