

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 3924P

MAKE :

MODEL : HYUNDAI SONATA

DATE 26/11/2018 14:17

got 5 mth old

China

China

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover / crd			\$ 538.80
	Front Bumper Sponge X sec			\$ 136.30
	Front Bumper Reinforcement X sec			\$ 504.10
	Front Bumper Grille (LH) X sec			\$ 17.60
	Front Bumper Bracket Top (LH) X sec			\$ 22.40
	Front Bumper Protector (LH) X sec			\$ 29.20
	Headlamp (LH) / crd			\$ 797.90
	Front Fender (LH) X reg			
	SUB TOTAL			\$ 2,046.30
	LESS 20%			\$ 409.26
	DISCOUNTED TOTAL			\$ 1,637.04
	Front Fender Advertisement Logo (LH) / m			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating-Repair Fender			\$ 400.00 200
	Spray Painting Charge			\$ 600.00 400
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	TOTAL LABOUR			\$ 1,100.00
	ESTIMATE TOTAL			\$ 2,837.04
LKK Auto Consultants hence notify the Repairer of the following: • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • No illegal modification parts allowed • Supplementary items must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ Kalvin (LKK), 27/11/18 11:15 hrs 2 By, 4/5 After Repair photo				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				