

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III18021472/APA3Q2

**Date:** 17/11/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKE3678T	<b>Insured Vehicle No :</b>	SHA7081U
Date of Loss: 21/11/2018	Nature of Claim: TP	Claim No: MCT18110676

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE3678T	Engine No:	1ZR159717
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104127644
Reg. Date:	27/02/2012 (Man. Year: 2011)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,322.65	3,398.87	1,923.78	36.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,760.00	1,060.00	37.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,142.65</b>	<b>5,158.87</b>	<b>2,983.78</b>	<b>36.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
(S\$)	8,142.65	4,100.00	4,042.65	49.65
<b>+ GST 7.00/7.00% (S\$)</b>	569.99	287.00	282.99	49.65
<b>Nett Amount (S\$)</b>	<b>8,712.64</b>	<b>4,387.00</b>	<b>4,325.64</b>	<b>49.65</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>Nett Liability (S\$)</b>		<b>4,747.00</b>		

#### INSPECTION

Date of Assignment:	27/11/2018	
Date Inspected:	28/11/2018 Inspected At:	Auto N Cars Services Pte Ltd (HQ) Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2020)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKE3678T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	50.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	650.20 FL	*493.60 FL
3	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
4	2		*REAR BUMPER RETAINER	Necessary	170.20 FL	*170.20 FL
5	1		*TRUNK LID	Buckled	690.50 FL	*690.50 FL
6	2		*TRUNK LID HINGES	Not Necessary	221.00 FL	*- FL
7	1		*TRUNK LID LOCK	Damaged	98.20 FL	*98.20 FL
8	1		*RH TRUNK LID LAMP	Not Necessary	455.90 FL	*- FL
9	1		*LH TRUNK LID LAMP	Not Necessary	455.90 FL	*- FL
10	1		*TRUNK LID LOCK STICKER	Not Necessary	45.10 FL	*- FL
11	1		*REAR BUMPER PARKING SENSOR	Damaged	210.00 FS	*200.00 FS
12	1		*TRUNK LID DUAL BADGE	Necessary	48.10 FL	*48.10 FL
13	1		*1.6 EMBLEM	Necessary	28.10 FL	*28.10 FL
14	1		*VVT-I EMBLEM	Necessary	39.20 FL	*39.20 FL
15	1		*TRUNK LID LOGO	Necessary	79.50 FL	*79.50 FL
16	1		*TRUNK LID COROLLA EMBLEM	Necessary	81.20 FL	*81.20 FL
17	1		*TRUNK LID ALTIS EMBLEM	Necessary	81.20 FL	*81.20 FL
18	1		*TRUNK LID WEATHERSTRIP	Cut	350.50 FL	*350.50 FL
19	1		*REAR END PANEL	Dented	610.20 FL	*610.20 FL
20	1		*REAR END PANEL INNER GARNISH	Deformed	210.50 FL	*210.50 FL
21	1		*REAR BUMPER REFLECTOR	Not Necessary	116.20 FL	*- FL
22	1		*RH TAILLAMP	Cracked	519.10 FL	*374.50 FL
23	1		*RH TAILLAMP RETAINER	Not Necessary	28.20 FL	*- FL
24	1		*LH TAILLAMP	Cut	519.10 FL	*374.50 FL
25	1		*LH TAILLAMP RETAINER	Not Necessary	28.20 FL	*- FL
26	1		*ENGINE LOWER CROSS MEMBER	Not Necessary	310.20 FL	*- FL
27	1		*FRONT ENGINE LOWER MOUNTING	Not Necessary	395.20 FL	*- FL
28	1		*REAR BUMPER SPONGE	Cracked	138.50 FL	*138.50 FL
29	1		*REAR BUMPER IMPACT BRACKET RH	Bent	85.00 FL	*85.00 FL
30	1		*SPARE TYRE TOP BOARD	Deformed	210.00 FL	*210.00 FL
31	2		*SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,010.20</b>	<b>4,448.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,687.55	1,049.63
<b>Total Parts (\$)</b>	<b>5,322.65</b>	<b>3,398.87</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK AND STRAIGHTEN BOTH REAR FENDER AND SPARE TYRE COMPARTMENT .CUT & WELD DAMAGED PANEL ,ADJUST AND REALIGN	New	1,300.00	800.00
2	TO PUTTY AND SPRAY RH & LH REAR FENDER ,REAR END PANEL,SPARE TYRE COMPARTMENT ,TRUNK LID ASSEMBLY AND REAR BUMPER	New	1,200.00	800.00
3	TO RUST PROOF THE AFFECTED AREAS	New	80.00	50.00
4	TO TRANSFER TRUNK LID FITTING & FIXTURES.TO CONDUCT WATER SEEPAGE TEST	New	180.00	80.00
5	TO CHECK WIRING AND ALL LIGHTING	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,820.00</b>	<b>1,760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >