commined C	MSIG DELETTING 28/11/18 6/10/37an
nt Workshop of	chicle No: XD 7288K Instired Public Highlity Hugtiong Contractor Tel: 63665005 976850
Policy No. Sum Immed Make of Veh (Client's Recor	Claim No: 577120 PLY Excess: D.O.A. 23/1118
Date/Time:	2-13pm@se/11/18 Person Contacted Ms. Word Ms. (heard Vehicle IN COLD)
Date/Time	Action/Instruction () Estimate huiven change huartiang.com.sg @ms.
Hp/ 18	Email preli revised to Keet wai
19/12/18	LS \$ 4800 confirmed by email (Red 1730.11, 269)

ASSIGNMENT

Estimated Cost: OD (TD) WS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No ×D 7286K at Workshop m/s Hwattong Contracter of No-9 Benoi Crescent knowed: Policy No. Chaims No. Sum insured: Excess.	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Trust / Trailer or Marke: MCRCCOCS Nov2 MB ACTROS c.c 1/946 Colour MULT! AC Insured / Std / NI / NA Sp. Reading 432671 T/Radio: Insured / Std / NI / NA Eng/No: C/No: WSB 93216 12 L 732589 Gen. Cond: Good / Carl / Poor / Burnt Steering: Worder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder / Jammed / Leaked / Burnt or
Make of Veh: Huiwen	Modi: Nil / S/Rim / STD A/Rim or
II MINS.	Tyre Size: F: 245/80R11-5
(Policy Condition)	R: TOP
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF WESTLAKE
Bal, or Market Value.	Front Rear
IDAC Accident Rport: Consistent? Yes or No	R/Ball 8 mm R/Ball 8/8 mm
GIA / PR Seen: Consistent? Yes or No	L/Bal. 8 mm L/Bal. 8/8 mm
Est Repairs: days Res. Yes or No	DOA 22/11/18
Lam Sum: % 3 Val.: Yes or No	Survey held at HUATIONS CONTRACTOR
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Domages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted	The U/C / Chassis frame / Body Structure affected due to collision
Digital / Time Action / Instruction	
RECEIVED 2.0	DEC 2018
IntuTion File Pass 107 : Prell. Report	Days Of Repair: 5
; Final Report	Resurvey No. of Trip: Survey Fee: 150
3 >0 12 - typist Add Fee	2: Site Insp (\$) _5+R5_ 5I
:	Interview (\$) Photos
Report Format :	Tech Invs (\$), one:
Lump Sum / LB.I: (5 4800)	Westerd (\$
	TOTAL 150

Veron Chen (LKKAuto)

From:

1

Veron Chen (LKKAuto)

Sent:

Tuesday, 4 December 2018 9:14 AM

To:

'Keet Wai Ng'

Cc:

SUR

Subject:

RE: MSIG ref: 577120 PLY | Third party vehicle XD7288K

Attachments:

XD 7288K PRELI REVISED.pdf

Dear Keet Wai,

Enclosed preliminary revised of vehicle XD 7288K

Date of survey: 29/11/2018 Number of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 28 November 2018 2:47 PM

To: 'Keet Wai Ng' <KeetWai_Ng@sg.msig-asia.com>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: MSIG ref: 577120 PLY | Third party vehicle XD7288K

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Keet Wai Ng [mailto:KeetWai Ng@sg.msig-asia.com]

Sent: Wednesday, 28 November 2018 10:37 AM

To: assignments@lkkauto.com; admin-d@lkkauto.com

Subject: MSIG ref: 577120 PLY | Third party vehicle XD7288K

Dear Sirs,

We would like the LKK to survey the damage on a without prejudice basis. We attach quotation on third party vehicle XD7288K and our Insured's narration of the accident.

Please confirm on this assignment. Thanks.

Regards, Ng Keet Wai Claims Services Direct line +65 6643 1336 | Direct fax +65 6643 1349 | keetwai_ng @sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way, #21-01 SGX Centre 2, Singapore 068807 | T: +65 6827 7888 |







A Member of MS&AD INSURANCE GROUP



This email has been checked for viruses by AVG antivirus software. www.avg.com

51 UBI AVE 1, 402-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref:

577120PLY

Our ref:

CS/MSG18021478/R1vd3

Date:4/12/2018

The Motor Claims Department
M/s MSIG INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO: XD 7288K

We thank you for your instruction on 28/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29/11/2018 at the premises of M/s <u>HUATIONG CONTRACTOR PTE LTD</u> and have the following to report:-

Workshop Estimate Amount	: \$\$6,530.11 : \$\$5,937.77 : \$\$282.34 : \$\$: \$\$		
Revised Estimate Amount			
"Check" Items Amount			
Market Value			
LTA Reimbursement Value			
Nett Value			

Description of Damage:

The vehicle sustained damages at the

front n/s portion

rear

nearside

affside

front

Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMMED RASUL

Automotive Assessor

Nivitha (LKK Auto)

From:

Keet Wai Ng <KeetWai_Ng@sg.msig-asia.com>

Sent:

Wednesday, 28 November 2018 10:37 AM

To: Subject: assignments@lkkauto.com; admin-d@lkkauto.com MSIG ref: 577120 PLY | Third party vehicle XD7288K

Attachments:

XD7288K.PDF; Loader accident 23-11-2018.pdf

Dear Sirs.

We would like the LKK to survey the damage on a without prejudice basis. We attach quotation on third party vehicle XD7288K and our Insured's narration of the accident.

Please confirm on this assignment. Thanks.

Regards, Ng Keet Wai Claims Services

Direct line +65 6643 1336 | Direct fax +65 6643 1349 | keetwai_ng @sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way, #21-01 SGX Centre 2, Singapore 068807 | T: +65 6827 7888 |

F: +65 6827 7800 | Co. Reg. No. 200412212G | msig.com.sg







A Member of MS&AD INSURANCE GROUP

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle Vehicle Owner Particulars Company Owner ID Type: 4322E Owner ID: Vehicle Details XD7288K Vehicle No.: No Vehicle to be Exported: 03 Dec 2018 Intended Deregistration Date: MERCEDES BENZ MB ACTROS 3336K 6X4 3300 (AUTO, ABS) Vehicle Make: Vehicle Model: Primary Colour: 2013 Manufacturing Year: 541972C0875967 Engine No.: WDB9321612L732589 Chassis No.: Maximum Power Output: \$118,111.00 Open Market Value: 07 Jun 2013 Original Registration Date: 07 Jun 2013 First Registration Date: Transfer Count: \$5,906.00 Actual ARF Paid: Intended PARF Rebate Details No PARF Eligibility: PARF Eligibility Expiry Date: \$0.00 PARF Rebate Amount: Intended COE Rebate Details 06 Jun 2023 COE Expiry Date: C - Goods Vehicle & Bus COE Category: COE Period(Years): \$57,051.00 OP Paid: \$26,069.00 COE Rebate Amount: \$26,069.00

Total Rebate Amount: The information contained herein is correct as at 03 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

TO A CONTRACTOR		
	ACCIDENT STATEMENT	
Date Of Report	23/11/2018 14:31	
Date Of Accident	22/11/2018 12:15	
Exact Location Of Accident	PANDAN ROAD (ISLAND CONCRETE INSIDE)	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XD7288K	
Insured/Policyholder		

HUATIONG CONTRACTOR PTE LTD

Co Reg No 198304322E

Email Address NOEMAIL Mobile Phone No

(LOCAL) +65-97685005 Alternative Phone No OFFICE-63665005

Vehicle Particulars

Name Of Registered Owner

Manufacturer MERCEDES-BENZ

Model ACTROS-11.9 D 3336K 6X4 3300 (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company GREAT EASTERN GENERAL INSURANCE LIMITED

Type Of Coverage COMPREHENSIVE

Fleet Policy YES

Policy Number

Cover Note Number

Driver

Name of Driver KARUPPAIN BALASUBRAMANIAN

Passport No/FIN G5855730M Date Of Birth 15/04/1967 Occupation OUTDOOR Date Of Driving Pass 15/02/2016

Driving Experience 2 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97685005 Fax Number (LOCAL) +65-62640870 Contact Number OFFICE-63665005

EMail Address NOEMAIL Address

NO.9 BENOI CRESCENT

Postcode

Was driver an employee of the Insured's Company YES

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident?
Was any injured conveyed to hospital by

155825

ambulance?

NO

Was any other material or property damaged?

NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

The second secon

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes.Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 22/11/2018 @ 11215HRS I WAS DRIVING MY COMPANY VEHICLE BEARING NO. XD7288K HEADING TO ISLAND CONCRETE @ PANDAN ROAD FOR LOADING 20MM STONE. AFTER UPON REACHING SITES I WAS REVERSING MY TRUCK TO BE IN POSITION FOR LOADING. SUDDENLY THERE IS A WHEEL LOADER NO. 11 REVERSE AND HIT MY FRONT LEFT. MY VEHICLE WAS BADLY DAMAGE. THERE WAS NO INJURIES IN THIS ACCIDENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO LARGE

Was there any audio recorded?

NO

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the serials of the accelera to turne up the claims present
- 2. This have must be completed by the PolicybullAlC and/or the Authorised Interes
- Information provided most for an graphful and accounts as assentite. Any will disconnectation or withdusting of material facts from binary from comparison to report of probability.
- The book and accretionic of this force by less raise companies is not an advetation of sollay family on the part of the less and companies.
- 5. Any faine reporting may be referred to the Police for Investigation.
- 6. The report will be howevered by the insurers of the GA Records Management Centre exhibition by the General Insurers of Association of Singapore (GA) for exhibiting and that copies of this report will for a fee bit made evaluate open application by inservant parties.
- By the ladgment of this report to the mounts, you hereby consent to the archborg of this report at the centre and to replace of the report being made available aboresaid.
- E. Consent under the Personal Data Protection Act (PDPA)

I understand, schnowledge, agree and consent that

- (a) the masser, my workshop and the Geograf treatment dangeration of Singapore ("SIA") may, are permitted to collect, such disclose and/or process my personal data/personal information see out in this (bore) and any other personal information provided by me or processed by my inside (processed information); and flucture and transfer each Personal information to all inside or () who have inside () incidend in the accident (all inside) who have inside () incidend in the accident (all inside () who have inside () incidend in the accident (but be collectively referred to as the "lossers"). The inside () is incident, the first parameter () in the parameter () of the parameter () or ().
 - (ii) processing, handling and/or desiring with my claims actuding the settlement of the claims and any necessary investigations relating to the claims:
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or stealing with my instructions or responding to any enquiries by me;
 - [vi] administering my claims (including the mailing of correspondence, obtainents, involves, reports at autions to me, which could recover disclaime of certain personal data about me to bring about delivery of the same as well as on the external open of revelopes/mail packages), amilitie.
 - (a) complying with applicable loss or admissioning, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all invalents) who have intered velociets in wolcoul in this accident and the insurers lawyers/law forms, may/are permitted to collect, use, clicities and/or process my Personal Information for one or mare of the above Purposes; and
- (c) my Personal information may/per be disclosed by any of the mourers and/or GIA to their third party service providers or report (and subject their (payers/few firms), which may be sted outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile alarms history for the purpose of froud detection, investigation, and management as present and all future claims.
- (e) the information to collected under (d) above may be chared / disclosed
 - (i) to all insurers analyze any other tood parties that assist in evaluating, mentiogening controlling or insuring the and regulators, law enforcement and government agencies as regularably required for the purposes started, or

his for complete with requirements under any regulations, laws or sport orders.


Polisheine's Signove

Driver's Signature (if drawn in out the policyhember)

Date & Time:

HEROLDIA COLOR SENSON S

Sketch Plan #2




Accident Photo



Accident Photo




























Driving License



YOU ARE LICENSED TO DAME WHILLIS IN THE HALDWAYS CLASSED.

ATTECUMENT

Class 28 - Maris Class 2 - Maris

Manageria et 2000; Mara des est antibes veges en 1000eg with et 2 passengers, cociones d'éven and ches tentes

CO THE WOOL


.

or putas rights and the present entire to bailing solder, without an about any next constructed to bailing and or pessengers and the property entires on Tobales

THE LOCKED PROPERTY AND

MF 4784

Identification Card





Huationg Contractor Pte Ltd

TTL che mer tak ciet im:

Repair Estimate

Damage Assessed by	Huiwen
Classification:	Claim 3rd party
Dwner:	HUATIONS CONTRACTOR PTE LTD
Date:	23/11/2018
Vehicle Type:	Goods (Dijen) Tipper / Dumper Truck
Registration Number:	XD7288K
Chassis No:	WD89321612L732589
Engine No	541972CD875967
Year of Make:	2015
Date of Registration:	07/06/2011

Remove/Replace

Additional Costs

		Line Item	Part Type	Dollar		
Labour Type	Operation	Description	Part Number	Amount	Labour Units	
BODY		Cabin Arry				
	Remove/Replace	Front Bonnet (Phato)		5674.25		
	Remove/Replace	Front Bonnet Grill X 2		\$203.00		
	Remove/Replace	Front LHS Bumper		5984.92	6 days	
	Remove/Replace	Front LHS Bumper Bracket - (Inner)		\$79.34		
	Remove/Replace	Front LHS Head Light including bracket 7		5812.25		
	Remove/Replace	Front LHS Pin - (Inner)		\$45.74		
	Remove/Replace	Front LHS Shock Absorber - (Inner)		\$343.66		

Front LHS Bearing Bracket - (Inner)

Paint

Additional Costs and Materials

BODY

1. ATT 31 3 - 40 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	17.011119			2.000.00
Additional Costs	Company Sticker			\$220.00
	Estimate Totals			
Labour Subtotal	Hours	Rate		Total
Body		48	30	51,440.00
Mechanical		0	30	\$0.00
Additional Costs				
Paint				\$500.00
Sticker				\$220.00
Parts Replacement Summary				54.370.11
#E.11501.E1470.E7-011010.E-000550				
Total Labour Costs				51,440.00
otal Parts Replacement Costs				\$4,370.11
otal Additional Costs				\$720.00
Gross Total				\$6,530.11

The Repairer of the following:

• To recurry before the treat painting:

• To display damaged pon(s) damag recurrent

- Parts prices are subject to confirmation.
- Triplanty survey is on a "Williast Prejuder" in......
- . Do like at modification(s) is attorned
- · Tapp's marriagy item(cf) must be requirement and

Actinounidges by Ressirer

Rasul Hp 900100 68
5 days
29/11/14 @ 1200 hs
4/3
Rasy after report

\$1,226.95

550000 450 -



Huatieng Contractor Pte Ltd

Fig. 65th State S. S. Charles (20)

Repair Estimate

Damage Assessed by:	Hulwen
Classification:	Cleim 3rd party
Owner	HUATIONS CONTRACTOR PTE LTD.
Date:	29/11/2018
Vehicle Type:	Scoots Open Tipper / Dumiper Truck
Registration Number:	XD7288K
Chassis No:	WD89321612L732589
Engine No:	54197200875967
Year of Make:	2018
Date of Registration:	07/06/2013

		Line Item	Part Type	Dollar	
Labour Type	Operation	Description	Part Number	Amount	Labour Units

BODY

Remove/Replace	Front Bonnet (Pa / (phuto)	\$674.25	
Remove/Replace	Front Bonnet Grill X 2 7 X SVC	\$203.00 X	
Remove/Replace	Front LHS Bumper 7444	\$984.92	
Remove/Replace	Front LHS Bumper Bracket - (Inner)	\$79.34	
Remove/Replace	Front LHS Head Light including bracket 784	\$812.25	6 days
Remove/Replace	Front LHS Pin - (Inner) 8/	\$45.74	
Remove/Replace	Front LHS Shock Absorber - (Inner)	\$343.66	
Remove/Replace	Front LH5 Bearing Bracket - (Inner) 284 (Glash)	\$1,226.95	

\$ 4167.11-10

= \$3750.396

BODY

Additional Costs and Materials				
Additional Costs	Paint		\$500.00 450	
Additional Costs	Company Sticker	NEC	522000 2000	

	Estimate To	tals			
Labour Subtotal	Hours		Rate	Total	0220000
Body		48	30	\$1.440.00	1200
Mechanical				50.00	
Additional Costs					Si Sange
Paint				\$500.00	#1820
Sticker				\$220.00	
Parts Replacement Summary				\$4,370.11	
					# 22 m 399 +
Total Labour Costs				\$1,440.00	# 3750.399 +
Total Parts Replacement Costs				\$4,370.11	
Total Additional Costs				\$720.00	C18817
Gross Total				\$6,530.11	
					= \$ 5600.390

8750 5530

N = \$ 2,000

= \$ 5600.399

Resy after report

LNK Auto Consultants hence notify The Repairer of the following:

To recurvey before all spray painting

To display damaged part(s) during recurvey

- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudica" Lesis
- lo illegel modification(a) is allowed.
- * Supplementary item(x) must be resurvatives -- c is subject to final epoporal into Ingolarina Company

Admonissips by Radairer V Бірпанивс

Done

Veron Chen (LKKAuto)

From:

Huiwen <huiwen.chong@huationg.com.sg>

Sent:

Wednesday, 19 December 2018 5:24 PM

To:

Veron Chen (LKKAuto)

Cc:

SUR

Subject:

RE: XD7288K-DOA: 23/11/2018

Hi Veron,

As spoken, we agree to the amount you have raise. Kindly prepare payment as below stated :

Cheque: Huationg Contractor Pte Ltd

*Note: kindly indicate on envelope with attention to me - Ms Chong Hui Wen.

Best Regards, Chong Hui Wen Workshop Admin Executive

HUATIONG CONTRACTOR PTE LTD (A subsidiary of Huationg Global Limited) No. 9 Benoi Crescent Singapore 629972 Hp: (65) 9768 5005

Tel: (65) 6431 0849 Fax: (65) 6264 0870

Email: hulwen.chong@huationg.com.sg Website: www.huationg.com.sg

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 14 December, 2018 10:29 AM

To: huiwen.chong@huationg.com.sg

Cc: SUR <sur@lkkauto.com>

Subject: XD7288K-DOA: 23/11/2018

Dear Hui Wen,

WITHOUT PREJUDICE

Offer Lump Sum \$4800/- @ 5 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En Autom	obile		
MSI	G INSURANCE (S	INGAPORE) PTE LTD	Ref : CS/MSG18021478/R1vd3e2			
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 21-12-2018 Code : MSG			
1.		Policy Particulars	:- THIRD PARTY CLAI	M		
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	XD 7288K		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	577120PLY	Excess (\$)	0.00		
	Assign From	NG KEET WAI	Assign Date	28/11/2018		
2.		Vehicle Parti	culars & Condition			
	Make & Model	MERCEDES BENZ MB ACTROS	c.c	11946		
	Engine No.	HIDDEN	Year of Reg.	2013		
	Chassis No.	WDB9321612L732589	Colour	MULTI COLOUR		
	Odometer	432677	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	NIL		
	General	FAIR				
3.		Condit	ions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	295/80 R22.5	WEST LAKE	8 mm		
	L/H Front Tyre	295/80 R22.5	WEST LAKE	8 mm		
	R/H Rear Tyre	295/80 R22.5 (D)	WEST LAKE	8/8 mm		
	L/H Rear Tyre	295/80 R22.5 (D)	WEST LAKE	8/8 mm		
4.		Descripti	on of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE FR ETAILS.	ONT N/S PORTION.			
5.	General Information					
	Accident Date	22/11/2018	Inspection Date	29/11/2018		
	Survey held at Repairer	HUATIONG- NO.9 BENOI CRES	SCENT			
5a.	Kupanu	D	emarks			
Ja.		ON WAS CONDUCTED ON A"WIT	THOUT PREJUDICE" BAS			
5b.	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. Estimate Days of Repair					
	ESTIMATED NOR	5				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 7288K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
- 1	FRONT BONNET	CRACKED	674.25	674.25
2	FRONT BONNET GRILL	SERVICEABLE	203.00	
- 1	FRONT LHS BUMPER	BUCKLED	984.92	984.92
1	FRONT LHS BUMPER BRACKET-(INNER)	CRACKED	79.34	79.34
-1	FRONT LHS HEAD LIGHT INCLUDING BRACKET	BROKEN	812.25	812.25
1	FRONT LHS PIN-(INNER)	BENT	45.74	45.74
-1	FRONT LHS SHOCK ABSORBER-(INNER)	BENT	343.66	343.66
1	FRONT LHS BEARING BRACKET-(INNER)	CRACKED	1,226.95	1,226.95
			4,370.11	4,167.11
	SPECIAL NETT ITEMS			
1	COMPANY STICKER (SN)	NECESSARY	220.00	200.00
	2004-2009 (March 2004-2006-2004-2005-00 X X O S C P)	100 YEAR PERSONNEL (1980)	220.00	200.00
	LABOUR			
	PAINT.		500.00	450.00
	BODY		1,440.00	1,200.00
			1,940.00	1,650.00
	GRAND TOTAL		6,530.11	6,017.11

RECOMMENDED COST OF LUMP SUM REPAIRS	4,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/MSG18021478/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatspeyer, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.