

A/S. REC. BY:

REF:

CS/Fc118021483/Dqd3

n2

Special Instruction:

Surveyor: Snykin

ASSIGNMENT (Office)

From (Person): Joanne Yong

of

FCI

Date/Time: 9:23am @ 28/11/18

Estimated Cost:

Bill to:

OD / ~~IP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 7402S

Insured:

SHC 7897Y

at Workshop m/s

Chunni Motor

Tel:

65425119

of

AMK ; soon Hock #01-05/06

Policy No:

Claim No:

D18008378 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time: 9:47am @ 28/11/18

Person Contacted:

Lynn

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 7402S - X
	SHC 7897Y - X
05/12/18 @ 2:20pm	revised to Joanne Yong by email.

REF:

ASSIGNMENT

COE August 2017

2017 August

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 13 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date: Person Contacted:

Veh No:

SHC 74028

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour:

Yellow

A/C

Insured / Std / NI / NA

Sp. Reading

216326

T/Radio: Insured / Std / NI / NA

Eng/No:

22R3059755

C/No:

JTDKB3FU203562737

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

S'

mm

R/Bal.

S'

mm

L/Bal.

S'

mm

L/Bal.

S'

mm

D.O.A.

23/11/2018

D.O.I.

28/11/2018

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front y Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First report SHC 78977

17/12/18

13
Jumper 1/5 192001- with 13 Bdy 2nd ✓
(Fed \$11018.74, 36%)

RECEIVED 24 2018

Date/Time: File Pass to?

☐

Preli. Report

11/24/12 turner

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

13

Resurvey No. of Trip:

2

Survey Fee

Transportation

) S - RS - ST

) Photos

) Other

Report Format:

Lump Sum / L.P.T. (\$) 7P

19200

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$

20x15 = 300

170 + 300
50
50 + 50
240

860

037
20/1/18



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008378MFSH
Our Ref: CS/FCI18021483/Dqd3

Date: 05 December 2018

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 7402S .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/11/2018 at the premises of M/s CHUNNI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 30,218.74 .
Revised Estimate Amount	: S\$ 24,023.38 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	26-11-2018	Our Ref No. D18008378MFSH
Accident Date	23-11-2018	Claim Type. Third Party
Insured Vehicle	SHC7897Y	Third Party Vehicle. SHC7402S
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE; WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 5 December 2018 2:20 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008378MFSH/1
Attachments: CSFCI18021483Dqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHC 7402S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 28 November 2018 9:50 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008378MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 28 November 2018 9:23 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008378MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team

SHC 7402S

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR TRUNK LID COVER <i>kt</i>			\$ 1,126.60	✓
REAR TRUNK LID LOCK <i>kt</i>			\$ 457.90	✓
REAR TRUNK LID COVER TRIM BOARD <i>NH</i>			\$ 254.40	X
REAR TRUNK LID RUBBER <i>defined</i>			\$ 365.20	✓
REAR TRUNK LID GLASS (BLACK COLOR) <i>Hec</i>			\$ 1,569.70	✓ <i>photo</i>
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>distorted</i>			\$ 889.70	✓
REAR TRUNK LID LOGO(PRIUS) <i>Hec</i>			\$ 52.90	✓
REAR TRUNK LID LOGO(HYBRID) <i>Hec</i>			\$ 52.90	✓
REAR TRUNK LID LOGO(TOYOTA STAR) <i>Hec</i>			\$ 47.00	✓
REAR BUMPER <i>Distorted</i>			\$ 458.60	✓
REAR BUMPER RE-INFORCEMENT <i>kt</i>			\$ 318.80	✓
REAR BUMPER UNDER COVER <i>defined</i>			\$ 552.60	✓
REAR BUMPER SIDE RETAINER <i>Scu</i>			\$ 112.70	X
REAR BUMPER UNDER SIDE COVER (RH) <i>defined</i>			\$ 232.00	✓ <i>9</i>
REAR BUMPER UNDER SIDE COVER (LH) <i>Scu</i>			\$ 232.00	X
REAR BUMPER UNDER SIDE CENTRE COVER <i>defined</i>			\$ 552.60	✓
REAR BUMPER TOWING COVER <i>disloyed</i>			\$ 82.70	✓
REAR BUMPER CLIPS <i>Hec</i>			\$ 22.00	✓
ARM SUB-ASSY, REAR BUMPER, RH <i>minority crack</i>			\$ 139.60	✓ <i>9</i>
ARM SUB-ASSY, REAR BUMPER, LH <i>minority crack</i>			\$ 139.60	X ✓
TAIL LAMP ASSY (UPPER) (LH/RH) <i>crack</i>		\$ 557.90	\$ 1,115.80	✓
TAIL LAMP ASSY (LOWER) (LH/RH) <i>crack</i>		\$ 548.40	\$ 1,096.80	✓
REAR END PANEL <i>Distorted</i>			\$ 602.10	✓
REAR END PANEL GARNISH <i>crack</i>			\$ 121.60	✓
REAR SPARE TYRE PANEL <i>2 leg</i>			\$ 667.70	X
REAR SPARE TYRE CHUSHION (FLR BOARD CENTRE) <i>NH</i>			\$ 101.40	X
REAR EXHAUST PIPE <i>kt</i>			\$ 1,163.40	✓ <i>9</i>
REAR EXHAUST PIPE HANGER <i>NH</i>			\$ 40.70	X
REAR EXHAUST PIPE INSULATOR <i>NH</i>			\$ 314.60	X
REAR WINDSCREEN GLASS WITH MOULDING <i>Hec</i>			\$ 1,778.30	✓ <i>photo</i>
REAR WIRING ASSY <i>NH</i>			\$ 582.40	X
		12938.40	\$ 15,244.30	
SUB TOTAL				
LESS 20% <i>25%</i>		9703.80	\$ 3,048.86	
DISCOUNTED TOTAL			\$ 12,195.44	
REAR NO. PLATE WITH TRIM COVER <i>kt</i>			\$ 100.00	NETT ✓
REAR TRUNK LID APPS STICKER <i>Hec</i>			\$ 40.00	NETT ✓
REAR TRUNK LID COMFORT & TEL NO. STCIKER <i>Hec</i>			\$ 60.00	NETT ✓
REAR BUMPER REVERSE SENSOR <i>Down</i>			\$ 135.70	NETT ✓
REAR BUMPER RUBBER MAT <i>defined</i>		431.70	\$ 50.00	NETT ✓
REAR WINDSCREEN SEALANT <i>Hec</i>			\$ 46.00	NETT ✓
			\$ 431.70	

FAX NO : 6542 6039

(LKK)

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
RADIATOR GRILLE crack		\$	438.00 ✓
RADIATOR GRILLE EMBLEM H/c		\$	88.00 —
LAMP ASSY, FOG, RH crack mounty		\$	920.00 —
LAMP ASSY, FOG, LH crack mounty		\$	920.00 —
FRONT BUMPER COVER distorted		\$	499.90 —
FRONT BUMPER REINFORCEMENT BT		\$	696.40 —
FRONT BUMPER REINFORCEMENT ABSORBER H/L		\$	115.70 X
FRONT BUMPER SPONGE torn		\$	78.80 —
FRONT BUMPER CENTRE GRILLE deformed		\$	301.90 —
FRONT BUMPER CLIPS H/C		\$	22.00 —
SUPPORT FR BUMPER, RH Svc		\$	81.70 X
SUPPORT FR BUMPER, LH Svc		\$	81.70 X
UNIT ASSY, HEADLAMP, RH (LED) mounty crack		\$	3,455.00 —
UNIT ASSY, HEADLAMP, LH (LED) mounty crack		\$	3,455.00 —
HEAD LAMP PANEL (RH) Z BT		\$	240.10 Z ✓
HEAD LAMP PANEL (LH) Z BT		\$	240.10 Z ✓
TOP PANEL CENTRE Z BT		\$	364.90 Z ✓
RADIATOR ASSY Z BT		\$	1,841.80 Z ✓
RADIATOR BOTTOM MOUNTING H/L		\$	27.50 X
STAY, RADIATOR SUPPORT, RH H/L		\$	65.70 X
STAY, RADIATOR SUPPORT, LH H/L		\$	65.70 X
DEFLECTOR, RADIATOR SIDE, RH H/L		\$	83.50 X
DEFLECTOR, RADIATOR SIDE, LH H/L		\$	77.00 X
CONDENSER ASSY, W/RECEIVER Z BT		\$	1,336.60 Z ✓
SUB TOTAL		\$	15,497.00
LESS 20% DISCOUNT		\$	3,099.40
DISCOUNTED TOTAL		\$	12,397.60
FRONT NO. PLATE BT		\$	25.00 NETT ✓
FRONT NO PLATE TRIM COVER CRACK BT		\$	30.00 NETT ✓
FRONT NO.PLATE GARNISH CRACK		\$	99.00 NETT ✓
		\$	154.00
LABOUR CHARGE			
Panel Beating		\$	1,000.00 500/-
Spray Painting Charge		\$	250.00 200/-
Wiring Charge		\$	50.00 30/-
Towing Charge		\$	60.00 H/L
Remove/Refill Aircon & Refill Gas		\$	150.00 80/-
Diagnosis & Resetting To Erase Fault Code		\$	480.00 H/L
TOTAL LABOUR		\$	1,990.00

SHC 7402S

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LABOUR CHARGE			
Panel Beating			\$ 1,600.00 800/-
Spray Painting Charge			\$ 1,000.00 700/-
Wiring Charge			\$ 50.00 30/-
Tuff Kote			\$ 50.00 40/-
Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
Remove/Refix Reverse Sensor			\$ 80.00 40/-
Remove/Refix Exhaust Pipe			\$ 150.00 60/-
		1750.00	
TOTAL LABOUR			\$ 3,050.00
ESTIMATE TOTAL			\$ 30,218.74
28/11/2018 @ 1145hrs LKA Antine L/Sure 8 ¹³ days. You LKK Auto			24023.37 L/S 19200/-

LKK Auto Consultants hereby notify
 the Driver/Owner that the vehicle is being
 surveyed on a "No Fault" basis
 and the repair cost is reserved and
 is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021483/Dqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7897Y	Veh. Inspected	SHC 7402S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008378MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	28/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU203562737	Colour	YELLOW	
Odometer	216326	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2018	Inspection Date	28/11/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7402S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RADIATOR GRILLE	CRACKED	438.00	438.00
1	RADIATOR GRILLE EMBLEM	NECESSARY	88.00	88.00
1	LAMP ASSY,FOG,RH	MOUNTING CRACKED	920.00	920.00
1	LAMP ASSY,FOG,LH	MOUNTING CRACKED	920.00	920.00
1	FRONT BUMPER COVER	DISTORTED	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	BENT	696.40	696.40
1	FRONT BUMPER REINFORCEMENT ABSORBER	NOT NECESSARY	115.70	-
1	FRONT BUMPER SPONGE	TORN	78.80	78.80
1	FRONT BUMPER CENTRE GRILLE	DEFORMED	301.90	301.90
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	SUPPORT FR BUMPER,RH	SERVICEABLE	81.70	-
1	SUPPORT FR BUMPER,LH	SERVICEABLE	81.70	-
1	UNIT ASSY,HEADLAMP,RH (LED)	MOUNTING CRACKED	3,455.00	3,455.00
1	UNIT ASSY,HEADLAMP,LH (LED)	MOUNTING CRACKED	3,455.00	3,455.00
1	HEAD LAMP PANEL (RH)	BENT	240.10	240.10
1	HEAD LAMP PANEL (LH)	BENT	240.10	240.10
1	TOP PANEL CENTRE	BENT	364.90	364.90
1	RADIATOR ASSY	BENT	1,841.80	1,841.80
1	RADIATOR BOTTOM MOUNTING	NOT NECESSARY	27.50	-
1	STAY,RADIATOR SUPPORT,RH	NOT NECESSARY	65.70	-
1	STAY,RADIATOR SUPPORT,LH	NOT NECESSARY	65.70	-
1	DEFLECTOR,RADIATOR SIDE,RH	NOT NECESSARY	83.50	-
1	DEFLECTOR,RADIATOR SIDE,LH	NOT NECESSARY	77.00	-
1	CONDENSER ASSY,W/RECEIVER	BENT	1,336.60	1,336.60
1	REAR TRUNK LID COVER	BENT	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	BENT	457.90	457.90
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	254.40	-
1	REAR TRUNK LID RUBBER	DEFORMED	365.20	365.20

Report Ref No. CS/FCI18021483/Dqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TRUNK LID GLASS (BLACK COLOR)	NECESSARY	1,569.70	1,569.70
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	DISTORTED	889.70	889.70
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	47.00	47.00
1	REAR BUMPER	DENTED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER UNDER SIDE COVER (RH)	DEFORMED	232.00	232.00
1	REAR BUMPER UNDER SIDE COVER (LH)	SERVICEABLE	232.00	-
1	REAR BUMPER UNDER SIDE CENTRE COVER	DEFORMED	552.60	552.60
1	REAR BUMPER TOWING COVER	DISLODGE	82.70	82.70
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	ARM SUB-ASSY, REAR BUMPER, RH	MOUNTING CRACKED	139.60	139.60
1	ARM SUB-ASSY, REAR BUMPER, LH	MOUNTING CRACKED	139.60	139.60
2	TAIL LAMP ASSY (UPPER)(LH/RH) @\$557.90	CRACKED	1,115.80	1,115.80
2	TAIL LAMP ASSY (LOWER)(LH/RH) @\$548.40	CRACKED	1,096.80	1,096.80
1	REAR END PANEL	DENTED	602.10	602.10
1	REAR END PANEL GARNISH	CRACKED	121.60	121.60
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	667.70	-
1	REAR SPARE TYRE CHUSHION (FLR BOARD CENTRE)	NOT NECESSARY	101.40	-
1	REAR EXHAUST PIPE	BENT	1,163.40	1,163.40
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	40.70	-
1	REAR EXHAUST PIPE INSULATOR	NOT NECESSARY	314.60	-
1	REAR WINDSCREEN GLASS WITH MOULDING	NECESSARY	1,778.30	1,778.30
1	REAR WIRING ASSY	NOT NECESSARY	582.40	-
	LESS 20% DISCOUNT		-6,148.26	-
	LESS 25% DISCOUNT		-	-6,959.23
			24,593.04	20,877.67

Report Ref No. CS/FCI18021483/Dqd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NO PLATE (SN)	BENT	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	BENT	30.00	30.00
1	FRONT NO PLATE GARNISH (SN)	CRACKED	99.00	99.00
1	REAR NO PLATE WITH TRIM COVER (SN)	BENT	100.00	100.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	DEFORMED	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
			585.70	585.70
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		2,600.00	1,300.00
	SPRAY PAINTING CHARGE.		1,250.00	900.00
	WIRING CHARGE.		100.00	60.00
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	DIAGNOSIS & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	40.00
	REMOVE/REFIX EXHAUST PIPE.		150.00	60.00
	TUFF KOTE.		50.00	40.00
			5,040.00	2,560.00
	GRAND TOTAL		30,218.74	24,023.37
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			19,200.00

Report Ref No. CS/FC118021483/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.