



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

28/11/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAYA

Joy

Accident date: 19/11/2018

Estimated repair cost for vehicle no: GBC2441H TOYOTA HIACE MANUAL 3.0 '11

S/n	Qty	Items	U/price	Amount
1	1	Rear R/H Tail Lamp <i>crushed</i>		\$378.20 ✓
2	1	Rear R/H Tail Lamp Lower Cover <i>scratched</i>		\$182.10 ✓
3	1	Rear R/H Tail Lamp Lower Cover Retainer <i>sticker</i>		\$122.10 +
4	1	Rear Bumper <i>cut</i>		\$380.10 ✓
5	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 30
6	1	Rear R/H Bumper Side Retainer <i>new</i>		\$121.25 ✓
7	1	Rear R/H Fender <i>distorted</i>		\$1,317.80 ✓
8	1	Rear R/H Fender Inner Panel <i>local repair</i>		\$1,271.10 300 (SV)
9	1	Rear R/H Fender Mud Flap <i>new</i>		\$84.00 +
10	1	Rear R/H Tyre <i>3 older</i>		\$350.00 +
11	1	Rear R/H Rim		\$650.00 +
12	1	Rear R/H Hub Cap <i>lt</i>		\$186.10 80 (SV)
13	1	Rear R/H Shock Absorber <i>3 new</i>		\$182.40 +
14	1	Rear R/H Axle Bearing <i>new</i>		\$321.20 +
15	1	Rear Axle		\$2,728.10 +

Subtotal :- \$8,326.45

2409.45

180708

SV 380

Labour charges

To remove & refit reverse sensor

~~\$100.00~~ 40

To remove & refit rear axle

~~\$380.00~~ +

To check wheel alignment

~~\$150.00~~ 80

To check wiring

1560.

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 60

Panel beating

~~\$1,800.00~~ 600

Spray painting

~~\$1,800.00~~ 750

Subtotal :- \$4,480.00

Total:- \$12,806.45

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 374708

1/s: 3K

0.5 days

3K
0.5 days