



Case Details

Case Reference Number : TAX/11/18/2110
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1215K

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4686-ID
 Assigned By : Kok Wah Wong

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
 Accident Date and Time : 23/11/2018 09:25 PM
 Vehicle Age(In Months) : 60

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace ▾
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give ▾
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give ▾
									Total Spare Part Cost	623.62	Surveyor Total	463.95	
									Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20	
									Final Spare Part Cost	498.90	Final Sur Total	371.16	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH REAR PORTION	338.00	200	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	-----------	-------------------------	-------------------------	---------

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
Total:		378.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60	
3	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
4	TO WASH AND VACUUM	60.00	0	
Total:		556.88	356.88	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	498.90	371.16
Total Labour Cost	338.00	200.00
Total Spray Painting	378.00	200.00
Other	556.88	356.88
Overall Total	1,771.78	1,128.04
Lump Sum Repair Option	☒	☒
Lump Sum Total	1,750.00	1,150.00
Surveyor Approved Amount		1,150.00
No of Repair Days*	3	2
Remarks	-	resurvey after repair / lump sum
Surveyor Name		Rasul

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Signature		
Survey Date	26/11/2018	Save Clear