

22/03/2002

ASS. REC. BY:

REF: CS

SPF18021507/K1vd302

Special Instruction:

Surveyor: KalvinASSIGNMENT (Office)From (Person): Frankie they

of

SPF

Date/Time:

28/11/18 2:40pm

Estimated Cost:

Bill to:

OD TP WS TP RES OD RES EVA INV MV CS

To Inspect Vehicle No:

SG1059M

Insured:

PA 40634

at Workshop m/s

Bo Aheend

Tel:

90296574

of

21 Dyongway

Policy No:

Claim No:

AEMD 105 009 2018 169

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

29/11/18
H.O.D. Endorsement:

Date/Time:

4:20pm 28/11/18

Person Contacted:

YongshunVehicle IN OUT

Date/Time

Action/Instruction

☒

Estimate

SG1059M-CC2/MIDA17006431/H1/92JOA: 9/3/17Frankie said no GIA.

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspected Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SH1059M Yr Regn: 31 Mar, 2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes Benz Citaro c.c. 6374
 Colour: Green A/C: Insured / Std / NI / NA
 Sp. Reading: 172181 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WEB62808323130314
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / Rim or
 Tyre Size: F: 275/70R22.5
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Conti
 Front _____ Rear _____
 R/Bal. 4 mm R/Bal. 4.4 mm
 L/Bal. 4 mm L/Bal. 4.4 mm
 D.O.A. 9/11/18 D.O.I. 29/11/18
 Survey held at Go - Ahead
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/12/18	Subst P/P # 11106.28 / 4 hrs. (Red 3856.16, 26%) SPF
	EST Range \$10K - \$15K

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 10/12 - typist

Report Format: TP

Lump Sum / I.B.I. (\$) 11,106.28

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	280
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	280

RECEIVED 10 DEC 2018

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Wednesday, 28 November 2018 2:48 PM
To: assignments; Catherine Chong
Cc: Rosalyn TAN (SPF); Abdul Rahman MOHAMAD SALIM (SPF); Olivia Lau (LKKAuto)
Subject: RE : AEMD/105/009/2018/169 Pre-repair Inspect for SG1059M

Your reference : SG1059M

Our reference : AEMD/105/009/2018/169

Catherine,

Please conduct a Pre-repair Inspection for vehicle SG1059M at Go Ahead Singapore Pte Ltd at No.2 Loyang Way, Singapore 508776

Please contact Mr.Tien Yong Shun at 90296574 for appointment.

4.10pm.
W

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/11/2018 14:19
Date Of Accident	09/11/2018 22:15
Exact Location Of Accident	GUARD POST ENTERING AIRPORT TERMINAL 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG1059M
Insured/Policyholder	
Name Of Registered Owner	GO AHEAD LOYANG PTE LTD
Co Reg No	201541900C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63847169

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CITARO O530-6.4 D AT TURBO ABS (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-16083754MFBP
Cover Note Number	

Driver

Name of Driver	TAN TONG HONG
NRIC No	S2710173I
Date Of Birth	07/10/1959
Occupation	OUTDOOR
Date Of Driving Pass	02/04/1992
Driving Experience	26 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90995008
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 58, CHAI CHEE DRIVE #10-118
Postcode	460058
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 CHAI CHEE DRIVE , POSTCODE: 469045 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2448999 - FAX NO: 62446558
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AT GUARD POST ENTERING PASSENGER TERMINAL 1 BUS INTERCHANGE, I WAS STOPPED BY THE POLICE OFFICER AS THEY HAD TO CONDUCT A ROUTINE CHECK ON MY BUS BEFORE ALLOWING ME TO ENTER THE TERMINAL. THE OFFICERS FOUND A WHITE BAG LEFT UNATTENDED AT ONE OF THE SEATS ON THE BUS AND I WAS ASKED TO DRIVE MY BUS TO THE RIGHT SIDE SO THAT THEY CAN PERFORM FURTHER CHECK ON THE BUS. WHILE THEY WERE CONDUCTING THEIR CHECKS, THE REAR RIGHT OF A POLICE BUS BEARING REGISTRATION NO. PA4063Y DRIVING ON THE LANE TO MY LEFT COLLIDED ONTO MY LEFT OF MY BUS AS IT WAS DRIVING PAST THE GUARD POST.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	DIFFERENT FORMAT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	PA4063Y
Vehicle Make/Model/Colour	POLICE BUS
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	ABDUL QAIYUM BIN HABIB MARICAN
NRIC/Passport Number	

Contact Number	91011697
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


Sketch Plan



Accident Photo



Accident Photo



28th Nov 2018

Quotation No.: Q18-OPS-1221

SPF Accident Claims Section

Automotive Engg & Mgmt
Police Logistics Dept
1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333
Tel: 64784840
Fax: 64784848

Dear Sir/Mdm

Estimated Cost of Repair job for SG 1059M (along GUARD POST ENTERING AIRPORT TERMINAL 1 involving SG1059M & PA4063Y)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled labour to Replace rear LHS bumper, 2 nd last LHS panel, 3 rd last LHS panel	2 day	\$880.00	\$1,760.00 880
2	Supply skilled labour & welding material to repair 2 nd last LHS panel bracket, conduct Non-destructive test & apply anti-rust coating	2 day	\$880.00	\$1,760.00 880
3	Supply skilled painter & paint material to spraypaint 2 nd last LHS panel, 3 rd last LHS panel, rear LHS bumper & rear LHS dome (3 color - Green color, silver, white)	3 day	\$880.00	\$2,640.00 1760
4	Rear LHS 2nd panel <i>Band -10%</i>	1 pc	\$2,528.6	\$2,528.6
5	Rear LHS last panel <i>Band -10%</i>	1 pc	\$3,272	\$3,272
6	Rear LHS bumper <i>wa -10%</i>	1 pc	\$642.3	\$642.3
7	Rear LHS tail lamp <i>cut -10%</i>	1 pc	\$843.3	\$843.3
8	Light Amber LED <i>cut -10%</i>	1 pc	\$80.00	\$80.00
9	Bracket <i>-10%</i>	1 pc	\$323.24	\$323.24
10	ARM <i>Band -10%</i>	2 pc	\$245.30	\$490.60
11	STOP PLUG <i>rec -10%</i>	2 pc	\$8.10	\$16.20
12	PLATE <i>rec -10%</i>	2 pc	\$20.1	\$40.20
13	HEXALOBULAR BOLT M6 x 16 <i>rec -10%</i>	8 pc	\$2.00	\$16.00
14	"Go-Ahead Singapore" Sticker <i>rec</i>	1 pcs	\$50.00	\$50.00

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR GST Reg. No. 200004370R

S/N	Description	Qty.	Unit Price	Total Price
15	Advertisement sticker <i>new</i>	1 lot	\$500.00	\$500.00 400
Sub-total				\$14,962.44

Terms and Conditions:

Payment Terms : 30 days upon invoice

Quotation Validity : 30 days

Lead Time : 7 Working day (not inclusive waiting for parts)

Price quoted subject to 7% GST

Yours faithfully



Tien Yong Shun
Operation Executive

Approval by

Keshi (LKK)
29/11/18 1000L.
4 Pys
part By Part
Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to resurvey
- Third party survey is on a "best price" basis
- No illegal modification is allowed
- Supplementary request for resurvey and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

11166-28

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



bizSAFE
S T R

ROC / CR GST Reg. No. 200004370R




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18021507/K1vd3e2	
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN : FRANKIE THAY		Date : 14-12-2018	
		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PA 4063Y	Veh. Inspected	SG 1059M
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/169	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	28/11/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ CITARO	c.c	6374
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WEB62808323130314	Colour	GREEN
Odometer	172181	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	4 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	4 mm
R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	4/4 mm
L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	4/4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/11/2018	Inspection Date	29/11/2018
Survey held at	GO AHEAD LOYANG PTE LTD LOYANG BUS DEPOT 2 LOYANG WAY SINGAPORE 508776		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 1059M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR LHS 2ND PANEL	BENT	2,528.60	2,528.60
1	REAR LHS LAST PANEL	BENT	3,272.00	3,272.00
1	REAR LHS BUMPER	CRACKED	642.30	642.30
1	REAR LHS TAIL LAMP	CUT	843.30	843.30
1	LIGHT AMBER LED	CUT	80.00	80.00
1	BRACKET	TO REPAIR SEE LABOUR	323.24	-
2	ARM @\$245.30	BENT	490.60	490.60
2	STOP PLUG @\$8.10	NECESSARY	16.20	16.20
2	PLATE @\$20.10	NECESSARY	40.20	40.20
8	HEXALOBULAR BOLT M6 X 16 @\$2.00	NECESSARY	16.00	16.00
	LESS 10% DISCOUNT		-	-792.92
			8,252.44	7,136.28
<u>SPECIAL NETT ITEMS</u>				
1	"GO-AHEAD SINGAPORE" STICKER (SN)	NECESSARY	50.00	50.00
1	LOT ADVERTISEMENT STICKER (SN)	NECESSARY	500.00	400.00
			550.00	450.00
<u>LABOUR</u>				
	SUPPLY SKILLED LABOUR TO REPLACE REAR LHS BUMPER, 2ND LAST LHS PANEL, 3RD LAST LHS PANEL. INCLUSIVE OF THE REPAIR OF BRACKET.		1,760.00	880.00
	SUPPLY SKILLED LABOUR & WELDING MATERIAL TO REPAIR 2ND LAST LHS PANEL BRACKET, CONDUCT NON-DESTRUCTIVE TEST & APPLY ANTI-RUST COATING.		1,760.00	880.00
	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO SPRAYPAINT 2ND LAST LHS PANEL, 3RD LAST LHS PANEL, REAR LHS BUMPER & REAR LHS DOME (3 COLOR - GREEN COLOR, SILVER, WHITE)		2,640.00	1,760.00
			-	-
			-	-
			-	-
			-	-
			6,160.00	3,520.00
GRAND TOTAL			14,962.44	11,106.28

Report Ref No. CS/SPF18021507/K1vd3e2



RECOMMENDED COST OF REPAIRS			11,106.28
-----------------------------	--	--	-----------

Report Ref No. CS/SPF18021507/K1vd3e2

NOTES : THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$15,000

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.