




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18021546/Apb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG			Date : 06-12-2019	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	YP 8643L	<b>Veh. Inspected</b>	SJQ 6708U	
<b>Policy No.</b>	VCA/P2101847	<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	S8M014MQ	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>	LYNN KHONG	<b>Assign Date</b>	29/11/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	TOYOTA ALTIS	<b>c.c</b>	1598	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009	
<b>Chassis No.</b>	MR053ZEE106144914	<b>Colour</b>	GREY	
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM	
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	195/55 R15	ACHILLES	6 mm	
<b>L/H Front Tyre</b>	195/55 R15	ACHILLES	6 mm	
<b>R/H Rear Tyre</b>	195/55 R15	ACHILLES	6 mm	
<b>L/H Rear Tyre</b>	195/55 R15	ACHILLES	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	23/11/2018	<b>Inspection Date</b>	29/11/2018	
<b>Survey held at</b>	BEST SOLUTION AUTOCARE PTE LTD 53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>10 Working Days</b>		