

CC 3 /AIG1802

LKK:
IDAC:

INS. CASE OWNER:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO: Driver Name / Age:

Driver Tel No.:

(V/L) (YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
4/11/18	SHF 7775-4	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
11/02/19	SHF 7775-4	After call ltr to OI:	11/02/19. OK
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: P/P SS 2,685.51

(4 days) Reduction: 68 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: SS 2,685.51

Loss of Rental (LOR): SS 761.14 (6 days) X 9/25.19

Loss of Use (LOU): SS 320.00 (60 x 6 days)

Loss of Income (LOI): SS - (S x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search SS 7.00

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -

Total: SS 3,803.65

Global Sum SS: 3,760.00

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1: SS 3,760.00

Name 1:

Payee 2: (Strike if N.A.) SS -

Name 2:

Payee 3: (Strike if N.A.) SS -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$ 320.00

COPY SENT
7/6/19

Surveyor: Ram

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF 2775 Yr Regn: 2017 / DC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HYBRID 1.8 c.c 1798Colour: MARON A/C: Insured / Std / NI / NASp. Reading: 81822 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STOKB3FU103576421Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 26/11/18 D.O.I. 28/11/18Survey held at SMRTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/18/2123P/B 2,685.51
(CRP: 5,825.20 / 60%)AIGSDL 3143R

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS, SI

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18021555/R1hb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 29-11-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDL 3143R	Veh. Inspected	SHF 277S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/11/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information



Accident Date	26/11/2018	Inspection Date	28/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Section A - Accident Details

Registration Number	SHF277S
Case Reference Number	TAX/11/18/2123
Registration Date	14/12/17
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CLEMENT CHIANG BOON HUI (JIANG WENHUI)
Type of Accident	Head to Rear
Accident Date and Time	26/11/18 5:51 PM
Accident Reported Date and Time	27/11/18 9:44 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	26/11/18 6:17 PM
Replacement Vehicle issued?	No
Job Card Number	24098971
Special Instruction to ARC, if any	TOWED \$60 / AIG - LKK
Prepared Date and Time	28/11/18 2:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$1,476.00	\$480.00
Total Spare Part Cost	\$4,876.79	\$1,625.51
Total Other Cost	\$1,144.00	\$180.00
TOTAL COST	\$8,510.79	\$2,685.51 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Zhi Yang Phua	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	28/11/2018 2:43 PM	28/11/2018 4:28 PM
Signature		
Remarks		P/P resurvey before paint

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$400.00 /
Total Labour	\$1,014.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$80.00 /
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00 X an
TO RESPRAY REAR PANEL	\$180.00	\$100.00 /
TO RESPRAY TAIL GATE	\$378.00	\$0.00 X an
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00 /
Total Spray Painting & Panel Beating	\$1,476.00	\$480.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$84.00	\$60.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00 X an
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00 X an
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$60.00 /
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00 X an
TO REMOVE / REFIT WINDSCREEN	\$240.00	\$0.00 X an
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$60.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00 X an
TO WASH AND VACUUM	\$60.00	\$0.00 X an
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 X an
Total Other Costs	\$1,144.00	\$180.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80 7.6	25.00	\$5.70	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80 7.6	25.00	\$5.70	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80 7.6	25.00	\$5.70	Replace	Replace
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00 22	25.00	\$16.50	Replace	Replace
		52599680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given X an

SMRT Accident Vehicle Repair Estimates

SMP Automotive Services Pte Ltd
 50 W... Industrial Park E4, Singapore 757705
 FAX Number : 6365552
 Estimator Telephone Number : 69602023
 Accident Reporting Number : 69602672

Date Generated : 28/12/2018

User ID : FokSuan

52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	X	See
52576470 40	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace	X	See
52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X	See
52592470 40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X	See
52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	X	See
52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$556.30	25.00	\$418.73	Replace	Replace	X	See
52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X	See
52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X	See
52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Check	X	See
58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X	See
66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X	See
58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X	See
	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	X	See
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	X	See
58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$629.80	100.00	\$0.00	Replace	Repair	X	See
76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	X	See
75442471 30	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	X	See
75441470 90	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	X	See
75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	X	See
67005474 40	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given	X	See
56117501 40	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	X	See
75571470 10	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$29.70	0.00	\$0.00	Replace	Not Given	X	See
75575470 51	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$19.70	0.00	\$0.00	Replace	Not Given	X	See
75574470 40	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X	See
75573471 10	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X	See
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	See
	STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X	See
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X	See
	NUMBER PLATE	0.00	\$35.00	0.00	\$0.00	Replace	Not Given	X	See
	NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given	X	See
Total			\$5,708.30		\$1,296.48				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace
		52566479 00	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
Total					438.70		329.03		

1625.51
 + 400.00
 + 660.00
 2685.51

9863.40

4 days



Case Details

Case Reference Number : TAX/11/18/2123
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF277S

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4734-ID
 Assigned By : Kok Wah Wong

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 26/11/2018 09:51 AM
 Vehicle Age(In Months) : 11

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace ▾
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace ▾
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give ▾
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give ▾
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63	Replace ▾

Total Spare Part Cost 4,547.76

Surveyor Total 1,296.43

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,547.76

Final Sur Total 1,296.43

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	1	0	Repair
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair
Total Spare Part Cost									4,547.76		Surveyor Total	1,296.43	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									4,547.76		Final Sur Total	1,296.43	

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace			
One Time Key In	Main			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Give
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	55.80	25.00	41.85	Replace	0	0	Not Give
One Time Key In	Main			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	29.70	25.00	22.27	Replace	0	0	Not Give
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS , BACK DOOR	1	19.70	19.70	25.00	14.77	Replace	0	0	Not Give
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , LH	1	29.90	29.90	25.00	22.42	Replace	0	0	Not Give
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , RH	1	29.90	29.90	25.00	22.42	Replace	0	0	Not Give
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give

Total Spare Part Cost 4,547.76

Surveyor Total 1,296.43

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,547.76

Final Sur Total 1,296.43

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give

Total Spare Part Cost 4,547.76

Surveyor Total 1,296.43

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,547.76

Final Sur Total 1,296.43

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	1,014.00	400	
Total:		1,014.00	400.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY FILLER RR BUMPER LH	180.00	80	
3	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
4	TO RESPRAY REAR PANEL	180.00	100	
5	TO RESPRAY TAIL GATE	378.00	0	
6	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
Total:		1,476.00	480.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	84.00	0	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
Total:		1,144.00	120.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60	
5	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
6	TO REMOVE / REFIT WINDSCREEN	240.00	0	
7	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR,	120.00	60	
8	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
9	TO WASH AND VACUUM	60.00	0	
10	TO REPLACE SUNDRY PARTS	100.00	0	
Total:		1,144.00	120.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,547.76	1,296.43
Total Labour Cost	1,014.00	400.00
Total Spray Painting	1,476.00	480.00
Other	1,144.00	120.00
Overall Total	8,181.76	2,296.43
Lump Sum Repair Option		
Lump Sum Total	0.00	2,296.43
Surveyor Approved Amount		2,296.43
No of Repair Days*	6	4
Remarks		P/P resurvey before paint
Surveyor Name		Rasul

Estimator Assesment(\$)

Surveyor Assesment(\$)

Signature

Rasul

Save

Clear

Survey Date

28/11/2018

Vic (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Thursday, 7 March, 2019 10:12 AM
To: CS A Team; admin
Subject: LOD Re: Accident on 26/11/2018 involving SHF 27SS & SDL 3143R (AIG's insured)
Our Ref: TAX/11/18/2123/lg
Attachments: TAX 11 18 2123.pdf

Dear All,

We quantify our claim as follows:-

Cost of Repair	\$2685.51
Loss of Rental	\$813.74 (6.5 days x \$125.19)
Loss of Income	\$390.00 (6.5 day x \$60.00)
LTA Search Fee	\$7.00
Total	\$3896.25

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) GIA report
- 4) Accident vehicle laid-up report
- 5) LTA search

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2018 Edit Reg		28 Nov 2018 00:00 Edit Adj Rpt	S\$2,685.51 Edit Estimates	S\$2,685.51 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	YOHANNES BIN ZAHARI, ID: S1461946A		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHF277S	Date of Loss:	26/11/2018 17:00 - :59 [11 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9659063690SG	Policy/Cover Note No.:	1700082372 (Comprehensive)
Vehicle Reg. No. (Insured):	SDL3143R	Policy No. (Claimant):	D-18090213MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 10/12/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SHF277S (9659063690SG)**
[SDL3143R]
TP
SMRT TAXIS PTE LTD
Nov 26 2018 5:00PM
[YOHANNES BIN ZAHARI]
SMRT Automotive Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#) ▼

Letters/Correspondences 1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	

Photos/Images 3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/02/19 16:31	Odometer Reading	 Load JPG ☒	
2	11/02/19 16:31	Chassis Number	 Load JPG ☒	
3	11/02/19 16:31	General View	 Load JPG ☒	
4	11/02/19 16:31	General View	 Load JPG ☒	
5	11/02/19 16:31	General View	 Load JPG ☒	
6	11/02/19 16:31	General View	 Load JPG ☒	
7	11/02/19 16:31	General View	 Load JPG ☒	
8	11/02/19 16:31	General View	 Load JPG ☒	
9	11/02/19 16:31	General View	 Load JPG ☒	
10	11/02/19 16:31	General View	 Load JPG ☒	
11	11/02/19 16:31	General View	 Load JPG ☒	
12	11/02/19 16:31	General View	 Load JPG ☒	
13	11/02/19 16:31	General View	 Load JPG ☒	
14	11/02/19 16:31	General View	 Load JPG ☒	
15	11/02/19 16:31	General View	 Load JPG ☒	
16	11/02/19 16:33	Reinspection Photo	 Load JPG ☒	
17	11/02/19 16:33	Reinspection Photo	 Load JPG ☒	
18	11/02/19 16:33	Reinspection Photo	 Load JPG ☒	
19	11/02/19 16:33	Reinspection Photo	 Load JPG ☒	
20	11/02/19 16:33	Reinspection Photo	 Load JPG ☒	
21	11/02/19 16:33	Reinspection Photo	 Load JPG ☒	
22	11/02/19 16:33	Reinspection Photo	 Load JPG ☒	

Documentation 1 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 17:29	TP ESTIMATE- MARKED	 Load PDF	
2	29/11/18 17:29	TP GIA REPORT	 Load PDF	
3	11/02/19 16:29	EMAIL TO OI	 Load PDF	
4	11/02/19 16:29	LETTER TO OI	 Load PDF	
5	16/07/19 15:50	AUTHORISATION TO ACT	 Load PDF	
6	16/07/19 15:50	RELEASE VOUCHER	 Load PDF	
7	16/07/19 15:50	WORKSHOP INVOICE	 Load PDF	
8	16/07/19 15:50	RENTAL RECEIPT	 Load PDF	
9	16/07/19 15:50	RENTAL MILEAGE	 Load PDF	

Letters/Correspondences

No	Finalized On		1 per page ▼	☒
10	16/07/19 15:50	LKK Auto Consultants Pte Ltd (HQ)		
		LTA SEARCH		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	1	Thumbnail Print
1	30/11/18 08:32	OI GIA REPORT	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDL3143R (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHF277S (TP veh)		
Date of Accident:	26/11/2018		

Global Sum Settlement	:	☒ [X]	Yes	☐ []	No
Repair Estimate	:	\$			9,863.40
Final Repair Cost	:	\$			3,750.00
Loss of Use	:	\$			6.00 days at \$60.00 per day
Rental (if any)	:	\$			6 days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (GLOBAL SUM)	:	\$			3,750.00

Is Third Party Workshop GIA Registered?		☐ []	YES	☒ [X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability				100 (%)
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No				BOLA Scenario No: _____
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	: \$	3,750.00
2)		: \$	
3)		: \$	
4)		: \$	
5)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

16 Jul
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18021555/R1HB3S2
Date: 16/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700082372
Claimant Vehicle No : SHF277S **Insured Vehicle No :** SDL3143R
 Date of Loss: 26/11/2018 Nature of Claim: TP Claim No: 9659063690SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF277S**
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR8257676
 Reg. Date: 14/12/2017 (Man. Year: 2017) Chassis No: JTDKB3FU103576421
 Colour: Maroon Odometer: 81822 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
 Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,229.40	1,625.51	4,603.89	73.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,634.00	1,060.00	2,574.00	70.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,863.40	2,685.51	7,177.89	72.77
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Car Rental (6.0 x S\$125.19/day) (S\$)		751.14		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,803.65		
Global Sum Settlement (S\$)		3,750.00		

INSPECTION

Date of Assignment: 28/11/2018
 Date Inspected: 28/11/2018 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, RR BUMPER ASSY (DISC 25%)	Deformed	423.90 F	*317.93 F
2	2		*PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	Necessary	7.60 F	*5.70 F
3	2		*PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	Necessary	7.60 F	*5.70 F
4	2		*PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	Necessary	7.60 F	*5.70 F
5	2		*SEAL, RR BUMPER ARM, RH & LH (DISC 25%)	Necessary	22.00 F	*16.50 F
6	1		*RETAINER, RR BUMPER, LH (DISC 25%)	Necessary	111.50 F	*83.63 F
7	1		*GUARD, RR BUMPER, LOWER (DISC 25%)	Deformed	558.30 F	*418.73 F
8	1		*NAME PLATE (PRIUS), LUGGAGE COMPARTMENT (DISC 25%)	Necessary	52.30 F	*39.23 F
9	1		*NAME PLATE (HYBRID), LUGGAGE COMPARTMENT (DISC 25%)	Necessary	52.30 F	*39.23 F
10	1		*EMBLEM SUB-ASSY REAR (DISC 25%)	Necessary	46.30 F	*34.73 F
11	1		*REAR BUMPER REINFORCEMENT (DISC 25%)	Bent	318.80 F	*239.10 F
12	1		*FILLER, RR BUMPER, LH (DISC 25%)	Cut	119.90 F	*89.93 F
13	1		*SENSOR REVERSE (SN)	Necessary	180.00 F	*180.00 F
14	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
15	1		*STICKER SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
16	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
17	1		*RETAINER, RR BUMPER, RH	Serviceable	112.70 F	*- F
18	1		*NUMBER PLATE	Serviceable	35.00 F	*- F
19	1		*NUMBER PLATE FRAME	Serviceable	25.00 F	*- F
20	1		*STOPPER, RR BUMPER, RH & LH	Not Necessary	4.30 F	*- F
21	1		*SEAL, RR BUMPER, RH	Not Necessary	85.20 F	*- F
22	1		*SEAL, RR BUMPER, LH	Not Necessary	85.20 F	*- F
23	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F
24	1		*COVER, GUARD RR BUMPER LOWER	Not Necessary	14.80 F	*- F
25	1		*FILLER, RR BUMPER, RH	Not Necessary	119.90 F	*- F
26	1		*FILLER, RR BUMPER, LH	Not Necessary	119.90 F	*- F
27	1		*COVER, REAR FLOOR UNDER, RH	Not Necessary	169.50 F	*- F
28	1		*COVER, REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
29	1		*COVER, REAR FLOOR UNDER, LH	Not Necessary	234.30 F	*- F
30	1		*TAIL GATE PANEL SUB-ASSY, BACK DOOR	Not Necessary	929.60 F	*- F
31	1		*TAIL GATE DAM, BACK DOOR GLASS UPPER	Not Necessary	27.90 F	*- F
32	1		*TAIL GATE MOULDING GLASS, BACK DOOR	Not Necessary	29.70 F	*- F
33	1		*TAIL GATE MOULDING LOWER GLASS, BACK	Not Necessary	19.70 F	*- F
34	1		*TAIL GATE MOULDING LOWER GLASS, BACK	Not Necessary	29.90 F	*- F
35	1		*TAIL GATE MOULDING LOWER GLASS, BACK	Not Necessary	29.90 F	*- F
36	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
37	1		*END PANEL SUB-ASSY, BODY LOWER BACK	Repair	629.80 F	*- F
38	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	Repair	891.20 F	*- F

F=Franchise part.

Total Parts (\$\$) 6,229.40 1,625.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	1,014.00	400.00
2	SPRAY PAINT.	New	1,476.00	480.00
3	TOWING CHARGE.	New	84.00	60.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	0.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	60.00
7	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	0.00
8	TO REMOVE / REFIT WINDSCREEN.	New	240.00	0.00
9	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	60.00
10	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	0.00
11	TO WASH AND VACUUM.	New	60.00	0.00
12	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
Gross Labour Cost (S\$)			3,634.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >