

ASS. REC. BY:

REF:

08/FCI18021569/Atd3n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Suzene Ter

of

FCI

Date/Time:

3:29pm @ 29/11/18

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ4580L

Insured:

SHC 7899S

at Workshop m/s

New Hock Teck

Tel:

G7 4792-41

of

1 Kaki Bukit Ave 6 # 01-43

Policy No:

Claim No:

D18008474 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/11/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:36pm @ 29/11/18

Person Contacted:

Sukyi

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLZ4580L - X

SHC7899S - CS/FCI18014582/T1qd3e2

DOA: 21/7/18

lump sum \$23,000+ (Red: 19,445.60; 45%)

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SL24580L Yr Regn: 2018 May.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make:

Hyundai Accent

C.C. 1368

Colour:

Grey.

A/C Insured / Std / NI / NA

Sp. Reading:

8971

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHCU41BTJ4423645

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14-

R:

175/70R14.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or: Kumho.

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A.

D.O.I. 29/11/18Survey held at: NHT.Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP / 1st Cap.

MR : 66K
PV : 42.6K
Nett : 23.4K.

RECEIVED 30 JAN 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 30th Typist

☒

Final Report

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / I.B.I: (\$ 23,000/-)

Days Of Repair: 28Resurvey No. of Trip: 32

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) \$ + RS. SI

) Photos

) Others

) 30/1/19

TOTAL

41X15= 615

170+615
50
50+50
218

1153

MOTOR SURVEY ASSIGNMENT

Date	28-11-2018	Our Ref No. D18008474MFSH
Accident Date	14-11-2018	Claim Type. Third Party
Insured Vehicle	SHC7899S	Third Party Vehicle. SLZ4580L
Survey Location	1 KAKI BUKIT AVE 6 BLK C #01-43 AUTOBAY@KAKI BUKIT	
Contact Person.	REENA	
Contact No.	67479241/ 0	Fax No. 67417276
Survey Type	WITHOUT PREJUDICE: NO EST.	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	NEW HOCK TECK MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.



New Cars

Used Cars

Sell My Car

Directory


Products

Insurance

Articles

Forum

Resources



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Cheapest F30 in market @ only \$86k, call now

Priced like a 316i but is a 320i valued for money and higher horsepower, call!

Friends Auto Traders - StarAd

Free VICOM evaluation
Free grooming and 6 months maintenance
In-house workshop ensures quality service
Member of SYTA and hire purchase association
100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

2 vehicles

Search

accent

Advanced Search

Search

View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection

accent Any Any Any Any Any Any Available



☐ Hyundai Accent 1.4A SDR (OPC) \$44,800 \$5,630 /yr 30-Oct-2015 1,368 cc 28,000 km Hatchback Available

\$0 Down Payment Available, Promotional Bank Loan At 2.28% Interest. Convention To Normal Plate Car, Monthly At \$555. 1 Owner With Original Regular Komoco Agent Maintain Condition, Decent Fuel Consumpt...

Taxis

Posted: 24-Nov-2018 Tags: 2015 Hyundai Accent, 2015 hyundai accent, Hyundai Accent, hyundai accent, Hyundai, Accent, accent, Used Hyundai



☐ Hyundai Accent 1.4A \$62,000 \$6,220 /yr 26-Mar-2018 1,368 cc 3,900 km Sedan Available

Accident Free, Very Low Mileage Done, The Most Reliable And Affordable Sedan In The Market. No Outstanding Loan. Buy With A Peace Of Mind, Don't Miss Before It's Gone. Comes With 5 Year Warranty And S...

Carro

Posted: 25-Nov-2018 Tags: 2018 Hyundai Accent, 2015 hyundai accent, Hyundai Accent, hyundai accent, Hyundai, Accent, accent, Used Hyundai

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or modifications, SUV, MPV, hatchbacks, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find the used accent, accent Singapore, used accent Singapore, used accent, used vehicles Singapore or even buy used accent Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare

 [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 2911Z

Vehicle Details

Vehicle No.: SLZ4580L
Vehicle to be Exported: No
Intended Deregistration Date: 16 Nov 2018
Vehicle Make: HYUNDAI
Vehicle Model: ACCENT (RB) 1.4 CVT
Primary Colour: Silver
Manufacturing Year: 2018
Engine No.: G4LCJU963788
Chassis No.: KMHCU41BTJU423645
Maximum Power Output: 73.6 kW (98 bhp)
Open Market Value: \$7,776.00
Original Registration Date: 03 May 2018
First Registration Date: 03 May 2018
Transfer Count: 0
Actual ARF Paid: \$7,776.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 02 May 2028
PARF Rebate Amount: \$5,832.00

Intended COE Rebate Details

COE Expiry Date: 02 May 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$38,830.00
COE Rebate Amount: \$36,736.00
Total Rebate Amount: \$42,568.00

The information contained herein is correct as at 16 Nov 2018

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

28/11/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 1st Cap.

Denise

Accident date: 14/11/2018

Estimated repair cost for vehicle no: SLZ4580L HYUNDAI ACCENT 1.4 A '18

CHASSIS: KMHC41BTJU423645

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>distorted</i>		\$1,277.40 ✓
2	2	Front Bonnet Hinge <i>Bent</i>	\$46.00	\$92.00 ✓
3	1	Front Bonnet Lock <i>Damaged</i>		\$105.80 ✓
4	2	Front Bonnet Stopper Rubber <i>Not new</i>	\$27.00	\$54.00 ✗
5	2	Front Head Lamp <i>cracked</i>	\$667.70	\$1,335.40 ✓
6	2	Front Head Lamp Lower Bracket <i>Damaged</i>	\$25.50	\$51.00 ✓
7	1	Front Bumper <i>Distorted</i>		\$468.30 ✓
8	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30 ✓
9	2	Front Bumper Side Retainer <i>new</i>	\$23.50	\$47.00 ✓
10	2	Front Bumper Fog Lamp <i>RH missing, LH cracked</i>	\$210.80	\$421.60 ✓
11	1	Front Bumper Number Plate <i>missing</i>		\$50.00 ✓
12	1	Front Bumper Number Plate Garnish <i>Defend</i>		\$23.00 ✓
13	1	Front Bumper Centre Lower Garnish <i>Defend</i>		\$89.80 ✓
14	1	Front Bumper Inner Sponge <i>cracked</i>		\$98.30 ✓
15	1	Front Bumper Reinforcement <i>Best</i>		\$405.20 ✓
16	1	Front Bumper Lower Reinforcement <i>new</i>		\$50.60 ✗
17	1	Front Bumper Towing Cover <i>missing</i>		\$33.20 ✓
18	1	Front Bumper Top Rubber <i>6x</i>		\$45.30 ✓
19	1	Front Bumper Top Beam <i>2nd</i>		\$216.60 ✗
20	2	Front Bumper Top Beam Bracket <i>5mm</i>	\$68.20	\$136.40 ✗
21	1	Front Grille <i>cracked</i>		\$235.80 ✓
22	1	Front Grille Emblem Logo <i>new</i>		\$39.90 ✓
23	2	Front Fender <i>LH cracked, RH distorted</i>	\$369.30	\$738.60 ✓
24	2	Front Fender Cowling <i>to be</i>	\$85.30	\$170.60 ✓
25	16	Front Fender Cowling Clip <i>new</i>	\$6.50	\$104.00 30 ✓
26	1	Front R/H Fender Side Bracket <i>Best</i>		\$38.90 ✓
27	1	Front R/H Fender Inner Panel <i>Distorted</i>		\$432.60 ✓
28	1	Front R/H Fender Housing <i>Distorted</i>		\$520.80 ✓
29	1	Front R/H Fender Housing Inner Panel <i>Repair</i>		\$498.10 ✗

30	1	Front Support Panel	Distorted		\$350.80	✓
31	1	Front Support Panel Top Cover	seized		\$45.20	✓
32	8	Front Support Panel Top Cover Clip	new	\$6.50	\$52.00	✓ 20.
33	2	Front Support Panel Side Air Duct Cover	Distorted	\$38.00	\$76.00	✓
34	2	Front Horn	new	\$116.20	\$232.40	✓ x
35	1	Front Air-Con Condenser	distorted		\$864.00	✓
36	1	Front Air-Con Section Pipe	2		\$576.40	✓
37	1	Front Air-Con Discharge Pipe	Bent		\$122.00	✓
38	1	Front Air-Con Pipe (Top Blower)	1		\$205.60	✓
39	1	Front Air Cleaner Box Assy	cracked		\$95.80	✓
40	1	Front Air Cleaner Box Air Duct	seized		\$38.90	✓
41	1	Front Radiator	Distorted		\$887.00	✓
42	1	Front Radiator Fan Motor Assy	smashed		\$420.00	✓
43	1	Front Radiator Top Hose	twisted		\$68.20	✓
44	1	Front Radiator Lower Hose	new		\$80.50	✓ x
45	1	Front Radiator Spare Tank	Distorted		\$90.60	✓
46	1	Front Wiper Tank	Distorted		\$89.50	✓
47	1	Front Wiper Tank Motor	cracked		\$112.60	✓
48	1	Front Wiper Garnish	cracked		\$268.50	✓
49	1	Front Engine Lower Cover	torn		\$128.00	✓
50	10	Front Engine Lower Cover Clip	new	\$6.50	\$65.00	✓ 20.
51	1	Front L/H Side Resonator	cracked		\$1,890.00	✓ 225
52	1	Front L/H Side Resonator Hose	new		\$321.40	✓ x
53	1	Front Battery (Nett)	seized		\$220.00	✓
54	1	Front Battery Lower Cover	torn		\$78.50	✓
55	1	Front Windscreen	cracked		\$944.00	✓
56	1	Front Windscreen Seal	2		\$85.00	✓
57	1	Front Windscreen Moulding	new		\$68.00	✓
58	1	Front Windscreen Erp Bracket Assy	1		\$65.00	✓ 20(SN).
59	2	Front Rim	RH Bent	\$1,156.30	\$2,312.60	✓ 200(SN)
60	2	Front Tyre	RH Seized	\$450.00	\$900.00	✓ 200(SN)
61	2	Front Lower Arm	Bent	\$266.00	\$532.00	✓
62	2	Front Knuckle Arm	Bent	\$363.60	\$727.20	✓
63	2	Front Knuckle Arm Bearing	new	\$171.10	\$342.20	✓
64	2	Front Shock Absorber	Bent	\$363.20	\$726.40	✓
65	2	Front Shock Absorber Mounting	new	\$85.30	\$170.60	✓
66	2	Front Stabilizer Bar	RH Bent	\$75.00	\$150.00	✓ 75.
67	2	Front Drive Shaft	RH Bent	\$989.90	\$1,979.80	✓ 989.90
68	1	Front Steering Rack	Bent		\$1,741.70	✓
69	1	Front Crossmember	Bent		\$1,438.00	✓
70	3	Front Engine Mounting	torn	\$308.00	\$924.00	✓
71	1	Front Gearbox Mounting	torn		\$237.10	✓
72	1	Front Air-Con Compressor	Damaged		\$1,659.80	✓

73	1	Front Antenna	3M		\$94.90	+
74	1	Front Exhaust Manifold	3M		\$3,926.50	+
75	1	Front Dashboard	Torn		\$1,192.40	✓
76	1	Front Dashboard Airbag	3 Activated		\$1,465.20	✓
77	1	Front Steering Airbag	3 Activated		\$1,090.90	✓
78	1	Front Steering Airbag Clock Sensor	3 Activated		\$219.70	✓
79	1	Front Airbag Control Unit			\$1,297.70	✓
80	2	Front Seat Belt	Activated	\$478.40	\$956.80	✓
81	2	Front Seat Belt Buckle	HP new	\$67.00	\$134.00	+
82	1	Front R/H Chassis	Repair		\$987.60	+
83	1	Oil Sump	cont'd		\$689.60	✓
84	1	Oil Sump Gasket	m		\$162.80	✓

Subtotal :- \$42,445.60

29460.90 SN 420
23568.72

Labour charges

To remove & refit front windscreen	\$120.00 ✓
Gum <i>NEC</i>	\$50.00 ✓
To remove & refit front engine	\$650.00 380
To remove & refit front steering rack, crossmember & drive shaft	\$450.00 200
To remove & refit front L/H & R/H undercarriage	\$450.00 400
To remove & refit air-con condenser, radiator, fan motor, antenna, manifold & air-con compressor	\$480.00 120
To remove & refit front dashboard	\$380.00 220
To remove & refit steering airbag, dashboard airbag, clock sensor, control unit, seat belt & buckle	\$450.00 350
To reset computer	\$350.00 150
To check wiring	\$150.00 30 <i>5560</i>
Tuff kote	\$150.00 80
Towing fee	\$150.00 60
Panel beating	\$2,800.00 200
Spray painting	\$2,000.00 1400

Subtotal :- \$8,630.00

Total:- \$51,075.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 29548.72
h/s: 2312
(Nett Value)

28 Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021569/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 31-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7899S	Veh. Inspected	SLZ 4580L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008474MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	29/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ACCENT	c.c	1368	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHCU41BTJU423645	Colour	GREY	
Odometer	8971	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	KUMHO	6 mm	
L/H Front Tyre	175/70 R14	KUMHO	6 mm	
R/H Rear Tyre	175/70 R14	KUMHO	6 mm	
L/H Rear Tyre	175/70 R14	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/11/2018	Inspection Date	29/11/2018	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		28 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 4580L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	DISTORTED	1,277.40	1,277.40
2	FRONT BONNET HINGE @\$46.00	BENT	92.00	92.00
1	FRONT BONNET LOCK	DAMAGED	105.80	105.80
2	FRONT BONNET STOPPER RUBBER @\$27.00	NOT NECESSARY	54.00	-
2	FRONT HEAD LAMP @\$667.70	CRACKED	1,335.40	1,335.40
2	FRONT HEAD LAMP LOWER BRACKET @\$25.50	DAMAGED	51.00	51.00
1	FRONT BUMPER	DISTORTED	468.30	468.30
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$23.50	NECESSARY	47.00	47.00
2	FRONT BUMPER FOG LAMP @\$210.80	O/S MISSING / N/S CRACKED	421.60	421.60
1	FRONT BUMPER NUMBER PLATE	MISSING	50.00	50.00
1	FRONT BUMPER NUMBER PLATE GARNISH	DEFORMED	23.00	23.00
1	FRONT BUMPER CENTRE LOWER GARNISH	DEFORMED	89.80	89.80
1	FRONT BUMPER INNER SPONGE	CRACKED	98.30	98.30
1	FRONT BUMPER REINFORCEMENT	BENT	405.20	405.20
1	FRONT BUMPER LOWER REINFORCEMENT	NOT NECESSARY	50.60	-
1	FRONT BUMPER TOWING COVER	MISSING	33.20	33.20
1	FRONT BUMPER TOP RUBBER	CUT	45.30	45.30
1	FRONT BUMPER TOP BEAM	NOT NECESSARY	216.60	-
2	FRONT BUMPER TOP BEAM BRACKET @\$68.20	NOT NECESSARY	136.40	-
1	FRONT GRILLE	CRACKED	235.80	235.80
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	39.90	39.90
2	FRONT FENDER @\$369.30	N/S BUCKLED / O/S DISTORTED	738.60	738.60
2	FRONT FENDER COWLING @\$85.30	TORN	170.60	170.60
16	FRONT FENDER COWLING CLIP @\$6.50	NECESSARY	104.00	30.00
1	FRONT R/H FENDER SIDE BRACKET	BENT	38.90	38.90
1	FRONT R/H FENDER INNER PANEL	DISTORTED	432.60	432.60
1	FRONT R/H FENDER HOUSING	DISTORTED	520.80	520.80
1	FRONT R/H FENDER HOUSING INNER PANEL	TO REPAIR SEE LABOUR	498.10	-

Report Ref No. CS/FCI18021569/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL	DISTORTED	350.80	350.80
1	FRONT SUPPORT PANEL TOP COVER	DEFORMED	45.20	45.20
8	FRONT SUPPORT PANEL TOP COVER CLIP @\$6.50	NECESSARY	52.00	20.00
2	FRONT SUPPORT PANEL SIDE AIR DUCT COVER @\$38.00	DISTORTED	76.00	76.00
2	FRONT HORN @\$116.20	NOT NECESSARY	232.40	-
1	FRONT AIR-CON CONDENSER	BENT	864.00	864.00
1	FRONT AIR-CON SECTION PIPE	BENT	576.40	576.40
1	FRONT AIR-CON DISCHARGE PIPE	BENT	122.00	122.00
1	FRONT AIR-CON PIPE (TOP BLOWER)	BENT	205.60	205.60
1	FRONT AIR CLEANER BOX ASSY	CRACKED	95.80	95.80
1	FRONT AIR CLEANER BOX AIR DUCT	DEFORMED	38.90	38.90
1	FRONT RADIATOR	DISTORTED	887.00	887.00
1	FRONT RADIATOR FAN MOTOR ASSY	SMASHED	420.00	420.00
1	FRONT RADIATOR TOP HOSE	TWISTED	68.20	68.20
1	FRONT RADIATOR LOWER HOSE	NOT NECESSARY	80.50	-
1	FRONT RADIATOR SPARE TANK	DISTORTED	90.60	90.60
1	FRONT WIPER TANK	DISTORTED	89.50	89.50
1	FRONT WIPER TANK MOTOR	CRACKED	112.60	112.60
1	FRONT WIPER GARNISH	CRACKED	268.50	268.50
1	FRONT ENGINE LOWER COVER	TORN	128.00	128.00
10	FRONT ENGINE LOWER COVER CLIP @\$6.50	NECESSARY	65.00	20.00
1	FRONT L/H SIDE RESONATOR	CRACKED	1,890.00	235.00
1	FRONT L/H SIDE RESONATOR HOSE	NOT NECESSARY	321.40	-
1	FRONT BATTERY	DEFORMED	220.00	220.00
1	FRONT BATTERY LOWER COVER	TORN	78.50	78.50
1	FRONT WINDSCREEN	CRACKED	944.00	944.00
1	FRONT WINDSCREEN SEAL	NECESSARY	85.00	85.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	68.00	68.00
2	FRONT LOWER ARM @\$266.00	BENT	532.00	532.00
2	FRONT KNUCKLE ARM @\$363.60	BENT	727.20	727.20
2	FRONT KNUCKLE ARM BEARING @\$171.10	NECESSARY	342.20	342.20
2	FRONT SHOCK ABSORBER @\$363.20	BENT	726.40	726.40

Report Ref No. CS/FCI18021569/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT SHOCK ABSORBER MOUNTING @\$85.30	NECESSARY	170.60	170.60
2	FRONT STABILIZER BAR @\$75.00	O/S BENT	150.00	75.00
2	FRONT DRIVE SHAFT @\$989.90	O/S BENT	1,979.80	989.90
1	FRONT STEERING RACK	BENT	1,741.70	1,741.70
1	FRONT CROSSMEMBER	BENT	1,438.00	1,438.00
3	FRONT ENGINE MOUNTING @\$308.00	TORN	924.00	924.00
1	FRONT GEARBOX MOUNTING	TORN	237.10	237.10
1	FRONT AIR-CON COMPRESSOR	DAMAGED	1,659.80	1,659.80
1	FRONT ANTENNA	NOT NECESSARY	94.90	-
1	FRONT EXHAUST MANIFOLD	NOT NECESSARY	3,926.50	-
1	FRONT DASHBOARD	TORN	1,192.40	1,192.40
1	FRONT DASHBOARD AIRBAG	ACTIVATED	1,465.20	1,465.20
1	FRONT STEERING AIRBAG	ACTIVATED	1,090.90	1,090.90
1	FRONT STEERING AIRBAG CLOCK SENSOR	ACTIVATED	219.70	219.70
1	FRONT AIRBAG CONTROL UNIT	ACTIVATED	1,297.70	1,297.70
2	FRONT SEAT BELT @\$478.40	ACTIVATED	956.80	956.80
2	FRONT SEAT BELT BUCKLE @\$67.00	NOT NECESSARY	134.00	-
1	FRONT R/H CHASSIS	TO REPAIR SEE LABOUR	987.60	-
1	OIL SUMP	CRACKED	689.60	689.60
1	OIL SUMP GASKET	NECESSARY	162.80	162.80
	LESS 20% DISCOUNT		-	-5,905.82
			39,168.00	23,623.28
	SPECIAL NETT ITEMS			
1	FRONT WINDSCREEN ERP BRACKET ASSY (SN)	NECESSARY	65.00	20.00
2	FRONT RIM @\$1156.30 (SN)	O/S BENT	2,312.60	200.00
2	FRONT TYRE @\$450.00 (SN)	O/S DEFORMED	900.00	200.00
1	GUM (SN)	NECESSARY	50.00	50.00
			3,327.60	470.00
	LABOUR			
	TO REMOVE & REFIT FRONT WINDSCREEN.		120.00	120.00
	TO REMOVE & REFIT FRONT ENGINE.		650.00	380.00

Report Ref No. CS/FC118021569/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT FRONT STEERING RACK,CROSSMEMBER & DRIVE SHAFT.		450.00	200.00
	TO REMOVE & REFIT FRONT L/H & R/H UNDERCARRIAGE.		450.00	400.00
	TO REMOVE & REFIT AIR-CON CONDENSER,RADIATOR,FAN MOTOR,ANTENNA,MANIFOLD & AIR-CON COMPRESSOR.		480.00	120.00
	TO REMOVE & REFIT FRONT DASHBOARD.		380.00	220.00
	TO REMOVE & REFIT STEERING AIRBAG,DASHBOARD AIRBAG,CLOCK SENSOR,CONTROL UNIT,SEAT BELT & BUCKLE.		450.00	350.00
	TO RESET COMPUTER.		350.00	150.00
	TO CHECK WIRING.		150.00	30.00
	TUFF KOTE.		150.00	80.00
	TOWING FEE.		150.00	60.00
	PANEL BEATING,INCLUSIVE OF THE REPAIR OF FRONT R/H FENDER HOUSING INNER PANEL AND FRONT R/H CHASSIS.		2,800.00	2,000.00
	SPRAY PAINTING.		2,000.00	1,400.00
			8,580.00	5,510.00
GRAND TOTAL			51,075.60	29,603.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				23,000.00

Report Ref No. CS/FCI18021569/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.