MINEYOT -	Truhkh	ASSIGN	MENT (Office)		02	
rom (Person):	Irene	of	Smo	Dat	e/Time: 0312201	8 918cm
Estimated Cost: _			Bill to:			
OD/TE/WS/T	PRES/ODRES/E				C	
To Inspect Vehicl		3KS 88PP.	Ζ	Insured:	GBC 93001	Κ
nt Workshop m/s	Her	turning		Tel:		37
of		Alexandra	Rd			
Policy No:	DISMTHCYED	00143	Claim No:	auto	1805070	-
Sum Insured:			Excess:			
Make of Veh: (Client's Record)			76	D.C	0111F1 _A.C	18
CA / REV / R Date/Tune:	EP. / REV 24 HRS B122018 109 m	wpt Person Contac	ted: Coolin.	14.50	LO,D. Endorsement:	
Date/Time A	ction/Instruction (/) Estin	rate			
	KS 6866Z - X					
	BC 9300K - X					
14/12/18@ 5.	4mm reuse	d to tre	ne via Meña Cavoline frant)	ren .		The state of the state of
24/1/1901	530 Combin	ed water	Caroline found	Reg B :	1693.20	6 days
	-11-00-11		Conta	1	-	

REF:	Sm O.		
· Elimpour , Taylly	×	1	
From Date: Estimated Cost. OD TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No. at Workshop m/s of Insured Policy No. Claims No. Sum Insured Excess: (Client's Record)	Type M.Car / M.Cycle / Bus / Van / Truck / Trailer or Make:	A/C: Insured / S T/Radio: Insured / S G 12040 E G 2/20 rnt ed / Burnt or ed / Burnt or	1799 td / NI / NA
Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No Consistent?: Yes or No Est. Repairs: Lum Sum: CA / REV / REP. / 24 HRS Person Contacted: Vehicle: In Date: Person Contacted:	R: O/S B8/DUN/EXNOVA/GY/FS/LIG TOYO/YOKO or Front R/Bal. mm L/Bal. mm D.O.A. Survey held at Des. of Damages: Frt / Rear / O	ZA / MIC / OHTSU / PIR / S Rear R/Bal. L/Bal. D.O.I. 3/17	mm mm
Date / Time Action / Instruction	Repute: 9 65		4/1/5010
Dute/Time File Pass to? : Prell. Report	Days Of Repair:	Survey Fee.	
Date/Time, File Return to?	dd Fee: Site Insp (\$	Transportation)S+RSSt) Photos	350 10
Report Format: NER-TP Lump Sum / I.B.I: (\$ 7693.20)	Tech Invs (\$) Others	
		TOTAL	360

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

IRENE JAMES HENRY

Date: 04 Dec 2018

Preliminary Advice

Insured Vehicle No : GBC9300K

TP Vehicle No

: SKS6866Z

Accident Date

: 17/11/2018

Make

: BMW X1

Assignment Date

: 03/12/2018

Date of Inspection : 03/12/2018

Est. Duration of Repair

: 6.00

Inspection At

: PERFORMANCE MOTORS LIMITED (BUKIT TIMAH)

896 DUNEARN ROAD #01-01 SIME DARBY CENTRE

SINGAPORE 489572

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,189.00
Revised Amount	:S\$	7,537.90
Check Items (Estimated)	:S\$	1,268.50
Total	:S\$	8,806.40

:SS Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	19 Nov 2018		03 Dec 2018 09:18 Assign	en 190 tiller			New Assignme Cancel Case	ent 	
	Main	R	eference		laim Details	Doc	uments	Show All	
	UBFOLDER DET	1000 000 000 000 000 000 000 000 000 00			and the same of th		Created by insu	rerl	
nsured: fain Clair	mant:		MING. ID: S89		98104531H				
ehicle Re	eg. No.:	OH YI MING, ID; S89054541 SKS6866Z Date of Loss: 17/11/2018 10:00 - :59 [6 Months and 22 Days Fr Reg Date (Man Yr)]				Days From LTA			
laim Typ	e:	TP /	CMTD1805070	,	olicy/Cover Note No.		D18MTHCVE000143 (Third Party Only)		
Vehicle Reg. No. (Insured):		GBC9:	300К	F	Policy No. (Claimant):		Jilly)		
			mana Natara I	Excess: Limited (Bukit Timah) 896 Dunearn Road #01-01 Sime Dar					
tepairer:		Timah	- Tel: 63190533	imited (Bukit	Timah) 896 Dunear	n Road #01-01 S	ime Darby Centre,	489572 Bukit	
landling 1	Insurer:	Somp 4618]	o Insurance Sing	apore Pte. Li	d. (HQ) - Tel: 6461	6555 [Handled	by IRENE JAMES	HENRY - 6322	
djuster:		LKK A	uto Consultants	Pte Ltd (HQ)	- Tel: 6256-3561	[Final Rpt due	e 12/12/2018]		
river/Cus	stodian (Insured)	: WU EN	QI (), NRIC: G2	610248R, Te	1: +6584035297				
SSOCIA	TED MAIL REC	EIVED				Vie	ew All Comp	ose Case Mail	
here are	no mail for this c	ase.					Comp	ose case mail	
ALL ASS	OCIATED TASK	s			View All S	earch Tasks	Create New Task	Complete	
Due Da lo results		Type Task	Group Subje	ct Handler	Assigned By	Completed	On Created	On Done?	

Shiau Chan (LKKAuto)

Siliau Cilaii (EKKO	
From:	Shiau Chan (LKKAuto)
Sent:	Thursday, 24 January 2019 1:53 PM
То:	'PBSP'; Taufikh (LKKAuto); SUR; CS A Team
Subject:	RE: FINAL REPORT / SKS6866Z / Sompo
Dear Caroline,	
WITHOUT PREJUDICE	
Confirm final fig \$7,69	93.20 before GST and 6 repair days.
Kindly send the releva	ant documents to SOMPO Insurance company.
Best Regards,	
Shiau Chan (Ms) Cas	se Handler
LKK Auto Consultant	
	il: siewsc@lkkauto.com fax: 6256-4315
Blk 51, Paya Ubi Industr	ial Park, Ubi Avenue 1, #02-25 S(408933)
	p@simedarby.com.sg>
Sent: Tuesday, 22 Jan	
	<taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com> RT / SKS6866Z / Sompo</cs-a@lkkauto.com></sur@lkkauto.com></taufikh@lkkauto.com>
Dear Sirs	
We refer to the abo	ove and attached Final Report.
Please confirm COR	as follows:

Total Labour: 4,484.00 Total Parts: 3,209.20

Total Labour & Parts: 7,693.20

Repair days: 6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number

Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	17/11/2018 12:25
Date Of Accident	17/11/2018 09:10
Exact Location Of Accident	OLD TAMPINES ROAD / FLORA ROAD INTERSECTION
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKS6866Z
Insured/Policyholder	
Name Of Registered Owner	OH YI MING
NRIC No	S8905454J
Email Address	YIMING.OH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91139087
Alternative Phone No	OTHERS-91139087
Vehicle Particulars	
Manufacturer	BMW
Model	X1
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1619290
Cover Note Number	
Driver	
Name of Driver	OH YI MING
NRIC No	S8905454J
Date Of Birth	05/02/1989
Occupation	INDOOR
Date Of Driving Pass	27/12/2010
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91139087

OTHERS-91139087

YIMING,OH@GMAIL,COM

Address

9 RHU CROSS #06-09 SINGAPORE

Postcode

437436

OWNER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by

NO NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBC9300K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category GOODS VEHICLE

Name of Driver

WU ENQI

NRIC/Passport Number

G2610248R

Contact Number

84035297

Address

Postcode

Insurance Company Name

SOMPO INSURANCE SINGAPORE PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

and the state of

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the malling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, Investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

17 how 18 11 worker

Driver's Signature

(If driver is not the policyholder)

Date & Time: 17 Nov 18 11:004M

Reporting Centre Personnel's Signature

GARY ---Performance 303 Alex Sime Darby ₽

OON

Name:

NRIC/FIN No .:

Sketch Plan Pg. 2

2 4 5 7 7 7 2

Policyholder's Signature

81 064 F)

MAELTI

Date & Time:

Driver's Signature

Date & Time:

(If driver is not the policyholder)

SKETCH PLAN ROAD DESCRIBE CIRCUMSTANCES OF THE ACCIDENT INCIDENT OCCURED AT A 9:13AM I WAS WAITING AT THE RED LIGHT TO THEN RIGHT. AFTER THE LIGHT TURNED GREEN, THE CAR IN FRONT OF ME SOT OFF. BEFORE I SET OFF, THE DELIVERY TRACK (GB (9300K) CRASHED INTO MY REAR. DECLARATION I/We declare the foregoing particulars are true in every respect. Performance Mon 303 Alexandro Anad Sime Darby Performance

Reporting Centre Personnel's Signature

Singaporu

Name:

NRIC/FIN No.:

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

BOOTLID SEALING

280, Kampong Arang Road East Coast Centre Singapore 438180 Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796601 (AfterSales) 64796604 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

19 NOV 2018

NH 165.55

165.55

Estimate No. Date Estimate Prepared By	: b1 4916 d : 19/11/2018 : Gary Poh C	3			Page No	. : 1 of 5	
- ESTIMATE REPAIR FOR - Oh Yi Ming (Hu Yiming) 9 Rhu Cross #06-09 Singapore 437436				OUNT - ales - Ser ore	40000 cvice		
EGN. NO.	CHASSIS NO.	REGN. DATE	MOD			MILEA	GE
KS6866Z	EG21246	26/04/2018	X1	sDrive18i		0	
To	SCRIPTION replace rear bumper,bootluse by the accident .	id & attachment includ	de knockinç			1700	VALUE 2,550.00
Pai	inting rear bumper ,bootlid					1805-	2,006.00
	carry out body cavity present	ervation.				100	118.00
То	replace rear windscreen g	lass.				487	574.00
То	conduct water leak tests.					6/5	75.00
То	supply and install rear win	dscreen solar film.				451	531.00
Su	ndries.					nic 80 7	150.00
				To	otal Labour	1:	6,004.00
BC RE RE	SCRIPTION OTLID AR LH BUMPER MOUNT AR RH BUMPER MOUNT BUMPER CARRIER			<u>QTY</u> 1 1	PRIC 1,230.50 160.55 160.55 468.30		VALUE 1,230.50 7 160.55 160.55 2 468.30
MC RE RR	DUNTING SMART OPENE AR TRIM UNDERRIDE PR BUMPER LH CORNER N BUMPER RH CORNER N	ROTECTION (X L MOUNTING		1 1 1	45.30 102.30 141.90 141.90	d	7 45.30 7 102.30 7 141.90 7 141.90
RE RE RE	AR BUMPER PANEL PRI AR BUMPER MIDDLE TR AR BUMPER MIDDLE TR AR BUMPER TRIM BOTT	MED RIM PANEL (PDC) RIM PANEL (PDC)		1 1 1	741.55 233.60 233.60 222.45	de	741.55 233.60 × 233.60 222.45
BM LE	MBLEM GROMMET MW PLAQUE WITH ADHES TTERING X1	SIVE FILM		2 1 1	71.25 64.10	~	1.60 71.25 64.10

BMS Dealer ' ,

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-8020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 63190533/530

(AfterSales) (Motorrad) (AfterSales) (Motorrad)



ESTIMATE

Estimate No.

: b1 49161

Date Estimated

: 19/11/2018

Prepared By

: Gary Poh Chai Hoon

REGN. NO. SKS6866Z CHASSIS NO.

EG21246

REGN. DATE 26/04/2018 MODEL

X1 sDrive18i


MILEAGE

0

Page No. : 2 of 5

Total Parts

4,185.00



LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before after s ray painting

To display damaged part is during resurvey

· Parts prices are subject to confirmation

. Third party survey is on a "Without Prejudice" basis

. No illegal modification(s) is allowed

· Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1 6,004.00 : Parts 4,185.00 8 0.00 Labour 2 0.00 Excess 713.23 Total GST @ 7% Grand Total 10,902.23

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

10715.30

Performance Motors Limited

A member of the Sime Darby Group Co, Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No.

b1 49161

Page No. :

Date Estimated : 19/11/2018

Prepared By

Gary Poh Chai Hoon

REPAIR FOR -

- ACCOUNT -

509

Oh Yi Ming (Hu Yiming)

Sompo Insurance Singapore Pte Ltd

9 Rhu Cross

50 Raffles Place

#06-09

#05-01/06 Singapore Land Tower

Singapore 048623

Singapore 437436

REGN NO

CHASSIS NO. EG21246

REGN DATE

MODEL

M LEAGE

SKS6866Z

26/04/2018

X1 sDrive18i

DISC. %

DESCRIPTION

ORIGINAL PRICE

NETT

To check electrical wiring system and lightings at the rear section for proper function

150.00

150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.55	4.00		10.20 Ne
# EXPANDING NUT *	1.00	2.00		2.00 na
# BUMP STOP *	3.35	10.00		33.50 Nec-
# EXPANDING RIVET *	1.35	10.00		13.50 14
# (DG) CLEANER R1 (100ML) *	26.15	1.00		26.15 me
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00		263.10 M
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00		27.85 14

Total Labour : Total Parts : Total Labour & Parts	150.00 376.30 5:Yhe9 bar GO = med 526.30
Page 1	Rejn Vi
102	The sections
99	9) (Wywy 2
ON THE ON THE MONTH	
	HE SURVEY PARTS PHO
1 30 3	S revise Edition
Calle	HANG STREET, SHARE SHARE

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401558W. QST Reg. No. M2-0020061-X



FINAL REPORT

Estimate No. : b1 49161

Page No. :

Date Estimated : 19/11/2018

Prepared By : Gary Poh Chai Hoon

REPAIR FOR -

- ACCOUNT -

509

Oh Yi Ming (Hu Yiming)

Sompo Insurance Singapore Pte Ltd

9 Rhu Cross

50 Raffles Place

#06-09

#05-01/06 Singapore Land Tower

Singapore 048623

Singapore 437436

REGN NO	CHASSIS NO.	REGN DATE	MODEL		M LEAG	Œ	
SKS6866Z	EG21246	26/04/2018	X1 sDrive18i		0		
DESCRIPTION	١	500 90000000000000000000000000000000000	ORIGI	NAL PRICE	DISC. %	NETT	
	r bumper and attachm nclude knocking out de			1700.00		1,700.00	
To spray paint	rear bumper and boot	lid		1805.00		1,805.00	
To carry out be (Per panel)	ody cavity preservation	1		100,00		100.00	
To remove and repairs	d install rear windscree	n glass to facilitate		574.00		574.00	
To conduct wa	ater leak tests			75.00		75.00	
# To check elect section for pro	trical wiring system and per function	d lightings at the rear		150.00	new	150.00	un
Sundries				80.00		80.00	
DESCRIPTION	V		UNIT PRICE	QTY	DISC. %	NETT	
REAR BUMPE REAR BUMPE REAR BUMPE EMBLEM GRO BMW PLAQUI LETTERING X # BUMP STOP BOOTLID SEA # EXPANDING F # (DG) CLEANEI	NUT * NDERRIDE PROTECT R PANEL PRIMED R MIDDLE TRIM PAN R TRIM BOTTOM (LI DMMET E WITH ADHESIVE FIL (1 * ALING RIVET *	IEL (PDC) NES) .M	2.55 1,230.50 1.00 102.30 741.55 233.60 222.45 0.80 71.25 64.10 3.35 165.55 1.35 26.15 131.55	4.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1		10.20 1,230.50 2.00 102.30 741.55 233.60 222.45 1.60 71.25 64.10 33.50 165.55 13.50 26.15 263.10	Un un un
# (DG/SL) GLAS	S PRIMER 30ML (VP2	206) *	27.85	1.00		27.85	Uh

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

SUPPLEMENTARY ITEMS

Total Labour :	4,484.00
Total Parts:	3,209.20
Total Labour & Parts :	7,693,20
Deduction for Excess:	0.00
Total Repair Costs less Excess:	7,693.20
GST @7%:	538.52
Grand Total:	8.231.72

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D18MTHCVE000143

Engine No:

Chassis No:

Odometer:

CS/SMO18021673/T1QBN2

Date:

25/01/2019

REFERENCE

Handling Insurer: Claimant Sompo Insurance Singapore Pte.

SKS6866Z

Insured Vehicle

No:

Policy No:

GBC9300K

Vehicle No: Date of Loss:

17/11/2018

Nature of Claim:

TP

Claim No:

CMTD1805070

F317H699B38B15A

3987 km

WBAJG12040EG21246

DESCRIPTION & IDENTIFICATION OF VEHICLE

Rea No:

SKS6866Z

Bronze

1499 cc

Make & Model: Reg. Date:

BMW X1, 1.8 SDRIVE 18L (A)

26/04/2018 (Man. Year: 2018)

Colour:

Engine Capacity:

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

225/50 R18

Bridgestone 6 mm

Rear Tyre Size: Rear Left Side:

Rear Right Side:

225/50 R18

Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,711.30	3,289.20	1,422.10	30.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,004.00	4,404.00	1,600.00	26.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,715.30	7,693.20	3,022.10	28.20
+ GST 7.00/7.00% (S\$)	750.07	538.52	211.55	28.20
Nett Amount (S\$)	11,465.37	8,231.72	3,233.65	28.20

INSPECTION

Date of Assignment:

03/12/2018

Date Inspected:

03/12/2018 Inspected At:

Performance Motors Limited (Bukit

Timah)

896 Dunearn Road #01-01 Sime Darby

Centre

Singapore 489572

Estimated Period of Repair:

6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jan 2019)

Parts: M1-SUV BMW X1 1.8 SDRIVE 18L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKS6866Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recom	mended	Parts
Necom	lilelided	a i aito

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,230.50FS	*1,230.50FS
2	1		*REAR LH BUMPER MOUNT	Not Necessary	160.55 FS	*-FS
3	1		*REAR RH BUMPER MOUNT	Not Necessary	160.55 FS	*-FS
4	1		*RR BUMPER CARRIER	Not Necessary	468.30 FS	*-FS
5	1		*MOUNTING SMART OPENER	Not Necessary	45.30 FS	*-FS
6	1		*REAR TRIM UNDERRIDE PROTECTION XL	Deformed	102.30 FS	*102.30 FS
7	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	141.90 FS	*-FS
8	1		*RR BUMPER RH CORNER MOUNTING	Not Necessary	141.90 FS	*-FS
9	1		*REAR BUMPER PANEL PRIMED	Deformed	741.55 FS	*741.55 FS
10	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Deformed	233.60 FS	*233.60 FS
11	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Not Necessary	233.60 FS	*-FS
12	1		*REAR BUMPER TRIM BOTTOM (LINES)	Deformed	222.45 FS	*222.45 FS
13	2		*EMBLEM GROMMET	Necessary	1.60 FS	
14	1		*BMW PLAQUE WITH ADHESIVE FILM	Necessary	71.25 FS	*71.25 FS
15	1		*LETTERING X1	Necessary	64.10 FS	*64.10 FS
16	1		*BOOTLID SEALING	Necessary	165.55 FS	*165.55 FS
17	4		*BLIND RIVET NUT M6	Necessary	10.20 FS	*10.20 FS
18	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
19	10		*BUMP STOP	Necessary	33.50 FS	*33.50 FS
20	10		*EXPANDING RIVET	Necessary	13.50 FS	
21	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
22	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
23	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	
24	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
F=Fr	anchise	part. S≅Spc	Nett.		-	
				Total Parts (S\$)	4,711.30	3,289.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

	Section # 1		
Recommend	ed	al	OUIT
Necommend	CU	ւսւ	Juui

Particulars	Lab.Type	Repairer's	Amount
ır Items			
TO REPLACE REAR BUMPER, BOOTLID & ATTACHMENT INCLUDE KNOCKING CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
PAINTING REAR BUMPER, BOOTLID	New	2,006.00	1,805.00
TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	32 <u>-</u>
TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	150.00	150.00
Gross Labour Cost (6,004.00	4,404.00
	TO REPLACE REAR BUMPER, BOOTLID & ATTACHMENT INCLUDE KNOCKING CAUSED BY THE ACCIDENT PAINTING REAR BUMPER, BOOTLID TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) TO REPLACE REAR WINDSCREEN GLASS TO CONDUCT WATER LEAK TESTS TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	TO REPLACE REAR BUMPER, BOOTLID & ATTACHMENT INCLUDE KNOCKING CAUSED BY THE ACCIDENT PAINTING REAR BUMPER, BOOTLID New TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) TO REPLACE REAR WINDSCREEN GLASS New TO CONDUCT WATER LEAK TESTS New TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM TO CHECK ELECTRICAL WIRING SYSTEM AND New LIGHTINGS AT THE REAR SECTION FOR PROPER	TO REPLACE REAR BUMPER, BOOTLID & ATTACHMENT New 2,550.00 INCLUDE KNOCKING CAUSED BY THE ACCIDENT PAINTING REAR BUMPER, BOOTLID New 2,006.00 TO CARRY OUT BODY CAVITY PRESERVATION (PER New 118.00 PANEL) TO REPLACE REAR WINDSCREEN GLASS New 574.00 TO CONDUCT WATER LEAK TESTS New 75.00 TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR New 531.00 FILM TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION

< END OF ESTIMATES >