



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 1739C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	565.80	-
1	FRONT BUMPER RETAINER (LH) (CONSISTENT)	NOT NECESSARY	80.40	-
1	FRONT BUMPER RETAINER (RH) (CONSISTENT)	NOT NECESSARY	80.40	65.20
1	FOG LAMP (RH) (CONSISTENT)	NOT NECESSARY	422.50	-
1	HEAD LAMP (RH) (CONSISTENT)	SCRATCHED	1,045.00	1,045.00
1	FRONT FENDER (RH) (CONSISTENT)	BUCKLED	980.00	687.20
1	FRONT FENDER INNER SHIELD (RH) (CONSISTENT)	DEFORMED	214.70	189.60
1	FRONT WHEEL RIM (NPA) (CONSISTENT)	CUT	-	-
1	FRONT ABSORBER (RH) (CONSISTENT)	NOT NECESSARY	520.00	-
1	FRONT ABSORBER TOP MOUNTING (RH) (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT KNUCKLE ARM (RH) (CONSISTENT)	NOT NECESSARY	651.30	-
1	FRONT LOWER ARM (RH) (CONSISTENT)	NOT NECESSARY	640.00	-
1	FRONT LINKAGE (RH) (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT WHEEL RIM CAP (RH) (CONSISTENT)	NOT NECESSARY	-	-
1	FRONT KNUCKLE BEATING (RH) (CONSISTENT)	NOT NECESSARY	599.10	-
	LESS 25% DISCOUNT		-	-496.75
			5,799.20	1,490.25
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	45.00	30.00
1	FRONT FENDER INNER SHIELD CLIP SET (RH) (SN) (CONSISTENT)	NECESSARY	45.00	30.00
1	FRONT TYRE (RH) (SN) (CONSISTENT)	NOT NECESSARY	220.00	-
			310.00	60.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING & LIGHTING SYSTEM.		60.00	30.00
	TO FOCUS HEAD LAMP ASSY .	NOT NECESSARY	50.00	-
	TO APPLY UNDERCARRIAGE ON AFFECTED AREAS.		60.00	40.00
	TO R&R FRONT WHEEL RIM ,TYRE AND BALANCING .		60.00	30.00
	TO CONDUCT WHEEL ALIGNMENT BEFORE AND AFTER.		150.00	60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO R&R FRONT UNDERCARRIAGE DAMAGE PARTS.	NOT NECESSARY	300.00	-
	TO REPAIR ,REPLACE & REALIGN DAMAGE AREAS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER .		1,000.00	400.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		800.00	400.00
			2,480.00	960.00
GRAND TOTAL			8,589.20	2,510.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CC4/ASM18021684/Gea3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.