

Charn's Customcraft  
1010 Bukit Merah Lane 3  
Singapore 159724

Claim Reference: THIRD PARTY CLAIM  
Assessment Number: CC000029  
Version: CHARNCUS/1  
Date Calculated: 29/11/2018 08:03

Full Report - V1  
Registration: SKZ8670X  
Printed: 29/11/2018 16:03

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Sharon Lee	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	THIRD PARTY CLAIM	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	BMW
Model:	4 Series
Sub Model:	420I
Model Sheet Number:	143 01
Registration:	SKZ8670X
Registration Month:	
Registration Year:	
VIN Number:	WBA3V12050P945211
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

#### Model Specs

FROM 03/2016	COMFORT PACKAGE
AUTO AIR CON	LED HEADLAMP
2.0 LTR 135KW	ACTIVE PROTECTION
WHEELS 8J X 18 ALLOY	EU SPECIFIC
TWO COAT METALLIC	PREPARE OFF VEHICLE

Taufik 9749 5749  
-wp-  
3/12/18 430pm  
Resurvey after repair  
4 days

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	29/11/2018
Pre-Accident Damage:	

#### Tyres Condition:

Tread Depth LHF:

Tread Depth LHR:

Tread Depth RHF:

Tread Depth RHR:

Direction of Impact:

Damage Areas:

**LKK Auto Consultants** hence notify the Repairer of the following:



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Audatex System Using Manufacturer Times

**Addresses****Cost Summary**

Total Labour	\$611.25
Total Paint/Material	\$149.10
Excess:	TBA
Grand Total Exc GST:	\$760.35
7 % GST:	\$53.22
Grand Total Inc GST:	\$813.57

**Repair Information****LABOUR**

Time Basis 12 WU = 1 HR. Price/CL 1 = \$45.00/HR  
Price/Dent = \$45.00/HR

**Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	ADD/TIME FOR MAIN WORK	1.0	3.75
32 00 590	ELECTR SUSPENSION ALIGNMENT (WITHOUT ADJUSTMENT BEFORE REP)	16.0	60.00
1482	REPAIR RIGHT FRONT DOOR	10.0*	37.50
2172	REPAIR R/SILL PANELLING	5.0*	18.75
3482	REPAIR R/R SIDE PANEL	5.0*	18.75

**LABOUR COST**

Total Work Units	37.0	
Panel / Mechanical Labour	1.7HRS	\$75.00
Visual Alignment Labour	1.4HRS	\$63.75
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	3.1HRS	\$138.75
Paint Labour	10.5HRS	\$472.50
Total Labour	13.6HRS	\$611.25

\*NOTE TIME BASIS = 12 WU / HOUR\*

**PAINT WORK**

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- EU SPECIFIC		
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	27.0	
3482	R/R SIDE PANEL REPAIR PAINTING >50%	30.0	
9552	R/R WHEEL REPAIR PAINTING >50%	12.0	
2172	R/SILL PANELLING SURFACE PAINT PLAST.	6.0	

**LABOUR COST - PAINT**

TIME(PAINT)	75.0
Preparation Main Work Plastic	5.0

# Charn's Customcraft

Claim Reference: THIRD PARTY CLAIM  
 Assessment Number: CC000029  
 Version: CHARNCUS/1  
 Date Calculated: 29/11/2018 08:03

Full Report - V1  
 Registration: SKZ8670X  
 Printed: 29/11/2018 16:03

Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	105.0	
Total Paintwork Labour	10.5HRS	\$472.50
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
Surface Paint Plastic		\$18.67
Repair Painting		\$92.83
Material-Const Main Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$149.10
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$149.10

## PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/05/2018	Bet.	Price (\$)
f:		OEM Parts					
g:		Original					
h:		Secondhand					
p:		Parallel					
x:		Exchange					
			Sub Total				\$0.00
			Mark Up From Cost	(15 %)			\$0.00
			<b>Total Parts</b>				<b>\$0.00</b>

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Total Extras** \$0.00

## Final Calculation

<b>Total Parts</b>	\$0.00
<b>Labour</b>	
Total Panel/Mechanical	\$75.00
Total Paintwork	\$472.50
Total Visual Alignment work	\$63.75
<b>Total Labour</b>	<b>\$611.25</b>
<b>Total Paint/Material Costs</b>	<b>\$149.10</b>
<b>Grand Total Excludes GST</b>	<b>\$760.35</b>
GST @ 7 %	\$53.22
<b>Grand Total Includes GST</b>	<b>\$813.57</b>

## Assessment Notes