

ASS. BY:

REF: CS/FCL18021726/KH02

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): WS Serene Lee of FCL Date/Time: 03-12-2018 5:30pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDJ 8130E Insured: SHA 219Lat Workshop m/s Wei Lee Tel: 6456 9830of Bk 9 Sin Ming Ind Est #01-32Policy No: _____ Claim No: D18008541MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7-11-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 03 04-12-2018 H.O.D. Endorsement: _____Date/Time: 03-12-2018 5:43pm Person Contacted: Karen Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
<u>03-12-2018</u>	<u>Estimate not yet done</u>
	<u>SDJ 8130E X</u>
	<u>SHA 219L - CS/FCL17004629/6XX</u>
	<u>DCA: 10/09/2016</u>
	<u>lump sum \$6150/- (Red: 5576.40, 47%)</u>

REF: FCI

ASSIGNMENT

From: Date: 1/12/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SDJ 8130 E
at Workshop n/s Wei ke
of BLK 9 Sin Ming Ind. Est #01-32

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: S 61k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS cup

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SDJ 8130 E Yr Regn: 11 / 16

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 2 C.C. 1496

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 28417 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM 60 J2H4A 01100929

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 29/11/18 D.O.I. 4/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/12 File pass to Carline

RECEIVED 17 JAN 2019

Date/Time: File Pass to?

1) P/I Typist
Date/Time: File return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 6150)

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Survey Fee:

Transportation

) \$ + R5, \$

) Photos

) Others

TOTAL

170+15
50
50+50
28
363

MOTOR SURVEY ASSIGNMENT

Date	03-12-2018	Our Ref No. D18008541MFSH
Accident Date	29-11-2018	Claim Type. Third Party
Insured Vehicle	SHA2919L	Third Party Vehicle. SDJ8130E
Survey Location	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32	
Contact Person.	KAREN SEAH	
Contact No.	64569830/ 0	Fax No. 64580128
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEI LEE MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

03, Nov 2018

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House S 068877

Attn: Motor claim-3rd party

Claiming against your insured vehicle no: SHA2919L

Accident involving vehicle no: SDJ8130E/SHA2919L

DOA: 29/11/2018 AT Hindhede walk outside Southaven 11 Condo

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SDJ8130E

To supply—

Description	Qty	Amount	
Lid	1	911.00	✓
Lid-Mazda logo	1	58.50	✓
Lid-Mazda 2 emblem	1	55.00	✓
Lid reflector,Rh	1	221.00	X
Lid lock	1	202.00	X
Taillamp	1	728.00	X
Rear bumper	1	850.00	✓
Rear bumper retainer	1	24.00	✓
Rear fender,Rh	1	909.00	✓
Fender cowl	1	206.00	✓
End panel	1	380.00	✓
Spare tyre panel	1	836.00	X
Rear cross member	1	2,450.00	✓
Rear wheel bearing hub	1	559.00	X
Rear absorber	1	267.00	X
Exhaust tailpipe	1	1,053.00	X
Air duct	1	46.00	✓
Sport rim	1	260.00	X
Tyre	1	180.00	✓
Parts		10,195.50	
Parts less 20%		2,039.10	
		8,156.40	

photo attached

Not authorized
Resunny B4 paint
11/11/18 @ 6150h 10 days
Part 5 5887-5
1177-90
2711-60
3000
7721-60
29-11-18
1544-00
6176-00
451

Tow fee

(B41) 150.00 50L

Sum 220.00 Zwaan

160.00 1201

180.00 100

1000000

..... 110

1,300.00	1100
1,300.00	100

280.00 260

200.00	278
80.00	621

726.40

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

Not Authorized
Person B4 paint
10 days

03, Nov 2018

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House S 068877

Attn: Motor claim-3rd party

Claiming against your insured vehicle no: SHA2919L

Accident involving vehicle no: SDJ8130E/SHA2919L

DOA: 29/11/2018 AT Hindhede walk outside Southaven 11 Condo

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SDJ8130E

To supply—

Description	Qty	Amount	
Lid	1	<i>B</i> 911.00	✓
Lid-Mazda logo	1	<i>in</i> 58.50	✓
Lid-Mazda 2 emblem	1	<i>in</i> 55.00	✓
Lid reflector,Rh	1	<i>in</i> 221.00	X
Lid lock	1	<i>in</i> 202.00	X
Taillamp	1	728.00	?
Rear bumper	1	<i>B</i> 850.00	✓
Rear bumper retainer	1	<i>D/S</i> 24.00	✓
Rear fender,Rh	1	<i>B</i> 909.00	✓
Fender cowlng	1	<i>CM</i> 206.00	✓
End panel	1	<i>B</i> 380.00	✓
Spare tyre panel	1	<i>in</i> 836.00	X
Rear cross member	1	2,450.00	?
Rear wheel bearing hub	1	559.00	?
Rear absorber	1	267.00	?
Exhaust tailpipe	1	1,053.00	?
Air duct	1	<i>Ad</i> 46.00	✓
Sport rim	1	260.00	?
Tyre	1	<i>Pr</i> 180.00	<i>John</i>
	Parts	10,195.50	
	Parts less 20%	2,039.10	
		8,156.40	

Vehicle No: SDJ8130E

Tow fee	(Bill)	150.00	7
Reverse sensor	Sum	220.00	2000
To remove/replace rear windscreen glass		160.00	1200
To remove/reinstall rear fender inner garnish, rear seater cushion, rear speaker		180.00	1000
Board enable repair job carryout.			
To remove damaged parts and attachments			
Cut n weld damaged fender, panel.			
Repair/reshape dented/damaged areas.			
Replace/align all parts into position.		1,300.00	11000
To spray paint		1,200.00	10000
To remove/replace rear member, absorber n wheel hub.		280.00	7
Redo wheel alignment.		80.00	600
		11,726.40	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021726/Ktbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2919L	Veh. Inspected	SDJ 8130E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008541MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	03/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 2 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6DJ2HAA01100929	Colour	METALLIC BLUE	
Odometer	28417	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R16	TOYO	8 mm	
L/H Front Tyre	185/60 R16	TOYO	8 mm	
R/H Rear Tyre	185/60 R16	TOYO	8 mm	
L/H Rear Tyre	185/60 R16	TOYO	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2018	Inspection Date	04/12/2018	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDJ 8130E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LID	BENT	911.00	911.00
1	LID-MAZDA LOGO	NECESSARY	58.50	58.50
1	LID-MAZDA 2 EMBLEM	NECESSARY	55.00	55.00
1	LID REFLECTOR,RH	SERVICEABLE	221.00	-
1	LID LOCK	TO REPAIR SEE LABOUR	202.00	-
1	TAILLAMP	SERVICEABLE	728.00	-
1	REAR BUMPER	BENT	850.00	850.00
1	REAR BUMPER RETAINER	DISTORTED	24.00	24.00
1	REAR FENDER,RH	BUCKLED	909.00	909.00
1	FENDER COWLING	CRACKED	206.00	206.00
1	END PANEL	BENT	380.00	380.00
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	836.00	-
1	REAR CROSS MEMBER	BENT	2,450.00	2,450.00
1	REAR WHEEL BEARING HUB	SERVICEABLE	559.00	-
1	REAR ABSORBER	SERVICEABLE	267.00	-
1	EXHAUST TAILPIPE	TO REPAIR SEE LABOUR	1,053.00	-
1	AIR DUCT	DENTED	46.00	46.00
1	SPORT RIM	SERVICEABLE	260.00	-
	LESS 20% DISCOUNT		-2,003.10	-1,177.90
			8,012.40	4,711.60
1	TYRE (80%)(SN)	PUNCTURE	180.00	144.00
	LESS 20% DISCOUNT		-36.00	-
			144.00	144.00
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	SCRATCHED	220.00	200.00
			220.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOW FEE.		150.00	50.00
	TO REMOVE/REPLACE REAR WINDSCREEN GLASS.		160.00	120.00
	TO REMOVE/REINSTALL REAR FENDER INNER GARNISH,REAR SEATER CUSHION,REAR SPEAKER BOARD ENABLE REPAIR JOB CARRYOUT.		180.00	100.00
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.CUT N WELD DAMAGED FENDER,PANEL,REPAIR/RESHAPE DENTED/DAMAGED AREAS.REPLACE/ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF LID LOCK,SPARE TYRE PANEL AND EXHAUST TAILPIPE.		1,300.00	1,100.00
	TO SPRAY PAINT.		1,200.00	1,000.00
	TO REMOVE/REPLACE REAR MEMBER,ABSORBER N WHEEL HUB.		280.00	240.00
	REDO WHEEL ALIGNMENT.		80.00	60.00
			3,350.00	2,670.00
	GRAND TOTAL		11,726.40	7,725.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,150.00

Report Ref No. CS/FCI18021726/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.