

ASS. REC. BY:

REF

CS3/lpc18019711/4-03-17

Special Instructions:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Ong Li

of

lpc

Date/Time: 04/12/2018, ...

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGD 3507G

Insured:

SJW 5372D

at Workshop m/s:

Team Auto pro

Tel:

90927

of

8/celei Bulat Ave 4 # 06-21 Premier

Policy No:

Claim No:

18/18/18/vpos/021072

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/10/18

CA / REV / REP. / REV 24 HRS (up)

Date/Time: 10-55am 30/10/18

Person Contacted:

Andy

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

SGD 3507G - X

SJW 5372D - CR4/lpc17006096/kda 3q2

DOA: 23/03/17

14/11/18

Submit PRS report

5/12/18

Submit L/S 3800 7dy (Red: 3800 150%)

G112- File pass to typist

DATE:

REF:

LP 2/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2 yrs. Enli. LTA 12423 SGH6824

RECEIVED 15 NOV 2010

Date/Time, File Pass to?

1) Input
Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

: Photos

: Others

TOTAL

450

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 4 December 2018 11:35 AM
To: Admin-D (LKKAuto); assignments
Cc: MT_Claim_SG; SUR
Subject: RE: Our Ref: MKR/404/8347/2018/as.wl; Your Ref: Your insured vehicle no. SJW 5372D; Our Ref :18/18/18/VP05/021072
Attachments: 21072 TP SURVEY REPORT.pdf

Hi Catherine/Nivitha

Attached is the TP survey report. Please let us have your surveyor's review and report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 30 October, 2018 10:57 AM
To: GERALD POH WEE BIN; assignments
Cc: MT_Claim_SG; SUR
Subject: RE: Our Ref: MKR/404/8347/2018/as.wl; Your Ref: Your insured vehicle no. SJW 5372D;

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Monday, 29 October 2018 4:34 PM
To: William Lee <william@roypartners.com.sg>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: RE: Our Ref: MKR/404/8347/2018/as.wl; Your Ref: Your insured vehicle no. SJW 5372D;

WITHOUT PREJUDICE

Dear William,

We are not agreeable to your list of Single Joint Experts and shall appoint LKK Auto Consultants Pte Ltd for the pre-repair survey

Aside to LKK – Attn : Catherine/Nivitha
Kindly proceed accordingly

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: William Lee [<mailto:william@roypartners.com.sg>]

Sent: Monday, 29 October, 2018 4:24 PM

To: GERALD POH WEE BIN

Cc: MT_Claim_SG; 'TeamAutoPro North'; 'Ashley'; 'Roy'

Subject: RE: Our Ref: MKR/404/8347/2018/as.wl; Your Ref: Your insured vehicle no. SJW 5372D;

Importance: High

Dear Sirs,

We refer to your email below.

Our client reject your list of proposed motor surveyors and propose Mr Dave from Sincere Appraisal as the Single Joint Expert.

Pursuant to the new NIMA protocol, kindly let us know within **2 working days** of receipt of our letter whether you agree or has any objections to the motor surveyor proposed by our client, failing which you are deemed to have agreed to the appointment of any of the motor surveyors proposed by our client.

Thanks & regards,

William Lee

M/s Roy & Partners

101 Cecil Street

#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : william@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

Sent: Monday, 29 October, 2018 2:37 PM

To: William Lee <william@roypartners.com.sg>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: Our Ref: MKR/404/8347/2018/as.wl; Your Ref: Your insured vehicle no. SJW 5372D;

WITHOUT PREJUDICE

Our Ref :18/18/18/VP05/021072

Dear William,

Please see attached and revert to us.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: William Lee [<mailto:william@roypartners.com.sg>]
Sent: Monday, 29 October, 2018 12:25 PM
To: MT_Claim_SG
Cc: 'TeamAutoPro North'
Subject: Our Ref: MKR/404/8347/2018/as.wl; Your Ref: Your insured vehicle no. SJW 5372D;
Importance: High

Our Ref: MKR/404/8347/2018/as.wl;
Your Ref: Your insured vehicle no. SJW 5372D;

Dear Sirs,

Attn: Motor claims department

CLAIMANT: CHEN YINWEN (OWNER OF SGD 3507G)
ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NO. SGD 3507G AND SJW 5372D ALONG TAMPINS AVE 10
BEFORE ENTRANCE OF TPE ON 28.10.2018 AT ABOUT 1745 HOURS.

We refer to the above matter.

We act for Chen Yinwen, the owner of motor car No. **SGD 3507G**.


We are instructed by our client to notify you of a road traffic accident on 28.10.2018 at about 5.45 pm along Tampines Ave 10 before entrance of TPE involving our client's motor car registration number **SGD 3507G** and motor car registration number **SJW 5372D** driven by your insured at the material time. A copy of the Singapore Accident Statement is attached.

As a result of the accident, our client's motor car **SGD 3507G** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SGD 3507D** at our client's repairer workshop, M/s Team AutoPro Pte Ltd at No. 8 Kaki Bukit Avenue 4 #06-21 Premier @ Kaki Bukit Singapore 415875, Your said surveyor may contact Mr. Alan Koh/Frederick Lim at 9092 7279/9674 6635. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

Thanks & regards,

William Lee
M/s Roy & Partners
101 Cecil Street
#11-09 Tong Eng Building
Singapore 069533
Tel : 6536 8466 Fax : 6536 1963
Email : william@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

VEHICLE INSPECTION REPORT

To : Chen Yin Wen

Our ref. : UAM18.10.34-AK-STP-TAP-SGD3507G

Date : 12 Nov 2018

REFERENCE

Assign by	: Chen Yin Wen	Insured	: To be advice
Assign on	: 29 Oct 2018	Policy no.	: To be advice
Inspection on	: 29 Oct 2018	Claim no.	: To be advice
Accident on	: 28 Oct 2018	Sum insured	: To be advice
Workshop name	: Team AutoPro Pte Ltd	Excess	: Not applicable
Inspection at	: 385 Sin Ming Drive	3rd party Veh.	: To be advice
	#01-02 Vicom Inspection Centre	3rd party ins.	: To be advice
	Singapore 575718		

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SGD3507G	Odometer	: 147167 km
Make / Model	: Toyota Vios 1.5E A	Chassis no.	: MR053HY4204170354
Regn. date	: 20 Feb 2006	Engine no.	: 1NZX364139
Body colour	: Red	Engine cap.	: 1497 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Good
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good

TYRE CONDITION ON VEHICLE


	Make	Size	Tread depth	Type of road wheel
Front N/S	: Yokohama	195/65R14	70%	Alloy
Front O/S	: Yokohama	195/65R14	70%	Alloy
Rear N/S	: Yokohama	195/65R14	70%	Alloy
Rear O/S	: Yokohama	195/65R14	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

* Denotes damaged component/s

POINT OF IMPACT

On the rear in the direction from rear to front.

**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

The impact of the collision has damaged / affected the bootlid, taillamp, rear bumper, rear end panel, spare tyre panel, rear fender, exhaust pipe and etc...

Please refer to Annex A (Appraisal Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 30 Oct 2018 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Team AutoPro Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 7,650.00 to carry out the repairs. Please refer to Annex A (Appraisal Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately 7 (Seven) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,

United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Registration no. : SGD3507G

Our reference : UAM18.10.34-AK-STP-TAP-SGD3507G

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
-----	-----	-------------	---------------------	-----------------------	------------------

LIST ITEMS

1	1	Bootlid	Dented	768.30	768.30
2	1	Bootlid logo	Necessary	81.20	81.20
3	1	Bootlid emblem " VIOS "	Necessary	92.30	92.30
4	1	Bootlid emblem " VVT-I "	Necessary	98.30	98.30
5	1	Bootlid emblem " 1.5 "	Necessary	58.30	58.30
6	1	Bootlid emblem " E "	Necessary	68.40	68.40
7	1	Bootlid outer moulding	Refer To Labour	212.30	0.00
8	1	Bootlid weatherstrip	Necessary	202.30	202.30
9	2	Bootlid hinge @ SGD 69.10	Re-used	138.20	0.00
10	1	Bootlid lock	Distorted	248.30	248.30
11	2	Rear number plate lamp @ SGD 41.70	Re-used	83.40	0.00
12	1	Rear bumper	Deformed	696.50	696.50
13	1set	Rear bumper clip	Necessary	50.00	50.00
14	2	Rear bumper side retainer @ SGD 168.20	Distorted	336.40	336.40
15	1	Rear end panel	Dented	688.50	688.50
16	1	Rear end panel top garnish	Deformed	196.50	196.50
17	1set	Rear end panel top garnish clip	Necessary	30.00	30.00
18	2	Taillamp @ SGD 397.50	Cracked	795.00	795.00
19	2set	Taillamp clip @ SGD 25.00	Necessary	50.00	50.00
20	2	Taillamp base panel @ SGD 251.30	Buckled	502.60	502.60
21	2	Rear fender @ SGD 662.40	To Repair	0.00	0.00
22	2	Rear fender inner shield @ SGD 134.10	Torn	268.20	268.20
23	2set	Rear fender inner shield clip @ SGD 20.00	Necessary	40.00	40.00
24	2	Rear fender inner trim @ SGD 210.80	Torn	421.60	421.60
25	2set	Rear fender inner trim clip @ SGD 30.00	Necessary	60.00	60.00
26	1	Exhaust pipe	Bend	682.00	682.00
27	1	Spare tyre panel	Buckled	841.10	841.10
28	1	Spare tyre panel top board centre	Damaged	185.50	185.50
29	2	Spare tyre panel top board side @ SGD 117.80	O/S Damaged	235.60	117.80
				8130.80	7579.10

Less	0% / 25%	0.00	1894.78
		8130.80	5684.33

SPECIAL NETT ITEMS

1	1	Sundries	Necessary	50.00	30.00
2	2	Taillamp seal @ SGD 50.00	Necessary	100.00	90.00
3	1	Bootlid sealant	Necessary	80.00	60.00
4	1	Rear end panel sealant	Necessary	80.00	60.00
5	1	Reverse sensor c/w control module	Shorted	300.00	280.00
				610.00	520.00
TOTAL				8740.80	6204.33

APPRAISEMENT SCHEDULE

Registration no. : SGD3507G

Our reference : UAM18.10.34-AK-STP-TAP-SGD3507G

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Part Balance C/F	8740.80	6204.33
<u>LABOUR & MISC CHARGES</u>					
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.		1600.00	1400.00 800
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	60.00 30
3		To remove and refit interior upholstery to facilitate the repair.		200.00	180.00 80
4		To remove and refit bootlid component to replace bootlid, check and re-adjust the close gap and alignment and water seepage.		100.00	80.00 60
5		To remove and refit, straighten and readjust exhaust pipe.	^^	180.00	150.00 X
6		To measure, drill holes on replaced rear bumper, position and install reverse sensor, check and test on the distance and functions.		80.00	60.00 50
7		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	180.00 60
8		Supply spray paint material and necessary items to respray bootlid, rear bumper, rear end panel, taillamp base panel, rear fender, spare tyre panel and other affected area / panel.		1500.00	1250.00 1000
TOTAL				3940.00	3360.00
				14005.60	
Total Parts and Labour Cost of Repair				12680.80	9564.33
Less (Lumpsum repair adjustment)					1914.33
Adjustment Parts and Labour Cost of Repair					7650.00




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC18019711/Utd3n2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Date : 11-12-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJW 5372D	Veh. Inspected	SGD 3507G	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/021072	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	04/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053HY4204170354	Colour	RED	
Odometer	147167	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R14	BRIDGESTONE	6 mm	
L/H Front Tyre	185/65 R14	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/65 R14	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/65 R14	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/10/2018	Inspection Date	30/10/2018	
Survey held at	TEAM AUTOPRO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 3507G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	DENTED	768.30	480.90
1	BOOTLID LOGO	NECESSARY	81.20	81.20
1	BOOTLID EMBLEM "VIOS"	NECESSARY	92.30	92.30
1	BOOTLID EMBLEM "VVT-I"	NECESSARY	98.30	98.30
1	BOOTLID EMBLEM "1.5"	NECESSARY	58.30	58.30
1	BOOTLID EMBLEM "E"	NECESSARY	68.40	68.40
1	BOOTLID OUTER MOULDING	NOT NECESSARY	212.30	-
1	BOOTLID WEATHERSTRIP	TWISTED	202.30	75.90
2	BOOTLID HINGE @\$69.10	NOT NECESSARY	138.20	-
1	BOOTLID LOCK	TWISTED	248.30	109.10
2	REAR NUMBER PLATE LAMP @\$41.70	NOT NECESSARY	83.40	-
1	REAR BUMPER	DISTORTED	696.50	361.90
1	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINER @\$168.20	BENT	336.40	92.00
1	REAR END PANEL	DENTED	688.50	688.50
1	REAR END PANEL TOP GARNISH	TWISTED	196.50	196.50
1	SET REAR END PANEL TOP GARNISH CLIP	NOT NECESSARY	30.00	-
2	TAILLAMP @\$397.50	CRACKED	795.00	795.00
2	SET TAILLAMP CLIP @\$25.00	NOT NECESSARY	50.00	-
2	TAILLAMP BASE PANEL @\$251.30	TO REPAIR SEE LABOUR	502.60	-
2	REAR FENDER @\$662.40	TO REPAIR SEE LABOUR	1,324.80	-
2	REAR FENDER INNER SHIELD @\$134.10	NOT NECESSARY	268.20	-
2	SET REAR FENDER INNER SHIELD CLIP @\$20.00	NOT NECESSARY	40.00	-
2	REAR FENDER INNER TRIM @\$210.80	NOT NECESSARY	421.60	-
2	SET REAR FENDER INNER TRIM CLIP @\$30.00	NOT NECESSARY	60.00	-
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	682.00	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	841.10	-
1	SPARE TYRE PANEL TOP BOARD CENTRE	NOT CHANGED	185.50	-

Report Ref No. CS3/LPC18019711/Utd3n2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SPARE TYRE PANEL TOP BOARD SIDE @\$117.80	NOT CHANGED	235.60	-
	LESS 25% DISCOUNT		-	-812.08
			9,455.60	2,436.22
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
2	TAILLAMP SEAL @\$50.00 (SN)	NOT NECESSARY	100.00	-
1	BOOTLID SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	50.00
1	REVERSE SENSOR C/W CONTROL MODULE (SN)	SHORTED	300.00	200.00
			610.00	290.00
	LABOUR			
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP BASE PANEL,REAR FENDER,EXHAUST PIPE AND SPARE TYRE PANEL.		1,600.00	800.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS.		80.00	30.00
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR.		200.00	80.00
	TO REMOVE AND REFIT BOOTLID COMPONENT TO REPLACE BOOTLID,CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.		100.00	60.00
	TO REMOVE AND REFIT,STRAIGHTEN AND READJUST EXHAUST PIPE.	NOT NECESSARY	180.00	-
	TO MEASURE,DRILL HOLES ON REPLACED REAR BUMPER,POSITION AND INSTALL REVERSE SENSOR,CHECK AND TEST ON THE DISTANCE AND FUNCTIONS.		80.00	50.00
	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION.		200.00	60.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY BOOTLID,REAR BUMPER,REAR END PANEL,TAILLAMP BASE PANEL,REAR FENDRE,SPARE TYRE PANEL AND OTHER AFFECTED AREA/PANEL.		1,500.00	1,000.00
			3,940.00	2,080.00



GRAND TOTAL		14,005.60	4,806.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CS3/LPC18019711/Utd3n2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.