

15/2/2019

INS. CASE OWNER:

Boon Shen

CC 6 / CTI1802

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

Date / Time:

11/12/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBE 8904P

Name of Insured:

BMW STAR MFG GROUP PTE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

20/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: CHAN TENG KAR 46yrs

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SMM1820560308

Policy No.:

OMLVEN309551600

Make / Model:

T-UPON

Place of Accident:

WOO EAVES AVE 12 THRS SLE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SUJ 69667

GBE 8904P

GBF1895

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

8/1/19
PK14/1/2019
PIL

21/8/19 - file pass type mandate report

2/12/19 - FILE PASS TO USP TO CLOSE

GBF1895
GBE 8904P 5 (11/18/2018) 13044-24/11/18spoke to PIC, confirmed involve in 3 car chain collision
informed TP claim and explain MFG, they agree to settle
and advise MFG will be withheld for the time being

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 14/1/2019

After call ltr to OI: 14/1/2019

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

26/2/2019

Sent By:

CPK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

78

If NO or B 28, Ass. Lia:

6%

Repair Cost:

S\$

8600.00

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

880.00

(S 80 x 11 days)

Loss of Income (LOI):

S\$

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/Independent)

Legal Cost

S\$

Total:

S\$

9480.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

9480.00

Name 1:

M Garage (East) Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

05/11/18

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of:

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

* Vehicle: IN / OUT

Date: Person Contacted:

Veh No: G13F189J. Yr Regn. 2016 June.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NU200 cc 1461

Colour: Silver. A/C: Insured / Std / NI / NA

Sp. Reading: 52459. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VSKYBAM2020126170.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70 R14C

R: 175/70 R14C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 03/12/18

Survey held at M Garage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chkn.

L/S: \$ 3,600.00 (Red) \$ 9,394.22 / 52.21 %

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18021791/Afb3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 04-12-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 8904P	Veh. Inspected	GBF 189J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/12/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/11/2018	Inspection Date	03/12/2018
Survey held at	MGARAGE (EAST) PTE LTD 23 KAKI BUKIT CENTRE AAS KAKI BUKIT CENTRE #04-01 SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MGARAGE (EAST) PTE LTD

23 Kaki Bukit Avenue 4 AAS Kaki Bukit Centre #04-01 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 200913013D

TO	: CHINA TAIPING	DATE	: 03/12/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: gbf189j	Poh Kim	
MODEL	: NISSAN NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 29-Nov-18
		TIME	: 13:10HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR LH <i>Defect</i>	1	\$ 1,850.00	\$ 1,850.00 ✓ 1545
2	REAR DOOR LOGO <i>new</i>	1	\$ 75.30	\$ 75.30 ✓
3	REAR DOOR EMBLEM 'NV200' <i>new</i>	1	\$ 87.00	\$ 87.00 ✓
4	REAR DOOR HINGE <i>new</i>	2	\$ 103.00	\$ 206.00 +
5	REAR DOOR CHECKER <i>new</i>	1	\$ 99.20	\$ 99.20 x
6	REAR DOOR UPPER LOCK <i>3rd</i>	1	\$ 142.00	\$ 142.00 ✓
7	REAR DOOR LOWER LOCK	1	\$ 142.00	\$ 142.00 ✓
8	REAR DOOR GLASS WITH MOULDING LH <i>new</i>	1	\$ 818.40	\$ 818.40 80
9	REAR DOOR RH <i>Disturbed</i>	1	\$ 1,850.00	\$ 1,850.00 1285
10	REAR DOOR EMBLEM 'DCI' <i>new</i>	1	\$ 92.10	\$ 92.10 ✓
11	REAR DOOR HINGE <i>3rd</i>	2	\$ 103.00	\$ 206.00 +
12	REAR DOOR CHECKER <i>1st</i>	2	\$ 99.20	\$ 198.40 +
13	REAR DOOR UPPER LOCK <i>3rd</i>	1	\$ 155.20	\$ 155.20 ✓
14	REAR DOOR LOWER LOCK <i>1st</i>	1	\$ 155.20	\$ 155.20 ✓
15	REAR DOOR GLASS WITH MOULDING RH <i>new</i>	1	\$ 920.70	\$ 920.70 80
16	REAR DOOR GLASS STRIPE <i>1st</i>	1	\$ 230.00	\$ 230.00 ✓
17	REAR DOOR NUMBER PLATE LAMP GARNISH <i>2nd</i>	1	\$ 380.00	\$ 380.00 ✓
18	REAR DOOR NUMBER PLATE LAMP (SET) <i>1st</i>	1	\$ 144.20	\$ 144.20 x

19	REAR DOOR WEATHERSTRIP <i>lt</i>	1	\$ 133.20	\$ 133.20	✓
20	REAR DOOR WIPER ARM <i>lt</i>	1	\$ 72.10	\$ 72.10	✓
21	REAR DOOR WIPER ARM COVER <i>missing</i>	1	\$ 52.90	\$ 52.90	✓
22	REAR DOOR WIPER MOTOR <i>Damaged</i>	1	\$ 355.20	\$ 355.20	✓
23	3RD BRAKE LIGHT <i>could</i>	1	\$ 355.20	\$ 355.20	✓ 185
24	REAR BUMPER <i>Rehnd</i>	1	\$ 688.20	\$ 688.20	✓
25	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 52.90	\$ 105.80	✓
26	REAR BUMPER REFLECTOR <i>RH missing, Hould</i>	2	\$ 80.20	\$ 160.40	✓
27	REAR BUMPER SPONGE <i>could</i>	1	\$ 103.00	\$ 103.00	✓
28	REAR BUMPER TOWINF COVER <i>new</i>	1	\$ 55.20	\$ 55.20	✓
29	TAILLAMP <i>Lt could</i>	2	\$ 288.50	\$ 577.00	✓ 288.50
30	TAILLAMP PANEL <i>Rejis</i>	2	\$ 155.60	\$ 311.20	✓
31	REAR END PANEL <i>Dented</i>	1	\$ 552.20	\$ 552.20	✓
32	REAR END PANEL TOP GARNISH <i>Rehnd</i>	1	\$ 120.00	\$ 120.00	✓
33	REAR FLOOR PANEL <i>Rejis</i>	1	\$ 1,550.00	\$ 1,550.00	✓
34	REAR FLOOR PANEL TOP MAT <i>torn</i>	1	\$ 922.50	\$ 922.50	✓ 450(SN)

72653

653877

SN: 450

TOTAL PRICE \$ 13,865.80
 LESS 10% \$ 1,386.58
 SUB TOTAL PRICE \$ 12,479.22

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER PLATE <i>Rehnd</i>	1	\$ 50.00	\$ 50.00	✓
2	REAR DOOR STICKER '70km/h' LH <i>new</i>	1	\$ 40.00	\$ 40.00	✓ 10
3	REAR DOOR NUMBER PLATE LAMP GARNISH CLIP <i>new</i>	1	\$ 20.00	\$ 20.00	✓ 10
4	REAR DOOR GLASS SEALANT <i>new</i>	2	\$ 100.00	\$ 200.00	✓ 20
5	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 25.00	\$ 25.00	✓
6	TAIL LAMP PANEL SEALANT <i>Rejis new</i>	2	\$ 80.00	\$ 160.00	✓
7	REAR END PANEL TOP GARNISH CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓ 10
8	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	✓ 60
9	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	✓
10	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	✓ 200
11	REVERSE CAMERA <i>Damaged</i>	1	\$ 220.00	\$ 220.00	✓

635

TOTAL \$ 1,255.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
-----	-----------------	-------	---------------	----------

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,000.00	1450	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	1200	
3	Tuff Coat	\$ 250.00	60	
4	WIRING CHECK	\$ 80.00	30	
5	TO REMOVE AND REFIX REAR DOOR MECHANISM (2 DOORS)	\$ 320.00	160	
6	REMOVE & REINSTALL REAR DOOR WINDOW GLASS	\$ 160.00	120	
7	TO REMOVE AND REFIX REVERSE SENSOR	\$ 100.00	50	
8	TO REMOVE AND REFIX REVERSE CAMERA	\$ 150.00	50	

TOTAL

\$4,260.00

3120

TOTAL PARTS COST : \$ 13,734.22
TOTAL LABOUR COST : \$ 4,260.00
TOTAL REPAIR COST : \$ 17,994.22

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian King.

h/s 10 Days

03/12/18.

total: 10743.77

h/s: 86K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

86K

Shu Pei (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 3 January 2019 12:57 PM
To: Shu Pei (LKKAUTO)
Cc: Poh Kin (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBE8904P (OI : CTI - TBA) and GBF189J (TP : LKK REF -CC6/CTI18021791/Afb3) on 29.11.2018 / our ref: SNM18D05603C02
Attachments: insured report.PDF

Dear Shu Pei,

Pls find Insured report.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

Sent: Tuesday, 4 December, 2018 2:39 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Poh Kin (LKKAUTO) <pohkin@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBE8904P (OI : CTI - TBA) and GBF189J (TP : LKK REF - CC6/CTI18021791/Afb3) on 29.11.2018

WITHOUT PREJUDICE

Dear Boon Sen,

We refer to the above matter.

We have inspected TP vehicle GBF 189J at M/s Mgarage (east) Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Poh Kin and he can be contacted at DID: 6841-2132.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18021791/Adb3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 05-12-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 8904P	Veh. Inspected	GBF 189J
Policy No.	DMCVSN3029551800	Coverage (\$)	0.00
Claim No.	SNM18D05603C02	Excess (\$)	0.00
Assign From		Assign Date	03/12/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VSKYBAM20Z0126170	Colour	SILVER
Odometer	52459	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14C	GOODYEAR	6 mm
L/H Front Tyre	175/70 R14C	GOODYEAR	6 mm
R/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm
L/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/11/2018	Inspection Date	03/12/2018
Survey held at	MGARAGE (EAST) PTE LTD 23 KAKI BUKIT CENTRE AAS KAKI BUKIT CENTRE #04-01 SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 189J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR LH	DENTED	1,850.00	1,545.00
1	REAR DOOR LOGO	NECESSARY	75.30	75.30
1	REAR DOOR EMBLEM 'NV200'	NECESSARY	87.00	87.00
2	REAR DOOR HINGE @ \$103.00	NOT NECESSARY	206.00	-
1	REAR DOOR CHECKER	NOT NECESSARY	99.20	-
1	REAR DOOR UPPER LOCK	DAMAGED	142.00	142.00
1	REAR DOOR LOWER LOCK	DAMAGED	142.00	142.00
1	REAR DOOR GLASS WITH MOULDING LH	NECESSARY	818.40	80.00
1	REAR DOOR RH	DISTORTED	1,850.00	1,285.00
1	REAR DOOR EMBLEM 'DCI'	NECESSARY	92.10	92.10
2	REAR DOOR HINGE @ \$103.00	NOT NECESSARY	206.00	-
2	REAR DOOR CHECKER @ \$99.20	NOT NECESSARY	198.40	-
1	REAR DOOR UPPER LOCK	DAMAGED	155.20	155.20
1	REAR DOOR LOWER LOCK	DAMAGED	155.20	155.20
1	REAR DOOR GLASS WITH MOULDING RH	NECESSARY	920.70	80.00
1	REAR DOOR GLASS STRIPE	CUT	230.00	230.00
1	REAR DOOR NUMBER PLATE LAMP GARNISH	DEFORMED	380.00	380.00
1	SET REAR DOOR NUMBER PLATE LAMP	NOT NECESSARY	144.20	-
1	REAR DOOR WEATHERSTRIP	CUT	133.20	133.20
1	REAR DOOR WIPER ARM	CUT	72.10	72.10
1	REAR DOOR WIPER ARM COVER	MISSING	52.90	52.90
1	REAR DOOR WIPER MOTOR	DAMAGED	355.20	355.20
1	3RD BRAKE LIGHT	CRACKED	355.20	185.00
1	REAR BUMPER	DEFORMED	688.20	688.20
2	REAR BUMPER SIDE RETAINER @ \$52.90	NECESSARY	105.80	105.80
2	REAR BUMPER REFLECTOR @ \$80.20	O/S MISSING / N/S CRACKED	160.40	160.40
1	REAR BUMPER SPONGE	CRACKED	103.00	103.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	55.20	-
2	TAILLAMP @\$288.50	N/SCRACKED	577.00	288.50
2	TAILLAMP PANEL @ \$155.60	TO REPAIR SEE LA	311.20	-

Report Ref No. CC6/CT118021791/Adb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	DENTED	552.20	552.20
1	REAR END PANEL TO GARNISH	DEFORMED	120.00	120.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,550.00	-
	LESS 10% DISCOUNT		-1,294.33	-726.53
			11,648.97	6,538.77
1	REAR FLOOR PANEL TOP MAT (SN)	TORN	922.50	450.00
	LESS 10% DISCOUNT		-92.25	-
			830.25	450.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER PLATE (SN)	NOT NECESSARY	50.00	-
1	REAR DOOR STICKER '70KM/H' LH (SN)	NECESSARY	40.00	10.00
1	REAR DOOR NUMBER PLATE LAMP GARNISH CLIP (SN)	NECESSARY	20.00	10.00
2	REAR DOOR GLASS SEALANT @ \$100.00 (SN)	NECESSARY	200.00	100.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	25.00	25.00
2	TAIL LAMP PANEL SEALANT @ \$80.00 (SN)	NOT NECESSARY	160.00	-
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	20.00	10.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
1	REVERSE CAMERA (SN)	DAMAGED	220.00	220.00
			1,255.00	635.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVING AND REPLACING PARTS.		2,000.00	1,450.00
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	1,200.00
	TUFF COAT.		250.00	60.00
	WIRING CHECK.		80.00	30.00
	TO REMOVE AND REFIX REAR DOOR MECHANISM (2 DOORS).		320.00	160.00
	REMOVE & REINSTALL REAR DOOR WINDOW GLASS.		160.00	120.00
	TO REMOVE AND REFIX REVERSE SENSOR.		100.00	50.00

Report Ref No. CC6/CT118021791/Adb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX REVERSE CAMERA.		150.00	50.00
			4,260.00	3,120.00
GRAND TOTAL			17,994.22	10,743.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,600.00

Report Ref No. CC6/CTI18021791/Adb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.