

04 DEC 2018 2nd Reminder for Liability?



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

67418434
Catherine
68411972
Lavinia
Lk Auto

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKQ9502P
Chassis No : JHMGK5850FX201574
Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)
Owner's Name : LOW CHIEK WEI
Ins Policy No. : 18-MW000222-R03
Date of Accident : 29/11/2018

Document No. : SQT18005124 Page 1
Date : 29. Nov 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B31000147
Date | Time : 29. Nov 2018 1:01:51 PM
Surveyor Name :
Survey Date : DID : +65 6846 5673
Authorisation Date : HP : +65 8100 6306
Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71729) OWNER: LOW CHIEK WEI OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 29/11/2018 @ 08.40AM SURVEYED BY: Adrian Ling@lkauto.com HP: 96893735 DATE: 05 DEC 2018 @ 09:30am REF NO: CC4/ASM18021804/Ja3 TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SMA5289S (TOYOTA/CAMRY/BLACK)						
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>neu</i>	1	60.00		60.00	4.20	64.20
74890-T5B-911	GARNISH ASSYRR.LICENSE <i>neu</i>	1	200.60	25	150.45	10.53	160.98
33500-T5A-J01	TAILLIGHT ASSYR. <i>neu</i>	1	223.90	25	167.92	11.75	179.67
73211-T5A-J01	GLASS SETRR.WINDSHIELD <i>neu</i>	1	625.60	25	469.20	32.84	502.04
34155-T5A-J01	LIGHT ASSYL.LID <i>neu</i>	1	81.70	25	61.27	4.29	65.56
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
74940-TZ5-A01	BUZZER ASSYSMART ?	1	60.40	25	45.30	3.17	48.47
38387-TZ5-A01	ANTENNA ASSYL.F. ?	1	59.30	25	44.47	3.11	47.58
75722-T5L-T01	EMBLEMRR. <i>neu</i>	1	10.90	25	8.17	0.57	8.74
04715-T5B-000ZZ	FACERR.BUMPER <i>Dehd</i>	1	502.50	25	376.87	26.38	403.25
71593-T5A-000	SPACERR.RR.BUMPER <i>neu</i>	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER <i>neu</i>	1	11.50	25	8.62	0.60	9.22
71502-T5A-000	GARNISHR.RR.BUMPER <i>neu</i>	1	14.30	25	10.72	0.75	11.47
71507-T5A-000	GARNISHL.RR.BUMPER	1	14.30	25	10.72	0.75	11.47
74440-T5A-003	WEATHERSTRIPTAILGATE <i>neu</i>	1	92.30	25	69.22	4.85	74.07
74800-T5A-J01	LOCK ASSYTAILGATE <i>neu</i>	1	78.90	25	59.17	4.14	63.31
68100-TAS-Z50ZZ	TAILGATE COMP <i>Dented</i>	1	730.60	25	547.95	38.36	586.31
66100-TAR-T10ZZ	PANEL COMPRR. <i>As Dented</i>	1	320.40	25	240.30	16.82	257.12
04655-T5A-J00ZZ	PANEL SETRR.FLOOR <i>neu</i>	1	710.90	25	533.17	37.32	570.49

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SKQ9502P

Chassis No : JHMGK5850FX201574

Model : JAZZ 1.5VTIR CVT 15YM (EURO 4)

Owner's Name : LOW CHIEK WEI

Ins Policy No. : 18-MW000222-R03

Date of Accident : 29/11/2018

Document No. : SQT18005124 Page 2

Date : 29. Nov 2018

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L15B31000147

Date | Time : 29. Nov 2018 1:01:51 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Item					<u>2896.81</u>	<u>202.76</u>	<u>3,099.57</u>
BOSUN	SUNDRIES	1	40.00		40.00 20	2.80	42.80
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00 80	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00 80	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00		140.00 120	9.80	149.80
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00		180.00 140	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00 X	17.50	267.50
BMU30A	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM. (N)	1	250.00		250.00 X	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00		350.00 300	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION. (N)	1	350.00		350.00 300	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM (N)	1	400.00		400.00 300	28.00	428.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00 280	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00		550.00 450	38.50	588.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00		2800.00 1800	196.00	2996.00
BKRP22B	CUT OFF & RENEW RR FLOOR PANEL RR R FENDER.	1	4800.00		4800.00 1960	336.00	5136.00
Sum Labor					<u>10760.00</u>	<u>753.20</u>	<u>11,513.20</u>

Survey By

Date & Time

Excess

Status

Signature

Adrian Lj

05/02/18

Not Authorized.

8/1/18

Before & After

06 Days.

Total Amount 13,656.81 955.96 14,612.77

Total (Inclusive of GST) 14,612.77

Printed on 30/11/2018 5:35:57 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)