



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

03/12/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA
Xiao Tony

TSMJYA 22500186989

Accident date: 01/12/2018

Estimated repair cost for vehicle no: SKR1384K SUZUKI SCROSS 1.6 A '15

CHASSIS: TSMJYA22S00186989

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Dented</i>		\$784.00 ✓
2	2	Front Bonnet Hinge <i>2 AP</i>	\$31.00	\$62.00 ✗
3	1	Front Bonnet Lock <i>1 AP</i>		\$83.00 ✗
4	1	Front Bonnet Inner Rubber <i>2</i>		\$65.00 ✓
5	1	Front Bonnet Insulator <i>1 AP NEU</i>		\$168.00 ✗
6	8	Front Bonnet Insulator Clip	\$6.50	\$52.00 ✗
7	1	Front L/H Fender <i>Distorted</i>		\$282.00 ✓
8	1	Front L/H Fender Protector <i>Deformed</i>		\$78.00 ✓
9	1	Front L/H Fender Cowling <i>Deformed</i>		\$70.00 ✓
10	10	Front L/H Fender Cowling Clip <i>neu</i>	\$6.50	\$65.00 ²⁰
11	1	Front L/H Head Lamp <i>cracked</i>		\$3,305.00 ✓
12	1	Front L/H Head Lamp HID Ballast <i>Cracked</i>		\$1,150.00 ✓
13	1	Front L/H Head Lamp Cover <i>NEU</i>		\$95.00 ✗
14	1	Front L/H Head Lamp Lower Bracket <i>NEU</i>		\$35.00 ✗
15	1	Front Bumper <i>Distorted</i>		\$488.00 ✓
16	1	Front Bumper Lower <i>Deformed</i>		\$351.00 ✓
17	10	Front Bumper Clip <i>neu</i>	\$6.50	\$65.00 ³⁰
18	2	Front Bumper Side Retainer <i>LH Damaged</i>	\$25.00	\$50.00 ²⁵
19	1	Front Bumper Inner Sponge <i>cracked</i>		\$110.00 ✓
20	1	Front Bumper Reinforcement <i>NEU</i>		\$281.00 ✗
21	1	Front Bumper Wiper Nozzle Cover <i>missing</i>		\$49.00 ✓
22	1	Front Bumper Wiper Nozzle Motor <i>Deformed</i>		\$110.00 ✓
23	1	Front Bumper Wiper Nozzle Bracket <i>neu</i>		\$45.00 ✗
24	1	Front L/H Bumper Fog Lamp <i>2 AP</i>		\$165.00 ✗
25	1	Front L/H Bumper Fog Lamp Cover Assy <i>1 AP</i>		\$98.00 ✗
26	1	Front Grille <i>2</i>		\$226.00 ✗
27	8	Front Grille Clip <i>1 AP</i>	\$6.50	\$52.00 ✗
28	1	Front Grille Emblem Logo		\$29.00 ✗
29	1	Front Support Panel Assy <i>Repair</i>		\$686.00 ✗

30	1	Front Fuse Box Assy <i>Overhd.</i>	\$1,650.00 X ⁶⁵⁵
31	1	Front L/H Rim <i>Wt</i>	\$659.00 ✓
32	1	Front L/H Tyre <i>N/A New</i>	\$380.00 X
33	1	Front L/H Lower Arm <i>Bent</i>	\$534.00 X ³⁸⁵
34	1	Front L/H Knuckle Arm <i>Bent</i>	\$326.00 ✓
35	1	Front L/H Knuckle Arm Bearing <i>na</i>	\$131.00 ✓
36	1	Front L/H Shock Absorber <i>Bent</i>	\$617.00 X ³⁸⁵
37	1	Front L/H Drive Shaft <i>N/A New</i>	\$821.00 X
38	1	Front Steering Rack <i>N/A New</i>	\$978.00 X
39	1	L/H Rocker Panel Skirt <i>N/A New</i>	\$336.00 X

9383
7975.55

Subtotal :- \$15,531.00

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas		\$380.00 X
To remove & refit fuse box, rocker panel skirt & check wiring		\$280.00 150
To remove & refit front L/H undercarriage		\$380.00 220
To remove & refit L/H drive shaft & steering rack		\$450.00 X
To check wheel alignment		\$150.00 80
To check wiring	2040	\$100.00 30
Towing fee		\$100.00 60
Tuff kote		\$150.00 X
Panel beating		\$1,600.00 800
Spray painting		\$1,600.00 700

Subtotal :- \$5,190.00

Total :- \$20,721.00

total 10015.55
L/S: 8K
07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

8K 07 Days