


ASS. REC. BY: Salina REF: CS3/AIG18009647/GV6-1 Special Instructions:
 Surveyor: Salina ASSIGNMENT (Office)
 From (Person): Salina of AIG Date/Time: 04.12.2018
 Estimated Cost: _____ Bill to: _____
 OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS
 To Inspect Vehicle No: SDH 6699F Insured: SJR 3637E
 at Workshop in/s: Venue motor clinic Tel: 9159 5951
 of No 25 Kaki Bukit Rd 4 #03-39 Synergy
 Policy No: 2100505524 Claim No: #54635951686-003
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 26/5/2018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: _____
 Date/Time: 12:05pm @ 28/11/18 Person Contacted: Mr. Jeron Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SDH 6699F - X</u>
	<u>SJR 3637E - X</u>
<u>3/11/18</u>	<u>Dismantled</u>
	<u>Submit LS</u>

10/12/18 ^ \$7850 8050 6 Days.
(Red 1010, 1190)


7/12/2018

RECEIVED 10 DEC 2018

Catherine Chong (LKK Auto)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Tuesday, 4 December, 2018 4:34 PM
To: SUR; Catherine Chong (LKK Auto)
Subject: ref: 7546359516SG-003 part 1 of 2
Attachments: 7546359516SG LOD PART 1.pdf

Dear Team,

Previously your surveyor had conducted the PRI of claimant's vehicle.

Enclosed is TP's independent surveyor report for your adjustment on the COR.

thank you,

Kind Regards,
Saliha

Saliha Syed Yusoff
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16, Singapore 079120
Tel +(65) 6419 1917 | Fax +(65) 68357416
www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

MOTORCAR (Rear)

Rear Position

Vehicle No: SDH 6699 F

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BR	✓	
1138	993627	Rear Number Plate Base	BR	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	CRA	✓	2
1141	992958	Rear Bumper	RE	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	RE	✓	1
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEL	✓	
1147	992976	Rear Bumper Bracket	RE	✓	
1148	993068	Rear Bumper Side Retainer	RE	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DMG	✓	
1159	993327	Rear End Panel	DT	✓	
1160	993339	Rear End Panel Top Garnish	BR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	Cut	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	LUT	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	BT	✓	
1182	991328	Tailgate Emblem	RE	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	CRA	✓	2
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NBC	✓	
1196	994607	Tailgate Glass Sealant	RE	✓	
1197	994629	Tailgate Lock	DT	✓	
1198	994651	Tailgate Rubber	WIL	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Inner Board	RE	✓	

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	RE	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim	RE	✓	
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

Claim Documents

*SDH6699F (7546359516SG)
[SJR3637E]
TP
WONG CHUEN YUE MARCUS
May 26 2018 3:00PM
[SHI YING]
Verve Autoclinic

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 11:45	General View	 Load JPG	☒
2	01/06/18 11:45	General View	 Load JPG	☒
3	01/06/18 11:45	General View	 Load JPG	☒
4	01/06/18 11:45	General View	 Load JPG	☒
5	01/06/18 11:45	General View	 Load JPG	☒
6	01/06/18 11:45	General View	 Load JPG	☒
7	01/06/18 11:45	General View	 Load JPG	☒
8	01/06/18 11:45	General View	 Load JPG	☒
9	01/06/18 11:45	General View	 Load JPG	☒
10	01/06/18 11:45	General View	 Load JPG	☒
11	01/06/18 11:45	General View	 Load JPG	☒
12	01/06/18 11:45	General View	 Load JPG	☒
13	01/06/18 11:45	General View	 Load JPG	☒
14	01/06/18 11:45	General View	 Load JPG	☒
15	01/06/18 11:45	General View	 Load JPG	☒
16	01/06/18 11:45	General View	 Load JPG	☒
17	01/06/18 11:45	General View	 Load JPG	☒
18	01/06/18 11:45	General View	 Load JPG	☒
19	01/06/18 11:45	General View	 Load JPG	☒
20	01/06/18 11:45	General View	 Load JPG	☒
21	01/06/18 11:45	General View	 Load JPG	☒
22	01/06/18 11:45	General View	 Load JPG	☒
23	01/06/18 11:45	General View	 Load JPG	☒
24	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
25	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
26	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
27	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
28	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
29	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
30	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
31	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
32	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
33	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
34	01/06/18 11:46	Dismantled Parts	 Load JPG	☒
35	01/06/18 11:46	Dismantled Parts	 Load JPG	☒

Photos/Images-					☒
No	Label/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
36	01/06/18 11:46	Dismantled Parts		Load JPG	☒
37	01/06/18 11:46	Dismantled Parts		Load JPG	☒
38	01/06/18 11:46	Dismantled Parts		Load JPG	☒
39	01/06/18 11:46	Dismantled Parts		Load JPG	☒
40	01/06/18 11:46	Dismantled Parts		Load JPG	☒
41	01/06/18 11:46	Dismantled Parts		Load JPG	☒
42	01/06/18 11:46	Dismantled Parts		Load JPG	☒
43	01/06/18 11:46	Dismantled Parts		Load JPG	☒
44	01/06/18 11:46	Dismantled Parts		Load JPG	☒
45	01/06/18 11:46	Dismantled Parts		Load JPG	☒
46	01/06/18 11:46	Dismantled Parts		Load JPG	☒
47	01/06/18 11:46	Dismantled Parts		Load JPG	☒
48	01/06/18 11:46	Dismantled Parts		Load JPG	☒
49	01/06/18 11:46	Dismantled Parts		Load JPG	☒
50	01/06/18 11:46	Dismantled Parts		Load JPG	☒
51	01/06/18 11:46	Dismantled Parts		Load JPG	☒
52	01/06/18 11:46	Dismantled Parts		Load JPG	☒
53	01/06/18 11:46	Dismantled Parts		Load JPG	☒
54	01/06/18 11:46	Dismantled Parts		Load JPG	☒
55	01/06/18 11:46	Dismantled Parts		Load JPG	☒
56	01/06/18 11:46	Dismantled Parts		Load JPG	☒
57	01/06/18 11:46	Dismantled Parts		Load JPG	☒
58	01/06/18 11:46	Dismantled Parts		Load JPG	☒
59	01/06/18 11:46	Dismantled Parts		Load JPG	☒
60	01/06/18 11:46	Dismantled Parts		Load JPG	☒
61	01/06/18 11:46	Dismantled Parts		Load JPG	☒
62	01/06/18 11:46	Dismantled Parts		Load JPG	☒
63	01/06/18 11:46	Dismantled Parts		Load JPG	☒
64	01/06/18 11:46	Dismantled Parts		Load JPG	☒
65	01/06/18 11:46	Dismantled Parts		Load JPG	☒
66	01/06/18 11:46	Dismantled Parts		Load JPG	☒
67	01/06/18 11:46	Dismantled Parts		Load JPG	☒
68	01/06/18 11:46	Dismantled Parts		Load JPG	☒
69	01/06/18 11:46	Dismantled Parts		Load JPG	☒
70	01/06/18 11:46	Dismantled Parts		Load JPG	☒
71	01/06/18 11:46	Dismantled Parts		Load JPG	☒
72	01/06/18 11:46	Dismantled Parts		Load JPG	☒
73	01/06/18 11:46	Dismantled Parts		Load JPG	☒
74	01/06/18 11:46	Dismantled Parts		Load JPG	☒
75	01/06/18 11:46	Dismantled Parts		Load JPG	☒
76	01/06/18 11:46	Dismantled Parts		Load JPG	☒
77	01/06/18 11:46	Dismantled Parts		Load JPG	☒
78	29/06/18 12:46	Photo After Spray		Load JPG	☒
79	29/06/18 12:46	Photo After Spray		Load JPG	☒
80	29/06/18 12:46	Photo After Spray		Load JPG	☒
81	29/06/18 12:46	Photo After Spray		Load JPG	☒
82	29/06/18 12:46	Photo After Spray		Load JPG	☒
83	29/06/18 12:46	Photo After Spray		Load JPG	☒

Photos/Images,				☒
No	Resabel/Réorder	LKK Auto Consultants Pte Ltd (HQ)		
84	29/06/18 12:46	Photo After Spray		Thumbnail ☒
85	29/06/18 12:46	Photo After Spray		Load JPG ☒
86	29/06/18 12:46	Photo After Spray		Load JPG ☒
87	29/06/18 12:46	Photo After Spray		Load JPG ☒
88	29/06/18 12:46	Photo After Spray		Load JPG ☒
89	29/06/18 12:46	Photo After Spray		Load JPG ☒
90	29/06/18 12:46	Photo After Spray		Load JPG ☒
91	29/06/18 12:46	Photo After Spray		Load JPG ☒
92	29/06/18 12:46	Photo After Spray		Load JPG ☒
93	29/06/18 12:46	Photo After Spray		Load JPG ☒
94	29/06/18 12:46	Photo After Spray		Load JPG ☒
95	29/06/18 12:46	Photo After Spray		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	05/06/18 14:35	OI GIA REPORT		Thumbnail ☒
			Load PDF	☒

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#) [Save](#) [Print](#)

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009647/GZ4D3S2
Date: 06/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100505524
Claimant Vehicle No: SDH6699F Insured Vehicle No: SJR3637E
Date of Loss: 26/05/2018 Nature of Claim: TP Claim No: 7546359516SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDH6699F
Make & Model: VOLKSWAGEN GOLF A7, 1.4 (A) Engine No: HIDDEN
Reg. Date: 01/01/1990 (Man. Year: 1990) Chassis No: WVVZZZ1KZAW367197
Colour: Black Odometer: 136814 km
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2018
Date Inspected: 28/05/2018 Inspected At: No.25 Kaki Bukit Rd4 #03-39 Synergy
Repairst: Verve Motor Clinic
10 Kaki Bukit Rd 2
Singapore 417868
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Broken	0.00 F	*-F
2	1		*REAR NUMBER PLATE BASE	Broken	0.00 F	*-F
3	1		*REAR BUMPER	Deformed	0.00 F	*-F
4	1		*REAR BUMPER LOWER	Deformed	0.00 F	*-F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
6	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*-F
7	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*-F
8	1		*REVERSE SENSOR	Damaged	0.00 F	*-F
9	1		*REAR END PANEL	Dented	0.00 F	*-F
10	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*-F
11	1		*REAR RH TAILLAMP	Cut	0.00 F	*-F
12	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*-F
13	1		*REAR BUMPER BRACKET	Deformed	0.00 F	*-F
14	1		*REAR LH TAILLAMP	Cut	0.00 F	*-F
15	1		*TAILGATE	Bent	0.00 F	*-F
16	1		*TAILGATE EMBLEM	Necessary	0.00 F	*-F
17	2		*TAILGATE LAMP	Cracked	0.00 F	*-F
18	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*-F
19	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*-F
20	1		*TAILGATE LOCK	Dented	0.00 F	*-F
21	1		*TAILGATE RUBBER	Twisted	0.00 F	*-F
22	1		*TAILGATE INNER BOARD	Deformed	0.00 F	*-F
23	1		*SPARE TYRE PANEL	Repair	0.00 F	*-F
24	1		*REAR LH FENDER INNER TRIM	Deformed	0.00 F	*-F
25	1		*REAR RH FENDER INNER TRIM	Deformed	0.00 F	*-F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 2014044340

INVOICE

Mr Wong Cheun Yue Marcus
C/o. 25 Kaki Bukit Road 4
Synergy@KB #03-39
Singapore 417800

Invoice No. : HA/1807-51

Date : 21/07/2018

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 606.00
SGD Dollar : Six Hundred Six Dollars Only.	
Our Reference : PAS/TP/0520518	
Vehicle No. : SDH6699E	
Make & Model : Volkswagen Golf (A)	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0520518

Date of Report : 21/07/2018

To : Mr Wong Cheun Yue Marcus
C/o. 25 Kaki Bukit Road 4
Synergy@KB #03-39
Singapore 417800

Date of Assignment : 28/05/2018
Report requested by : Mr Wong Cheun Yue Marcus
Date of Accident : 26/05/2018
Date of Inspection : 28/05/2018
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SDH6699E
Make & Model : Volkswagen Golf (A)
Date of Registration : 12/08/2010
Colour : Met. Black

Engine Capacity (cc) : 1390cc
Mileage (km) : 136814km
Chassis / Frame No. : WVWZZZ1KZAW367197
Engine No. : CAV188880

TYRE CONDITION

Front LH : 5 mm
Make : Michelin

Front RH : 5 mm
Make : Michelin

Rear LH : 5 mm
Make : Michelin

Rear RH : 5 mm
Make : Michelin

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Verve Motorclinic Pte Ltd
25, Kaki Bukit Road 4, Synergy@KB, #03-39, Singapore 417800

ASSESSMENT

Repairer's Estimate : \$ 12,894.20
Revised Amount : \$ 11,330.70
Less Excess : \$ -
Recommended Reserve : \$ 9,060.00 (Lump Sum)

Estimated Normal Period of Repairs : 10 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

Vehicle No: SDH6699E

Report No.: PAS/TP/0520518

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Verve Motorclinic Pte Ltd, 25, Kaki Bukit Road 4, Synergy@KB, #03-39, Singapore 417800.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear portion.

DAMAGES

The tailgate, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, taillamps, rear reflectors, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$11,330.70.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,060.00.


This inspection was conducted entirely on a **'Without Prejudice'** basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 2014044340

Vehicle No.: SDH6699E

Report No.: PAS/TP/0520518

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$S)	Our Assessment (\$S)
1	1 pc	Tailgate	Dented	\$ 1,984.65	\$ 1,984.65
2	1 pc	Tailgate windscreen moulding	Necessary	\$ 97.07	\$ 97.07
3	2 pcs	Tailgate stay support R/L	Refit	\$ 327.68	\$ -
4	1 pc	Tailgate emblem w.handle (VW)	Dented/Cracked	\$ 352.41	\$ 352.41
5	1 pc	Tailgate emblem (GOLF)	Dented/Necessary	\$ 51.84	\$ 51.84
6	1 pc	Tailgate emblem (TSI)	Dented/Necessary	\$ 39.25	\$ 39.25
7	2 pcs	Tailgate reflector lamp R/L	Cracked	\$ 583.62	\$ 583.62
8	1 pc	Tailgate inner trim	Dented/Deformed	\$ 178.69	\$ 178.69
9	1 pc	Tailgate lock	Dented/Jammed	\$ 281.62	\$ 281.62
10	1 pc	Tailgate lock striker	Bent	\$ 43.97	\$ 43.97
11	1 pc	Rr weatherstrip	Torn/Necessary	\$ 278.46	\$ 278.46
12	2 pcs	Taillamp R/L	Cracked/Broken	\$ 656.26	\$ 656.26
13	2 pcs	Taillamp panel R/L	Dented/Repair	\$ 582.34	\$ -
14	1 pc	Rr bumper	Dented	\$ 1,406.82	\$ 1,406.82
15	1 pc	Rr bumper diffuser	Dented/Loop Cracked	\$ 310.34	\$ 310.34
16	4 pcs	Rr bumper sensor	Dented/Broken	\$ 953.24	\$ 714.93
17	2 pcs	Rr no.plate lamp R/L	Cracked/Broken	\$ 124.48	\$ 124.48
18	1 pc	Rr bumper center guide	Dented/Broken	\$ 86.21	\$ 86.21
19	2 pcs	Rr bumper side guide R/L	Dented/Cracked	\$ 73.68	\$ 73.68
20	2 pcs	Rr bumper side support R/L	Cracked/Necessary	\$ 108.32	\$ 108.32
21	1 pc	Rr bumper reinforcement	Dented/Distorted	\$ 570.31	\$ 570.31
22	1 pc	Rr end panel	Dented	\$ 629.35	\$ 629.35
23	1 pc	Rr end panel garnish	Dented/Cracked	\$ 118.25	\$ 118.25
24	2 pcs	Rr fender trim R/L	Torn/Deformed	\$ 299.14	\$ 299.14
25	2 pcs	Rr fender R/L	Dented/Repair		
26	1 pc	Rr floor panel	Dented/Repair		
27	2 pcs	Rr chassis member R/L	Dented/Repair		
				\$ 10,138.00	\$ 8,989.67
Less Discount: 10%				\$ 1,013.80	\$ 898.97
List Parts Sub-Total:				\$ 9,124.20	\$ 8,090.70
1	1 pc	Tailgate windscreen sealant	Necessary	\$ 40.00	\$ 40.00
2	1 pc	Rr no.plate (w/bracket)	Dented/Broken	\$ 50.00	\$ 50.00
3	1 pc	Rr end panel sealant	Necessary	\$ 40.00	\$ 40.00
Special Nett Sub-Total:				\$ 130.00	\$ 130.00
Parts Total:				\$ 9,254.20	\$ 8,220.70

8513.05

7661.75

40

120



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 2014044340

Vehicle No.: SDH6699E

Report No.: PAS/TP/0520518

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To transfer tailgate component parts to new tailgate.	\$ 100.00	\$ 80.00 60
2	To transfer rear windscreen to new tailgate.	\$ 120.00	\$ 120.00 ✓
3	To check rear electrical wiring system.	\$ 60.00	\$ 50.00 30
4	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 140.00	\$ 120.00 60
5	To remove, replace and/or transfer rear reverse sensors to new bumper & reset control unit.	\$ 180.00	\$ 160.00 50
6	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,200.00	\$ 990.00 800
7	To conduct chassis alignments.	\$ 320.00	\$ 300.00 X NV
8	To spray painting, blending on affected and adjacent area.	\$ 1,400.00	\$ 1,200.00 900
9	To spray anti-rust coating on new and affected panels.	\$ 120.00	\$ 90.00 60
Labour Total :		\$ 3,640.00	\$ 3,110.00 2080
Total (Parts & Labour) :		\$ 12,894.20	\$ 11,330.70

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 9,060.00

Under normal circumstances, the repairs should be completed within a reasonable period

of **10 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

116 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009647/Gvbs2-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 17-12-2018



ATTN: SALIHA

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 3637E	Veh. Inspected	SDH 6699F
Policy No.	2100505524	Coverage (\$)	0.00
Claim No.	7546359516SG	Excess (\$)	0.00
Assign From	SALIHA	Assign Date	04/12/2018

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WVWZZZ1KZAW367197	Colour	BLACK
Odometer	136814	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45R17	MICHELIN	6 mm
L/H Front Tyre	225/45R17	MICHELIN	6 mm
R/H Rear Tyre	225/45R17	MICHELIN	6 mm
L/H Rear Tyre	225/45R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/05/2018	Inspection Date	28/05/2018
Survey held at	VERVE AUTOCLINIC BLK 25 KAKI BUKIT ROAD 4 #03-39 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDH 6699F

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DENTED	1,984.65	1,984.65
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	97.07	97.07
2	TAILGATE STAY SUPPORT R/L @ \$163.84	REFIT	327.68	-
1	TAILGATE EMBLEM W.HANDLE (VW)	DENTED / CRACKED	352.41	352.41
1	TAILGATE EMBLEM (GOLF)	DENTED / NECESSARY	51.84	51.84
1	TAILGATE EMBLEM (TSI)	DENTED / NECESSARY	39.25	39.25
2	TAILGATE REFLECTOR LAMP R/L @ \$291.81	CRACKED	583.62	583.62
1	TAILGATE INNER TRIM	DENTED / DEFORMED	178.69	178.69
1	TAILGATE LOCK	DENTED / JAMMED	281.62	281.62
1	TAILGATE LOCK STRIKER	BENT	43.97	43.97
1	RR WEATHERSTRIP	TORN / NECESSARY	278.46	278.46
2	TAILLAMP R/L @ \$328.13	CRACKED / BROKEN	656.26	656.26
2	TAILLAMP PANEL R/L @ \$291.17	TO REPAIR SEE LABOUR	582.34	-
1	RR BUMPER	DENTED	1,406.82	1,406.82
1	RR BUMPER DIFFUSER	DENTED / LOOP CRACKED	310.34	310.34
4	RR BUMPER SENSOR @ \$238.31	DENTED / BROKEN 2PCS ONLY	953.24	476.62
2	RR NO. PLATE LAMP R/L @ \$62.24	CRACKED / BROKEN	124.48	124.48
1	RR BUMPER CENTER GUIDE	DENTED / BROKEN	86.21	86.21
2	RR BUMPER SIDE GUIDER/L @ \$36.84	DENTED / CRACKED	73.68	73.68
2	RR BUMPER SIDE SUPPORT R/L @ \$54.16	CRACKED / NECESSARY	108.32	108.32
1	RR BUMPER REINFORCEMENT	DENTED / DISTORTED	570.31	570.31
1	RR END PANEL	DENTED	629.35	629.35

Report Ref No. CS3/AIG18009647/Gvbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR END PANEL GARNISH	DENTED / CRACKED	118.25	118.25
2	RR FENDER TRIM R/L @ \$149.57	TORN / DEFORMED	299.14	299.14
2	RR FENDER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
2	RR CHASSIS MEMBER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-1,013.80	-875.14
			9,124.20	7,876.22
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	RR NO. PLATE (W/BRACKET) (SN)	DENTED / BROKEN	50.00	40.00
1	RR END PANEL SEALANT (SN)	NECESSARY	40.00	40.00
			130.00	120.00
	<u>LABOUR</u>			
	TO TRANSFER TAILGATE PARTS TO NEW TAILGATE.		100.00	60.00
	TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE.		120.00	120.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		60.00	30.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS.		140.00	60.00
	TO REMOVE, REPLACE AND / OR TRANSFER REAR REVERSE SENSORS TO NEW BUMPER & RESET CONTROL UNIT.		180.00	50.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCUSIVE OF THE REPAIR OF TAILLAMP PANEL R/L, RR FENDER R/L, RR FLOOR PANEL AND RR CHASSIS MEMBER R/L.		1,200.00	800.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	320.00	-
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,400.00	900.00
	TO SPRAY ANTI-RUST COATING ON NEW AFFECTED PANELS.		120.00	60.00
			3,640.00	2,080.00
	GRAND TOTAL		12,894.20	10,076.22

Report Ref No. CS3/AIG18009647/Gvbs2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,050.00
---	--	--	----------

Report Ref No. CS3/AIG18009647/Gvbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.