

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18021849/R1KA3Q2

Date: 18/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994692

Claimant
Vehicle No : SHB6000E **Insured Vehicle No :** GR9873K

Date of Loss: 28/11/2018 Nature of Claim: TP Claim No: 4987771761SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SHB6000E | | |
| Make & Model: | TOYOTA PRIUS TAXI, 1.8 (A) | Engine No: | 2ZR6025429 |
| Reg. Date: | 30/10/2013 (Man. Year: 2013) | Chassis No: | JTDKN36U705693626 |
| Colour: | Maroon | Odometer: | 510418 km |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/65R15 | Rear Tyre Size: | 195/65R15 |
| Front Left Side: | Falken 5 mm | Rear Left Side: | Falken 5 mm |
| Front Right Side: | Falken 5 mm | Rear Right Side: | Falken 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 3,602.40 | 576.53 | 3,025.87 | 84.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,721.00 | 780.00 | 1,941.00 | 71.33 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 6,323.40 | 1,356.53 | 4,966.87 | 78.55 |
| Approved Total (Overridden) (\$\$) | | 1,250.00 | | |
| Nett Amount (\$\$) | 6,323.40 | 1,250.00 | 5,073.40 | 80.23 |
| + Loss of Use (5.0 x S\$50.00/day) (\$\$) | | 250.00 | | |
| + Car Rental (5.0 x S\$101.12/day) (\$\$) | | 505.60 | | |
| + Doc/Search Fee (\$\$) | | 7.00 | | |
| Nett Liability (\$\$) | | 2,012.60 | | |
| Global Sum Settlement (\$\$) | | 2,000.00 | | |

INSPECTION

Date of Assignment: 30/11/2018

Date Inspected: 30/11/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|------------|-----------|
| 1 | 1 | | *BUMPER REAR (DISC 25%) | Torn | 458.60 F | *343.95 F |
| 2 | 1 | | *BUMPER CLIPS (DISC 25%) (10 PCS) | Necessary | 16.10 F | *12.08 F |
| 3 | 1 | | *BUMPER SIDE RETAINER RR/LH (DISC 25%) | Necessary | 94.80 F | *71.10 F |
| 4 | 1 | | *STICKER DECAL 6555 8888 (SN) | Necessary | 21.60 F | *21.60 F |
| 5 | 2 | | *PIXEL STICKER (SN) | Necessary | 120.00 F | *120.00 F |
| 6 | 1 | | *SMRT LOGO (SN) | Necessary | 7.80 F | *7.80 F |
| 7 | 1 | | *BUMPER LIP COVER RR/LH | Serviceable | 72.20 F | *- F |
| 8 | 1 | | *BUMPER SEAL ,RR LH | Serviceable | 88.90 F | *- F |
| 9 | 1 | | *FENDER RR/LH | Repair | 766.80 F | *- F |
| 10 | 1 | | *SOLAR FILM | Not Necessary | 125.00 F | *- F |
| 11 | 1 | | *FENDER LINER RR/LH | Not Necessary | 141.30 F | *- F |
| 12 | 1 | | *QUARTER GLASS RR/LH | Not Necessary | 168.10 F | *- F |
| 13 | 1 | | *SEALANT W/SCREEN | Not Necessary | 37.00 F | *- F |
| 14 | 1 | | *WHEEL DISC | Not Necessary | 1,484.20 F | *- F |

F=Franchise part.

Total Parts (\$\$) **3,602.40** **576.53**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | PANEL BEATING & BODY WORK | New | 845.00 | 300.00 |
| 2 | SPRAY PAINT | New | 936.00 | 400.00 |
| 3 | TO CHECK WIRING AND SYSTEM FUNCTION | New | 80.00 | 0.00 |
| 4 | TO APPLY RUST-PROOFING ON AFFECTED AREA | New | 100.00 | 20.00 |
| 5 | TO DO WHEEL ALIGNMENT /TYRE BALANCING | New | 120.00 | 0.00 |
| 6 | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | New | 120.00 | 0.00 |
| 7 | TO TEST AND REFIX REVERSE SENSOR SYSTEM | New | 120.00 | 60.00 |
| 8 | TO REMOVE & REFIT REAR QUARTER GLASS LH | New | 120.00 | 0.00 |
| 9 | TO REMOVE /REFIT SEAT | New | 120.00 | 0.00 |
| 10 | TO REPLACE SUNDRY PARTS | New | 100.00 | 0.00 |
| 11 | TO WASH AND VACUUM | New | 60.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 2,721.00 | 780.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >