



Case Details

Case Reference Number : TAX/11/18/2130
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB6000E

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4760-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 28/11/2018 09:10 AM
 Vehicle Age(In Months) : 61

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace ▾
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace ▾
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give ▾
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give ▾
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▾
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give ▾

Total Spare Part Cost	2,654.66	Surveyor Total	576.53
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	0
Final Spare Part Cost	2,123.73	Final Sur Total	576.53

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
3	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60	
6	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0	
7	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
8	TO REMOVE / REFIT SEAT	120.00	0	
9	TO REPLACE SUNDRY PARTS	100.00	0	
10	TO WASH AND VACUUM	60.00	0	
Total:		1,065.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,123.73	576.53
Total Labour Cost	845.00	300.00
Total Spray Painting	936.00	400.00
Other	1,065.00	80.00
Overall Total	4,969.73	1,356.53
Lump Sum Repair Option	☒	☐
Lump Sum Total	4,950.00	1,356.53
Surveyor Approved Amount		1,356.53
No of Repair Days*	5	3
Remarks	-	P/P resurvey before paint
Surveyor Name		Rasul

Estimator Assesment(\$)		Surveyor Assesment(\$)
Signature		
Survey Date	Save Clear	
	30/11/2018	