

ASS. REC. BY:

REF:

CS/CT48021878/T14b2

Special Instruction:

Surveyor:

Tanjah

ASSIGNMENT (Office)

Mufimen

From (Person):

Elaine Cheong

of

CTL

Date/Time:

04.12.2018 6:10pm

Estimated Cost:

Bill to:

OD / IR / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFV 8600D

Insured:

SJW 6555L

at Workshop m/s

Automotive Repair

Tel:

of

38 woodlands Ind Park E1 #05-18

Policy No:

PMPCSN 3014821800

Claim No:

SNM18 D05580C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21.11.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Shu Juan

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SFV 8600D - x
	SJW 6555L - NA / ALH11005165/22
	DOA 20182011

Taylor

REF: CTL

ASSIGNMENT

From: Date: 04/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFV 8600D

at Workshop m/s

of 58 Woodlands Ind Park E1 #05-18

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Raymond

Veh No:

SFV 8600D

Yr Regn:

2015 June.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 2

C.C.

1496.

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

108/42.

T/Radio:

Insured / Std / NI / NA

Eng/No:

Ct/No:

SM 6052 HAA 011 00195

Gen. Cond: ~~Good~~ / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

4/12/18 04pm

Survey held at

Automotive Repair.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/11

*Email - 4/5 \$3800, 6 days to Raymond.
CRed: 0472, 63%*

RECEIVED 12 MAR 2019

Date/Time. File Pass to?

8/3 Typist

Date/Time. File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

)

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

3800/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018		04 Dec 2018 18:10 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS			[Created by insurer]																					
Insured:																								
Main Claimant:		ENG HUP ENGINEERING PTE LTD, Co. Reg. No.: 199803209H																						
Vehicle Reg. No.:		SFV8600D	Date of Loss:	29/11/2018 12:00 - :59																				
Claim Type:		TP / SNM18D05580C02	Policy/Cover Note No.:	DMPCSN3014821800																				
Vehicle Reg. No. (Insured):		SJW6555L	Policy No. (Claimant):	S28767319MCY																				
		Excess:	S\$500.00																					
Repairer:		Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18, 757700 Woodlands - Tel: 64688834																						
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]																						
Claimant's Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888																						
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/12/2018]																						
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail																					
There are no mail for this case.																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1811-109

DATE : 30-Nov-2018

POLICY NO. : MSIG 528767319MCY

VEHICLE REG. NO. : SFV8600D

VEHICLE MAKE : MAZDA2 5-DOOR HATCHBACK 1.5L

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Rear Bumper	1	\$ 920.00	\$ de 920.00
2	Rear Bumper Clip	10	\$ 5.00	\$ de 50.00
3	Rear Bumper Retainer RH	1	\$ 40.00	\$ X 40.00
4	Rear Bumper Retainer RH LH	1	\$ 40.00	\$ de 40.00
5	Rear Bumper Bracket LH	1	\$ 20.00	\$ de 20.00
6	Rear Bumper Stay LH	1	\$ 30.00	\$ X 30.00 de
7	Rear Tail Lamp LH	1	\$ 780.00	\$ X 780.00
8	Rear Tailgate Lamp LH	1	\$ 280.00	\$ X 280.00
9	Rear Tailgate	1	\$ 980.00	\$ de 980.00
10	Rear Tailgate Rubber Seal	1	\$ 180.00	\$ de 180.00
11	Rear Tailgate Lock	1	\$ 220.00	\$ de 220.00
12	Rear Tailgate Switch Open	1	\$ 110.00	\$ de 110.00
13	Rear Mazda Logo Emblem	1	\$ 60.00	\$ de 60.00
14	Rear "Mazda2" Emblem	1	\$ 60.00	\$ de 60.00
15	Rear SkyActiv Emblem	1	\$ 70.00	\$ de 70.00
16	Rear Spare Tire Floor Panel	1	\$ 880.00	\$ de 880.00
17	Rear Spare Tyre Board Top Cover	1	\$ 320.00	\$ de 320.00 de
18	Rear Spare Tire Floor Foam Center -phant	1	\$ 200.00	\$ de 200.00
19	Rear Windscreen Molding	1	\$ 70.00	\$ de 70.00
20	Rear License Plate Lamp	2	\$ 70.00	\$ de 140.00
21	Rear Fender LH	1	\$ 980.00	\$ de 980.00
22	Rear Fender Shield LH	1	\$ 60.00	\$ de 60.00
23	Rear Fender Clip	10	\$ 5.00	\$ de 50.00
24	Rear Fender Inner Trim LH	1	\$ 220.00	\$ de 220.00
25	End Panel	1	\$ 400.00	\$ de 400.00
26	End Panel Garnish	1	\$ 180.00	\$ de 180.00
Total Spare Parts				\$ 7,340.00
	SPECIAL NETT			
27	Rear License Plate	1	\$ 40.00	\$ de 40.00
28	Rear Windscreen Sealant	1	\$ 40.00	\$ de 40.00
29	Reverse Sensor	1	\$ 200.00	\$ de 200.00
Total Special Nett				\$ 280.00 ✓

3540
20% - 2832

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1811-109

DATE : 30-Nov-2018

POLICY NO. : MSIG 528767319MCY

VEHICLE REG. NO. : SFV8600D

VEHICLE MAKE : MAZDA2 5-DOOR HATCHBACK 1.5L

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	LABOUR			
30	Spray painting Whole Rear Panel	1	\$ 800.00	\$ 700 800.00
31	Repair, Replace and Refill Affected Accident Area	1	\$ 800.00	\$ 700 800.00
32	Remove and Replace Rear Windscreen	1	\$ 120.00	\$ ✓ 120.00
33	Transfer Door Fittling and Window Mechanism to New Door	1	\$ 80.00	\$ 60 80.00
34	Remove and Replace Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ x 80.00
35	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 30 80.00
36	Check and rectify electrical wiring	1	\$ 20.00	\$ ✓ 20.00
Total Labour				\$ 1,980.00
Amount Before Excess				\$ 9,600.00
Add GST @ 7%				672.00
Total Amount Payable				\$ 10,272.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Total Labour \$ 1,980.00
 Amount Before Excess \$ 9,600.00
 Add GST @ 7% 672.00
 Total Amount Payable \$ 10,272.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 97495747/
 62563561

WP
 4/12/18 4pm

Resurvey after repair
 LKK Auto

surelkkauto.com

6 days

2832

280

1630

4742

4/5/3800

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18021878/T1TBN2

Date: 18/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3014821800
Claimant Vehicle No :	SFV8600D	Insured Vehicle No :	SJW6555L
Date of Loss:	29/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05580C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFV8600D	Engine No:	P520272347
Make & Model:	MAZDA 2, 1.5 HATCHBACK L SP.6EAT (A)	Chassis No:	JM6DJ2HAA01100195
Reg. Date:	18/06/2015 (Man. Year: 2015)	Odometer:	108142 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,620.00	3,112.00	4,508.00	59.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,630.00	350.00	17.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,600.00	4,742.00	4,858.00	50.60
Approved Total (Overridden) (\$\$)		3,800.00		
(\$\$)	9,600.00	3,800.00	5,800.00	60.42
+ GST 7.00/7.00% (\$\$)	672.00	266.00	406.00	60.42
Nett Amount (\$\$)	10,272.00	4,066.00	6,206.00	60.42

INSPECTION

Date of Assignment:	04/12/2018	
Date Inspected:	04/12/2018 Inspected At:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18 Singapore 757700
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2019)
Parts:	144	MAZDA 2 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFV8600D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	920.00 F	*920.00 FL
2	10		*REAR BUMPER CLIP	Necessary	50.00 F	*50.00 FL
3	1		*REAR BUMPER RETAINER RH	Not Necessary	40.00 F	*- FL
4	1		*REAR BUMPER RETAINER LH	Necessary	40.00 F	*40.00 FL
5	1		*REAR BUMPER BRACKET LH	Necessary	20.00 F	*20.00 FL
6	1		*REAR BUMPER STAY LH	Deformed	30.00 F	*30.00 FL
7	1		*REAR TAIL LAMP LH	Not Necessary	780.00 F	*- FL
8	1		*REAR TAILGATE LAMP LH	Not Necessary	280.00 F	*- FL
9	1		*REAR TAILGATE	Bent	980.00 F	*980.00 FL
10	1		*REAR TAILGATE RUBBER SEAL	Necessary	180.00 F	*180.00 FL
11	1		*REAR TAILGATE LOCK	Not Necessary	220.00 F	*- FL
12	1		*REAR TAILGATE SWITCH OPEN	Not Necessary	110.00 F	*- FL
13	1		*REAR MAZDA LOGO EMBLEM	Necessary	60.00 F	*60.00 FL
14	1		*REAR MAZDA EMBLEM	Necessary	60.00 F	*60.00 FL
15	1		*REAR SKYACTIV EMBLEM	Necessary	70.00 F	*70.00 FL
16	1		*REAR SPARE TIRE FLOOR PANEL	Repair	880.00 F	*- FL
17	1		*REAR SPARE TYRE BOARD TOP COVER	Deformed	320.00 F	*320.00 FL
18	1		*REAR SPARE TIRE FLOOR FOAM CENTER	Deformed	200.00 F	*200.00 FL
19	1		*REAR WINDSCREEN MOLDING	Necessary	70.00 F	*70.00 FL
20	2		*REAR LICENSE PLATE LAMP	Distorted	140.00 F	*140.00 FL
21	1		*REAR FENDER LH	Repair	980.00 F	*- FL
22	1		*REAR FENDER SHIELD LH	Not Necessary	60.00 F	*- FL
23	10		*REAR FENDER CLIP	Not Necessary	50.00 F	*- FL
24	1		*REAR FENDER INNER TRIM LH	Not Necessary	220.00 F	*- FL
25	1		*END PANEL	Bent	400.00 F	*400.00 FL
26	1		*END PANEL GARNISH	Not Necessary	180.00 F	*- FL
27	1		*REAR LICENSE PLATE	Cracked	40.00 FS	*40.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
29	1		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,620.00	3,820.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	708.00
Total Parts (\$\$)	7,620.00	3,112.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING WHOLE REAR PANEL	New	800.00	700.00
2	REPAIR ,REPLACE AND REFILL AFFECTED ACCIDENT AREA	New	800.00	700.00
3	REMOVE AND REPLACE REAR WINDSCREEN	New	120.00	120.00
4	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR	New	80.00	60.00
5	REMOVE AND REPLACE REAR EXHAUST PIPE AND SILENCER ,RE-ALIGN	New	80.00	0.00
6	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR	New	80.00	30.00
7	CHECK AND RECTIFY ELECTRICAL WIRING	New	20.00	20.00
Gross Labour Cost (S\$)			1,980.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >