

SS. REC. BY:

REF:

CS/CTI 8021889/D4bn2

Special Instruction:

Survivor:

Bryan

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTI

Date/Time:

04/22/018 5:16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 7174K

Insured:

ABD 8089Y

at Workshop m/s

Chunni motor

Tel:

of

Blk 10 Amk Ind Park JA 403-19

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01-12-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

05/22/018 9:07am

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHA 7174K - NS/INC1609484 / Highsn2	DA: 12.10.16
	ABD 8089Y - NA / CTI 17000965 / 24	DA: 13.01.17

REF:

ASSIGNMENT

02B 2024 April

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est Repairs: 108 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHA 7174K

Veh Regn:

April 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / T/A / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

C/C:

1685

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

309197

T/Radio:

Insured / Std / NI / NA

Eng/No:

D4FDGU613571

C/No:

KMHLCB41UMGU087792

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

205/60 R16

R:

— " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

01/12/2018

D.O.I.

05/12/2018

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

H/b Front

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Chun Teiping GBD 8089Y

28/12/18 final 2/5 11,000/- - its 10 days 7 ✓

cred: 10962.88; 49%)

RECEIVED 02 JAN 2019

Date/Time, File Pass to?

☐

Prel. Report

1) 31/12 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

1) \$ = Rm. 01

1) Photos

1) Others:

Report Format :

Lump Sum / L.B.I: (\$

11,000/-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

220

(OTN)

Nivitha (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Tuesday, 4 December 2018 5:16 PM
To: assignments
Cc: chunnimotor@gmail.com
Subject: FW: Accident involving veh no: SHA 7174K & GBD 8089Y on 01.12.18
Attachments: 03122018153513.pdf

Dear LKK personnel

Please assist to do the PRI assignment. We will create in Merimen later on

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Monday, 3 December, 2018 3:42 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Accident involving veh no: SHA 7174K & GBD 8089Y on 01.12.18

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 7174 K

Technician:

Mileage: 309197

Time Printed 5.12.18 11:52 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
5°46'		-3°00' 3°00'
3°56'		-0°19' 5°41'
6°34'		-1°30' 1°30'
11°47'		
17°33'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
2°03'		-3°00' 3°00'
4°10'		-0°19' 5°41'
-0°06'		-1°30' 1°30'
10°22'		
12°25'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
3°43'		-3°00' 3°00'
-0°14'		-3°00' 3°00'
1°25'		-3°00' 3°00'
6°28'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°56'		-3°30' 2°30'
0°15'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°37'		-3°30' 2°30'
-0°04'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°19'		-3°00' 3°00'
0°11'		-3°00' 3°00'
0°09'		-3°00' 3°00'

MCD618155668 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 02/12/2018 12:24
 SUBMITTED BY: Huang XianYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/12/2018 12:24
Date Of Accident	01/12/2018 11:00
Exact Location Of Accident	ANG MO KIO OPEN AIR CARPARK ST 22
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7174K
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	PHUA BOON KIAT (PAN WENJIE)
NRIC No	S7122682D
Date Of Birth	07/07/1971
Occupation	OUTDOOR
Date Of Driving Pass	07/03/1990
Driving Experience	28 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97915357
Fax Number	
Contact Number	
Email Address	LESLIEPHUABK@GMAIL.COM

Address BLK 133 YISHUN STREET 11 #03-189
Postcode 760133
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions DRIZZLING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident : 3P REVERSE

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD8089Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver NG SEW BEE
NRIC/Passport Number S1367799I
Contact Number
Address
Postcode
Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage REAR
No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON. 1 Dec 2018 @ 1100 hrs. I vert A

used drawing out from a open Cor pante Shmagut

at the above location. Suddenly Unit B

Reverse and let vet A left front I vet A

got a shock and E-brake. at the point

of accident no park in vet (A).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 109003021R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

10 survey by UCL (Bryan)

VEHICLE NO : SHA 7174K

DATE : 3.12.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

China taiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover broken			\$ 1,052.20 ✓
	Front Bumper Bracket Top (RH) NW			\$ 22.40 X
	Front Bumper Bracket (LH) broken			\$ 24.60 ✓
	Headlamp Support Top Cover NW			\$ 222.60 X
	Headlamp Support Panel Assy broken			\$ 907.40 ✓
	Headlamp (LH) broken			\$ 1,388.00 ✓
	Headlamp Halogen Bulb (LH) NW			\$ 14.40 X
	Front Fender (LH) BNC			\$ 566.30 ✓
	Front Fender Apron Panel (LH) BNC			\$ 637.00 ✓
	Front Fender Shield (LH) torn			\$ 174.90 ✓
	Air Cleaner Bottom Assy broken			\$ 325.00 ✓
	Front Wheel Rim (LH) ? distorted			\$ 325.30 Z ✓
	Front Wheel Hub Cap (LH) cut			\$ 107.10 ✓
	Front Wheel Bearing Z Done			\$ 150.90 Z ✓
	Front Shock Absorber (Assy) (LH) Z distorted			\$ 342.20 Z ✓
	Front Shock Absorber Mounting (LH) NW			\$ 108.80 X
	Front Drive Shaft (LH) NW & Done			\$ 1,030.80 Z ✓
	Rack & Pinion Assy NW Done			\$ 969.60 Z ✓
	STG Tie End Z distorted			\$ 62.60 Z ✓
	Stabilizer Bar Z distorted			\$ 252.30 Z ✓
	Stabilizer Bar Bush (LH) NW			\$ 16.40 X
	Stabilizer Bar Link Z distorted			\$ 61.10 Z ✓
	Stabilizer Bracket NW			\$ 24.00 X
	Front Suspension Lower Arm (LH) Z distorted			\$ 529.30 Z ✓
	Knuckle Arm (LH) Z distorted			\$ 552.00 Z ✓
	Engine Under Cover NW			\$ 334.60 X
	Engine Crossmember NW distorted			\$ 2,094.40 Z ✓
	Inter Cooler NW			\$ 1,032.50 X
	Inter Cooler Mounting (2 PCS) NW			\$ 25.90 X
	ABS Sensor, LH NW			\$ 234.00 X
	Wiring-Engine NW broken mounting			\$ 3,326.00 Z ✓
	Electric Power Steering NW			\$ 4,880.50 X
	SUB TOTAL			\$ 21,795.10
	LESS 20%			\$ 4,359.02
	DISCOUNTED TOTAL			\$ 17,436.08
	Front Tyre (LH) SVC			\$ 216.00
				Nett X

SHA 7174K

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 700/-
	Spray Painting Charge			\$ 750.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Towing Charge			\$ 50.00 40/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Re-set Frt ABS System			\$ 200.00 40/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 40/-
	Remove/Refix Dashboard			\$ 450.00 150/-
	Remove/Refix Fuse Box		1780.00	\$ 180.00 50/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 40/-
	TOTAL LABOUR			\$ 4,180.00
	ESTIMATE TOTAL			\$ 21,832.88
				21952.88
	05/12/2018 e 1200hrs		13603.20	
	NA Antenna		120.80	
	2/5m 8 ¹⁰ days.	Supp		
			13804.00	
			4/5 11000/-	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK FIELD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7174K (Supplementary)

DATE : 10.12.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Air Cleaner B <i>broken</i>			\$ 151.00
				\$ 151.00
				\$ 30.20
				\$ 120.80
	<p style="text-align: right;">SUB TOTAL</p> <p style="text-align: right;">LESS 20%</p> <p style="text-align: right;">DISCOUNTED TOTAL</p> <p><i>Bryan 10/12/2018</i></p> <p><i>2KK Auto</i></p> <p><i>[Signature]</i></p>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118021889/DTBN2
Date: 04/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3049051802
Claimant Vehicle No:	SHA7174K	Insured Vehicle No:	GBD8089Y
Date of Loss:	01/12/2018	Nature of Claim:	TP
		Claim No:	SNM18D05673C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7174K	Engine No:	D4FDGU613571
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU087792
Reg. Date:	21/04/2016 (Man. Year: 2016)	Odometer:	309197 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,772.88	12,024.00	5,748.88	32.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,780.00	2,400.00	57.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,952.88	13,804.00	8,148.88	37.12
Approved Total (Overridden) (\$\$)		11,000.00		
(\$\$)	21,952.88	11,000.00	10,952.88	49.89
+ GST 7.00/7.00% (\$\$)	1,536.70	770.00	766.70	49.89
Nett Amount (\$\$)	23,489.58	11,770.00	11,719.58	49.89

INSPECTION

Date of Assignment:	06/12/2018	
Date Inspected:	05/12/2018	Inspected At: CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047

Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2019)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7174K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Broken	1,052.20 FL	*1,052.20 FL
2	1		*FRONT BUMPER BRACKET TOP (RH)	Not Necessary	22.40 FL	*- FL
3	1		*FRONT BUMPER BRACKET (LH)	Broken	24.60 FL	*24.60 FL
4	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
5	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
6	1		*HEADLAMP (LH)	Broken	1,388.00 FL	*1,388.00 FL
7	1		*HEADLAMP HALOGEN BULB (LH)	Not Necessary	14.40 FL	*- FL
8	1		*FRONT FENDER (LH)	Buckled	566.30 FL	*566.30 FL
9	1		*FRONT FENDER APRON PANEL (LH)	Buckled	637.00 FL	*637.00 FL
10	1		*FRONT FENDER SHIELD (LH)	Torn	174.90 FL	*174.90 FL
11	1		*AIR CLEANER BOTTOM ASSY	Broken	325.00 FL	*325.00 FL
12	1		*FRONT WHEEL RIM (LH)	Distorted	325.30 FL	*325.30 FL
13	1		*FRONT WHEEL HUB CAP (LH)	Cut	107.10 FL	*107.10 FL
14	1		*FRONT WHEEL BEARING	Damaged	150.90 FL	*150.90 FL
15	1		*FRONT SHOCK ABSORBER (ASSY)(LH)	Distorted	342.20 FL	*342.20 FL
16	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*- FL
17	1		*FRONT DRIVE SHAFT (LH)	Damaged	1,030.80 FL	*1,030.80 FL
18	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
19	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
20	1		*STABILIZER BAR	Distorted	252.30 FL	*252.30 FL
21	1		*STABILIZER BAR BUSH (LH)	Not Necessary	16.40 FL	*- FL
22	1		*STABILIZER BAR LINK	Distorted	61.10 FL	*61.10 FL
23	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	*- FL
24	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	529.30 FL	*529.30 FL
25	1		*KNUCKLE ARM (LH)	Distorted	552.00 FL	*552.00 FL
26	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*- FL
27	1		*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	*2,094.40 FL
28	1		*INTER COOLER	Not Necessary	1,032.50 FL	*- FL
29	1		*INTER COOLER MOUNTING (2PCS)	Not Necessary	25.90 FL	*- FL
30	1		*ABS SENSOR,LH	Not Necessary	234.00 FL	*- FL
31	1		*WIRING-ENGINE	Mounting Broken	3,326.00 FL	*3,326.00 FL
32	1		*ELECTRIC POWER STEERING	Not Necessary	4,880.50 FL	*- FL
33	1		*AIR CLEANER B	Broken	151.00 FL	*151.00 FL
34	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	22,162.10	15,030.00
- List Item Discount on L Items 20.00/20.00% (S\$)	4,389.22	3,006.00
Total Parts (S\$)	17,772.88	12,024.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	700.00
2	SPRAY PAINTING CHARGE	New	750.00	600.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	TOWING CHARGE	New	50.00	-
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	RE-SET FRT ABS SYSTEM	New	200.00	-
9	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	-
10	REMOVE/REFIX DASHBOARD	New	450.00	150.00
11	REMOVE/REFIX FUSE BOX	New	180.00	50.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	-
Gross Labour Cost (\$\$)			4,180.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >