Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012821/GVBE2-1

Date: 11/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. A28786683MCY Policy No:

Claimant Vehicle SKA1068M Insured Vehicle No: SKM46U

No:

TP Date of Loss: 07/07/2018 Nature of Claim: Claim No: 564214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA1068M**

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B3518554 Reg. Date: 24/04/2015 (Man. Year: 2015) Chassis No: RU11018540 Colour: Odometer: 140387 km Blue

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

215/60 R16 Front Tyre Size: 215/60 R16 Rear Tyre Size: Front Left Side: Rear Left Side: Linglong 6 mm Linglong 6 mm Rear Right Side: Linglong 6 mm Front Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,533.50	3,011.20	2,522.30	45.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,120.00	1,430.00	2,690.00	65.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,653.50	4,441.20	5,212.30	53.99
Approved Total (Overridden) (S\$)		3,550.00		
Nett Amount (S\$)	9,653.50	3,550.00	6,103.50	63.23

INSPECTION

Date of Assignment: 16/07/2018

Date Inspected: 06/12/2018 Inspected At: Jd Motorsports Pte Ltd (HQ)

25 KAKI BUKIT ROAD 4, #06-38

SYNERGY@KB Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG Manager: VERON CHEN Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Dec 2018)

Parts: M1-SUV HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SKA1068M)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR (CTR) BUMPER	Replaced	880.00 F	*880.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Replaced	74.00 F	*74.00 FL
3	1		*SET REAR BUMPER FASTENERS	Replaced	35.00 F	*35.00 FL
4	1		*REAR UNDER COVER	Reuse	162.00 F	*- FL
5	1		*SET REAR UNDER COVER FASTENERS	Replaced	32.00 F	*32.00 FL
6	1		*TAILGATE	Replaced	1,450.00 F	*1,200.00 FL
7	1		*TAILGATE LOGO EMBLEM	Replaced	32.00 F	*32.00 FL
8	1		*TAILGATE VEZEL EMBLEM	Replaced	56.00 F	*56.00 FL
9	1		*TAILGATE INNER LOCK	Not Necessary	280.00 F	*- FL
10	1		*TAILGATE WEATHERSTRIP	Replaced	135.00 F	*135.00 FL
11	1		*REAR WINDSCREEN MOULDING	Replaced	145.00 F	*145.00 FL
12	1		*REAR EXHAUST CHROME	Not Necessary	97.50 F	*- FL
13	1		*REAR WARNING BUZZER	Not Necessary	75.00 F	*-FL
14	1		*REAR END PANEL ASSY	Repaired	580.00 F	*- FL
15	1		*SET REVERSE SENSOR	Replaced	300.00 FS	*200.00 FS
16	1		*REAR BUMPER GUARD	Replaced	800.00 FS	*500.00 FS
17	1		*REAR BUMPER SCUFF PLATE	Replaced	180.00 FS	*120.00 FS
18	1		*TAILGATE BOTTOM CHROME MOULDING	Replaced	100.00 FS	*80.00 FS
19	1		*TUBE REAR END PANEL SEALANT	Not Necessary	60.00 FS	*-FS
20	1		*TUBE REAR WINDSCREEN SEALANT	Replaced	60.00 FS	*40.00 FS
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.			
				Sub Total (S\$)	5,533.50	3,529.00
			Liet Hom Discount on Lite	0 00/00 000/ (CA)	0.00	

- List Item Discount on L Items 0.00/20.00% (S\$) 0.00 517.80

Total Parts (S\$) 5,533.50 3,011.20

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	_abour Items						
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,820.00	500.00			
2	TO CHECK WIRING AND REWIRE	New	80.00	30.00			
3	TO REMOVE AND REINSTALL TAILGATE COMPONENTS }	New	80.00	60.00			
4	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY }	New	120.00	0.00			
5	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	250.00	100.00			
6	TO REMOVE AND REINSTALL REVERSE SENSOR	New	140.00	40.00			
7	TO REMOVE AND REINSTALL REVERSE CAMERA	New	160.00	40.00			
8	TO REMOVE AND REINSTALL REAR EXHAUST MUFFLER	New	120.00	0.00			
9	TO ANTI-RUST	New	150.00	60.00			
10	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	1,200.00	600.00			
	Gross Labour Cost (S\$)		4,120.00	1,430.00			
	Report was unsubmitted during	this print-out.					

< END OF ESTIMATES >