

15/5/2011

INS. CASE OWNER:

CC /EQI1802

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(VL: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OLGIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE. Date/Time: 22/11/19

Sent By: VIC

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: L9 \$5 6,050.00

(5 days) Reduction: 65 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

SS

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 6,050.00

Loss of Rental (LOR):

SS

700.00

(

5

x

days)

X \$100

Loss of Use (LOU):

SS

—

(

5

x

days)

Loss of Income (LOI):

SS

—

(

5

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

—

Disbursement:

SS

—

(e.g. Tow/ Independent)

Legal Cost

SS

—

Total:

SS 6,757.45

Global Sum SS: —

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

6,757.45

Name 1:

ZOOM AUTOWORKS PTE LTD

Payee 2: (Strike if N.A.)

SS

—

Name 2:

—

Payee 3: (Strike if N.A.)

SS

—

Name 3:

—

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$100.00

b/c
2/12/17
ow



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ18021897/Ueb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 05-12-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 280H		Veh. Inspected	SLD 4945J
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	05/12/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
4. Description of Damages				
5. General Information				
Accident Date	03/12/2018		Inspection Date	05/12/2018
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

D.O.A : 3rd December 2018

4th December 2018

OWNER : Muhammad Izaq Fazrul Bin Sulaiman

REG. NO. : SLD 4945 J

MAKE/MODEL : HONDA VEZEL

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMOUNT(S\$)
	LIST ITEMS	
1	Rear Windscreen Moulding	\$ 121.80
1	Rear Tailgate 95-3	\$ 1100.50
2	Rear Tailgate Dampers	\$ 331.60
1	Rear Tailgate Inner Trim Board	\$ 225.00
1	Rear Tailgate Inner Pull Pocket	\$ 32.00
2	Rear Tailgate Lamps	\$ 570.00
1	Rear Tailgate Lock	\$ 269.50
1	Rear Tailgate Logo	\$ 40.30
1	Rear Tailgate Rubber	\$ 227.00
1	Rear Tailgate Opening Switch Set	\$ 175.00
1	Rear Tailgate "VEZEL" Emblem	\$ 56.20
2	Rear Taillamp 460.50 x 2 = 921	\$ 1360.00
2	Rear Taillamp Panel	\$ 310.00
1	Rear End Panel	\$ 533.70
1	Rear End Panel Inner Garnish	\$ 140.50
1	Rear Keyless Sensor	\$ 189.50
1	Rear Bumper 762-70	\$ 863.50
1	Rear Bumper - Side	\$ 225.30
1	Rear Bumper Brackets	\$ 97.00
1	Rear Bumper Lower Garnish	\$ 325.00
2	Rear Bumper Reflector 150	\$ 303.80
1	Rear Bumper Side Retainer	\$ 50.90
1	Rear Floor Board	\$ 187.60
1	Rear Floor Panel	\$ 1,145.70
1	Rear Exhaust Silencer	\$ 840.30
2	Rear Exhaust Mountings	\$ 49.00
2	Rear Fenders	\$ 3,001.40
2	Rear Fender Air Gate	\$ 96.00
2	Rear Fender Wheel Housing	\$ 1,370.00

2 Rear Fender Inner Shield	\$ 17	299.60	X
2 Rear Fender Inner Trim Board 245	\$ 0/57m	490.00	176
2 Rear Fender Wheel Arch Garnish	\$ 20/70m	601.40	—
2 Rear Fender Quarter Glass Moulding	\$ 17	230.00	X
	\$	14,859.10	5905
LESS 20%	\$	2,971.82	4724
	\$	11,887.28	

SPECIAL NETT ITEMS

1 Rear Windscreen Sealant	\$ nu	80.00	40
1 Rear Bumper Clip (1 Set)	\$ nu	45.00	✓
1 Rear Reverse Camera	\$ shud	380.00	300
1 Rear Reverse Sensor (1 Set)	\$ shud	350.00	200
	\$	855.00	

S/N

LABOUR CHARGES

1	To remove, replace damaged lamps & check up wiring	\$	80.00	20
2	To remove & refit inner garnishes	\$	150.00	80
3	To remove & refit rear reverse sensor	\$	150.00	50
4	To remove & refit rear reverse camera	\$	150.00	—
5	To transfer rear tailgate mechanism & wiring assembly	\$	120.00	60
6	To remove & refit rear windscreen glass	\$	180.00	120
7	To remove, refit & replace exhaust silencer & mountings	\$	150.00	60
8	To apply undercoating	\$	200.00	80
9	Panel Beating	\$	1,800.00	800
10	To re-spray the affected areas	\$	1,600.00	1000
		\$	4,580.00	7529
		\$	17,322.28	

LK's Auto Consultants hence notify
the Repairer of the following:

- To inspect & before after spray painting
- To replace damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Catherine Chong (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Wednesday, 5 December, 2018 10:40 AM
To: 'assignments'
Cc: Admin A
Subject: RE: Pre-Repair Inspection for SLD 4945 J // Accident on 03/12/2018 @ 11:00HR at along Junction of Seletar West Link & Seletar Aerospace Drive involving Vehicle Number SLD 4945 J & GBE 280 H
Attachments: New Doc 2018-12-04 14.44.19.pdf; EQIC-MARS00003015-GBE280H-GIA.PDF

Dear Catherine,

Attach both parties report.

Liability is cleared, proceed to direct settle if possible.

Regards,

Janet Tan
Senior Executive | Claims

05.12.2018 @ 11:55am
Elin veh in.

Marius



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]
Sent: Wednesday, December 5, 2018 10:37 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: Re: Pre-Repair Inspection for SLD 4945 J // Accident on 03/12/2018 @ 11:00HR at along Junction of Seletar West Link & Seletar Aerospace Drive involving Vehicle Number SLD 4945 J & GBE 280 H

Dear Janet,

Please arrange LKK.

On Wed, Dec 5, 2018, 10:36 Janet Tan <janet.tan@eqinsurance.com.sg> wrote:

Without Prejudice

Save As To Costs

Dear Elin,

For pre repair survey request, please email to eqiprs@eqinsurance.com.sg

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee

9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070
11) Infiniti Appraisal Service Tel : 96684818/90099001 Fax: 64587432	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify i

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]

Sent: Tuesday, December 4, 2018 2:57 PM

To: EQI PRS <EQIPRS@eqinsurance.com.sg>

Subject: Pre-Repair Inspection for SLD 4945 J // Accident on 03/12/2018 @ 11:00HR at along Junction of Seletar West Link & Seletar Aerospace Drive involving Vehicle Number SLD 4945 J & GBE 280 H

Dear Sir/Madam,

We are instructed by Muhammad Izaq Fazrul Bin Sulaiman to notify you of a road traffic accident on 03/12 /2018

at about 11:00HR at along Junction of Seletar West Link & Seletar Aerospace Drive involving our client's vehicle registration number

SLD 4945 J

and vehicle registration number GBE 280 H driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178 08.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 20 December 2018 3:02 PM
To: 'Zoomautowerks@gmail.com'
Subject: Accident Involving SLD 4945J & GBE 280H on 03/12/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: SLD 4945J
Our Ref: CC4/EQI18021897/Ueb3

Dear Sir/Madam,

Accident Involving SLD 4945J & GBE 280H on 03/12/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ18021897/Uhb3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 10-12-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 280H	Veh. Inspected	SLD 4945J	
Policy No.	DMCPHQ18-004829	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	RU11115701	Colour	SILVER	
Odometer	071220	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	7 mm	
L/H Front Tyre	215/60 R16	DUNLOP	7 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2018	Inspection Date	05/12/2018	
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 4945J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	121.80	121.80
1	REAR TAILGATE	BADLY DENTED	100.50	953.00
2	REAR TAILGATE DAMPERS	NOT NECESSARY	331.60	-
1	REAR TAILGATE INNRT TRIM BOARD	DEFORMED / CRACKED	225.00	225.00
1	REAR TAILGATE INNER PULL POCKET	NOT NECESSARY	32.00	-
2	REAR TAILGATE LAMPS	NOT NECESSARY	570.00	-
1	REAR TAILGATE LOCK	TWISTED / BENT	269.50	269.50
1	REAR TAILGATE LOGO	NOT NECESSARY	40.30	-
1	REAR TAILGATE RUBBER	TWISTED	227.00	227.00
1	SET REAR TAILGATE OPENING SWITCH	NOT NECESSARY	175.00	-
1	REAR TAILGATE "VEZEL" EMBLEM	NECESSARY	56.20	56.20
2	REAR TAILLAMP	CRACKED	1,360.00	921.00
2	REAR TAILLAMP PANEL	TO REPAIR SEE LABOUR	310.00	-
1	REAR END PANEL	DENTED	533.70	533.70
1	REAR END PANEL INNER GARNISH	TWISTED	140.50	140.50
1	REAR KEYLESS SENSOR	NOT NECESSARY	189.50	-
1	REAR BUMPER	DENTED	863.50	762.70
1	REAR BUMPER - SIDE	DENTED / DEFORMED	225.30	225.30
1	REAR BUMPER BRACKETS	BENT	97.00	97.00
1	REAR BUMPER LOWER GARNISH	TWISTED / TORN	325.00	325.00
2	REAR BUMPER REFLECTOR	O/S CRACKED	303.80	150.00
1	REAR BUMPER SIDE RETAINER	BENT	50.90	50.90
1	REAR FLOOR BOARD	NOT NECESSARY	187.60	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,145.70	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	840.30	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	49.00	-
2	REAR FENDERS	TO REPAIR SEE LABOUR	3,001.40	-

Report Ref No. CC4/EQ18021897/Uhb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER AIR GATE	NOT NECESSARY	96.00	-
2	REAR FENDER WHEEL HOUSING	NOT NECESSARY	1,370.00	-
2	REAR FENDER INNER SHIELD	NOT NECESSARY	299.60	-
2	REAR FENDER INNER TRIM BOARD	O/S TWISTED	490.00	245.00
2	REAR FENDER WHEEL ARCH GARNISH	DEFORMED / TORN	601.40	601.40
2	REAR FENDER QUARTER GLASS MOULDING	NOT NECESSARY	230.00	-
	LESS 20% DISCOUNT		-2,971.82	-1,181.00
			11,887.28	4,724.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	REAR REVERSE CAMERA (SN)	SHORTED	380.00	300.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
			855.00	585.00
	<u>LABOUR</u>			
	TO REMOVE, REPLACE DAMAGED LAMPS & CHECK UP WIRING.		80.00	20.00
	TO REMOVE & REFIT INNER GARNISHES.		150.00	80.00
	TO REMOVE & REFIT REAR REVERSE SENSOR. }		150.00	50.00
	TO REMOVE & REFIT REAR REVERSE CAMERA. }		150.00	-
	TO TRANSFER REAR TAILGATE MECHANISM & WIRING ASSEMBLY.		120.00	60.00
	TO REMOVE & REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE, REFIT & REPLACE EXHAUST SILENCER & MOUNTINGS.		150.00	60.00
	TO APPLY UNDERCOATING.		200.00	80.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR TAILLAMP PANEL, REAR FLOOR PANEL, REAR EXHAUST SILENCER AND REAR FENDERS.		1,800.00	800.00
	TO RE-SPRAY THE AFFECTED AREAS.		1,600.00	1,000.00
			4,580.00	2,270.00
	GRAND TOTAL		17,322.28	7,579.00

Report Ref No. CC4/EQ18021897/Uhb3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,050.00
---	--	--	----------

Report Ref No. CC4/EQ118021897/Uhb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.