

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 5819X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID EMBLE LOGO (CONSISTENT)	NECESSARY	48.00	48.00
1	REAR BOOT LID CRUZE LOGO (CONSISTENT)	NECESSARY	45.00	45.00
1	REAR BOOT LID CHEVROLET LOGO (CONSISTENT)	NECESSARY	38.00	38.00
1	REAR BOOT LID NUMBER PLATE (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR BOOT LID INNER LOCK (CONSISTENT)	NOT NECESSARY	385.00	-
1	REAR BOOT LID INNER RUBBER (CONSISTENT)	NOT NECESSARY	188.00	-
1	REAR BOOT LID SIDE REFLECTOR -LH (CONSISTENT)	NOT NECESSARY	420.00	-
1	REAR TAIL LAMP -LH (CONSISTENT)	CRACKED	320.00	320.00
4	REAR TAIL LAMP CLIPS @\$5.00 (CONSISTENT)	NECESSARY	20.00	10.00
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,450.00	1,151.00
2	REAR BUMPER SIDE BRACKET @\$67.00 (CONSISTENT)	NECESSARY	134.00	134.00
10	REAR BUMPER CLIPS @\$5.00 (CONSISTENT)	NECESSARY	50.00	30.00
1	REAR BUMPER REVERSE SENSOR (CONSISTENT)	DAMAGED	350.00	200.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	700.00	689.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$145.00 (CONSISTENT)	NOT NECESSARY	290.00	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	968.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	283.00	-
	LESS 10% DISCOUNT		-	-266.50
			5,739.00	2,398.50
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	GUM .	NOT NECESSARY	50.00	-
	TO REMOVE & REFIX CUSHION.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIX REVERSE SENSOR .		100.00	50.00
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TUFF KOTE.		120.00	40.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		800.00	300.00

Report Ref No. CC4/ASM18021907/Aga3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPRAY PAINTING .		800.00	500.00
			2,170.00	920.00
	GRAND TOTAL		7,909.00	3,318.50

RECOMMENDED COST OF LUMP SUM REPAIRS		2,650.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM18021907/Aga3q2



**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.