



Case Details

Case Reference Number : TAX/12/18/2010
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4803M

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4807-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 03/12/2018 03:30 AM
 Vehicle Age(In Months) : 30

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95 <i>del</i>	Replace ▾
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08 <i>del</i>	Replace ▾
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00 <i>del</i>	Replace ▾
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0 <i>X</i>	Not Give ▾
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0 <i>X</i>	Not Give ▾
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0 <i>X</i>	Not Give ▾
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0 <i>?</i>	Check ▾
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10 <i>del</i>	Replace ▾
Total Spare Part Cost									1,092.08		Surveyor Total	547.13	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									1,092.08		Final Sur Total	547.13	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	-----------	-------------------------	-------------------------	---------

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH REAR PORTION	388.00	200	
Total:		388.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	0	
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
2	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
3	TO WASH AND VACUUM	60.00	0	
4	TO REPLACE SUNDRY PARTS	100.00	20	
Total:		360.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,092.08	547.13
Total Labour Cost	388.00	200.00
Total Spray Painting	558.00	200.00
Other	360.00	80.00
Overall Total	2,398.08	1,027.13
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,027.13
Surveyor Approved Amount		1,027.13
No of Repair Days*	3	2

Estimator Assesment(\$)	Surveyor Assesment(\$)
Remarks	Resurvey before paint
Surveyor Name	Taufikh
Signature	
Survey Date	04/12/2018
Save Clear	

Taufikh 97495949
-WP-

4/12/18

2 days

Resurvey before paint

sur @ lkkauto.com

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: