

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA9096P

DATE: 4. Dec. 2018

MAKE : HYUNDAI

DOA: 3. Dec. 2018

MODEL : i40

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Door – LH <i>X repa</i>			\$2,201.10
1	Rocker Cover Garnish – LH <i>X repa</i>			\$341.10
1	Rear Bumper <i>Refound</i>			\$544.50
10	Rear Bumper Clips <i>new</i>		\$2.20	\$22.00
1	Rear Wheel Cover – LH <i>new</i>			\$107.10
SUB TOTAL				\$3,215.80
LESS 20%				\$643.16
DISCOUNTED TOTAL				\$2,572.64
1	Rear Door APP sticker <i>new</i>			\$80.00
1	Rear Bumper Rubber Mat <i>new</i>			\$50.00
				Nett
				Nett
				\$130.00
Labour Charge				
1	Panel Beating			\$600.00 <i>400</i>
1	Spray Painting Charge			\$900.00 <i>800</i>
1	Tuff Kote			\$50.00 <i>X 1.4</i>
1	Remove/refix reverse sensor			\$120.00 <i>30</i>
1	Transfer of Door			\$120.00 <i>X 2.1</i>
TOTAL LABOUR				\$1,790.00
ESTIMATE TOTAL				\$4,492.64
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "No Fault Prejudice" basis
- No illegal modification(s) is allowed
- No supplementary item(s) must be resurveyed and approved by the Insurance Company

TOTAL LABOUR

ESTIMATE TOTAL

Date:

Larry Ng

Kah (114)

4/12/18 1020h

3 Pys

4s

After Repair p/h