

Surveyor

Marus.

REF: ALH

ASSIGNMENT

From: Date: 13.12.2018

Estimated Cost:

OD (P) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBK 2125D

at Workshop m/s A.S. Phoon

of Blk 3007 Ubi Rd 1 #01-436

Insured: 52121909J

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr. Kee

(Policy Condition)

1030um

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 7500

IDAC Accident Rpt: Consistent? : Yes or No

C/A / PR Seen Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

2694C

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction LTA 3710
6 yrs 6 mth.

Veh No: FBK 2125D Yr Regn: 5-115

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: P. 9.0 IME

C.C 148

Colour: red

A/C: Insured / Std / NI / NA

Sp. Reading: 23/75

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PFVBF 3C5CF100 0157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 120/70-12

R: 4.80 - 12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Duro

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. mm

L/Bal. 6 mm

D.O.A. 24.1/18

D.O.I. 13/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

) S + RS. SI

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL