

SMC2635K [SKH6372P1] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



1/87: Rear View



2/87: Rear View Left



3/87: Rear View Right

TOYOTA MOTOR CORPORATION JAPAN

MODEL DAA-ZYX10-AHXB-A

ENGINE 2TR-E

DISPL 1797 mL

SERIAL NO. 11912

PLANT OTUN

1K0 FC2U H3

166

P610 -03A

A photograph showing the rear three-quarter view of a silver Toyota Aygo. The car is parked on a light-colored floor, possibly in a showroom or exhibition space. The rear features a prominent black plastic bumper, a small black roof rack, and a distinctive rear light assembly. The car's design is compact and modern.

https://singapore.merimen.com/claims/index.cfm?fusebox=SVCdoc&fuseaction=dsp_... 10/15/2018

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



7/87: General View



8/87: General View



9/87: General View

SMC2635K [SKH6372P1] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



10/87: General View



11/87: General View



12/87: General View

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/87: General View



14/87: General View



15/87: General View

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



16/87: General View



17/87: General View



18/87: General View

SMC2635K ISKH6372P1 - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



19/87: General View



20/87: General View



21/87: General View

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



22/87: General View



23/87: General View



24/87: General View

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



25/87: General View



26/87: General View



27/87: General View

SMC2635K [SKH6372P1] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



28/87: General View



29/87: General View



30/87: General View

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



31/87: Reinspection Photo



32/87: Reinspection Photo



33/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



34/87: Reinspection Photo



35/87: Reinspection Photo



36/87: Reinspection Photo

SMC2635K ISKH6372P1 - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



37/87: Reinspection Photo



38/87: Reinspection Photo



39/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



40/87: Reinspection Photo



41/87: Reinspection Photo



42/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



43/87: Reinspection Photo



44/87: Reinspection Photo



45/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



46/87: Reinspection Photo



47/87: Reinspection Photo



48/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



49/87: Reinspection Photo



50/87: Reinspection Photo



51/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



52/87: Reinspection Photo



53/87: Reinspection Photo



54/87: Reinspection Photo

SMC2635K [SKH6372P1] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



55/87: Reinspection Photo



56/87: Reinspection Photo



57/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



58/87: Reinspection Photo




59/87: Reinspection Photo



60/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



61/87: Reinspection Photo



62/87: Reinspection Photo



63/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



64/87: Reinspection Photo



65/87: Reinspection Photo



66/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



67/87: Reinspection Photo



68/87: Reinspection Photo



69/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



70/87: Reinspection Photo



71/87: Reinspection Photo



72/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



73/87: Reinspection Photo



74/87: Reinspection Photo



75/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



76/87: Reinspection Photo



77/87: Reinspection Photo



78/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



79/87: Reinspection Photo



80/87: Reinspection Photo



81/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



82/87: Reinspection Photo



83/87: Reinspection Photo



84/87: Reinspection Photo

SMC2635K [SKH6372P] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



85/87: Reinspection Photo



86/87: Reinspection Photo



87/87: Reinspection Photo