

INSURANCE

INS. CASE OWNER:

1001

CC 3/EQ1802 2005, Ag/My

LKK:

IDAC:

Surveyor:

Advan

DOI:

ASSIGNMENT

15/12/18

Date / Time:

6/12/18

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GR4 98 2E

Name of Insured:

RANTR FIRE SYSTEMS PTE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

11/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SOPIHAN BIN KHAWAB REPAIRER

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L YES / NO)

Insured Liability:

%

Final? Yes / No

524081K



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

che  
Fulco



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

6/12/18  
9PM

MA - send lor

16/10 - File Pass RT type report  
21/10 - Pending mandate approval (approved)  
- after 13,011-40 (Pending acceptance)  
- after 13,011-40, file pass to send by

STAGE

DATE / PIC

Non-Reporting Ir (1st):  
Non-Reporting Ir (2nd):  
Non-Reporting Ir (Final):  
Notification Ir (if non-pickup):  
Call OH  
After call Ir to OH

Documentation Check List: Handler Typist

Notification Ir (if non-pickup) ☒  
After call Ir to OH ☒  
Authorisation To Act ☒  
Release Voucher ☒  
Final Repair Bill ☒  
Car Rental Invoice ☒  
Towing Invoice ☒  
LTA / GIA ☒  
Medical Bill ☒  
PIR ☒  
Mandate/Reject Instruction ☒  
LOD ☒  
Payment Breakdown Form ☒  
Post-Repair Photos ☒  
Others ☒

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PIP \$5 11,340.00, 5 days Reduction: \$1021 = \$4

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

\$100 (Agreed / Assessed) BOLA S/N No.: 27

Repair Cost:

(W/OST) \$5 12,026.20

Loss of Rental (LOR):

\$5 612.00, 5 days x \$122.40 (W/OST)

Loss of Use (LOU):

\$5 - (S x days)

Loss of Income (LOI):

\$5 - (S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search:

\$5 2.00

Medical:

\$5 2779.15

Disbursement:

\$5 - (e.g. Tow/Independent)

Legal Cost:

\$5 -

Total:

\$5 15,009.95

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

\$5 13,009.95

Name 1:

Cycle & Carriage Tulko Motor Dealer Pte Ltd

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

OK  
ATM/OK

COMMENT

1) Claim status: Normal/Reject/Private Settle  
2) Report Format: TP  
3) Survey fee: \$400.00

REF: EOL

## ASSIGNMENT

From: Date 13.12.2018

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLZ 4081K

at Workshop no:

Cycle & Carriage  
330 Ubi Rd 3

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

MORG

(Policy Condition)

10am

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lump Sum:

100%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No SLZ4081K - Yr Regn: 2018 May.

Type: M/Car M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Sorento

C.C. 2199.

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp Reading:

15911

T/Radio: Insured / Std / NI / NA

Eng/No:

ChNo:

KNA P1481BMJS448734.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/60R18

R:

235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A:

D.O.I:

13/12/18

Survey held at

Cycle and Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP EQ.

28-1-19 \$11,240.

(Red = \$2700 / 44%)

Date/Time, File Pass to:

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to:

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. \$ + RS. 2.

1. Phone

1. Other

TOTAL

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/EQ118022005/Ajb3

Date: 14.12.2018

The Motor Claims Department  
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLZ4081K**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.12.2018 at the premises of M/s Cycle & Carriage Fulco Motor Dealer Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	19,570.00
Revised Estimate Amount	: S\$	10,889.00
"Check" Items Amount	: S\$	3,236.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

ADRIAN LING  
Licensed Appraiser

\$19,942.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ18022005/jb3

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 06-12-2018



Code : EQI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 982E	Veh. Inspected	SLZ 4081K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/12/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	30/11/2018	Inspection Date	
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



**CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

REPAIRER CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD - EUNOS LINK SERVICE CENTRE

**MOTOR VEHICLE CLAIM DISCHARGE VOUCHER**

ATTN: **EQ INSURANCE COMPANY LIMITED**

5 Maxwell Road #17-00

Tower Block, MND Complex,

Singapore 069110

OWNER	: <u>SYED AMEERUDIN S/O SYED RAFAEUDDIN</u>	VEHICLE NO	: <u>SLZ4081K</u>
VEHICLE MODEL	: <u>KIA/SORENTO 2.2A</u>	THIRD PARTY #	: <u>GBG982E</u>
ACCIDENT DATE	: <u>30/11/2018</u>	WIP NO	: <u>14758</u>

I/WE CERTIFY THAT THE VEHICLE HAS BEEN FULLY REPAIRED TO MY ENTIRE SATISFACTION AND THE PAYMENT OF REPAIRER'S CHARGES ARE CLAIMABLE UNDER THE POLICY WILL BE DEEMED IN FULL AND THE FINAL SETTLEMENT OF MY CLAIMS.

OWNER/INSURED SIGNATURE

DATE : \_\_\_\_\_

TIME : \_\_\_\_\_



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110	Cust No/Name LCV05433/Mr Syed Ameerudin S/O Syed Rafe Reg No/Reg Date SLZ4081K / 02/05/2018 Date In/Mileage 17/12/2018/ 16058 Chassis No KNAPH81BMJ5448734 Engine No D4HBJH364710 Make/Model KIA/SORENTO 2.2 A SX SR GDCO Colour/Trim B4U / WK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000061	Credit	29/12/2018/ 09:42	DS	218 / MarsLer	14758		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	SUNDRY						50.00
	C & C LOGO						
S	MIPNT88088						80.00
	TO CHECK REAR LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS						
S	MIPNT88088						300.00
	TO REMOVE & RE-INSTALL ALL CARPET,TRIMMINGS & REAR SEAT TO GIVE WAY ACCESS FOR REPAIR						
S	MIPNT88088						300.00
	TO INSTALL NEW TAILGATE GLASS TO NEW TAILGATE PANEL						
S	MIPNT88088						100.00
	SEALANT KIT FOR TAILAGTE GLASS						
S	MIPNT88088						220.00
	TO INSTALL RIKE COOL FILM FOR NEW TAILGATE GLASS						
S	MIPNT88088						250.00
	TO CONDUCT COMPUTER DIAGNOSTIC,PROGRAMMING, & RESETTING						
S	MIPNT88088						300.00
	TO TRANSFER ALL DOOR COMPONENTS & MECHANISM						
S	MIPNT98088						1800.00
	SPRAY PAINTING ON REAR ACCIDENT NEW PANELS & ACCIDENT REPAIRED AREAS						
	TAILGATE,REAR BUMPER,RR END PNL,BOTH RR FENDER REAR SPOILER						
S	MIPNT88088						1470.00
	TO REPLACE DAMAGED PARTS CUT & WELD REAR END PANEL STRAIGHTEN,REFORM,ALIGN REAR ACCIDENT AFFECTED AREAS						
M	SUNDRY						250.00
	JERGA DETAILS (CAR PAINT RECTIFICATION AND SERVICES) -REAR END PANEL						

Confirm &amp; accepted by

Finalization 29/12/18

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110	Cust No/Name LCV05433/Mr Syed Ameerudin S/O Syed Rafe Reg No/Reg Date SLZ4081K / 02/05/2018 Date In/Mileage 17/12/2018/ 16058 Chassis No KNAPH81BMJ5448734 Engine No D4HB3H364710 Make/Model KIA/SORENTO 2.2 A SX SR GDCO Colour/Trim B4U / WK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000061	Credit	29/12/2018/ 09:42	DS	218 / MarsLer	14758
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
-REAR WINDSCREEN					
X KS 73700 C5 121	PANEL ASSY-TAIL GATE	1.00	1445.00	0.00	1445.00
X KS 87110 C5 000	GLASS ASSY - TAILGAT	1.00	690.00	0.00	690.00
M KS 86114 2L 000	PAD-WINDSHIELD	4.00	17.00	0.00	68.00
M KS 86114 3D 000	PAD-W/SHLD GLASS	6.00	2.00	0.00	12.00
M KS 87115 C5 000	STOPPER T/GLASS	2.00	4.00	0.00	8.00
X KS 92700 C5 000	LAMP ASSY - HIGH MOU	1.00	212.00	0.00	212.00
X KS 86310 C5 010	EMBLEM-SORENTO	1.00	28.00	0.00	28.00
X KS 86333 C5 000	EMBLEM - ECO DYNAMIC	1.00	37.00	0.00	37.00
X KS 86611 C5 510	UPR COVER-RR BUMPER	1.00	605.00	0.00	605.00
X KS 86612 C5 500	LWR COVER - REAR BUM	1.00	565.00	0.00	565.00
X KS 86665 C5 510	SKID PLATE - REAR BU	1.00	90.00	0.00	90.00
X KS 0G032 50 037A	FASTERNER- BUMPER	10.00	2.00	0.00	20.00
X KS 96890 C5 500B 4U	ULTRASONIC SENSOR	2.00	187.00	0.00	374.00
X KS 86630 C5 510	RAIL ASSY-REAR BUMPE	1.00	341.00	0.00	341.00
X KS 86661 C5 000	BRACKET ASSY - REAR	1.00	25.00	0.00	25.00
X KS 86662 C5 000	BRACKET ASSY - REAR	1.00	25.00	0.00	25.00
X KS 92405 C5 510	LAMP ASSY-REAR FOG &	1.00	129.00	0.00	129.00
X KS 92406 C5 510	LAMP ASSY-REAR FOG &	1.00	129.00	0.00	129.00
X KS 86683 C5 500	HOLDER-PARKING ASSIS	2.00	5.00	0.00	10.00
X KS 86667 C5 500	CAP-TOW HOOK	1.00	8.00	0.00	8.00
X KS 28710 C5 811	EXHAUST ASSY	1.00	1177.00	0.00	1177.00
X KS 98811 3W 100	REAR WIPER ARM <i>changed</i>	1.00	53.00	0.00	53.00
X KS 86320 C5 100	EMBLEM-KIA <i>new</i>	1.00	69.00	0.00	69.00
Z NOTES					
ACCIDENT ON 30/11/2018 ALONG PASIR RIS DR 12					
OWNER CLAIMING THIRD PARTY					
REQUIRED REPLACEMENT CAR (R/A-22008)					
TP # GBG982E TP INSURER : EQ INSURANCE					

Confirm &amp; accepted by

*Finalization**29/12/18*

Authorized signatory and company stamp

Parts	6,120.00
Labour	0.00
Standard Menu	0.00
Specialist Job	4,820.00
Others (Lub, etc)	0.00
Sundry	300.00
Total (w/o GST)	11,240.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr SYED AMEERUDIN S/O SYED RAFEEUDD Blk 473 Pasir Ris Drive 6 #09-496 Singapore 510473	Cust No/Name LCV05433/Mr Syed Ameerudin S/O Syed Rafe Reg No/Reg Date SLZ4081K / 02/05/2018 Date In/Mileage 05/12/2018/ 0 Chassis No KNAPH81BMJ5448734 Engine No D4HBJH364710 Make/Model KIA/SORENTO 2.2 A SX SR GOCO Colour/Trim B4U / WK
Contact No Mobile: 81337746	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00001	Cash	06/12/2018/ 08:03	DS	323 / ChrisBulaciac	14758			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDAY								✓ 50.00
C & C LOGO								✓ 80.00
S MIPNT88088								300 1200.00
TO CHECK REAR LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS								✓ 300.00
S MIPNT88088								100 300.00
TO REMOVE & RE-INSTALL ALL CARPET, TRIMMINGS & REAR SEAT TO GIVE WAY ACCESS FOR REPAIR								✓ 220.00
S MIPNT88088								✓ 250.00
TO INSTALL NEW TAILGATE GLASS TO NEW TAILGATE PANEL								300.00
S MIPNT88088								100 300.00
SEALANT KIT FOR TAILGATE GLASS								✓ 220.00
S MIPNT88088								✓ 250.00
TO INSTALL RIKE COOL FILM FOR NEW TAILGATE GLASS								300.00
S MIPNT88088								240 2940.00
TO CONDUCT COMPUTER DIAGNOSTIC, PROGRAMMING, & RESETING								1470
S MIPNT88088								3000.00
TO TRANSFER ALL DOOR COMPONENTS & MECHANISM								
S MIPNT98088								
SPRAY PAINTING ON REAR ACCIDENT NEW PANELS & ACCIDENT REPAIRED AREAS								
TAILGATE, REAR BUMPER, RR END PNL, BOTH RR FENDER REAR SPOILER								
S MIPNT88088								
TO REPLACE DAMAGED PARTS CUT & WELD REAR END PANEL STRAIGHTEN, REFORM, ALIGN REAR ACCIDENT AFFECTED AREAS								
M KS 73700 C5 121				PANEL ASSY-TAIL GATE	1.00	1445.00	0.00	✓ 1445.00
M KS 87110 C5 000				GLASS ASSY - TAILGAT	1.00	690.00	0.00	✓ 690.00
M KS 86114 2L 000				PAD-WINDSHIELD	4.00	17.00	0.00	✓ 68.00
M KS 86114 3D 000				PAD-W/SHLD GLASS	6.00	2.00	0.00	✓ 12.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 30% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





# CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE



CYCLE &amp; CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr SYED AMEERUDIN S/O SYED RAFEEUDD Blk 473 Pasir Ris Drive 6 #09-496 Singapore 510473	Cust No/Name LCV05433/Mr Syed Ameerudin S/O Syed Rafe
Contact No Mobile: 81337746	Reg No/Reg Date SLZ4081K / 02/05/2018
	Date In/Mileage 05/12/2018/ 0
	Chassis No KNAPH81BMJ5448734
	Engine No D4HBJH364710
	Make/Model KIA/SORENTO 2.2 A SX SR GDCO
	Colour/Trim B4U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CSM00001	Cash	06/12/2018/ 08:03	DS	323 / ChrisBulaciac	14758	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M KS 87115 C5 000		STOPPER T/GLASS <i>new</i>	2.00	4.00	0.00	8.00
M KS 87210 C5 000		SPOILER - REAR <i>new</i>	1.00	915.00	0.00	915.00
M KS 92700 C5 000		LAMP ASSY - HIGH MOU <i>changed</i>	1.00	212.00	0.00	212.00
M KS 86310 C5 010		EMBLEM-SORENTO <i>new</i>	1.00	28.00	0.00	28.00
M KS 86333 C5 000		EMBLEM - ECO DYNAMIC <i>new</i>	1.00	37.00	0.00	37.00
M KS 92403 C5 600		LH INNER LAMP <i>new</i>	1.00	827.00	0.00	827.00
M KS 92404 C5 600		RH INNER LAMP <i>new</i>	1.00	827.00	0.00	827.00
M KS 92401 C5 600		LH OUTER COMB LAMP <i>new</i>	1.00	493.00	0.00	493.00
M KS 92402 C5 600		RH OUTER COMB LAMP <i>new</i>	1.00	493.00	0.00	493.00
M KS 92501 3K 000		LAMP ASSY - LICENSE <i>new</i>	2.00	33.00	0.00	66.00
M KS 65910 C5 000		PANEL ASSY-BACK <i>new</i>	1.00	526.00	0.00	526.00
M KS 86611 C5 510		UPR COVER-RR BUMPER <i>new</i>	1.00	605.00	0.00	605.00
M KS 86612 C5 500		LWR COVER - REAR BUM <i>new</i>	1.00	565.00	0.00	565.00
M KS 86665 C5 510		SKID PLATE - REAR BU <i>new</i>	1.00	90.00	0.00	90.00
M JJMR200300		CLIP, BUMPER <i>new</i>	20.00	2.00	0.00	40.00
M KS 96890 C5 500B 4U		ULTRASONIC SENSOR <i>2 piece changed</i>	4.00	187.00	0.00	748.00
M KS 86630 C5 510		RAIL ASSY-REAR BUMPE <i>new</i>	1.00	341.00	0.00	341.00
M KS 91885 C5 030		WIRING HARNESS - R.P <i>new</i>	1.00	240.00	0.00	240.00
M KS 86661 C5 000		BRACKET ASSY - REAR <i>new</i>	1.00	25.00	0.00	25.00
M KS 86662 C5 000		BRACKET ASSY - REAR <i>new</i>	1.00	25.00	0.00	25.00
M KS 92405 C5 510		LAMP ASSY-REAR FOG & <i>new</i>	1.00	129.00	0.00	129.00
M KS 92406 C5 510		LAMP ASSY-REAR FOG & <i>new</i>	1.00	129.00	0.00	129.00
M KS 86653 C5 500		COVER-BLANKING RR FO <i>new</i>	1.00	44.00	0.00	44.00
M KS 86654 C5 500		COVER-BLANKING RR FO <i>new</i>	1.00	44.00	0.00	44.00
M KS 95420 C5 500		ANTENNA ASSY-SMARTKE <i>new</i>	1.00	53.00	0.00	53.00
M KS 86683 C5 500		HOLDER-PARKING ASSIS <i>new</i>	2.00	5.00	0.00	10.00
M KS 85684 C5 500		HOLDER - PARKING ASS <i>new</i>	2.00	5.00	0.00	10.00
M KS 85667 C5 500		CAP-TOW HOOK <i>new</i>	1.00	8.00	0.00	8.00
M KS 85710 C5 811		EXHAUST ASSY <i>new</i>	1.00	1177.00	0.00	1177.00
Z NOIES						
ACCIDENT ON 30/11/2018 ALONG PASIR RIS DR 12						
OWNER CLAIMING THIRD PARTY						
REQUIRED REPLACEMENT CAR						

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



**CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
Mr S ED AMEERUDIN S/O SYED RAFAEUD Blk 73 Pasir Ris Drive 6 #09-06 Singapore 510473	Cust No/Name LCV05433/Mr Syed Ameerudin S/O Syed Rafe Reg No/Reg Date SLZ4081K / 02/05/2018 Date In/Mileage 05/12/2018/ 0 Chassis No KNAPH81BMJ5448734 Engine No D4HBJH364710 Make/Model KIA/SORENTO 2.2 A SX SR GDCO Colour/Trim B4U / WK
Contact No Mobile: 81337746	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	06/12/2018/ 08:03	DS	323 / ChrisBulaclac	14758

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TP # GBG982F TP INSURER : EQ INSURANCE				
<p>Adrian Lij 13/12/18. 05 Days. 07 days → 6th Day To replace.</p> <p><i>Estimate</i></p> <p><i>Estimate</i></p> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting.</li> <li>• To display damaged parts during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p>				

Confirm & accepted by

Parts	10,930.00
Labour	0.00
Standard Menu	0.00
Specialist Job	8,590.00
Others(Lub,etc)	0.00
Sundry	50.00
<b>Total(w/o GST)</b>	<b>19,570.00</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## Shu Pei (LKKAUTO)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Friday, 7 December 2018 11:15 AM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** Admin A; Joy Irene (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving GBG982E (OI : EQI - DM18HO03330-JG) AND SLZ4081K (TP : LKK REF - CC3/EQI18022005/jb3) on 30.11.2018  
**Attachments:** GBG982E (AMENDED).pdf

Dear Shu Pei

Attached our insured's accident report for your attention.  
Please let us know your prelim advice soonest.

Best Regards,

Joel Goh

Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Thursday, December 6, 2018 5:44 PM  
**To:** Joel Goh  
**Cc:** Admin A; Joy Irene (LKKAUTO)  
**Subject:** Direct Settlement - Accident Involving GBG982E (OI : EQI - TBA) AND SLZ4081K (TP : LKK REF - CC3/EQI18022005/jb3) on 30.11.2018

### WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

We have received a new assignment from M/s Cycle & Carriage Fulco Motor Dealer Pte Ltd – Ubi and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:  
- TP's EST & GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6749 5792.

Thank you.

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeei@lkkauto.com](mailto:shupeei@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/EQ118022005/Agb3

23 SEPTEMBER 2019

**RANGER FIRE SYSTEMS PTE LTD**  
1002 TOA PAYOH INDUSTRIAL PARK  
SINGAPORE 319074

Dear Sir/Madam,

**ACCIDENT INVOLVING GBG 982E AND SLZ 4081K ON 30/11/2018**

We refer to the above accident. We are the Appointed Surveyor and Loss Adjuster Company by your Motor Insurer (EQ INSURANCE COMPANY LIMITED) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

This is to inform you that we received a Third Party Claim from SLZ 4081K.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Your full co-operation in the handling of the claim is required and kindly submit the following to [ceciliachong@lkkauto.com](mailto:ceciliachong@lkkauto.com) within 10 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Driver's driving license or foreign driving license (if any)
- Driver's Work Permit
- Employment Letter/ Authorisation letter from your company

Please call us if you have further queries.

Yours faithfully,

CECILIA CHONG



---

Case Handler  
DID: 6749 4274  
FAX: 6741 4108  
EMAIL: [ceciliachong@lkkauto.com](mailto:ceciliachong@lkkauto.com)

c.c. *EQ INSURANCE COMPANY LIMITED*  
*(Motor Claims Dept)*

---

---

---

**Cecilia Chong (LKK Auto)**

---

**From:** Cecilia Chong (LKK Auto)  
**Sent:** Friday, 8 November 2019 2:50 PM  
**To:** Joel Goh (joel.goh@eqinsurance.com.sg)  
**Subject:** YOUR REF: DM18HO03330-JG (OUR REF: CC3/EQI18022005/Agb3q2) \*\*\* ACCIDENT INVOLVING GBG 982E & SLZ 4081K ON 30/11/2018 \*\*\*  
**Attachments:** ADJUSTMENT REPORT.pdf; INSPECTION REPORT.pdf; LKK RESURVEY PHOTO.pdf; LKK SURVEY PHOTO.pdf; LOD AND OTHER DOCUMENTS.pdf; PARF COE REBATE.pdf

EQ ref : **DM18HO03330-JG**  
LKK ref : CC3/EQI18022005/Agb3q2

Dear Sirs/Madam,

**ACCIDENT INVOLVING GBG 982E(EQ-OI) AND SLZ 4081K(TP) ON 30/11/2018**

We refer to the above matter.

This is a head-to-rear collision.

A letter was sent out to the Insured to notify Third Party claim and NCD issues. No further feedback till to date.

We seek your approval to offer Third Party repairer "**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD**" at **\$13,332.40(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 19,942.00	\$ 12,026.80
2. Loss of Rental (5days x \$192.60)w/GST	\$ 963.00	\$ 963.00 (5days x \$192.60)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
4. MEDICAL FEE	\$ 335.15	\$ 335.15
Total	\$ 21,247.60	<b><u>\$ 13,332.40</u></b>

\*\*5days recommendation for repair.

Market Value	: \$126,000.00 (est)
LTA Rebate	: \$ 51,900.00 (est)
Nett Value	: <b><u>\$ 74,100.00 (est)</u></b>

Enclosed here with all the relevant documents for your perusal.

**Kindly let us have your approval/instruction.**



Best Regards,

Cecilia Chong | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [CeciliaChong@lkkauto.com](mailto:CeciliaChong@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI18022005/Agb3q2

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 11-12-2019



Code : EQI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 982E	Veh. Inspected	SLZ 4081K
Policy No.	DMCPHQ18-003374	Coverage (\$)	0.00
Claim No.	DM18HO03330-JG	Excess (\$)	0.00
Assign From		Assign Date	13/12/2018

## 2. Vehicle Particulars & Condition

Make & Model	KIA SORENTO	c.c	2199
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAPH81BMJ5448734	Colour	BLUE
Odometer	15911	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/60 R18	YOKOHAMA	6 mm
L/H Front Tyre	235/60 R18	YOKOHAMA	6 mm
R/H Rear Tyre	235/60 R18	YOKOHAMA	6 mm
L/H Rear Tyre	235/60 R18	YOKOHAMA	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	30/11/2018	Inspection Date	13/12/2018
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 4081K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	C&C LOGO (SN)	NECESSARY	50.00	50.00
1	PANEL ASSY -TAIL GATE (SN)	DISTORTED	1,445.00	1,445.00
1	GLASS ASSY -TAILGAT (SN)	NECESSARY	690.00	690.00
4	PAD-WINDSHIELD (SN)	NECESSARY	68.00	68.00
6	PAD-W/SHLD GLASS (SN)	NECESSARY	12.00	12.00
2	STOPPER T/GLASS (SN)	NECESSARY	8.00	8.00
1	SPOILER -REAR (SN)	TO REPAIR SEE LABOUR	915.00	-
1	LMPA ASSY -HIGH MOU (SN)	CRACKED	212.00	212.00
1	EMBLEM -SORENTO (SN)	NECESSARY	28.00	28.00
1	EMBLEM -ECO DYNAMIC (SN)	NECESSARY	37.00	37.00
1	LH INNER LAMP (SN)	NOT NECESSARY	827.00	-
1	RH INNER LAMP (SN)	NOT NECESSARY	827.00	-
1	LH OUTER COMB LAMP (SN)	NOT NECESSARY	493.00	-
1	RH OUTER COMB LAMP (SN)	NOT NECESSARY	493.00	-
2	LAMP ASSY-LICENSE (SN)	NOT NECESSARY	66.00	-
1	PANEL ASSY -BACK (SN)	TO REPAIR SEE LABOUR	526.00	-
1	UPR COVER -RR BUMPER (SN)	DEFORMED	605.00	605.00
1	LWR COVER -REAR BUM (SN)	DEFORMED	565.00	565.00
1	SKID PLATE -REAR BU (SN)	DEFORMED	90.00	90.00
20	CLIP ,BUMPER (SN)	NECESSARY	40.00	20.00
4	ULTRASONIC SENSOR (SN)	DAMAGED (2 PCS ONLY)	748.00	374.00
1	RAIL ASSY -REAR BUMPE (SN)	DEFORMED	341.00	341.00
1	WIRING HARNESS -R.P (SN)	NOT NECESSARY	240.00	-
1	BRACKET ASSY -REAR (SN)	NECESSARY	25.00	25.00
1	BRACKET ASSY -REAR (SN)	NECESSARY	25.00	25.00
1	LAMP ASSY REAR FOG & (SN)	DAMAGED	129.00	129.00
1	LAMP ASSY REAR FOG & (SN)	DAMAGED	129.00	129.00
1	COVER -BLANKING RR FO (SN)	NOT NECESSARY	44.00	-
1	COVER -BLANKING RR FO (SN)	NOT NECESSARY	44.00	-

Report Ref No. CC3/EQ118022005/Agb3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ANTENNA ASSY -SMARTKE (SN)	NOT NECESSARY	53.00	-
2	HOLDER -PARKING ASSIS (SN)	NECESSARY	10.00	10.00
2	HOLDER -PARKING ASS (SN)	NOT NECESSARY	10.00	-
1	CAP -TOW HOOK (SN)	DEFORMED	8.00	8.00
1	EXHAUST ASSY (SN)	BENT	1,177.00	1,177.00
1	REAR WIPER ARM (SN) (ADDITIONAL)	CRACKED	53.00	53.00
1	EMBLEM -KIA (SN) (ADDITIONAL)	NECESSARY	69.00	69.00
			11,102.00	6,170.00
	<b>LABOUR</b>			
	CAR PAINT RECTIFICATION AND SERVICES-REAR END PANEL ,REAR WINDSCREEN. (ADDITIONAL)		250.00	250.00
	TO CHECK REAR LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS.		80.00	80.00
	TO REMOVE & REINSTALL ALL CARPET ,TRIMMINGS & REAR SEAT TO GIVE WAY ACCESS FOR REPAIR.		1,200.00	300.00
	TO INSTALL NEW TAILGATE GLASS TO NEW TAILGATE PANEL .		300.00	300.00
	SEALANT KIT FOR TAILGATE GLASS.		300.00	100.00
	TO INSTALL RIKE COOL FILM FOR NEW TAILGATE GLASS .		220.00	220.00
	TO CONDUCT COMPUTER DIAGNOSTIC ,PROGRAMMING ,& RESETTNG.		250.00	250.00
	TO TRANSFER ALL DOOR COMPONENTS & MECHANISM.		300.00	300.00
	SPRAY PAINTING ON REAR ACCIDENT NEW PANELS & ACCIDENT REPAIRED AREAS TAILGATE ,REAR BUMPER ,RR END PNL ,BOTH RR FENDER REAR SPOILER.		2,940.00	1,800.00
	TO REPLACE DAMAGED PARTS CUT & WELD REAR END PANEL STRAIGHTEN ,REFORM ,ALIGN REAR ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF SPOILER -REAR AND PANEL ASSY -BACK .		3,000.00	1,470.00
			-	-
			-	-
			-	-
			8,840.00	5,070.00
	<b>GRAND TOTAL</b>		<b>19,942.00</b>	<b>11,240.00</b>

Report Ref No. CC3/EQ118022005/Agb3q2



RECOMMENDED COST OF REPAIRS			11,240.00
-----------------------------	--	--	-----------

Report Ref No. CC3/EQ118022005/Agb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.