



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
Mr SYED AMEERUDIN S/O SYED RAFEEUDD Blk 473 Pasir Ris Drive 6 #09-496 Singapore 510473  Contact No Mobile: 81337746	Cust No/Name	LCV05433/Mr Syed Ameerudin S/O Syed Rafe
	Reg No/Reg Date	SLZ4081K / 02/05/2018
	Date In/Mileage	05/12/2018/ 0
	Chassis No	KNAPH81BMJ5448734
	Engine No	D4HBJH364710
	Make/Model	KIA/SORENTO 2.2 A SX SR GDCO
	Colour/Trim	B4U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	06/12/2018/ 08:03	DS	323 / ChrisBulaclac	14758
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SUNDRY					✓ 50.00
C & C LOGO					✓ 80.00
S MIPNT88088					300 1200.00
TO CHECK REAR LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS					✓ 300.00
S MIPNT88088					100 300.00
TO REMOVE & RE-INSTALL ALL CARPET, TRIMMINGS & REAR SEAT TO GIVE WAY ACCESS FOR REPAIR					✓ 220.00
S MIPNT88088					✓ 250.00
TO INSTALL NEW TAILGATE GLASS TO NEW TAILGATE PANEL					✓ 300.00
S MIPNT88088					✓ 220.00
SEALANT KIT FOR TAILGATE GLASS					✓ 250.00
S MIPNT88088					✓ 300.00
TO INSTALL RIKE COOL FILM FOR NEW TAILGATE GLASS					✓ 2940.00
S MIPNT88088					1470
TO CONDUCT COMPUTER DIAGNOSTIC, PROGRAMMING, & RESETTING					3000.00
S MIPNT88088					
TO TRANSFER ALL DOOR COMPONENTS & MECHANISM					
S MIPNT98088					
SPRAY PAINTING ON REAR ACCIDENT NEW PANELS & ACCIDENT REPAIRED AREAS					
TAILGATE, REAR BUMPER, RR END PNL, BOTH RR FENDER REAR SPOILER					
S MIPNT88088					
TO REPLACE DAMAGED PARTS					
CUT & WELD REAR END PANEL					
STRAIGHTEN, REFORM, ALIGN REAR ACCIDENT AFFECTED AREAS					
M KS 73700 C5 121	PANEL ASSY-TAIL GATE	1.00	1445.00	0.00	✓ 1445.00
M KS 87110 C5 000	GLASS ASSY - TAILGAT	1.00	690.00	0.00	✓ 690.00
M KS 86114 2L 000	PAD-WINDSHIELD	4.00	17.00	0.00	✓ 68.00
M KS 86114 3D 000	PAD-W/SHLD GLASS	6.00	2.00	0.00	✓ 12.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
Mr SYED AMEERUDIN S/O SYED RAFEEUDD Blk 473 Pasir Ris Drive 6 #09-496 Singapore 510473  Contact No Mobile: 81337746	Cust No/Name	LCV05433/Mr Syed Ameerudin S/O Syed Rafe
	Reg No/Reg Date	SLZ4081K / 02/05/2018
	Date In/Mileage	05/12/2018/ 0
	Chassis No	KNAPH81BMJ5448734
	Engine No	D4HBJH364710
	Make/Model	KIA/SORENTO 2.2 A SX SR GDCO
	Colour/Trim	B4U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00001	Cash	06/12/2018/ 08:03	DS	323 / ChrisBulaclac	14758		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	KS	87115 C5 000	STOPPER T/GLASS	2.00	4.00	0.00	8.00
M	KS	87210 C5 000	SPOILER - REAR	1.00	915.00	0.00	915.00
M	KS	92700 C5 000	LAMP ASSY - HIGH MOU	1.00	212.00	0.00	212.00
M	KS	86310 C5 010	EMBLEM-SORENTO	1.00	28.00	0.00	28.00
M	KS	86333 C5 000	EMBLEM - ECO DYNAMIC	1.00	37.00	0.00	37.00
M	KS	92403 C5 600	LH INNER LAMP	1.00	827.00	0.00	827.00
M	KS	92404 C5 600	RH INNER LAMP	1.00	827.00	0.00	827.00
M	KS	92401 C5 600	LH OUTER COMB LAMP	1.00	493.00	0.00	493.00
M	KS	92402 C5 600	RH OUTER COMB LAMP	1.00	493.00	0.00	493.00
M	KS	92501 3K 000	LAMP ASSY - LICENSE	2.00	33.00	0.00	66.00
M	KS	65910 C5 000	PANEL ASSY-BACK	1.00	526.00	0.00	526.00
M	KS	86611 C5 510	UPR COVER-RR BUMPER	1.00	605.00	0.00	605.00
M	KS	86612 C5 500	LWR COVER - REAR BUM	1.00	565.00	0.00	565.00
M	KS	86665 C5 510	SKID PLATE - REAR BU	1.00	90.00	0.00	90.00
M	JJMR	200300	CLIP, BUMPER	20.00	2.00	0.00	40.00
M	KS	96890 C5 500B 4U	ULTRASONIC SENSOR	4.00	187.00	0.00	748.00
M	KS	86630 C5 510	RAIL ASSY-REAR BUMPE	1.00	341.00	0.00	341.00
M	KS	91885 C5 030	WIRING HARNESS - R.P	1.00	240.00	0.00	240.00
M	KS	86661 C5 000	BRACKET ASSY - REAR	1.00	25.00	0.00	25.00
M	KS	86662 C5 000	BRACKET ASSY - REAR	1.00	25.00	0.00	25.00
M	KS	92405 C5 510	LAMP ASSY-REAR FOG &	1.00	129.00	0.00	129.00
M	KS	92406 C5 510	LAMP ASSY-REAR FOG &	1.00	129.00	0.00	129.00
M	KS	86653 C5 500	COVER-BLANKING RR FO	1.00	44.00	0.00	44.00
M	KS	86654 C5 500	COVER-BLANKING RR FO	1.00	44.00	0.00	44.00
M	KS	95420 C5 500	ANTENNA ASSY-SMARTKE	1.00	53.00	0.00	53.00
M	KS	86683 C5 500	HOLDER-PARKING ASSIS	2.00	5.00	0.00	10.00
M	KS	86684 C5 500	HOLDER - PARKING ASS	2.00	5.00	0.00	10.00
M	KS	86667 C5 500	CAP-TOW HOOK	1.00	8.00	0.00	8.00
M	KS	28710 C5 811	EXHAUST ASSY	1.00	1177.00	0.00	1177.00
Z NOTES							
ACCIDENT ON 30/11/2018 ALONG PASIR RIS DR 12							
OWNER CLAIMING THIRD PARTY							
REQUIRED REPLACEMENT CAR							

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
Mr SYED AMEERUDIN S/O SYED RAFAEUD Blk 473 Pasir Ris Drive 6 #09-496 Singapore 510473  Contact No Mobile: 81337746	Cust No/Name	LCV05433/Mr Syed Ameerudin S/O Syed Rafe
	Reg No/Reg Date	SLZ4081K / 02/05/2018
	Date In/Mileage	05/12/2018/ 0
	Chassis No	KNAPH81BMJ5448734
	Engine No	D4HBJH364710
	Make/Model	KIA/SORENTO 2.2 A SX SR GDCO
	Colour/Trim	B4U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	06/12/2018/ 08:03	DS	323 / ChrisBulaclac	14758

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TP # GBG982E TP INSURER : EQ INSURANCE				
<p align="center"> <i>Adrian Ling</i>  <i>13/12/18.</i>  <i>05 days, 07 days → End Panel To replace.</i>  <i>SL/S</i> </p> <p align="center"><b>Estimate</b></p>				

Confirm & accepted by	Parts	10,930.00
	Labour	0.00
Authorized signatory and company stamp	Standard Menu	0.00
	Specialist Job	8,590.00
	Others (Lub, etc)	0.00
	Sundry	50.00
	Total (w/o GST)	19,570.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.