

ASS. REC. BY:

REF:

CS3 / ms(18016520 / Ua81

Special Instruction:

Surveyor

MURIS

ASSIGNMENT (Office)

From (Person):

Pauline Thom

of

ms(17

Date/Time:

06/11/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SU 446UR

Insured:

SFR 1616B

at Workshop m/s:

Z-One Automotiv

Tel:

6250 2115.

of

Bik 1 Kaki Bukit Ave 6 #01-87

Policy No:

28629423 AYW

Claim No:

569815

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/09/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

11.09.2018 1039AM

Person Contacted:

Yvonne

Vehicle: IN/OUT

Date/Time

Action/Instruction (X) Estimate

Do Not Finalize

SU 446UR - X

SFR 1616B - X

Dismantle: 11/9/2018

Sumat 45 4900 SL (Red & 800, 14%)

RECEIVED 13 DEC 2018

12/12/2018

(08/11/13) Wef

ASS. REC. BY: Morris

REF:

MS16/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 4464Rat Workshop m/s zone

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

BAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Sac: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 42239

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 4464R Regn: 11/17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (A)Make: Toyota Sienta Hybrid 1496Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 32958 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NHP1707106111Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 9/9/18

Survey held at _____

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 11/9/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS No seal.
3500 - 4500

RECEIVED 13 SEP 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: PRE

Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2018		11 Sep 2018 09:33 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	Jesse Satria, Oeni, ID: S8428443B		[Created by insurer]	
Main Claimant:	Edition Auto			
Vehicle Reg. No.:	SLU4464R	Date of Loss:		09/09/2018 10:00 - :59 [9 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 569815	Policy/Cover Note No.:		28629423AVW (Comprehensive) Coverage: 31/10/2017 - 30/10/2018
Vehicle Reg. No. (Insured):	SFR1616B	Policy No. (Claimant):		
		Excess:		
Repairer:	Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/12/2018]			
Adj Asp. Remarks:	OI not reported, SJE disagree - assign LKK Contact : Yvonne at 6250 2115 or HP 9755 2115			

ASSOCIATED MAIL RECEIVED

- MSIG_SG (06/12/2018): Report Send Back Alerts - SLU4464R (TP)

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Billing Name & Address

Edition Auto

c/o No.1 Kaki Bukit Ave 6, Blk D

#01-87 AutoBay@Kaki Bukit

Singapore 417883

Invoice No 09-18009/AY

Date 24 Sep 2018

Vehicle No : SLU 4464 R

Model : Toyota Sienta

Item	Descriptions	Amount S\$
1	Date of inspection : <u>10 Sep 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>115</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 715.00</u>
	SDLS : SEVEN HUNDRED AND FIFTEEN ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 09-18009/AY / 2018
Date of Report : 24 Sep 2018

Edition Auto
c/o No.1 Kaki Bukit Ave 6, Blk D
#01-87 AutoBay@Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 9 Sep 2018

As per your instruction dated 10 Sep 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLU 4464 R . We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLU 4464 R
Model : Toyota Sienta
Year / Capacity : 2017/1496
Chassis No : NHP170-7106111
Engine No : 1NZ8352045
Mileage : 32958
Colour : Grey

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 195/60 R15	Michelin	6.00	mm	Sport
REAR	O/S	: 195/60 R15	Michelin	6.00	mm	Sport
FRONT	N/S	: 195/60 R15	Michelin	6.00	mm	Sport
REAR	N/S	: 195/60 R15	Michelin	6.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Z-One Automotive Pte Ltd
No.1 Kaki Bukit Ave 6, Blk D
#01-87 AutoBay@Kaki Bukit
Singapore 417883

5. Estimated normal period of repair : 7 working days to complete.
6. Enclosed number of photograph : 115 copies.
7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SLU 4464 R
Report No: TP/ 09-18009/AY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear windscreen moulding	Necessary	\$ 75.30	\$ 75.30
1	Rear tailgate	Damage	\$ 1286.30	\$ 1286.30
1	Rear tailgate inner board	Intact	\$ 975.00	\$ 975.00
1	Rear tailgate inner handle	Damage	\$ 65.00	\$ 65.00
2	Rear tailgate lamps	Intact	\$ 206.00	\$ 206.00
1	Rear tailgate lock	Damage	\$ 468.30	\$ 468.30
1	Rear tailgate logo	Necessary	\$ 67.50	\$ 67.50
1	Rear tailgate outer handle	Damage	\$ 240.00	\$ 240.00
1	Rear tailgate rubber	Necessary	\$ 387.60	\$ 387.60
2	Rear taillamps	Intact	\$ 750.00	\$ 750.00
1	Rear centre bumper	Damage	\$ 378.81	\$ 378.81
2	Rear side bumpers	Damage	\$ 320.00	\$ 320.00
1	Rear lower bumper	Damage	\$ 975.00	\$ 975.00
2	Rear bumper side retainers	Necessary	\$ 151.22	\$ 151.22
2	Rear bumper reflectors	O/S Damage	\$ 174.80	\$ 87.40
2	Rear number plate lamps	Damage	\$ 90.00	\$ 90.00
1	Rear spare tyre tray	Damage	\$ 572.00	\$ 572.00
1	Rear end panel outer	Damage	\$ 525.00	\$ 525.00
1	Rear end panel inner garnish	Damage	\$ 256.40	\$ 256.40
1	Rear end panel smart sensor	Damage	\$ 161.60	\$ 161.60
Discount 25.0%			\$ 8125.83	\$ 6107.43
			\$ 2031.46	\$ 1526.86
			\$ 6094.37	\$ 4580.57

Special Nett Items

1	Rear windscreen sealant	Necessary	\$ 60.00	\$ 50.00
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00
			\$ 340.00	\$ 330.00

5760.03
4336.02

Spare Parts Total \$ 6434.37 \$ 4910.57

Vehicle No: SLU 4464 R
Report No: TP/ 09-18009/AY / 2018

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 6434.37	\$ 4910.57
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00 30
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$ 80.00 60
3	To remove and refit rear bumper sensor.	\$ 150.00	\$ 80.00 50
4	To remove and refit rear windscreen glass.	\$ 200.00	\$ 120.00 ✓
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1100.00	\$ 880.00 600
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1100.00	\$ 880.00 700
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 90.00 50
Total		<u>\$ 9334.37</u>	<u>\$ 7080.57</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 5700.00

SDLS: FIVE THOUSAND SEVEN HUNDRED ONLY


Qualified Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2018		11 Sep 2018 09:33 Edit Adj Rpt	S\$4,900.00 Edit Estimates	S\$4,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: Jesse Satria, Oeni , ID: S8428443B									
Main Claimant: Edition Auto									
Vehicle Reg. No.: SLU4464R		Date of Loss: 09/09/2018 10:00 - :59 [9 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 569815		Policy/Cover Note No.: 28629423AVW (Comprehensive) Coverage: 31/10/2017 - 30/10/2018							
Vehicle Reg. No. (Insured): SFR1616B		Policy No. (Claimant): Excess:							
Repairer: Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/12/2018]									
Adj Asg. Remarks: Oi not reported, SJE disagree - assign LKK Contact : Yvonne at 6250 2115 or HP 9755 2115									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (06/12/2018): Report Send Back Alerts - SLU4464R (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLU4464R (569815)**
[SFR1616B]
TP
Edition Auto
Sep 9 2018 10:00AM
[Jesse Satria, Oeni]
Z-one Automotive Pte Ltd - Kb

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	13/09/18 09:35	Accident Statement From: SC - Reg. No: SFR1616B, Claimant: JESSE SATRIA OENI		Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	11/09/18 15:34	Chassis Number		Load JPG	☒
2	11/09/18 15:34	Odometer Reading		Load JPG	☒
3	11/09/18 15:35	General View		Load JPG	☒
4	11/09/18 15:35	General View		Load JPG	☒
5	11/09/18 15:35	General View		Load JPG	☒
6	11/09/18 15:35	General View		Load JPG	☒
7	11/09/18 15:35	General View		Load JPG	☒
8	11/09/18 15:35	General View		Load JPG	☒
9	11/09/18 15:35	General View		Load JPG	☒
10	11/09/18 15:35	General View		Load JPG	☒
11	11/09/18 15:35	General View		Load JPG	☒
12	11/09/18 15:35	General View		Load JPG	☒
13	11/09/18 15:35	General View		Load JPG	☒
14	11/09/18 15:35	General View		Load JPG	☒
15	11/09/18 15:35	General View		Load JPG	☒
16	11/09/18 15:35	General View		Load JPG	☒
17	11/09/18 15:35	General View		Load JPG	☒
18	11/09/18 15:35	General View		Load JPG	☒
19	11/09/18 15:35	General View		Load JPG	☒
20	11/09/18 15:35	General View		Load JPG	☒
21	11/09/18 15:35	General View		Load JPG	☒
22	11/09/18 15:35	General View		Load JPG	☒
23	11/09/18 15:35	General View		Load JPG	☒
24	11/09/18 15:35	General View		Load JPG	☒
25	11/09/18 15:35	General View		Load JPG	☒
26	11/09/18 15:35	General View		Load JPG	☒
27	11/09/18 15:35	General View		Load JPG	☒
28	11/09/18 15:35	General View		Load JPG	☒
29	11/09/18 15:35	General View		Load JPG	☒
30	11/09/18 15:35	General View		Load JPG	☒
31	11/09/18 15:35	General View		Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	11/09/18 15:35	General View	 Load JPG	✓
33	11/09/18 15:35	General View	 Load JPG	✓
34	11/09/18 15:35	General View	 Load JPG	✓
35	11/09/18 15:35	General View	 Load JPG	✓
36	11/09/18 15:35	General View	 Load JPG	✓
37	11/09/18 15:35	General View	 Load JPG	✓
38	11/09/18 15:35	General View	 Load JPG	✓
39	11/09/18 15:35	General View	 Load JPG	✓
40	11/09/18 15:35	General View	 Load JPG	✓
41	11/09/18 15:35	General View	 Load JPG	✓
42	11/09/18 15:35	General View	 Load JPG	✓
43	11/09/18 15:35	General View	 Load JPG	✓
44	11/09/18 15:35	General View	 Load JPG	✓
45	11/09/18 15:35	General View	 Load JPG	✓
46	11/09/18 15:35	General View	 Load JPG	✓
47	11/09/18 15:35	General View	 Load JPG	✓
48	11/09/18 15:35	General View	 Load JPG	✓
49	11/09/18 15:35	General View	 Load JPG	✓
50	11/09/18 15:35	General View	 Load JPG	✓
51	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
52	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
53	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
54	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
55	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
56	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
57	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
58	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
59	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
60	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
61	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
62	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
63	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
64	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
65	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
66	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
67	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
68	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
69	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
70	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
71	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
72	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
73	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
74	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
75	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
76	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
77	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
78	11/09/18 15:35	Reinspection Photo	 Load JPG	✓
79	11/09/18 15:35	Reinspection Photo	Load JPG	✓

Assessment Reports			1 per page ▾	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	11/09/18 15:35	Reinspection Photo	Load JPG	✓
81	11/09/18 15:35	Reinspection Photo	Load JPG	✓
82	11/09/18 15:35	Reinspection Photo	Load JPG	✓
83	11/09/18 15:35	Reinspection Photo	Load JPG	✓
84	11/09/18 15:35	Reinspection Photo	Load JPG	✓
85	11/09/18 15:35	Reinspection Photo	Load JPG	✓
86	11/09/18 15:35	Reinspection Photo	Load JPG	✓
87	14/09/18 19:22	Reinspection Photo	Load JPG	✓
88	14/09/18 19:22	Reinspection Photo	Load JPG	✓
89	14/09/18 19:22	Reinspection Photo	Load JPG	✓
90	14/09/18 19:22	Reinspection Photo	Load JPG	✓
91	14/09/18 19:22	Reinspection Photo	Load JPG	✓
92	14/09/18 19:22	Reinspection Photo	Load JPG	✓
93	14/09/18 19:22	Reinspection Photo	Load JPG	✓
94	14/09/18 19:22	Reinspection Photo	Load JPG	✓
95	14/09/18 19:22	Reinspection Photo	Load JPG	✓
96	14/09/18 19:22	Reinspection Photo	Load JPG	✓
97	14/09/18 19:22	Reinspection Photo	Load JPG	✓
98	14/09/18 19:22	Reinspection Photo	Load JPG	✓
99	14/09/18 19:22	Reinspection Photo	Load JPG	✓
100	14/09/18 19:22	Reinspection Photo	Load JPG	✓
Documentation			1 per page ▾	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/09/18 16:02	Pri from Crossborders LLC	Load PDF	
2	10/09/18 16:02	Survey Disagree on SJE - assign LKK	Load PDF	
3	13/09/18 09:36	SLU4464R E-FILE REPORT From:SC - Reg. No: SFR1616B, Claimant: JESSE SATRIA OENI	Load PDF	
4	15/11/18 12:40	SURVEY REPORT	Load PDF	
5	15/11/18 12:40	SURVEY PHOTOS	Load PDF	
6	15/11/18 12:41	SURVEY PHOTOS 1	Load PDF	
7	15/11/18 12:41	SURVEY PHOTOS 2	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/18 13:46	PRS INVOICE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016520/UQBS2-1
Date: 19/12/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28629423AVW
Claimant Vehicle No :	SLU4464R	Insured Vehicle No :	SFR1616B
Date of Loss:	09/09/2018	Nature of Claim:	TP
		Claim No:	569815

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU4464R	Engine No:	1NZ8352045
Make & Model:	TOYOTA SIENTA, 1.5 G CVT (A)	Chassis No:	NHP1707106111
Reg. Date:	30/11/2017 (Man. Year: 2017)	Odometer:	32958 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,434.37	4,575.02	1,859.35	28.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,610.00	1,290.00	44.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,334.37	6,185.02	3,149.35	33.74
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	9,334.37	4,900.00	4,434.37	47.51
+ GST 7.00/7.00% (S\$)	653.41	343.00	310.41	47.51
Nett Amount (S\$)	9,987.78	5,243.00	4,744.78	47.51

INSPECTION

Date of Assignment:	11/09/2018	Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit Singapore 417883
Date Inspected:	11/09/2018 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2018)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU4464R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	75.30 FL	*75.30 FL
2	1		*REAR TAILGATE	Dented	1,286.30 FL	*1,286.30 FL
3	1		*REAR TAILGATE INNER BOARD	Not Necessary	975.00 FL	*- FL
4	1		*REAR TAILGATE INNER HANDLE	Deformed	65.00 FL	*65.00 FL
5	2		*REAR TAILGATE LAMPS	Not Necessary	206.00 FL	*- FL
6	1		*REAR TAILGATE LOCK	Twisted	468.30 FL	*468.30 FL
7	1		*REAR TAILGATE LOGO	Necessary	67.50 FL	*67.50 FL
8	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	240.00 FL	*- FL
9	1		*REAR TAILGATE RUBBER	Twisted	387.60 FL	*387.60 FL
10	2		*REAR TAILLAMPS	Not Necessary	750.00 FL	*- FL
11	1		*REAR CENTRE BUMPER	Deformed	378.81 FL	*378.81 FL
12	2		*REAR SIDE BUMPERS	Deformed	320.00 FL	*320.00 FL
13	1		*REAR LOWER BUMPER	Deformed / Torn	975.00 FL	*975.00 FL
14	2		*REAR BUMPER SIDE RETAINERS	Necessary	151.22 FL	*151.22 FL
15	2		*REAR BUMPER REFLECTORS	Not Necessary	174.80 FL	*- FL
16	2		*REAR NUMBER PLATE LAMPS	Broken	90.00 FL	*90.00 FL
17	1		*REAR SPARE TYRE TRAY	Twisted	572.00 FL	*572.00 FL
18	1		*REAR END PANEL OUTER	Dented	525.00 FL	*525.00 FL
19	1		*REAR END PANEL INNER GARNISH	Twisted	256.40 FL	*256.40 FL
20	1		*REAR END PANEL SMART SENSOR	Cracked	161.60 FL	*161.60 FL
21	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
22	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	8,465.83	6,020.03
- List Item Discount on L Items 25.00/25.00% (S\$)	2,031.46	1,445.01
Total Parts (S\$)	6,434.37	4,575.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.	New	50.00	30.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.	New	150.00	60.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR.	New	150.00	50.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	200.00	120.00
5	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	1,100.00	600.00
6	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	1,100.00	700.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	150.00	50.00
Gross Labour Cost (\$\$)			2,900.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >