

Version:

INS. CASE OWNER:

CC ^{6 III} /AIG1802

WTV, Aigb39

LKK
IDAC

Surveyor:

Adrian

DOE

ASSIGNMENT

5/10/18

Date / Time:

5/10/18

Registered in Merimen:

2/10/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

4BB 248A

Claim No.:

ML2118/1/18

Name of Insured:

EMPHING TRUCKS TRADING

Policy No.:

W491122

Insured Tel No.:

HP:

Make / Model:

MLH

Excess Sec II :SS

D.O.A:

06/10/18

Place of Accident:

THRU THRU WEST ST 72
THRU THRU WEST ST 72

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SAMUEN VASUP SANSUL

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L YES / NO) KPHUT

Insured Liability:

Final ? Yes / No

5/10/18



INSRS:
WSP:
Tel:
Liability:
RMKS:

Long



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
14/10/18	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	
	After call Itr to OI	NA
	Documentation Check List: Handler	Typist
	Notification Itr (if non-pickup)	☒
	After call Itr to OI	☒
	Authorisation To Act	☒
	Release Voucher	☒
	Final Repair Bill	☒
	Car Rental Invoice	☒
	Towing Invoice	☒
	LTA / GIA	☒
	Medical Bill	☒
	PIR	☒
	Mandate/Reject Instruction	☒
	LOD	☒
	Payment Breakdown Form	☒
	Post-Repair Photos	☐
	Others	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:
Repair Cost:	SS	
Loss of Rental (LOR):	SS	(days)
Loss of Use (LOU):	SS	(\$ 60 x 8 days)
Loss of Income (LOI):	SS	(\$ x days)
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search	SS	
Medical:	SS	
Disbursement:	SS	(e.g. Tow/Independent)
Legal Cost:	SS	
Total:	SS	Global Sum SS: 5,500
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS	Name 1: LEANG AUTOMOTIVE
Payee 2: (Strike if N.A.)	SS	Name 2: X
Payee 3: (Strike if N.A.)	SS	Name 3: X

REF:

POLICY NO.

12/08/09.

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

TP III

MV: 17K

PV: 9.8K

Nett: 7.2K.

Veh No

SJS3521A

Vt Regn

2009 August.

Type: MC Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Attis.

C/S

1598

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

257617.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053ZEE106/54531

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

195/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

05/12/18.

Survey held at:

Leany.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 - 3 - 5 - 9

1 - 2 - 3 - 4

1 - 2 - 3 - 4

Report Format:

Lump Sum / I.B.I. / S

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Work and (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III18022072/Ajb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 07-12-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 2498A	Veh. Inspected	SJS 3521A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/12/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/12/2018	Inspection Date	05/12/2018	
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SIS3521A.
 Toyota Altis 1598cc
 MRO53ZEE106151531

TP III
 Joy.

Front Bumper	Distorted	563.80 ✓
Front Bumper Clips	new	30 ✓
Front Bumper Side Holder RH	2nd	60.70 ✓
Front Bumper Reinforcement	At	339.70
Front Bumper Fog Lamp RH	Cracked	279.52 ✓
Front Bumper Fog Lamp Cover RH	Cracked	96.30 ✓
Front Bumper Logo	new	32.80 ✓
Front Bumper Top Rubber	new	69.70 X
Front Bumper Lower Grille	behind	106.50 ✓
Front Grille	cracked	298.80 ✓
Front Grille clips	new	20 ✓
Headlamp RH	Smashed	635 ✓
Front Support Panel	Repair	699.90 X
Front RH fender	Distorted	585 ✓
Front RH Fender Lower Shield	torn	169.30 ✓
Front RH Fender Lower Shield clips	new	30 ✓
Front RH Fender Bracket	Bent	30.80 ✓
Bonnet	Distorted	894.50 ✓

STS3521A.

Wiper Wipers Tank	cracked	109.60. ✓
Wiper Washer Motor.	new	210.20. ✗
Engine Undercover	ton	193.10. ✓
Engine Undercover Clips	new	30. ✓
Front RH Tyre	NE new	280(SN) ✗
Front RH Wheel Rim	wt	580(SN) 400(SN)
Front RH Shock Absorber	Bent	335.20. ✓
Front RH Knuckle Arm	Bent	562.70. ✓
Front RH Lower Arm	Bent	371.80. ✓
Front RH Wheel Hub c/w Bearing Band		130.80. ✓
Steering Rack and Pinion	xbl new	1685.20. ✗

SJS3521A.

Panel Bending

Spray Painting

Wiring

To remove condenser, radiator and to re-gas. 180 X

To remove undercarriage

To perform alignment test.

Towing Fees.

~~1200~~ 600

~~1200~~ 700

~~50~~ 30

~~380~~ 220

~~150~~ 80

60. ✓

hist: 5906.

Len 25/: 4429.50

S.N: 400

labour: 1690.

total: 6519.50

H/S: 5.2K.

06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Stamford Tyres International Pte Ltd

23 Kaki Bukit Road 4

#01-12/13 Synergy@KB

Singapore 417801

Phone Number: 6702 3355

Fax Number: 6341 6993

Customer:	Date:	12/7/2018 11:24 AM
Company:	VIN	SJS3521A
License NO:	Technician:	
Odometer:	Order NO:	

VEHICLE ALIGNMENT REPORT

TOYOTA, COROLLA ALTIS E141, 07-12 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	---	2°00'	3°30'	---
		Right	---	2°00'	3°30'	---
	Camber	Left	-0°18'	-1°15'	0°15'	-0°18'
		Right	-0°36'	-1°15'	0°15'	-0°36'
	Toe	Left	-0°24'	-0°06'	0°06'	-0°27'
		Right	0°45'	-0°06'	0°06'	0°45'
Total		0°21'	-0°11'	0°11'	0°18'	
Rear	Camber	Left	-1°12'	-2°00'	-1°00'	-1°12'
		Right	-1°36'	-2°00'	-1°00'	-1°36'
	Toe	Left	0°15'	-0°01'	0°13'	0°15'
		Right	-0°03'	-0°01'	0°13'	-0°03'
		Total	0°12'	-0°03'	0°26'	0°12'
	Max Thrust Angle		-0°09'	---		-0°09'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		---	11°15'	11°15'	---
	Right		---	11°15'	11°15'	---
Included Angle	Left		---	---	---	---
	Right		---	---	---	---
Toe Out On Turns	Left		---	---	---	---
	Right		---	---	---	---
Max Turn Inside	Left		---	---	---	---
	Right		---	---	---	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		-3mm	---	---	-3mm
	Rear		-8mm	---	---	-8mm
Track Width Diff.			-1mm			-1mm
Wheel Base Diff.			5mm			5mm
Front Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Rear Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Frame Angle						---

CASH SALES / WORK ORDER
MENG RECOVERY SERVICES

24 HOURS TOWING SERVICE

160 Sin Ming Drive #03-19 Sin Ming Autocity Singapore 575722

H/P: 9851 0566

NO.: 11646

Date: 04.12.18

宝号

Messrs: A4 2

车号

Vehicle No: SJS 3521A

车型

Model No: TOYOTA A7

由

From: JURONG WEST DIX 732

到

To: W1

时间 (日/夜)

Time (day / night):

司机

Driver: 126

其他

Others:

CASH \$: 70.00

☐

ACC

☐

M/S

☐

C/W

☐

D/W

注意: 本公司时所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to Your vehicle whilst being towed.

Received Signature

for **MENG RECOVERY SERVICES**

View Received Message

This mail is associated with :

***SJS3521A (MC2018/2969)**
[GBB2498A]

TP

LEE MAN

Dec 4 2018 12:00PM

[*]

Leang Automotive

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **29/04/2019 10:11 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$5500.00) - SJS3521A - Claim Handler: C. Meenachi

Approved:5500.00:OUR RECOMMENDATION IS AS FOLLOWS : COR \$5,200.00 LOU(\$60x8DAYS) 480.00 GIA SEARCH FEE 29.00 TOTAL 5,709.00
OFFER TP WORKSHOP GLOBAL \$5,500.00

DOCUMENTS SUMMARY

There are no documents.

LEANG AUTOMOTIVE

Auto Bay @ Kaki Bukit 1 Kaki Bukit Ave 6 #01-68 Singapore 417883
Tel: 6909 3048 Fax: 6909 3046

25.04.2019

Our ref: SJS 3521A

M/s INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street; #05 - IOB Building, Singapore 049711

Dear Sir,

ACCIDENT INVOLVING SJS 3521A AND GBB 2498A ON 04.12.2018

We write in behalf of the owner of SJS 3521A to claim as follows:

1) COST OF REPAIRS	: \$5,200.00
2) LOSS OF RENTAL	: \$1,080.00 ((\$120 x 9 days)
3) GIA SEARCH	: \$ 29.00
4) TOWING	: \$ 70.00
TOTAL	: \$6,379.00

We enclosed supporting documents as follows:

- 1) Letter of Authority;
- 2) Final Bill; and
- 3) Rental Receipt

We hope to receive our prompt response.

LEANG AUTOMOTIVE



Date: _____

To: M/s Leang Automotive
No. 1 Kaki Bukit Avenue 6
#01-68
Singapore 417883

LETTER OF AUTHORITY & INDEMNITY


I/We LEE MAN NRIC No./ Co Registration No. S2554407B of (address) BLK 736 Jurong West St 75 #09-13 (B) 640736 the registered owner (or his/her/their/agent) of motor vehicle registration no. 8393E21A hereby authorise M/s Leang Automotive ("the Repairer") to commence repairs to my/our vehicle and to forward the claim for inter alia the costs of repairs to the owner/insured of the Third Party responsible for the said accident on (date) 4/12/2018 involving motor vehicle nos 68B2498A along BLK 732 Jurong West St 73. I further authorise M/s Leang Automotive to sign and execute all documents in my name including but not limited to the Discharge Voucher in connection with the claim against the Third Party

However, if the third party rejects liability for whatever reasons and/or if the claim is reverted to my/our insurers and my/our insurers do not settle the repair costs and disbursements under my/our own insurance policy, I/we will be fully responsible for the repair costs and disbursements.

I also agree that if I do not fully co-operate in the Third Party claim, I will be responsible for any losses incurred by my Repairer.

My/our vehicle is repaired by the Repairer on my/our own free will and without any threat, inducement and/or promise.

In the event that the Repairer is compelled to enforce this undertaking, I/we agree that I/we shall pay for the legal costs incurred by the Repairer on a solicitor and client full indemnity basis.


Signature/ Co. Stamp

This Discharge Voucher applies only to the claimant's claim for property damage and will not affect the personal injuries claim and/or uninsured losses claim on a later date.

Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792M | GST Reg. No. M2-0078806-X
 64 Cecil Street | #04 | W05 | #06-02 | IOB Building | Singapore 048711
 Office (65) 63476100 Email: insure@ii.com.sg
 Fax (65) 62244174 Website: www.ii.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER
III-Direct Settlement (PODS)

India Ref: MC2018/2969
 Claimant Ref: SJS 3521A

We/I, LEANG AUTOMOTIVE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 5,500.00 (GLOBAL SUM) (repair cost), S\$ - (loss of use/rental), S\$ - (search fee), vehicle no. SJS 3521A that was damaged pursuant to the accident which occurred on 04.12.2018 (date) at JURONG WEST STREET 73 (location) involving vehicle no. GBB 2488A (insured vehicle). This is pursuant to the inspection conducted on 05/12/2018 (date) at "the workshop".

We/I confirm that we/I am/am authorized by the owner LEE MAN ("the third party claimant") of vehicle no. SJS 3521A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herewith the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expenses that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and/or expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SJS 3521A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,500.00 to LEANG AUTOMOTIVE

Dated this 09 day of 05 20 19

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

KEON LEANG
 Signed by "the workshop" (with chop)
87280470H
Blk 988A Jurong West
9193 #18-625 6764/988

WITNESS:

Signature:


Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD199607198R51 UBI AVENUE 1 #01-25PAYA UBI INDUSTRIAL PARK (S) 408933

This Discharge Voucher applies only to the claimant's claim for property damage and will not affect the personal injuries claim and/or uninsured losses claim on a later date.

Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.

No. 1297

Auto Bay @ Kaki Bukit 1 Kaki Bukit Ave 6 #01-68 Singapore 417883
Tel: 6909 3048 Fax: 6909 3046

M/s India International Insurance Pte Ltd

Vehicle No: 8583521A

Vehicle Model: TOYOTA ALTIS

Date: 26-12-2018

Quantity	DESCRIPTION	Unit Price	\$ Amount	cts
	Repair Costs		\$5200	
	This Discharge Voucher applies only to the claimant's claim for property damage and will not affect the personal injuries claim and/or uninsured losses claim on a later date.			
	Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.			
	E & O. E	TOTAL \$	\$5200	

Authorized Signature

For LEANG AUTOMOTIVE

TAX INVOICE

Our Ref No: GR-18-191151
Date of Request: 11/12/2018

Your Ref No: WALK IN NG

LEANG AUTOMOTIVE - KAKI BUKIT
AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68
SINGAPORE 417883

Dear Sir/Madam,

Your Vehicle No: SJS3521A
Date of Accident: 04/12/2018
Place of Accident: BLK 732 JURONG WEST ST73
Involving Vehicle No: GBB2498A

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

TAX INVOICE

Our Ref No: GR-18-191153
Date of Request: 11/12/2018

Your Ref No: WALK IN NG

LEANG AUTOMOTIVE - KAKI BUKIT
AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68
SINGAPORE 417883

Dear Sir/Madam,

Date of Accident: 04/12/2018
Vehicle No: SJS3521A
Place of Accident: BLK 732 JURONG WEST ST 73
Involving Vehicle No: GBB2498A

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GBB2498A	BLK 732 JURONG WEST ST 73	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Dec 2018 Edit Reg		05 Dec 2018 00:00 Edit Adj Rpt	S\$5,200.00 Edit Estimates	S\$5,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: PUFFING TUCKS TRADING, Co. Reg. No.: -									
Main Claimant: LEE MAN, ID: S2554407B									
Vehicle Reg. No.: SJS3521A		Date of Loss: 04/12/2018 12:00 - :59 [111 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MC2018/2969		Policy/Cover Note No.: M497132							
Vehicle Reg. No. (Insured): GBB2498A		Policy No. (Claimant): 5052971977-06							
		Excess:							
Repairer: Leang Automotive (Kaki Bukit) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68, 417883 Kaki Bukit - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/12/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (29/04/2019): Alert - Adj Mandate Approved (S\$5500.00) - SJS3521A - Claim Handler: C. Meenachi - III_SG (17/04/2019): Alert - Adj Mandate Approved (S\$0.00) - SJS3521A - Claim Handler: C. Meenachi									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS3521A (MC2018/2969)
[GBB2498A]
TP
LEE MAN
Dec 4 2018 12:00PM
[PUFFING TUCKS TRADING]
Leang Automotive

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	26/12/18 12:49	General View				 Load JPG		☒	
2	26/12/18 12:49	General View				 Load JPG		☒	
3	26/12/18 12:49	General View				 Load JPG		☒	
4	26/12/18 12:49	General View				 Load JPG		☒	
5	26/12/18 12:49	General View				 Load JPG		☒	
6	26/12/18 12:49	General View				 Load JPG		☒	
7	26/12/18 12:49	General View				 Load JPG		☒	
8	26/12/18 12:49	General View				 Load JPG		☒	
9	26/12/18 12:49	General View				 Load JPG		☒	
10	26/12/18 12:49	General View				 Load JPG		☒	
11	26/12/18 12:49	General View				 Load JPG		☒	
12	26/12/18 12:49	General View				 Load JPG		☒	
13	26/12/18 12:49	General View				 Load JPG		☒	
14	26/12/18 12:49	General View				 Load JPG		☒	
15	26/12/18 12:49	General View				 Load JPG		☒	
16	26/12/18 12:49	General View				 Load JPG		☒	
17	26/12/18 12:49	General View				 Load JPG		☒	
18	26/12/18 12:49	General View				 Load JPG		☒	
19	26/12/18 12:49	General View				 Load JPG		☒	
20	26/12/18 12:49	General View				 Load JPG		☒	
21	26/12/18 12:49	General View				 Load JPG		☒	
22	26/12/18 12:49	General View				 Load JPG		☒	
23	26/12/18 12:49	General View				 Load JPG		☒	
24	26/12/18 12:49	General View				 Load JPG		☒	
25	26/12/18 12:49	General View				 Load JPG		☒	
26	26/12/18 12:49	General View				 Load JPG		☒	
27	26/12/18 12:49	General View				 Load JPG		☒	
28	26/12/18 12:49	General View				 Load JPG		☒	
29	26/12/18 12:49	General View				 Load JPG		☒	
30	26/12/18 12:49	General View				 Load JPG		☒	
31	26/12/18 12:49	General View				 Load JPG		☒	
32	26/12/18 12:49	General View				 Load JPG		☒	
33	26/12/18 12:49	General View				 Load JPG		☒	
34	26/12/18 12:49	General View				 Load JPG		☒	
35	26/12/18 12:49	Reinspection Photo				 Load JPG		☒	
36	26/12/18 12:49	Reinspection Photo				 Load JPG		☒	
37	26/12/18 12:49	Reinspection Photo				 Load JPG		☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
39	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
40	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
41	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
42	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
43	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
44	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
45	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
46	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
47	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
48	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
49	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
50	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
51	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
52	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
53	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
54	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
55	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
56	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
57	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
58	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
59	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
60	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
61	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
62	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
63	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
64	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
65	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
66	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
67	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
68	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
69	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
70	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
71	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
72	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
73	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
74	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
75	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
76	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
77	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
78	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
79	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
80	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
81	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
82	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
83	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
84	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
85	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
86	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
87	26/12/18 12:49	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
89	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
90	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
91	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
92	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
93	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
94	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
95	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
96	26/12/18 12:49	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/12/18 16:50	TP GIA REPORT	 Load PDF	
2	25/04/19 11:45	GIA SEARCH	 Load PDF	
3	16/05/19 09:08	WORKSHOP INVOICE	 Load PDF	
4	16/05/19 09:08	AUTHORISATION TO ACT FORM	 Load PDF	
5	16/05/19 09:08	DISCHARGE VOUCHER	 Load PDF	
6	16/05/19 09:08	LOD	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/12/18 09:12	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18022072/AJB3Q2

Date: 16/05/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M497132

Claimant Vehicle No: SJS3521A

Insured Vehicle No: GBB2498A

Date of Loss: 04/12/2018

Nature of Claim: TP

Claim No: MC2018/2969

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS3521A

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Reg. Date: 12/08/2009 (Man. Year: 2009)

Colour: Black

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 3ZZ4919814

Chassis No: MR053ZEE106151531

Odometer: 257617 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,431.00	4,829.50	4,601.50	48.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	1,690.00	1,530.00	47.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,651.00	6,519.50	6,131.50	48.47
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	12,651.00	5,200.00	7,451.00	58.90
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		5,709.00		
Global Sum Settlement (S\$)		5,500.00		

INSPECTION

Date of Assignment: 05/12/2018

Date Inspected: 05/12/2018 Inspected At:

Leang Automotive (Kaki Bukit)
AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT
AVE 6 #01-68
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS3521A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	563.80 F	*563.80 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDER RH	Damaged	60.70 F	*60.70 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	339.70 F	*339.70 FL
5	1		*FRONT BUMPER FOG LAMP RH	Cracked	279.50 F	*279.50 FL
6	1		*FRONT BUMPER FOG LAMP COVER RH	Cracked	96.30 F	*96.30 FL
7	1		*FRONT BUMPER LOGO	Necessary	32.80 F	*32.80 FL
8	1		*FRONT BUMPER TOP RUBBER	Not Necessary	69.70 F	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Deformed	106.50 F	*106.50 FL
10	1		*FRONT GRILLE	Cracked	298.80 F	*298.80 FL
11	1		*FRONT GRILLE CLIPS	Necessary	20.00 F	*20.00 FL
12	1		*HEADLAMP RH	Smashed	635.00 F	*635.00 FL
13	1		*FRONT SUPPORT PANEL	Repair	699.90 F	*- FL
14	1		*FRONT RH FENDER	Distorted	585.00 F	*585.00 FL
15	1		*FRONT RH FENDER INNER SHIELD	Torn	169.30 F	*169.30 FL
16	1		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 F	*30.00 FL
17	1		*FRONT RH FENDER BRACKET	Bent	30.80 F	*30.80 FL
18	1		*BONNET	Dented	894.50 F	*894.50 FL
19	1		*WIPER WASHER TANK	Cracked	109.60 F	*109.60 FL
20	1		*WIPER WASHER MOTOR	Not Necessary	210.20 F	*- FL
21	1		*ENGINE UNDERCOVER	Torn	193.10 F	*193.10 FL
22	1		*ENGINE UNDERCOVER CLIPS	Necessary	30.00 F	*30.00 FL
23	1		*FRONT RH TYRE	Not Necessary	280.00 FS	*- FS
24	1		*FRONT RH WHEEL RIM	Cut	580.00 FS	*400.00 FS
25	1		*FRONT RH SHOCK ABSORBER	Bent	335.20 F	*335.20 FL
26	1		*FRONT RH KNUCKLE ARM	Bent	562.70 F	*562.70 FL
27	1		*FRONT RH LOWER ARM	Bent	371.80 F	*371.80 FL
28	1		*FRONT RH WHEEL HUB C/W BEARING	Damaged	130.90 F	*130.90 FL
29	1		*STEERING RAICK AND PINION	Not Necessary	1,685.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,431.00	6,306.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,476.50
Total Parts (\$\$)	9,431.00	4,829.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,200.00	700.00
3	WIRING	New	50.00	30.00
4	TO REMOVE CONDENSER ,RADIATOR AND TO RE-GAS	New	180.00	0.00
5	TO REMOVE UNDERCARRIAGE	New	380.00	220.00
6	TO PERFORM ALIGNMENT TEST	New	150.00	80.00
7	TOWING FEES	New	60.00	60.00
Gross Labour Cost (S\$)			3,220.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >