



Case Details

Case Reference Number : BUS/12/18/1005

Type of Repair : Accident Repair

Vehicle Registration Number : SMB94P

Company Type : SMRT Buses Ltd

Estimation ID : EST-4841-ID

Assigned By : Claiming Case Owner Team

Insurance Company Name : EQ Insurance Company Ltd

Accident Date and Time : 02/12/2018 08:35 AM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main	GLASS	6009353	WINDSCREEN,FRT:R/H,FOR MB OC500 BUS	1	931.50	931.50	10.00	838.35	Replace	1	838.35	Replace ▾
Standard	Main	CONSUMABLE	4006315	ACTIVATOR	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace ▾
Standard	Main	CONSUMABLE	4006314	ADHESIVE:DIRECT GLAZING	4	37.00	148.00	0.00	148.00	Replace	4	148.00	Replace ▾
Standard	Main	CONSUMABLE	4006313	PRIMER (SIKA 206 G+P)	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace ▾
Total Spare Part Cost									1,146.35		Surveyor Total	1,146.35	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									917.08		Final Sur Total	1,146.35	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	1,060	
Total:		1,325.00	1,060.00	

Spray Cost Detail


S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	528	
Total:		616.00	528.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	-----------	-------------------------	-------------------------	---------

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	917.08	1,146.35
Total Labour Cost	1,325.00	1,060.00
Total Spray Painting	616.00	528.00
Other	0.00	0.00
Overall Total	2,858.08	2,734.35
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	2,734.35
Surveyor Approved Amount		2,734.35
No of Repair Days*	4	3
Remarks	-	resurvey after repair / lump sum
Surveyor Name		Rasul
Signature		 Save Clear
Survey Date	06/12/2018	