

ASS. REC. BY:

REF:

CS/MSG18022110/Dgd3^{s2}

Special Instruction:

Surveyor:
Mennen

Bryen

ASSIGNMENT (Office)

From (Person): Lui Siew Wei

of

M81G

Date/Time: 10/12/18 @ 9.40am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 3346S

Insured:

SLP 7853H

at Workshop m/s

Chunni Motor

Tel:

G542 5119

of

Blk 10, AMK Autopoint # 01-05/06

Policy No: A29069766 MKF

Claim No:

578220

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/12/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

10.44am @ 10/12/18

Person Contacted:

Lynn

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 3346S-CC3/LCR18012710/KIWA3

DOA: 10/7/18

SLP 7853H-X

13/12/18 @ 3.34pm revised to Siew Wei via Mennen.

REF:

ASSIGNMENT

COE July 2024

2016 July

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop no/s:

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 8 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHD 3346 S

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

C.C.

1685

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp. Reading:

212017

T/Radio:

Insured / Std / NI / NA

Eng/No:

D4FDGU66005

ChNo:

KMHLB41UMGU092187

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

- 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal:

S

mm

R/Bal:

S

mm

L/Bal:

S

mm

L/Bal:

S

mm

D.O.A:

06/12/2018

D.O.I:

10/12/2018

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSIG SLP 7853 H

28/12/18

piname 2/5 10500/- with 10 days 7 m
(CLM 66148.08, 37%)

RECEIVED 31 DEC 2018

28/12/2018

Date/Time, File Pass to?

☐

Prel. Report

1) 31/12 12:00 PM

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation:

) S + RS / GI

) Photos

) Others

Report Format:

MER-TP

Lump Sum / I.B. (\$) :

10500

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

200
10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2018		10 Dec 2018 09:40 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD3346S	Date of Loss:	06/12/2018 02:00 - :59 [28 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 578220	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019
Vehicle Reg. No. (Insured):	SLP7853H	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lui Siew Wei - 6594 2547]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/12/2018]		
Driver/Custodian (Insured):	LOW WEI CAI WILLIE (), NRIC: S8615620B, Tel: +6598538272		
Adj Asg. Remarks:	Liability not clear. SJE AGREE IHS. pls contact lynn/ Irene 6542 5119 or 6542 7162		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD618157004 / ComfortDelGro Engineering Pte Ltd - Layan
 ENTRY DATE & TIME: 06/12/2018 10:46
 SUBMITTED BY: Catherine For May Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/12/2018 10:46
 Date Of Accident 06/12/2018 02:45
 Exact Location Of Accident MIDDLE RD X VICTORIA ST
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD3346S
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number
 Driver
 Name of Driver ONG PANG MING
 NRIC No S7219678C
 Date Of Birth 03/06/1972
 Occupation OUTDOOR
 Date Of Driving Pass 13/05/1999
 Driving Experience 19 YEARS AND 6 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-86098693
 Fax Number
 Contact Number
 Email Address STEVEN072@YAHOO.COM.SG

Address 604C 13-736 PUNGGOL ROAD
Postcode 823604
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP7853H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LOW WEI CAI WILLIE
NRIC/Passport Number S8615620B
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRT LEFT
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name ONG PANG MING

Approximate Age	46
Injuries Sustain	NECK,BACK,SHOULDER
Injured person in which vehicle?	SHD3346S
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 06.12.2018 @ 10:30 Hrs

Reporting Centre Personnel's Signature
Name: Reema Choo
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 06.12.2018 at about 02:45 hours I was travelling along Middle Road Towards Nicoll Highway x Junction
of Victoria Street with no passenger onboard .
I was wanting to proceed straight with green light in my favour , Suddenly Veh B (SLP 7853H) cut into my
lane and Collided into my taxi A - Front Right portion .
After the accident we then alighted and exchange our particulars .
After the accident I suffered pain at my Shoulder , Neck and Back area , Will consult a doctor later on .
I have company video and photos at scene to support my claims .
Veh B (SLP 7853H) - Mr low Wei Cai , Willie

DECLARATION

COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 06.12.2018

@ 10:30hrs

Reporting Centre Personnel's Signature

Name: *REINNA CHOW*

NRIC/FIN No.:

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHD 3346 S

Technician:

Mileage: 212017

Time Printed 10.12.18 1:34 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°53'		-3°00' 3°00'
3°44'		-0°19' 5°41'
0°04'		-1°30' 1°30'
21°25'		
20°32'		

Camber

Caster

Toe

SAI

Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
3°42'		-3°00' 3°00'
3°40'		-0°19' 5°41'
8°38'		-1°30' 1°30'
7°56'		
11°38'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-4°35'		-3°00' 3°00'
0°04'		-3°00' 3°00'
13°29'		-3°00' 3°00'
8°43'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-2°26'		-3°30' 2°30'
-0°19'		-1°30' 1°30'

Camber

Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°42'		-3°30' 2°30'
0°18'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°44'		-3°00' 3°00'
-0°02'		-3°00' 3°00'
-0°18'		-3°00' 3°00'

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

10 Survey by LK Lprian

VEHICLE NO : SHD 3346S

DATE : 6.12.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille after 2 hours mounting broken			\$ 1,110.10	* ✓
	Radiator Grille H Emblem 4x			\$ 39.50	X
	Front Bumper Cover distorted			\$ 1,052.20	✓
	Front Bumper Grille (RH) SVC			\$ 41.60	X
	Front Bumper Bracket Top (RH) new			\$ 22.40	X
	Front Bumper Bracket (RH) broken			\$ 24.60	✓
	Headlamp Support Panel Assy broken			\$ 907.40	✓
	Headlamp (RH) broken / cut			\$ 1,388.00	✓
	Front Fender (RH) Buc			\$ 566.30	✓
	Front Fender Apron Panel (RH) Distorted			\$ 637.00	✓
	Front Fender Shield (RH) deformed			\$ 174.90	✓
	Front Fender Retainer SVC			\$ 24.60	X
	Wiper Container 2x deformed			\$ 61.90	* ✓
	Wiper Container Motor new			\$ 75.00	X
	Front Windscreen Moulding new new			\$ 113.30	* ✓
	Front Windscreen Pillar Outer (RH) new Distorted			\$ 1,745.50	* ✓
	Front Wheel Rim (RH) 2 distorted			\$ 325.30	* ✓
	Front Wheel Hub Cap (RH) cut			\$ 107.10	✓
	Front Wheel Bearing 2 Done			\$ 150.90	* ✓
	Front Shock Absorber (Assy) (RH) 2 distorted			\$ 342.20	* ✓
	Front Shock Absorber Mounting (RH) new			\$ 108.80	X
	Front Drive Shaft (RH) new distorted			\$ 1,030.80	* ✓
	Rack & Pinion Assy new Done			\$ 969.60	* ✓
	STG Tie End 2 distorted			\$ 62.60	* ✓
	Stabilizer Bar 2 distorted			\$ 252.30	* ✓
	Stabilizer Bar Bush (RH) new			\$ 16.40	X
	Stabilizer Bar Link 2 distorted			\$ 61.10	* ✓
	Stabilizer Bracket new			\$ 24.00	X
	Front Suspension Lower Arm (RH) 2 distorted			\$ 529.30	* ✓
	Knuckle Arm (RH) 2 distorted			\$ 552.00	* ✓
	Engine Crossmember new distorted			\$ 2,094.40	* ✓
	ABS Sensor new			\$ 234.00	X
			14258.80		
			11407.04		
	SUB TOTAL			\$ 14,845.10	
	LESS 20%			\$ 2,969.02	
	DISCOUNTED TOTAL			\$ 11,876.08	
	Front Tyre (RH) SVC			\$ 216.00	Nett X
	Front Windscreen Sealant new new		46.00	\$ 46.00	Nett * ✓
				\$ 262.00	

SHD 3346S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 700/-
	Spray Painting Charge			\$ 1,000.00 700/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 30/-
	Towing Charge			\$ 50.00 114
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Re-set Frt ABS System		1750.00	\$ 200.00 114
	Remove/Refix Front Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 114
	Remove/Refix Aircon & Refill Gas			\$ 150.00 114
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 114
	TOTAL LABOUR			\$ 4,510.00
	ESTIMATE TOTAL			\$ 16,648.08
	10/12/2018 @ 1200hrs HA Actual 2/5 hrs 8 days 10 24K Auto		13203.04 4/5 10500/-	
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer: Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lui Siew Wei

Date: 13 Dec 2018

Preliminary Advice

Insured Vehicle No	: SLP7853H	Accident Date	: 06/12/2018
TP Vehicle No	: SHD3346S	Assignment Date	: 10/12/2018
Make	: HYUNDAI I40	Est. Duration of Repair	: 8.00
Date of Inspection	: 10/12/2018		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,648.08
Revised Amount	:S\$	13,203.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,203.04

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Dec 2018		10 Dec 2018 09:40 Edit Adj Rpt	S\$10,500.00 Edit Estimates	S\$10,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD3346S	Date of Loss:	06/12/2018 02:00 - :59 [28 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 578220	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019
Vehicle Reg. No. (Insured):	SLP7853H	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lui Siew Wei - 6594 2547]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 09/01/2019]		
Driver/Custodian (Insured):	LOW WEI CAI WILLIE (), NRIC: S8615620B, Tel: +6598538272		
Adj Asg. Remarks:	Liability not clear, SJE AGREE IHS. pls contact lynn/ Irene 6542 5119 or 6542 7162		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD3346S (578220)

[SLP7853H]

TP

COMFORT TRANSPORTATION PTE LTD

Dec 6 2018 2:00AM

[GRAB RENTALS PTE LTD]

Chunni Motor Work Pte Ltd - Amk

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/12/18 16:52	Accident Statement From:SC - Reg. No: SLP7853H, Claimant: GRAB RENTALS PTE LTD	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/12/18 15:34	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/12/18 18:35	Front View Left	Load JPG	☒
2	25/12/18 18:35	Front View Right	Load JPG	☒
3	25/12/18 18:37	General View	Load JPG	☒
4	25/12/18 18:37	General View	Load JPG	☒
5	25/12/18 18:37	General View	Load JPG	☒
6	25/12/18 18:37	General View	Load JPG	☒
7	25/12/18 18:37	General View	Load JPG	☒
8	25/12/18 18:37	General View	Load JPG	☒
9	25/12/18 18:37	General View	Load JPG	☒
10	25/12/18 18:37	General View	Load JPG	☒
11	25/12/18 18:37	General View	Load JPG	☒
12	25/12/18 18:37	General View	Load JPG	☒
13	25/12/18 18:37	General View	Load JPG	☒
14	25/12/18 18:37	General View	Load JPG	☒
15	25/12/18 18:37	General View	Load JPG	☒
16	25/12/18 18:37	General View	Load JPG	☒
17	25/12/18 18:37	General View	Load JPG	☒
18	25/12/18 18:37	General View	Load JPG	☒
19	25/12/18 18:37	General View	Load JPG	☒
20	25/12/18 18:37	General View	Load JPG	☒
21	25/12/18 18:37	General View	Load JPG	☒
22	25/12/18 18:37	General View	Load JPG	☒
23	25/12/18 18:37	General View	Load JPG	☒
24	25/12/18 18:37	General View	Load JPG	☒
25	25/12/18 18:37	General View	Load JPG	☒
26	25/12/18 18:37	General View	Load JPG	☒
27	25/12/18 18:37	General View	Load JPG	☒
28	25/12/18 18:37	General View	Load JPG	☒
29	25/12/18 18:37	General View	Load JPG	☒
30	25/12/18 18:37	General View	Load JPG	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	25/12/18 18:37	General View	 Load JPG	☒
32	25/12/18 18:37	General View	 Load JPG	☒
33	25/12/18 18:37	General View	 Load JPG	☒
34	25/12/18 18:37	General View	 Load JPG	☒
35	25/12/18 18:37	General View	 Load JPG	☒
36	25/12/18 18:37	General View	 Load JPG	☒
37	25/12/18 18:37	General View	 Load JPG	☒
38	25/12/18 18:37	General View	 Load JPG	☒
39	25/12/18 18:37	General View	 Load JPG	☒
40	25/12/18 18:37	General View	 Load JPG	☒
41	25/12/18 18:37	General View	 Load JPG	☒
42	25/12/18 18:37	General View	 Load JPG	☒
43	25/12/18 18:37	General View	 Load JPG	☒
44	25/12/18 18:37	General View	 Load JPG	☒
45	25/12/18 18:37	General View	 Load JPG	☒
46	25/12/18 18:37	General View	 Load JPG	☒
47	25/12/18 18:37	General View	 Load JPG	☒
48	25/12/18 18:37	General View	 Load JPG	☒
49	25/12/18 18:37	General View	 Load JPG	☒
50	25/12/18 18:37	General View	 Load JPG	☒
51	25/12/18 18:37	General View	 Load JPG	☒
52	25/12/18 18:37	General View	 Load JPG	☒
53	25/12/18 18:37	General View	 Load JPG	☒
54	25/12/18 18:37	General View	 Load JPG	☒
55	25/12/18 18:37	General View	 Load JPG	☒
56	25/12/18 18:37	General View	 Load JPG	☒
57	25/12/18 18:37	General View	 Load JPG	☒
58	25/12/18 18:37	General View	 Load JPG	☒
59	25/12/18 18:37	General View	 Load JPG	☒
60	25/12/18 18:37	General View	 Load JPG	☒
61	25/12/18 18:38	Odometer Reading	 Load JPG	☒
62	25/12/18 18:38	Chassis Number	 Load JPG	☒
63	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
64	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
65	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
66	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
67	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
68	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
69	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
70	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
71	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
72	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
73	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
74	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
75	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
76	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
77	25/12/18 18:38	Reinspection Photo	 Load JPG	☒
78	25/12/18 18:38	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
79	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
80	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
81	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
82	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
83	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
84	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
85	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
86	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
87	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
88	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
89	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
90	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
91	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
92	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
93	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
94	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
95	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
96	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
97	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
98	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
99	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
100	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
101	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
102	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
103	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
104	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
105	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
106	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
107	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
108	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
109	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
110	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
111	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
112	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
113	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
114	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
115	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
116	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
117	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
118	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
119	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
120	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
121	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
122	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
123	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
124	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
125	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
126	25/12/18 18:38	Reinspection Photo	 Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
127	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
128	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
129	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
130	25/12/18 18:38	Reinspection Photo	 Load JPG	✓
131	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
132	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
133	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
134	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
135	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
136	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
137	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
138	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
139	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
140	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
141	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
142	25/12/18 18:39	Reinspection Photo	 Load JPG	✓
143	25/12/18 18:39	Finishing Photo	 Load JPG	✓
144	25/12/18 18:39	Finishing Photo	 Load JPG	✓
145	25/12/18 18:39	Finishing Photo	 Load JPG	✓
146	25/12/18 18:39	Finishing Photo	 Load JPG	✓
147	25/12/18 18:39	Finishing Photo	 Load JPG	✓
148	25/12/18 18:39	Finishing Photo	 Load JPG	✓
149	25/12/18 18:39	Finishing Photo	 Load JPG	✓
150	25/12/18 18:39	Finishing Photo	 Load JPG	✓
151	25/12/18 18:39	Finishing Photo	 Load JPG	✓
152	25/12/18 18:39	Finishing Photo	 Load JPG	✓
153	25/12/18 18:39	Finishing Photo	 Load JPG	✓
154	25/12/18 18:39	Finishing Photo	 Load JPG	✓

Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/12/18 16:52	estimate repair From: SC - Reg. No: SLP7853H, Claimant: GRAB RENTALS PTE LTD	 Load PDF	
2	07/12/18 16:52	TP SHD3346S E-REPORT From: SC - Reg. No: SLP7853H, Claimant: GRAB RENTALS PTE LTD	 Load PDF	
3	10/12/18 09:35	SJE AGREE IHS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18022110/DQD3S2

Date: 02/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29069766MKF

Claimant Vehicle No: SHD3346S

Insured Vehicle No: SLP7853H

Date of Loss: 06/12/2018

Nature of Claim: TP

Claim No: 578220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD3346S

Make & Model: HYUNDAI I40, 1.7 D (A)

Engine No: D4FDGU660005

Reg. Date: 21/07/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMGU092187

Colour: Blue

Odometer: 212017 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 5 mm

Rear Left Side: Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,138.08	11,453.04	685.04	5.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	1,750.00	2,760.00	61.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,648.08	13,203.04	3,445.04	20.69
Approved Total (Overridden) (S\$)		10,500.00		
(S\$)	16,648.08	10,500.00	6,148.08	36.93
+ GST 7.00/7.00% (S\$)	1,165.37	735.00	430.37	36.93
Nett Amount (S\$)	17,813.45	11,235.00	6,578.45	36.93

INSPECTION

Date of Assignment: 10/12/2018

Date Inspected: 10/12/2018

Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)

Blk 10 #01-05/06, AMK Autopoint

Singapore 568047

Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_print&caseid=770366&extid=289835&CFID=46371647&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2019)
Parts:	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3346S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Mtg Broken	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Not Necessary	39.50 FL	*- FL
3	1		*FRONT BUMPER COVER	Distorted	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER GRILLE (RH)	Serviceable	41.60 FL	*- FL
5	1		*FRONT BUMPER BRACKET TOP (RH)	Not Necessary	22.40 FL	*- FL
6	1		*FRONT BUMPER BRACKET (RH)	Broken	24.60 FL	*24.60 FL
7	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
8	1		*HEADLAMP (RH)	Broken / Cut	1,388.00 FL	*1,388.00 FL
9	1		*FRONT FENDER (RH)	Buckled	566.30 FL	*566.30 FL
10	1		*FRONT FENDER APRON PANEL (RH)	Dented	637.00 FL	*637.00 FL
11	1		*FRONT FENDER SHIELD (RH)	Deformed	174.90 FL	*174.90 FL
12	1		*FRONT FENDER RETAINER	Serviceable	24.60 FL	*- FL
13	1		*WIPER CONTAINER	Deformed	61.90 FL	*61.90 FL
14	1		*WIPER CONTAINER MOTOR	Not Necessary	75.00 FL	*- FL
15	1		*FRONT WINDSCREEN MOULDING	Necessary	113.30 FL	*113.30 FL
16	1		*FRONT WINDSCREEN PILLAR OUTER (RH)	Dented	1,745.50 FL	*1,745.50 FL
17	1		*FRONT WHEEL RIM (RH)	Distorted	325.30 FL	*325.30 FL
18	1		*FRONT WHEEL HUB CAP (RH)	Cut	107.10 FL	*107.10 FL
19	1		*FRONT WHEEL BEARING	Damaged	150.90 FL	*150.90 FL
20	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	342.20 FL	*342.20 FL
21	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*- FL
22	1		*FRONT DRIVE SHAFT (RH)	Distorted	1,030.80 FL	*1,030.80 FL
23	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
24	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
25	1		*STABILIZER BAR	Distorted	252.30 FL	*252.30 FL
26	1		*STABILIZER BAR BUSH (RH)	Not Necessary	16.40 FL	*- FL
27	1		*STABILIZER BAR LINK	Distorted	61.10 FL	*61.10 FL
28	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	*- FL
29	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	529.30 FL	*529.30 FL
30	1		*KNUCKLE ARM (RH)	Distorted	552.00 FL	*552.00 FL
31	1		*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	*2,094.40 FL
32	1		*ABS SENSOR	Not Necessary	234.00 FL	*- FL
33	1		*FRONT TYRE (RH)	Serviceable	216.00 FS	*- FS
34	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	15,107.10	14,304.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,969.02	2,851.76
Total Parts (\$\$)	12,138.08	11,453.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	2,000.00	700.00
2	SPRAY PAINTING CHARGE.	New	1,000.00	700.00
3	WIRING CHARGE.	New	50.00	30.00
4	TUFF KOTE.	New	50.00	30.00
5	TOWING CHARGE.	New	50.00	0.00
6	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT.	New	120.00	60.00
8	RE-SET FRT ABS SYSTEM.	New	200.00	0.00
9	REMOVE / REFIX FRONT WINDSCREEN GLASS.	New	120.00	80.00
10	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT.	New	90.00	0.00
11	REMOVE / REFIX AIRCON & REFILL GAS.	New	150.00	0.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	New	480.00	0.00
Gross Labour Cost (S\$)			4,510.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >