

INS. CASE OWNER:

CC 3, TP 180 2230, K7239

LKK:
IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

7/12/2018

Date / Time:

7/12/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :S\$

D.O.A: 6/12/2018

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHD 99102



INSRS:

WSP: Trans-cab

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

DATE / PIC
Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:
Documentation Check List: Handler Typist
Notification ltr (if non-pickup)
After call ltr to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA :
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:
Post-Repair Photos:
Others:

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost: LG	S\$ 15,900.00	(16 days) Reduction: 88 %	Email ☐ Call ☐
-----------------	---------------	----------------------------	--

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
------------------	------------	---------------	--

Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
------------------	---	------------------------------------	---------------------------

Repair Cost:	S\$ -		
--------------	-------	--	--

Loss of Rental (LOR):	S\$ -	(days)	
-----------------------	-------	---------	--

Loss of Use (LOU):	S\$ -	(\$ x days)	
--------------------	-------	--------------	--

Loss of Income (LOI):	S\$ -	(\$ x days)	
-----------------------	-------	--------------	--

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]			
---	--	--	--

GIA/LTA Search:	S\$ -		
Medical:	S\$ -		
Disbursement:	S\$ -	(e.g. Tow/ Independent)	
Legal Cost:	S\$ -		
Total:	S\$	Global Sum S\$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐

Payee 1:	S\$ -	Name 1:	
Payee 2: (Strike if N.A.)	S\$ -	Name 2:	
Payee 3: (Strike if N.A.)	S\$ -	Name 3:	

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

ASS. REC. BY:

REF: TLKenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: _____

16 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

10/12File pass to CatherineU/Sym 815,500 MaxCRUD: 110,969.7A (88%)Veh No: S140 9910 ZYr Regn: 06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitudec.c. 1995Colour M. White / Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading 536906

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABLISAUC277432Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NI / S/Rim / STD A/Rim or

Tyre Size: _____

F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 0 mmL/Bal. 0 mmD.O.A. 6/12/18

Rear

R/Bal. 0 mmL/Bal. 0 mmD.O.I. 7/12/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S - RS - SI

Fees: _____

Others: _____

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

11623
170 + 1746 = 1910
11623
54
36
80
2076

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z**AAD1812-046***Not Authorized**1 Long & 1**Book Value ??*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9910Z

VF1ABL15AUC277432

~~TOYOTA~~~~PRIS~~

6.12.2018

III

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>BT/CM</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>CM</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	✓
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMPR RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>CM</i> 135.97	✓
8	1 BUMPR RETAINER LH REAR	\$	<i>CM</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>BR</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	✓
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	<i>Solra</i> 161.53
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>SL</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

30	1 FENDER PANEL REAR LH	\$	Bu 3,299.13	✓
31	1 WHEELARCH REAR LH	\$	Sh 543.47	X
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Deform 671.45	✓
33	1 FUEL FLAG	\$	Sh 343.57	X
34	1 WHEEL HOUSING PANEL REAR LH	\$	R 4,682.09	X
35	1 CHASSIS PANEL REAR LH L70Y	\$	B 3,766.43	✓
36	1 TAILLAMP LH	\$	mgum 552.55	✓
37	1 TAILLAMP PANEL LH	\$	R 986.70	✓
38	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM 404.56	✓
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Br/Bu 2,189.88	✓
41	1 SPARE WHEEL PANEL TRIM	\$	Sh 612.21	X
42	1 EXHAUST REAR	\$	R 7,489.05	X
43	1 EXHAUST CAP REAR	\$	R 230.49	X

TOTAL	\$	38,607.73
10%	\$	3,860.77
	\$	34,746.95

Specical Nett

1	1SET PARKING AID	\$	Shat 700.00	Good
2	1SET REAR BUMPER CLIP	\$	na 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sh 17.82	X
11	1SET BOOT FINISHER CLIP	\$	na 24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na 30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na 30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na 45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	na 28.00	✓

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

18	1 FENDER INNER TRIM CLIP RH	\$	na 28.00 X
19	1 TAILLAMP CLIP RH	\$	na 5.00 X
20	1 TAILLAMP CLIP LH	\$	na 5.00 ✓
21	2 REAR WINDSCREEN SELANT	\$	na 80.00 4500
22	1 WINDSCREEN MOULDING	\$	na 100.00 ✓
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 3000
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na 385.00 X
25	1 SPARE TYRE	\$	na 330.00 X

TOTAL \$ 2,225.02

TOTAL PARTS \$ 36,971.97**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 1100
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 2000
To Rust-Proofing Of The Affected Areas.	\$	170.00 120
To reinstall rear bumper parking sensor.	\$	170.00 60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 } 60
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 } 100

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	801
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X
		14720	
TOTAL	\$	14,340.00	

Over All Total	\$	51,311.97
-----------------------	-----------	------------------

(LUMP SUM)

Repair Days

~~20 DAYS~~
16 days

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9910Z

VF1ABL15AUC277432

RENAULT

LATITUDE

6.12.2018

III

PART**LIST**

1	1	BUMPER COVER FRT	\$	Bu 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	SL 181.75
3	1	BUMPER ABSORBER FRT	\$	SL 394.68
4	1	BUMPER RETAINER FRT LH	\$	SL 151.41
5	1	BUMPER SUPPORT FRT	\$	SL 123.88
6	1	BUMPER RETAINER FRT RH	\$	SL 150.77 } X
7	1	BUMPER SUPPORT FRT	\$	SL 123.88
8	1	BUMPER UNDERTRAY FRT	\$	SL 472.83
9	1	BUMPER GRILLE LOWER FRT	\$	SL 266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$	SL 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.21
12	1	BUMPER BEAM FRT	\$	R 914.08
13	1	TOW COVER FRT	\$	SL 28.61
14	1	RADIATOR GRILLE	\$	CM 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	R 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	CM 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	CM 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	R 89.79 X
19	1	FRONT BRACE PANEL	\$	R 177.22 X
20	1	HORN	\$	SL 314.17 X
21	1	HORN BRACKET	\$	R 40.45 X
22	1	HEADLAMP LH	\$	CM 1,184.43 ✓
22	1	HEADLAMP HARNESS	\$	SL 928.29 X
22	1	HEADLAMP RH	\$	mgcm 1,184.43 ✓
22	1	HEADLAMP HARNESS	\$	R 928.29 X
22	1	HEADLAMP PANEL FRT LH	\$	R 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	R 152.15 X
26	1	BONNET	\$	R 1,941.63 ✓

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

27	1	BONNET INSULATOR	\$	Sn	405.73	X
28	1	BONNET STRUT LH	\$	Sn	88.61	X
29	1	BONNET STRUT RH	\$	Sn	88.61	X
30	1	BONNET HINGE LH	\$	R	348.31	X
31	1	BONNET HINGE RH	\$	R	348.31	X
32	1	BONNET LOCK	\$	DI	305.48	
33	1	BONNET CABLE	\$	Sn	119.19	
34	1	BONNET CABLE COVER	\$	Sn	161.03	
35	1	BONNET SEAL OUTER	\$	Sn	92.36	
36	1	BONNET SEAL INNER	\$	Sn	157.28	
37	1	FENDER PANEL FRT LH	\$	R	783.83	
38	1	WHEELARCH FRT LH	\$	Sn	278.84	
39	1	FENDER BRACKET LOWER LH	\$	Sn	15.79	
40	1	FENDER INSULATOR LH	\$	Sn	130.84	
41	1	FENDER PANEL FRT RH	\$	R	783.83	
42	1	WHEELARCH FRT RH	\$	Sn	278.84	
43	1	FENDER BRACKET LOWER RH	\$	Sn	15.79	
44	1	FENDER INSULATOR RH	\$	Sn	130.84	
45	1	WIPER RESERVOIR	\$	Sn	348.25	
46	1	WIPER RESERVOIR NECK	\$	Sn	136.11	
47	1	WIPER RESERVOIR MOTOR	\$	Sn	270.06	
48	1	AIR CLEANER LOWER	\$	Sn	271.26	
49	1	AIR CLEANER HOSE	\$	Sn	76.14	
50	1	AIR CLEANER BOX	\$	Sn	464.20	
51	1	TURBO DUCT	\$	Sn	1,027.80	
52	1	A/C HEATER VALVE	\$	Sn	484.50	
53	1	SUBFRAME OUTER FRT	\$	Sn	2,652.45	
54	1	SUBFRAME BRACKET OUTER LH	\$	R	92.36	
55	1	SUBFRAME BRACKET OUTER RH	\$	R	92.36	
56	1	ENGINE UNDERTRAY	\$	Sn	564.98	
57	1	A/C CONDENSER	\$	Sn	2,020.37	X
58	1	A/C CONDENSER GARNISH LH UPPER	\$	Sn	39.67	
59	1	A/C CONDENSER GARNISH RH UPPER	\$	Sn	39.67	
60	1	A/C CONDENSER GARNISH LH	\$	Sn	58.81	
61	1	A/C CONDENSER GARNISH RH	\$	Sn	59.60	
62	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sn	208.39	
63	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sn	658.72	
74	1	A/C PIPE COMPRESSOR	\$	Sn	334.29	

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

75	1	A/C PIPE	\$	S\$ 658.72	}	X
76	1	A/C COMPRESSOR	\$	S\$ 2,684.61		
77	1	AIR COOLER	\$	S\$ 792.60		
78	1	AIR INTERCOOLER HOSE (LONG)	\$	S\$ 1,014.13		
79	1	AIR INTERCOOLER HOSE (Short)	\$	S\$ 375.14		
80	1	TRANSMISSION COOLER	\$	S\$ 1,219.30	}	X
81	1	TRANSMISSION COOLER PAD	\$	S\$ 17.96		
82	1	RADIATOR	\$	S\$ 1,202.20	}	X
83	2	RADIATOR STUD UPPER	\$	S\$ 14.41		
84	2	RADIATOR BUSH UPPER	\$	S\$ 50.12		
85	2	RADIATOR MTG LOWER	\$	S\$ 55.85		
86	1	RADIATOR FAN COWLING	\$	S\$ 820.54		
87	1	RADIATOR FAN MOTOR LH	\$	S\$ 967.36		
88	1	RADIATOR FAN MOTOR RH	\$	S\$ 1,479.46		
89	1	RADIATOR TANK	\$	S\$ 324.62		
90	1	RADIATOR HOSE UPPER	\$	S\$ 240.56		
91	1	RADIATOR HOSE LOWER	\$	S\$ 491.18		
92	1	RADIATOR TANK HOSE	\$	S\$ 61.18		
93	1	AUTO COMPUTER	\$	S\$ 5,032.17		
94	1	INJECTION COMPUTER	\$	S\$ 4,706.30		
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S\$ 5,154.52		
96	1	STEERING PUMP ELECTRIC	\$	S\$ 2,306.90		
97	1	STEERING PINION RACK	\$	S\$ 4,413.11		

TOTAL	\$	63,994.74
10%	\$	6,399.47
	\$	57,595.27

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	S\$ 52.00	✓
2	1SET	BUMPER CLIP FRT	\$	S\$ 66.00	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AAD1812-046

3	1	BUMPER BRACKET CLIP FRT LH	Acknowledged by Repairer	\$	nn	12.00	}
4	1	BUMPER SUPPORT CLIP FRT LH	Signature:	\$	nn	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	Date:	\$	nn	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH		\$	nn	10.50	
7	1	TOW COVER FRT		\$	nn	14.50	
8	1SET	RADAITOR GRILLE SCREW		\$	nn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP		\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP		\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT		\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD		\$	nn	30.00	
21	1	Windscreen moulding		\$	nn	100.00	}
22	1SET	Front licence plate with holder		\$	Ref	80.00 25.00	

TOTAL	\$	562.50
TOTAL PARTS	\$	58,157.77

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	500 6,000.00
Towing Fees.	\$	120.00 500
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 4400
To rust-proofing of the affected areas.	\$	170.00 300
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X
To lift-up engine with gear box and refit.	\$	440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 X
To remove and refit air bag system and reset.	\$	480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 1001
To replace, refix and top up coolant for radiator	\$	170.00 501
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X

TOTAL \$ **17,000.00****Over All Total** \$ **75,157.77****Repair Days (LUMP SUM)****20 Days**

4 days

Mei Kwan (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 16 January, 2020 10:19 AM
To: Mei Kwan (LKKAUTO)
Cc: Admin A; Hsiao Tong (LKKAUTO); Vic (LKKAUTO)
Subject: RE: Request of Survey report-your ref no: AAD1812-046/ our Ref: D18008678MFSH;accident involving SHC7044S and SHD9910Z on 06-12-2018
Attachments: SHD9910Z 06.12.2018 - III.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Categories: HMK

Without Prejudice

Dear Mei Kwan

Enclosed is the estimate marking for your action.

Net Book Value : \$ 50,052.23

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 14 January, 2020 7:53 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: Request of Survey report-your ref no: AAD1812-046/ our Ref: D18008678MFSH;accident involving SHC7044S and SHD9910Z on 06-12-2018

Dear Wai Yin,

Please provide finalised estimate.

“ Wishing you a Happy and Prosperous Lunar New Year ”



Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Sent: Tuesday, 14 January, 2020 5:50 PM

To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Request of Survey report-your ref no: AAD1812-046/ our Ref: D18008678MFSH;accident involving SHC7044S and SHD9910Z on 06-12-2018

Dear Wai Yin,

This case is under Mei Kwan.

Dear Mei Kwan,

CC3/TP18022130/Ka3

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Tuesday, 14 January 2020 5:44 PM

To: SUR <sur@lkkauto.com>

Subject: FW: Request of Survey report-your ref no: AAD1812-046/ our Ref: D18008678MFSH;accident involving SHC7044S and SHD9910Z on 06-12-2018

Without Prejudice

Dear Sir

Can we check the survey report send to FCIL?

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63

Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

From: Ng Wai Yin [<mailto:waiyin.ng@transcab.com.sg>]

Sent: Thursday, 26 December, 2019 4:48 PM

To: 'SUR' <sur@lkkauto.com>

Subject: RE: Request of Survey report-your ref no: AAD1812-046/ our Ref: D18008678MFSH;accident involving SHC7044S and SHD9910Z on 06-12-2018

Without Prejudice

Dear Sir

Please send a copy of the survey report to FCIL.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63

Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 26 December, 2019 1:48 PM

To: waiyin.ng@transcab.com.sg; claims@transcab.com.sg

Cc: Merina Chia <MerinaChia@msfirstcapital.com.sg>; CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Subject: Request of Survey report-your ref no: AAD1812-046/ our Ref: D18008678MFSH;accident involving SHC7044S and SHD9910Z on 06-12-2018

WITHOUT PREJUDICE

Dear Sir,

We refer to your letter of claim dated 13-12-2019

Please let us have survey report for this case

Thanks & Regards,

Motor Claims Department

MS First Capital Insurance Ltd

cwsmotorclaims@msfirstcapital.com.sg



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9910Z

VF1ABL15AUC277432

~~TOYOTA~~~~PRIUS~~

6.12.2018

III

Not Authorized
1 Day & ?
Book Value ??

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>BT/CM</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>CM</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>CM</i> 135.97	✓
8	1 BUMEP R RETAINER LH REAR	\$	<i>CM</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>BR</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	✓
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	<i>Solin</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>RE</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>RE</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>R</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

30	1 FENDER PANEL REAR LH	\$	Bu 3,299.13	✓
31	1 WHEELARCH REAR LH	\$	SL 543.47	X
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Deform 671.45	✓
33	1 FUEL FLAG	\$	SL 343.57	X
34	1 WHEEL HOUSING PANEL REAR LH	\$	R 4,682.09	X
35	1 CHASSIS PANEL REAR LH L70Y	\$	Bu 3,766.43	✓
36	1 TAILLAMP LH	\$	M3um 552.55	✓
37	1 TAILLAMP PANEL LH	\$	Bu 986.70	✓
38	1 OUTER PANEL REAR (End Panel)	\$	Bu 1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM 404.56	✓
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu/Bu 2,189.88	✓
41	1 SPARE WHEEL PANEL TRIM	\$	SL 612.21	X
42	1 EXHAUST REAR	\$	R 7,489.05	X
43	1 EXHAUST CAP REAR	\$	R 230.49	X

TOTAL	\$	38,607.73
10%	\$	3,860.77
	\$	34,746.95

Special Nett

1	1SET PARKING AID	\$	Shay 700.00	600.00
2	1SET REAR BUMPER CLIP	\$	na 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	SL 17.82	X
11	1SET BOOT FINISHER CLIP	\$	na 24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na 30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na 30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na 45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	na 28.00	✓

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

18	1 FENDER INNER TRIM CLIP RH	\$	28.00 X
19	1 TAILLAMP CLIP RH	\$	5.00 X
20	1 TAILLAMP CLIP LH	\$	5.00
21	2 REAR WINDSCREEN SELANT	\$	80.00 405N
22	1 WINDSCREEN MOULDING	\$	100.00
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00 305N
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00 X
25	1 SPARE TYRE	\$	330.00 X

TOTAL	\$	2,225.02
--------------	-----------	-----------------

TOTAL PARTS	\$	36,971.97
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 1100
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 2000
To Rust-Proofing Of The Affected Areas.	\$	170.00 120
To reinstall rear bumper parking sensor.	\$	170.00 60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	801
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	na 380.00	X
TOTAL	\$	14,340.00	

Over All Total \$ 51,311.97**(LUMP SUM)****Repair Days 20 DAYS**

16 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9910Z

VF1ABL15AUC277432

RENAULT

LATITUDE

6.12.2018

III**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Ben</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68
4	1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77 } X
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61
14	1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>R</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>SL</i> 314.17 X
21	1	HORN BRACKET	\$	<i>R</i> 40.45 X
22	1	HEADLAMP LH	\$	<i>CM</i> 1,184.43 ✓
22	1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
22	1	HEADLAMP RH	\$	<i>mycm</i> 1,184.43 ✓
22	1	HEADLAMP HARNESS	\$	<i>R</i> 928.29 X
22	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
26	1	BONNET	\$	<i>B</i> 1,941.63 ✓

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

27	1	BONNET INSULATOR	\$	S _h	405.73	X
28	1	BONNET STRUT LH	\$	S _h	88.61	X
29	1	BONNET STRUT RH	\$	S _h	88.61	X
30	1	BONNET HINGE LH	\$	R	348.31	X
31	1	BONNET HINGE RH	\$	R	348.31	X
32	1	BONNET LOCK	\$	DIT	305.48	
33	1	BONNET CABLE	\$	S _h	119.19	X
34	1	BONNET CABLE COVER	\$	S _h	161.03	
35	1	BONNET SEAL OUTER	\$	S _h	92.36	
36	1	BONNET SEAL INNER	\$	S _h	157.28	
37	1	FENDER PANEL FRT LH	\$	R	783.83	
38	1	WHEELARCH FRT LH	\$	S _h	278.84	
39	1	FENDER BRACKET LOWER LH	\$	S _h	15.79	
40	1	FENDER INSULATOR LH	\$	S _h	130.84	
41	1	FENDER PANEL FRT RH	\$	R	783.83	
42	1	WHEELARCH FRT RH	\$	S _h	278.84	
43	1	FENDER BRACKET LOWER RH	\$	S _h	15.79	
44	1	FENDER INSULATOR RH	\$	S _h	130.84	
45	1	WIPER RESERVOIR	\$	S _h	348.25	
46	1	WIPER RESERVOIR NECK	\$	S _h	136.11	
47	1	WIPER RESERVOIR MOTOR	\$	S _h	270.06	
48	1	AIR CLEANER LOWER	\$	S _h	271.26	X
49	1	AIR CLEANER HOSE	\$	S _h	76.14	
50	1	AIR CLEANER BOX	\$	S _h	464.20	
51	1	TURBO DUCT	\$	S _h	1,027.80	
52	1	A/C HEATER VALVE	\$	S _h	484.50	
53	1	SUBFRAME OUTER FRT	\$	S _h	2,652.45	
54	1	SUBFRAME BRACKET OUTER LH	\$	R	92.36	
55	1	SUBFRAME BRACKET OUTER RH	\$	R	92.36	
56	1	ENGINE UNDERTRAY	\$	S _h	564.98	
57	1	A/C CONDENSER	\$		2,020.37	?
58	1	A/C CONDENSER GARNISH LH UPPER	\$	S _h	39.67	X
59	1	A/C CONDENSER GARNISH RH UPPER	\$	S _h	39.67	
60	1	A/C CONDENSER GARNISH LH	\$	S _h	58.81	
61	1	A/C CONDENSER GARNISH RH	\$	S _h	59.60	
62	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	S _h	208.39	
63	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	S _h	658.72	
74	1	A/C PIPE COMPRESSOR	\$	S _h	334.29	

Trans-cab Auto Services Pte Ltd**AAD1812-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

75	1	A/C PIPE	\$	S\$ 658.72	} X
76	1	A/C COMPRESSOR	\$	H 2,684.61	
77	1	AIR COOLER	\$	S\$ 792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	S\$ 1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	S\$ 375.14	
80	1	TRANSMISSION COOLER	\$	S\$ 1,219.30	}
81	1	TRANSMISSION COOLER PAD	\$	S\$ 17.96	
82	1	RADIATOR	\$	1,202.20 ?	} X
83	2	RADIATOR STUD UPPER	\$	S\$ 14.41	
84	2	RADIATOR BUSH UPPER	\$	S\$ 50.12	
85	2	RADIATOR MTG LOWER	\$	S\$ 55.85	
86	1	RADIATOR FAN COWLING	\$	S\$ 820.54	
87	1	RADIATOR FAN MOTOR LH	\$	S\$ 967.36	
88	1	RADIATOR FAN MOTOR RH	\$	S\$ 1,479.46	
89	1	RADIATOR TANK	\$	S\$ 324.62	
90	1	RADIATOR HOSE UPPER	\$	S\$ 240.56	
91	1	RADIATOR HOSE LOWER	\$	S\$ 491.18	
92	1	RADIATOR TANK HOSE	\$	S\$ 61.18	
93	1	AUTO COMPUTER	\$	S\$ 5,032.17	
94	1	INJECTION COMPUTER	\$	S\$ 4,706.30	
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S\$ 5,154.52	
96	1	STEERING PUMP ELECTRIC	\$	S\$ 2,306.90	
97	1	STEERING PINION RACK	\$	S\$ 4,413.11	

TOTAL	\$	63,994.74
10%	\$	6,399.47
	\$	57,595.27

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	H 52.00	✓
2	1SET	BUMPER CLIP FRT	\$	H 66.00	✓

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	}	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50		
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00		
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50		
7	1	TOW COVER FRT	\$	Sh	14.50		
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00		
21	1	Windscreen moulding	\$	na	100.00		
22	1SET	Front licence plate with holder	\$	Pl	80.00		

TOTAL	\$	562.50
TOTAL PARTS	\$	58,157.77

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	500 6,000.00
Towing Fees.	\$	120.00 500
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 4400
To rust-proofing of the affected areas.	\$	170.00 300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00 X
To check steering geometry and computer wheel alignment	\$	na 220.00 X

Trans-cab Auto Services Pte Ltd

AAD1812-046

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9910Z

To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To lift-up engine with gear box and refit.	\$	nn 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To remove and refit air bag system and reset.	\$	nn 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 1001
To replace, refix and top up coolant for radiator	\$	170.00 501
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X

TOTAL	\$	17,000.00
--------------	-----------	------------------

Over All Total	\$	75,157.77
-----------------------	-----------	------------------

Repair Days (LUMP SUM)	20 Days
-------------------------------	----------------

4 days

LJK Auto Consultants hence notify
 the Repairer of the following:
 • To ensure below work is completed
 • To ensure damaged parts during recovery
 • Parts price must be in confirmation
 • This recovery is on a "Without Prejudice" basis
 • No claim settlement is allowed
 • Settlement must be recovered after
 is subject to approval from Insurance Company

Authorized Signatory

Signature

Date

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD9910Z

Vehicle to be Exported: Yes

Intended Deregistration Date: 06 Dec 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C001172

Chassis No.: VF1ABL15AUC277432

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 05 Jun 2014

First Registration Date: 05 Jun 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 04 Jun 2022

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 04 Jun 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$57,338.00

COE Rebate Amount: \$25,049.00

Total Rebate Amount: \$34,422.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Dec 2018

OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CC3/TP18022130/Kha3q2

NO.2 ANG MO KIO STREET 63 SINGAPORE 569111

Date : 11-02-2020



Code : TP378

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHD 9910Z
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	07/12/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC277432	Colour	METALLIC WHITE / RED
Odometer	536906	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S & FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/12/2018	Inspection Date	07/12/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	16 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.1 of 9

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9910Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BENT / CRACKED	1,108.46	1,108.46
1	BUMPER LOWER REAR	CRACKED	768.84	768.84
1	BUMPER BRACKET CTR REAR	CRACKED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	CRACKED	135.97	135.97
1	BUMPER RETAINER LH REAR	CRACKED	44.99	44.99
1	BUMPER REFLECTOR LH	BROKEN	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKER LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKER RH REAR	BENT	225.95	225.95
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-

Report Ref No. CC3/TP18022130/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER PANEL REAR LH	BUCKLED	3,299.13	3,299.13
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR LH	DEFORMED	671.45	671.45
1	FUEL FLAG	SERVICEABLE	343.57	-
1	WHEEL HOUSING PANEL REAR LH	TO REPAIR SEE LABOUR	4,682.09	-
1	CHASSIS PANEL REAR LH L70Y	BENT	3,766.43	3,766.43
1	TAILLAMP LH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	BENT	986.70	986.70
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	BENT / BUCKLED	2,189.88	2,189.88
1	SPARE WHEEL PANEL TIRM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	BUMPER COVER FRT	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	DENTED	225.36	225.36
1	RADIATOR GRILLE FRAME	CRACKED	1,353.75	1,353.75

Report Ref No. CC3/TP18022130/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRAME FULL SUPPORT PANEL	CRACKED	615.90	615.90
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	CRACKED	1,184.43	1,184.43
1	HEADLAMP HARNESS	SERVICEABLE	928.29	-
1	HEADLAMP RH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP HARNESS	TO REPAIR SEE LABOUR	928.29	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	BENT	1,941.63	1,941.63
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	DISTORTED	305.48	305.48
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-

Report Ref No. CC3/TP18022130/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	TURBO DUCT	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET OUTER RH	TO REPAIR SEE LABOUR	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPANSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	TO REPAIR SEE LABOUR	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-

Report Ref No. CC3/TP18022130/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	INJECTION COMPUTER	SERVICEABLE	4,706.30	-
1	RHD HYDRAULIC POWER (RACK & PINION)	SERVICEABLE	5,154.52	-
1	STEERING PUMP ELECTRIC	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK	SERVICEABLE	4,413.11	-
	LESS 10% DISCOUNT		-10,227.94	-3,038.22
			92,051.48	27,343.94
1	BOOT WEATHERSTRIP (50%) (SN)	CUT	323.05	161.53
	LESS 10% DISCOUNT		-32.31	-
			290.74	161.53
SPECIAL NETT ITEMS				
1	SET PARKING AID (SN)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-

Report Ref No. CC3/TP18022130/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER '6555-3333' (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NECESSARY	28.00	28.00
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	DENTED	80.00	25.00
			2,787.52	1,171.00
LABOUR				
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .			6,000.00	1,100.00

Report Ref No. CC3/TP18022130/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,BOOT LOCK CATCH,WHEEL HOUSING PANEL REAR LH,EXHAUST REAR AND EXHAUST CAP REAR.		6,000.00	2,000.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.}		170.00	60.00
	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.}		170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.)		170.00	100.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.)		170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.		380.00	80.00
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,FRAME FULL SUPPORT BRACKET,FRONT BRACE PANEL,HORN BRACKET,HEADLAMP HARNESS,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,}		-	-
	BONNET HINGE LH,BONNET HINGE RH,FENDER PANEL FRT LH,FENDER PANEL FRT RH,SUBFRAME BRACKET OUTER LH,SUBFRAME BRACKET OUTER RH AND A/C COMPRESSOR.		6,000.00	500.00

Report Ref No. CC3/TP18022130/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP,OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK ,PIPES ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			31,720.00	4,890.00
GRAND TOTAL			126,849.74	33,566.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,500.00

Report Ref No. CC3/TP18022130/Kha3q2



Report Ref No. CC3/TP18022130/Kha3q2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.