

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 745Z

DATE: 10. Dec. 2018

MAKE : HYUNDAI

MODEL : i40

DOA: 10. Dec. 2018

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper ✓			\$553.00
10	Rear Bumper Clips ✓		\$2.20	\$22.00
1	Rear Bumper Sponge ?			\$103.50
2	Rear Bumper Brackets – RH/LH ✓		\$80.30	\$160.60
1	Rear Bumper Undercover ✓			\$228.00
1	Rear Bumper Reflector – RH ✕			\$27.40
SUB TOTAL				\$1,094.50
LESS 20%				\$218.90
DISCOUNTED TOTAL				\$875.60
1	Reverse Sensor ✕			\$135.70
1	Advertisement – Rear Bumper ✓			\$50.00
2	Advertisement – Rear Fender – RH/LH ✓		\$100.00	\$200.00
1	Rear Bumper Rubber Mat ✓			\$50.00
				\$435.70
Labour Charge				
1	Panel Beating			\$300.00
1	Spray Painting Charge			\$300.00
1	Remove/refix Reverse Sensor			\$120.00
TOTAL LABOUR				\$720.00
ESTIMATE TOTAL				\$2,031.30
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No final quotation(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Larry Ng

1/Calvin 11/11/14

11/12/14 11:00h

2 hrs

L/s

After Repair p 16

Nett

Nett

Nett

200

200

200