

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1812/003
Policy No:	5104565643	Date of Loss:	05/12/2018
Vehicle Reg. No.:	SMD4107A	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SHF664H
Any Injuries?	no	Contact No:	
Insured/Claimant:	IRENE LIM LEH LING	Driver:	PETER KNG WEE HONG

Make/Model:	Honda, Civic - JHMF16	Vehicle Reg. Date:	28/08/2012
Vehicle Colour:	WHITE	Engine Number:	R16B11001673
Chassis No:	JHMF1630CS201171	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - CHANGE/CROSS LANE
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	3,136.10
Miscellaneous Items	59.00
Labour	810.00
Paintwork Labour	750.00
Towing	0.00

Gross Total(\$\$):	4,755.10
GST 7.00%(\$\$):	332.86
Nett Amount(\$\$):	5,087.96

This claim is handled by: Sky Toh T C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not authorized
man
d/s
3 days
12/12/18
take photo after rep.

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>Deep cut</i>	0.00	264.00	+10.00	290.40 ✓
2	1	REAR BUMPER SIDE RETAINER RH <i>MR</i>	0.00	12.00	+10.00	13.20 ✓
3	1	REAR FENDER RH <i>n</i>	0.00	561.00	+10.00	617.10 X
4	1	REAR DOOR RH <i>n</i>	0.00	0.00	+10.00	0.00 X
5	1	REAR WHEEL RIM RH <i>cut</i>	0.00	720.00	+10.00	792.00 450
6	1	REAR WHEEL HUB RH <i>17</i>	0.00	330.00	+10.00	363.00 X
7	1	REAR WHEEL HUB BEARING RH <i>17</i>	0.00	180.00	+10.00	198.00 X
8	1	REAR SHOCK ABSORBER RH <i>17</i>	0.00	154.00	+10.00	169.40 X
9	1	REAR LOWER ARM RH <i>17</i>	0.00	319.00	+10.00	350.90 X
10	1	REAR KNUCKLE ARM RH <i>17</i>	0.00	231.00	+10.00	254.10 X
11	1	REAR WINDSCREEN MOULDING <i>17</i>	0.00	80.00	+10.00	88.00
Total Parts (\$\$)						3,136.10

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS <i>MR</i>	0.00	35.00	0.00	35.00 ✓
2	1	REAR WINDSCREEN SEALANT <i>17</i>	0.00	24.00	0.00	24.00 X
Sub Total (\$\$)						59.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 20
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 50
3	1	To Conduct Computer Wheel Alignment.	80.00	80.00	0.00	80.00 ✓
4	1	To Dismantle and Refit Rear Undercarriage.	220.00	220.00	0.00 <i>17</i>	220.00 X
5	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00 <i>17</i>	100.00 X
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	300.00	300.00	0.00	300.00 ✓
Gross Labour Cost (\$\$)						810.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	50.00	0.00 <i>MR</i>	50.00 X
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	700.00	700.00	0.00	700.00 600
Gross Labour Cost (\$\$)						750.00