

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHC8144E  
 MAKE : HYUNDAI  
 MODEL : i40

DATE: 10. Dec. 2018

DOA: 6. Dec. 2018 **CHINA**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover <i>X repair</i>			\$544.50
1	Front Bumper Side Bracket - RH <i>X su</i>			\$24.60
1	Front Bumper Top Bracket - RH <i>X su</i>			\$22.40
10	Front Bumper Clips <i>X m</i>		\$2.20	\$22.00
1	Headlamp Panel <i>X su</i>			\$907.40
1	Headlamp - RH <i>X su</i>			\$1,388.00
1	Front Fender - RH <i>X su</i>			\$566.30
	<i>front RH wheel cover / hubcap</i>			<i>\$107.10</i>
	<b>SUB TOTAL</b>			<b>\$3,475.20</b>
	<b>LESS 20%</b>			<b>\$695.04</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$2,780.16</b>
1	Advertisement - LHF Fender <i>X m</i>			\$100.00 <b>Nett</b>
	<b>Labour Charge</b>			
1	Panel Beating			\$400.00 <i>200</i>
1	Spray Painting Charge			\$500.00 <i>200</i>
1	Tuff Kote			\$50.00 <i>X m</i>
1	Wiring Charge			\$50.00 <i>X m</i>
	<b>TOTAL LABOUR</b>			<b>\$1,000.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$3,880.16</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "As is" basis
- No illegal modifications
- Supplemental work is subject to approval

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

*Kalvin Ucky*  
*10/12/18 12:25h*  
*2 Bn*  
*PH*  
*After Repair photo*

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.