

ASS. REC. BY:

REF:

TJ /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 3156R Yr Regn: 01, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude cc 1995

Colour M. White/Red A/C: Insured / Std / NI / NA

Sp. Reading 426285 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABL15AUC 276551

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front B.S 6 mm Rear Dun 3 mm

R/Bal. 6 mm R/Bal. 3 mm

L/Bal. 7 mm L/Bal. 8 mm

D.O.A. 7/12/18 D.O.I. 10/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/12 File pass to Catherine, not ready

Lg 4,350.00

CASH: 40,541.71 (90%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

Kh

Trans-cab Auto Services Pte Ltd

AAD1812-052

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R

Not Authorised
U/Sy B 4350h
Re

Vehicle No.:

SHC 5156R

Chassis No.:

VF1ABL15AUC276551

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

7.12.2018

Third Party Insurer :

III

| PART | | LIST | |
|------|--------------------------------------|------|----------|
| 1 | DOOR PANEL REAR LH | \$ | 2,844.66 |
| 1 | DOOR GUIDE REAR LH | \$ | 176.82 |
| 1 | DOOR HINGE UPPER LH | \$ | 274.50 |
| 1 | DOOR HINGE LOWER LH | \$ | 300.55 |
| 1 | DOOR CHECK REAR LH | \$ | 203.06 |
| 1 | DOOR LOCK REAR LH | \$ | 908.75 |
| 1 | DOOR HANDLE OUTER REAR LH | \$ | 126.49 |
| 1 | DOOR HANDLE CAP REAR LH | \$ | 35.52 |
| 1 | DOOR HANDLE SEAL REAR LH | \$ | 7.89 |
| 1 | DOOR HANDLE COVER REAR LH | \$ | 13.22 |
| 1 | DOOR HANDLE MODULE REAR LH | \$ | 133.60 |
| 1 | DOOR REGULATOR REAR LH | \$ | 1,135.10 |
| 1 | DOOR REGULATOR MOTOR REAR LH | \$ | 893.75 |
| 1 | DOOR REGULATOR NUT REAR LH | \$ | 12.43 |
| 1 | DOOR REGULATOR MOTOR SCREW REAR L70Y | \$ | 6.31 |
| 1 | DOOR FINISHER REAR LH | \$ | 423.10 |
| 1 | DOOR MOULDING REAR LH | \$ | 176.82 |
| 1 | DOOR MOULDING CLIP L70Y | \$ | 5.92 |
| 1 | DOOR MOULDING SCREW L70Y | \$ | 6.91 |
| 1 | DOOR CASING REAR LH | \$ | 1,509.06 |
| 1 | DOOR WATER SHIELD REAR LH | \$ | 30.39 |
| 1 | DOOR CASING CLIP | \$ | 12.63 |
| 1 | DOOR CASING LIGHT L70Y | \$ | 48.74 |
| 1 | DOOR FINISHER INNER REAR LH | \$ | 323.44 |
| 1 | DOOR FINISHER BRACKET INNER REAR LH | \$ | 46.97 |
| 1 | DOOR FINISHER BRACKET INNER REAR LH | \$ | 20.33 |
| 1 | DOOR FINISHER BRACKET INNER REAR LH | \$ | 20.33 |
| 1 | DOOR FINISHER BRACKET INNER REAR LH | \$ | 20.33 |
| 1 | DOOR GRAB HANDLE REAR LH | \$ | 210.96 |

Trans-cab Auto Services Pte Ltd

AAD1812-052

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R

| | | | | |
|---|--------------------------------|--------|------------------|---|
| 1 | DOOR BLIND REAR LH | \$ | 741.80 | } |
| 1 | DOOR WHEATHESTRIIP REAR LH | \$ | 410.66 | |
| 1 | DOOR SEAL REAR LH | \$ | 162.02 | |
| 1 | DOOR GLASS RUNNER SEAL REAR LH | \$ | 229.31 | |
| 1 | DOOR WAIST SEAL OUTER REAR LH | \$ | 334.69 | |
| 1 | DOOR WAIST SEAL INNER REAR LH | \$ | 115.64 | } |
| 1 | FENDER PANEL REAR LH | \$ | 3,299.13 | |
| 1 | FENDER PANEL INNER TRIM REAR | \$ | 671.45 | |
| 1 | WHEELARCH REAR LH | \$ | 543.47 | |
| 1 | ROCKER PANEL INNER GARNISH LH | \$ | 466.51 | |
| 1 | ROCKER PANEL INNER LH | \$ | 1,024.79 | } |
| 1 | ROCKER PANEL CENTER LH | \$ | 990.25 | |
| 1 | WHEEL HOUSING PANEL REAR LH | \$ | 4,682.09 | |
| 1 | CHASSIS PANEL REAR LH L70Y | \$ | 3,766.43 | |
| 1 | HEADLAMP LH | \$ | 1,184.43 | |
| 1 | BUMPER COVER REAR | \$ | 1,108.46 | } |
| 1 | BUMPER LOWER REAR | \$ | 768.84 | |
| 1 | BUMPER BRACKET CTR REAR | \$ | 113.47 | |
| 1 | BUMPER BRACKET SIDE LH REAR | \$ | 135.97 | |
| 1 | BUMPER RETAINER LH REAR | \$ | 44.99 | |
| 1 | FUEL FLAP L70Y | \$ | 343.57 | } |
| 1 | DOOR PANEL FRT LH | \$ | 2,844.66 | |
| | | \$ | 33,911.20 | |
| | | 10% \$ | 3,391.12 | |
| | | \$ | 30,520.08 | |

Special Nett

| | | | | |
|---|-------------------------------|----|---------------|---|
| 1 | REAR DOOR STICKER '6555 3333' | \$ | 80.00 | } |
| 1 | DOOR CHECK BOLT | \$ | 22.69 | |
| 1 | DOOR GUIDE SCREW | \$ | 10.85 | |
| 1 | DOOR HINGE BOLT | \$ | 10.85 | |
| 1 | DOOR HINGE NUT RH | \$ | 14.60 | |
| 1 | DOOR CHECK BOLT | \$ | 22.69 | |
| 1 | DOOR CHECK NUT | \$ | 3.75 | |
| 1 | DOOR LOCK SCREW L70Y | \$ | 6.12 | |
| 1 | DOOR CATCH SCREW L70Y | \$ | 10.06 | |
| | TOTAL | \$ | 181.63 | |

Trans-cab Auto Services Pte Ltd

AAD1812-052

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5156R

| | | |
|--------------------|-----------|------------------|
| TOTAL PARTS | \$ | 30,701.71 |
|--------------------|-----------|------------------|

LABOUR

| | | | |
|---|----|----------|-----|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 6,000.00 | 800 |
| Putty and spray painting of the affected portion. | \$ | 6,000.00 | 440 |
| To rust-proofing of the affected areas. | \$ | 170.00 | 30 |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | 380.00 | 100 |
| To check steering geometry and computer wheel alignment | \$ | 220.00 | ~ X |
| To transfer of tire, rim and on wheel balancing. | \$ | 170.00 | ~ X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 | 20 |
| To transfer of Rear fender fittings, attachment and perform water seepage test. | \$ | 380.00 | ~ X |
| To transfer of Rear bumper fittings, attachment and perform water seepage test. | \$ | 380.00 | 60 |
| To transfer of Rear door fittings, attachment and perform water seepage test. | \$ | 380.00 | ~ X |

| | | |
|--------------|-----------|------------------|
| TOTAL | \$ | 14,250.00 |
|--------------|-----------|------------------|

| | | |
|-----------------------|-----------|------------------|
| Over All Total | \$ | 44,951.71 |
|-----------------------|-----------|------------------|

LUMP SUM (REPAIR DAY)**20 DAYS**
5 day

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|---|---------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 3878K |
| Vehicle Details | |
| Vehicle No.: | SHC5156R |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 07 Dec 2018 |
| Vehicle Make: | RENAULT |
| Vehicle Model: | LATITUDE 2.0L DCI AUTO D/AB 4DR |
| Primary Colour: | Red |
| Manufacturing Year: | 2013 |
| Engine No.: | M9R8839C000857 |
| Chassis No.: | VF1ABL15AUC276551 |
| Maximum Power Output: | 127.0 kW (170 bhp) |
| Open Market Value: | \$19,998.00 |
| Original Registration Date: | 14 Jan 2014 |
| First Registration Date: | 14 Jan 2014 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$12,498.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 13 Jan 2022 |
| PARF Rebate Amount: | \$9,373.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 13 Jan 2022 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 8 |
| PQP Paid: | \$60,888.00 |
| COE Rebate Amount: | \$23,590.00 |
| Total Rebate Amount: | \$32,963.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 07 Dec 2018

OK

Print Received Message

This mail is associated with :

***SHC5156R (MCT18120180)**

[SHC1942P]

TP

TRANS-CAB SERVICES PTE LTD

Dec 7 2018 3:00AM

Trans-cab Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 22/02/2019 10:54 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SHC5156R - Claim Handler: Sherini Pillai

Approved:0.00:video footage clearly shows TP beat Red Light. As such, kindly reject claim

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 27 February, 2019 1:45 PM
To: Ng Wai Yin
Cc: claims; 'Jasmine Tan'; Admin A; Vic (LKKAUTO)
Subject: RE: TCS REF: AAD1812-052--Accident involving SHC1942P & SHC5156R on 07.12.18 (MCT18120180/SP) LKK REF CC3/III18022292/Kha3
Attachments: Video - Accident.MP4

Without Prejudice

Dear Wai Yin,

We refer to the below email.

Please be informed that our principal had further reviewed the matter and based on the available information and evidence provided, our principal is in the view that our Insured Driver is not liable of this accident.

Our Insured reported that he was crossing the junction with traffic light still on his favour. Please see attached video footage for your reference.

As such, we have our principal's instruction and we are unable to look into your client's claim.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Ng Wai Yin [<mailto:waiyin.ng@transcab.com.sg>]
Sent: 19 February, 2019 2:31 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Gabriel Wee <Gabriel@iii.com.sg>
Subject: TCS REF: AAD1812-052--Accident involving SHC1942P & SHC5156R on 07.12.18

WITHOUT PREJUDICE

Dear Sir/ Madam

We are making a claim against your client SHC 1942P.

Enclosed is our GIA report and LOD for your perusal and action.

Original hard copy will be mailed to you by post.

Hope to receive your offer soon.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|---|---------------|--|---|---|------------|---|
| Main | 11 Dec 2018 Edit Reg | | 10 Dec 2018 00:00 Edit Adj Rpt | \$4,350.00 Edit Estimates | \$4,350.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R | | | | | | | | |
| Main Claimant: | TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K | | | | | | | | |
| Vehicle Reg. No.: | SHC5156R | Date of Loss: | 07/12/2018 03:00 - :59 [58 Months and 23 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / MCT18120180 | Policy/Cover Note No.: | MCOM0015 | | | | | | |
| Vehicle Reg. No. (Insured): | SHC1942P | Policy No. (Claimant): | VPX/P1680520 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: | | | | | | | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai] | | | | | | | | |
| Claimant's Insurer: | AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/12/2018] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> III_SG (22/02/2019): Alert - Adj Mandate Approved (\$0.00) - SHC5156R - Claim Handler: Sherini Pillai III_SG (14/12/2018): Alert - Adj Mandate Maintained - SHC5156R - Claim Handler: Sherini Pillai | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SHC5156R (MCT18120180)
[SHC1942P]
TP
TRANS-CAB SERVICES PTE LTD
Dec 7 2018 3:00AM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
|---|-----------------|--|---|-------------------------------------|
| Video | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 19/02/19 15:16 | Video - Accident (OID) | Load MP4 | |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 26/12/18 09:36 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 26/12/18 09:36 | Chassis Number | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 26/12/18 09:37 | General View | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 14/12/18 11:00 | TP ESTIMATE - MARKED | Load PDF | |
| 2 | 14/12/18 11:00 | TP GIA REPORT | Load PDF | |
| 3 | 27/02/19 13:46 | EMAIL TO TP REJECT | Load PDF | |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 12/12/18 09:17 | Singapore Accident Statement | Load PDF | |

Documents Checklist

| | | | |
|--|--|--|--|
| DOCUMENTS CHECKLIST | | | Reset Save Print |
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18022292/KHA3Q2

Date: 28/02/2019

REFERENCE

| | | | |
|-----------------------|---------------------------------------|----------------------|-------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | MCOM0015 |
| Claimant Vehicle No : | SHC5156R | Insured Vehicle No : | SHC1942P |
| Date of Loss: | 07/12/2018 | Nature of Claim: | TP |
| | | Claim No: | MCT18120180 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | SHC5156R | | |
| Make & Model: | RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) | Engine No: | M9R8839C000857 |
| Reg. Date: | 14/01/2014 (Man. Year: 2013) | Chassis No: | VF1ABL15AUC276551 |
| Colour: | Metallic White/Red | Odometer: | 426285 km |
| Engine Capacity: | 1995 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|-------------|
| Front Tyre Size: | 215/60 R16 | Rear Tyre Size: | 215/60 R16 |
| Front Left Side: | Giti 7 mm | Rear Left Side: | Giti 8 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Dunlop 3 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|------------------|--------------|
| Parts | 30,701.70 | 3,966.83 | 26,734.87 | 87.08 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 14,250.00 | 1,450.00 | 12,800.00 | 89.82 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 44,951.70 | 5,416.83 | 39,534.87 | 87.95 |
| Approved Total (Overridden) (S\$) | | 4,350.00 | | |
| (S\$) | 44,951.70 | 4,350.00 | 40,601.70 | 90.32 |
| + GST 7.00/7.00% (S\$) | 3,146.62 | 304.50 | 2,842.12 | 90.32 |
| Nett Amount (S\$) | 48,098.32 | 4,654.50 | 43,443.82 | 90.32 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 10/12/2018 | | |
| Date Inspected: | 10/12/2018 | Inspected At: | Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111 |
| Estimated Period of Repair: | 5.0 days | | |

Adjuster: KENNETH KONG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 28 Feb 2019) |
| Parts: 143 | RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SHC5156R) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|-------------|-------------|--------------|
| 1 | 1 | | *DOOR PANEL REAR LH | Repair | 2,844.66 FL | *-FL |
| 2 | 1 | | *DOOR GUIDE REAR LH | Serviceable | 176.82 FL | *-FL |
| 3 | 1 | | *DOOR HINGE UPPER LH | Repair | 274.50 FL | *-FL |
| 4 | 1 | | *DOOR HINGE LOWER LH | Repair | 300.55 FL | *-FL |
| 5 | 1 | | *DOOR CHECK REAR LH | Serviceable | 203.06 FL | *-FL |
| 6 | 1 | | *DOOR LOCK REAR LH | Repair | 908.75 FL | *-FL |
| 7 | 1 | | *DOOR HANDLE OUTER REAR LH | Serviceable | 126.49 FL | *-FL |
| 8 | 1 | | *DOOR HANDLE CAP REAR LH | Serviceable | 35.52 FL | *-FL |
| 9 | 1 | | *DOOR HANDLE SEAL REAR LH | Serviceable | 7.89 FL | *-FL |
| 10 | 1 | | *DOOR HANDLE COVER REAR LH | Serviceable | 13.22 FL | *-FL |
| 11 | 1 | | *DOOR HANDLE MODULE REAR LH | Serviceable | 133.60 FL | *-FL |
| 12 | 1 | | *DOOR REGULATOR REAR LH | Serviceable | 1,135.10 FL | *-FL |
| 13 | 1 | | *DOOR REGULATOR MOTOR REAR LH | Serviceable | 893.75 FL | *-FL |
| 14 | 1 | | *DOOR REGULATOR NUT REAR LH | Serviceable | 12.43 FL | *-FL |
| 15 | 1 | | *DOOR REGULATOR MOTOR SCREW REAR L70Y | Serviceable | 6.31 FL | *-FL |
| 16 | 1 | | *DOOR FINISHER REAR LH | Serviceable | 423.10 FL | *-FL |
| 17 | 1 | | *DOOR MOULDING REAR LH | Serviceable | 176.82 FL | *-FL |
| 18 | 1 | | *DOOR MOULDING CLIP L70Y | Serviceable | 5.92 FL | *-FL |
| 19 | 1 | | *DOOR MOULDING SCREW L70Y | Serviceable | 6.91 FL | *-FL |
| 20 | 1 | | *DOOR CASING REAR LH | Serviceable | 1,509.06 FL | *-FL |
| 21 | 1 | | *DOOR WATER SHIELD REAR LH | Serviceable | 30.39 FL | *-FL |
| 22 | 1 | | *DOOR CASING CLIP | Serviceable | 12.63 FL | *-FL |
| 23 | 1 | | *DOOR CASING LIGHT L70Y | Serviceable | 48.74 FL | *-FL |
| 24 | 1 | | *DOOR FINISHER INNER REAR LH | Serviceable | 323.44 FL | *-FL |
| 25 | 1 | | *DOOR FINISHER BRACKET INNER REAR LH | Serviceable | 46.97 FL | *-FL |
| 26 | 1 | | *DOOR FINISHER BRACKET INNER REAR LH | Serviceable | 20.33 FL | *-FL |
| 27 | 1 | | *DOOR FINISHER BRACKET INNER REAR LH | Serviceable | 20.33 FL | *-FL |
| 28 | 1 | | *DOOR FINISHER BRACKET INNER REAR LH | Serviceable | 20.33 FL | *-FL |
| 29 | 1 | | *DOOR GRAB HANDLE REAR LH | Serviceable | 210.96 FL | *-FL |
| 30 | 1 | | *DOOR BLIND REAR LH | Serviceable | 741.80 FL | *-FL |
| 31 | 1 | | *DOOR WEATHERSTRIP REAR LH | Serviceable | 410.66 FL | *-FL |
| 32 | 1 | | *DOOR SEAL REAR LH | Serviceable | 162.02 FL | *-FL |
| 33 | 1 | | *DOOR GLASS RUNNER SEAL REAR LH | Serviceable | 229.31 FL | *-FL |
| 34 | 1 | | *DOOR WAIST SEAL OUTER REAR LH | Serviceable | 334.69 FL | *-FL |
| 35 | 1 | | *DOOR WAIST SEAL INNER REAR LH | Serviceable | 115.64 FL | *-FL |
| 36 | 1 | | *FINISHER PANEL REAR LH | Bent | 3,299.13 FL | *3,299.13 FL |
| 37 | 1 | | *FINISHER PANEL INNER TRIM REAR | Serviceable | 671.45 FL | *-FL |
| 38 | 1 | | *WHEELARCH REAR LH | Serviceable | 543.47 FL | *-FL |
| 39 | 1 | | *ROCKER PANEL INNER GARNISH LH | Serviceable | 466.51 FL | *-FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------|---------------|-------------|--------------|
| 40 | 1 | | *ROCKER PANEL INNER LH | Repair | 1,024.79 FL | *- FL |
| 41 | 1 | | *ROCKER PANEL CENTER LH | Repair | 990.25 FL | *- FL |
| 42 | 1 | | *WHEEL HOUSING PANEL REAR LH | Repair | 4,682.09 FL | *- FL |
| 43 | 1 | | *CHASSIS PANEL REAR LH L70Y | Repair | 3,766.43 FL | *- FL |
| 44 | 1 | | *HEADLAMP LH | Serviceable | 1,184.43 FL | *- FL |
| 45 | 1 | | *BUMPER COVER REAR | Buckled | 1,108.46 FL | *1,108.46 FL |
| 46 | 1 | | *BUMPER LOWER REAR | Serviceable | 768.84 FL | *- FL |
| 47 | 1 | | *BUMPER BRACKET CTR REAR | Serviceable | 113.47 FL | *- FL |
| 48 | 1 | | *BUMPER BRACKET SIDE LH REAR | Serviceable | 135.97 FL | *- FL |
| 49 | 1 | | *BUMPER RETAINER LH REAR | Serviceable | 44.99 FL | *- FL |
| 50 | 1 | | *FUEL FLAP L70Y | Serviceable | 343.57 FL | *- FL |
| 51 | 1 | | *DOOR PANEL FRT LH | Repair | 2,844.66 FL | *- FL |
| 52 | 1 | | *REAR DOOR STICKER 6555 3333 | Not Necessary | 80.00 FS | *- FS |
| 53 | 1 | | *DOOR CHECK BOLT | Not Necessary | 22.69 FS | *- FS |
| 54 | 1 | | *DOOR GUIDE SCREW | Not Necessary | 10.85 FS | *- FS |
| 55 | 1 | | *DOOR HINGE BOLT | Not Necessary | 10.85 FS | *- FS |
| 56 | 1 | | *DOOR HINGE NUT RH | Not Necessary | 14.60 FS | *- FS |
| 57 | 1 | | *DOOR CHECK BOLT | Serviceable | 22.69 FS | *- FS |
| 58 | 1 | | *DOOR CHECK NUT | Serviceable | 3.75 FS | *- FS |
| 59 | 1 | | *DOOR LOCK SCREW L70Y | Serviceable | 6.12 FS | *- FS |
| 60 | 1 | | *DOOR CATCH SCREW L70Y | Serviceable | 10.06 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 34,092.82 | 4,407.59 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 3,391.12 | 440.76 |
| Total Parts (\$\$) | 30,701.70 | 3,966.83 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|------------------|-----------------|
| Labour Items | | | | |
| 1 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 6,000.00 | 800.00 |
| 2 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 6,000.00 | 440.00 |
| 3 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | 30.00 |
| 4 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 100.00 |
| 5 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 6 | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 7 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 20.00 |
| 8 | TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 9 | TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 60.00 |
| 10 | TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 14,250.00 | 1,450.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >