

22/03/2002

ASS. REC. BY:

REF:

CS/FCL18032319/K gbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office) ✓

From (Person): (WS Eileen Lee

of

FCL

Date/Time:

11.12.018 532pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 6256L

Insured:

SH 8888K

at Workshop m/s

Complete vms

Tel:

of

176 Sin Ming Drive #03-14

Policy No:

Claim No:

D18008760MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19-12-1018

(Client's Record)

CA / REV / REP. / REV 24 HRS / 100% IDS

12.12.018

H.O.D. Endorsement:

Date/Time: 11.12.018 550pm.

Person Contacted:

Li Hin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLB 6256L - X

SH 8888K - RES / 12/11/014069 / Hjt/gj

DA: 15072011

13/12/018 7.02pm revised to Eileen Lee by email.

31/12 82761.70 email & confirm (Red to 7325.85, 46%)

REF:

FD.

ASSIGNMENT

From:

Date:

12-12-2018

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLB 61562

at Workshop m/s

Complete VMS

of

Blk 176 Sin Ming Drive #03-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8137k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLB 62562

Yr Regn:

04 16

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

M C 200

C.C.

1991

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

46456

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W002050422R121458

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F: Yoko 205/60R16

R: Mic

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

4

mm

L/Bal.

9

mm

L/Bal.

4

mm

D.O.A.

9/12/18

D.O.I.

12/12/18

Survey held at

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Rear d/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/12 File pass to Catherine

RECEIVED 02 JAN 2019

Date/Time, File Pass to?

1) 07/11 11:00 AM

Date/Time, File Return to?

2)

Report Format:

7P

Lump Sum / I.B.I. (\$)

2761.70

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

) \$ + R5. SI

) Photos

) Others

TOTAL

140

50

50

13

253



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008760MFSH

Date: 13 December 2018

Our Ref: CS/FCI18022319/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 6256L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/12/2018 at the premises of M/s COMPLETE VMS and have the following to report:-

Workshop Estimate Amount	: S\$ 5,097.55 .
Revised Estimate Amount	: S\$ 2,761.70 .
"Check" Items Amount	: S\$ 363.85 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	11-12-2018	Our Ref No. D18008760MFSH
Accident Date	09-12-2018	Claim Type. Third Party
Insured Vehicle	SH8888K	Third Party Vehicle. SLB6256L
Survey Location	176 SIN MING DRIVE #03-14SIN MING AUTOCARE COMPLEX	
Contact Person.	LILY/LI HUI (TEL: 64539622)	
Contact No.	64550012/ 0	Fax No. 65540012
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	COMPLETE VMS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 13 December 2018 3:02 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008760MFSH/1
Attachments: CSFC118022319Kqb.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLB 6256L.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 11 December 2018 5:47 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008760MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin
LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 11 December, 2018 5:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008760MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

K THOMAS ABRAHAM
44 SIRAT ROAD
SINGAPORE 545798

Attention : THE OWNER
Contact : 85222499

Estimate : ES006537

Date : 11/12/2018
Vehicle Num. : SLB6256L
Make/Model : MERCEDES C200-2016
Chassis/Eng# : WDD2050422R121458/274920304813
Accident Date : 09/12/2018
Claim No. :
Reference :
Policy No. :

Not Authorised
1. B.1
Runway B4 pain
2 days
82761.70

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS :		
2.	1	REAR BUMPER		
3.	8	REAR BUMPER TOW COVER		
4.	1	REAR BUMPER CLIP		
5.	1	REAR BUMPER INSIDE PART		
6.	2	REAR BUMPER SPONGE		
7.	1	REAR BUMPER BRACKET		
		REAR BUMPER LOWER LIP		

Nett Total S\$:

5.00% Discount S\$:

1.	2	SPECIAL NETT ITEMS :		
		REVERSE SENSOR		

Special Nett Total S\$:

LABOUR :

RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED
CHANGE REVERSE SENSOR, DIAGNOSE AND RESETTNG
TO KNOCK AND STRAIGHTEN REAR END PANEL, REAR CHASSIS
FRAME AND CHANGE ALL NECESSARY PARTS

Labour Total S\$:

SingDollars : Five Thousand Ninety-Seven & Cents Fifty-Five Only

Total S\$: 5,097.55

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022319/Kqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 03-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8888K	Veh. Inspected	SLB 6256L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008760MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	11/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES C200 (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	201	
Chassis No.	WDD2050422R121458	Colour	BLACK	
Odometer	46456	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	9 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	9 mm	
R/H Rear Tyre	205/60 R16	MICHELIN	4 mm	
L/H Rear Tyre	205/60 R16	MICHELIN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/12/2018	Inspection Date	12/12/2018	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 6256L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	BUCKLED	1,817.00	1,817.00
1	REAR BUMPER TOW COVER (N)	DENTED	69.00	69.00
8	REAR BUMPER CLIP @\$8.00 (N)	NECESSARY	64.00	64.00
1	REAR BUMPER INSIDE PART (N)	SERVICEABLE	112.00	-
1	REAR BUMPER SPONGE (N)	SERVICEABLE	165.00	-
2	REAR BUMPER BRACKET @\$53.00 (N)	TO REPAIR SEE LABOUR	106.00	-
1	REAR BUMPER LOWER LIP (N)	CUT	336.00	336.00
	LESS 5% DISCOUNT		-133.45	-114.30
			2,535.55	2,171.70
SPECIAL NETT ITEMS				
2	REVERSE SENSOR @\$306.00 (SN)	SERVICEABLE	612.00	-
			612.00	-
LABOUR				
	RUST PROOFING TREATMENT.	NOT NECESSARY	100.00	-
	SPRAY PAINT DAMAGED AREA AFFECTED.		800.00	280.00
	CHANGE REVERSE SENSOR,DIAGNOSE AND RESETTING.		150.00	60.00
	TO KNOCK AND STRAIGHTEN REAR END PANEL,REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET.		900.00	250.00
			1,950.00	590.00
GRAND TOTAL			5,097.55	2,761.70
RECOMMENDED COST OF REPAIRS				2,761.70

Report Ref No. CS/FC118022319/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.